

Form 100

SALES REPRESENTATIVE

SURVEYOR

From (Person)

Estimated Cost

☒ ON

To Inspect Vehicle No.

at Workshop no.

of

Policy No.

Sum Insured

Make of Veh.
(Client's Record)

CA / REV

Date/Time

REF

ASSIGNMENT (Office)

SPF

Bill to

Insured

Tel.

Claim No.

Excess

D.O.A

H.O.D. Endorsement

Vehicle - IN / OUT

Person Contacted

05/SPF19004618/Jrd302

Hwee Jie

Wei Yea Kim 6478 4527

Date/Time 12/2/19 @ 5:26pm

QX 5249P

K&S

Sungei Kadut Drive 2D

9857 6861

HOMSPFET016000399

REV 24 HRS

11/3/19 @ 3:18pm

Mr. Kong

Date/Time	Action/Instruction	Estimate	D.O.A
	QX 5249P -	08/SPF19000772/Btd3	-
15/3/19	check with Hwee Jie man - HR follow		
15/3/19	Revert to Wei Yea by email		
3/4/19	@ 1134gm Kim Peng said can submit our report		
3/4/19	Parts - \$ 7392 man - HR C 86 HR		

ASS. REC. BY:

Hwee Jie

REF: CPF

Pls call Mr. Kong.

ASSIGNMENT

From:

Date:

12/31/19

Estimated Cost:

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No:

QX5249D

at Workshop m/s

K8S

of

Sungai Kadut Drive 2D

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Mr. Kong

9857 6861

afternoon pls call him

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

QX5249DP

Yr Regn:

22/04/2005

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Toyota Altis

C.C.

- 159

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: Nil / ☒ S/Rim / ☐ STD A/Rim or

Tyre Size:

F: 185/70 R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

13/3/19

Survey held at

K8S

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 03 APR 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

3/4 - typist

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format:

Lump Sum / L&L (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

20

20



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R



Nivitha (LKK Auto)

From: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>
Sent: Tuesday, 12 February 2019 5:26 PM
To: assignments
Cc: Kim Pang CHAY (SPF); Kwee Huat TAN (SPF); Perry HE (SPF); Bernard SEAH (SPF); Peng Seng NG (SPF); Rashid ABU HASAN (SPF); 'Ai Phing (LKKAuto)'; 'Shiau Chan (LKKAuto'
Subject: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX5249P)
Attachments: QX5249P.xlsx

Hi Catherine,

Please provide Appraisal Services for the following SPF vehicles at SMRT Automotive Services:

- **QX5249P**

In attached, please find the recommended Parts and Labour required for the repair of this vehicle.

Kindly contact the following SMRT personnel for viewing of the damaged vehicle:

- Mr Kong Sew Kui
- Mr Jason Yeo

Thank you and best regards,

WeiYea LIM
Contract Management
AEMD, Police Logistics Department
Singapore Police Force
DID: (65) 6478 4844



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."



Scope Of Work
Home Team Agency

SCOPE OF WORK

1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

CONTRACTOR :	SMRT	VEH TYPE :	FRC	UNIT :	JURONG EAST NPC
VEH NO :	QX5249P		REPAIR TYPE :	ACCIDENT	
VEH MAKE/MODEL :	TOYOTA ALTIS		ODOMETER :	VEHICLE CANNOT START	

Reference No.	5249/SPF/4W/19/01/22
---------------	----------------------

iLMS No.	1100017442
----------	------------

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)
1	Scope Of Repairs					
1.1	Front Bumper <i>BUC /</i>	\$180.00	1			
1.2	Front RH Bumper Retainer <i>CRA /</i>	\$24.00	1			
1.3	Front LH Bumper Retainer <i>CRA /</i>	\$24.00	1			
1.4	Radiator Grill <i>MIS /</i>	\$120.00	1			
1.5	Car Emblem <i>NEC /</i>	\$18.00	1			
1.6	Front Number Plate <i>DEF /</i>	\$50.00	1			
1.7	Front Bumper Reinforcement <i>DD /</i>	\$138.00	1			
1.8	Front Bumper RH Reinforcement Bracket <i>BT /</i>	\$12.00	1			
1.9	Front Bumper LH Reinforcement Bracket <i>BT /</i>	\$12.00	1			
1.10	Lock Panel <i>BT /</i>	\$60.00	1			
1.11	Front Support Panel <i>BT /</i>	\$660.00	1			
1.12	RHS Head Lamp <i>CRA /</i>	\$216.00	1			
1.13	LHS Head Lamp <i>CRA /</i>	\$216.00	1			
1.14	RHS Fog Lamp <i>SCR /</i>	\$84.00	1			
1.15	Air Con Compressor <i>?</i>	\$468.00	1			
1.16	Air Con Condenser <i>BT /</i>	\$220.00	1			
1.17	Air Con Pipe (Discharge Hose) <i>BT /</i>	\$180.00	1			
1.18	Air Con Pipe (Cooler Hose) <i>BT /</i>	\$342.00	1			
1.19	Radiator <i>DD /</i>	\$300.00	1			
1.20	Radiator Cowling <i>CRA /</i>	\$96.00	1			
1.21	Radiator Fan Blade <i>? CRA /</i>	\$48.00	1			
1.22	Radiator Fan Motor <i>? DD /</i>	\$108.00	1			
1.23	Radiator Upper Hose <i>BT /</i>	\$22.00	1			
1.24	Radiator Lower Hose <i>CUA /</i>	\$22.00	1			
1.25	Wiper Tank <i>DD /</i>	\$48.00	1			
1.26	ABS Pump <i>?</i>	\$2,280.00	1			
1.27	Alternator <i>?</i>	\$384.00	1			
1.28	Front RH Fender <i>BUC /</i>	\$120.00	1			
1.29	Front LH Fender <i>BUC /</i>	\$120.00	1			
1.30	Bonnet Cover <i>BUC /</i>	\$360.00	1			
1.31	Bonnet Cover RHS Hinges <i>BT /</i>	\$33.00	1			
1.32	Bonnet Cover LHS Hinges <i>BT /</i>	\$33.00	1			
1.33	Bonnet Cover Insulator <i>DEF /</i>	\$108.00	1			
1.34	Bonnet Cover Inlet Rubber <i>X ny</i>	\$14.00	1			
1.35	Bonnet Cover Lock <i>MIS /</i>	\$30.00	1			
1.36	Bonnet Stand Holder <i>NEC /</i>	\$8.00	1			
1.37	Bonnet Stand Stopper <i>BT /</i>	\$8.00	1			
1.38	RHS Engine Mounting <i>?</i>	\$84.00	1			
1.39	LHS Engine Mounting <i>?</i>	\$54.00	1			
1.40	Front Engine Mounting <i>?</i>	\$48.00	1			
1.41	Gear Box Engine Mounting <i>?</i>	\$54.00	1			
2	Additional Services					
2.1	Supply & Install battery 75D23L (61-71Amp) SOR5A	\$187.68	1	0%	187.68	187.68
Remarks:		Item 1.12, 1.17, 1.18 & 1.32 requires Overseas Indentment. ETA:- 6 to 8 weeks			Parts Total:	

S/N	LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)
1	Scope Of Repairs			
1.1	Front Bumper:		5	
	Remove & Replace Front Bumper			
	Remove & Replace Both Side Front Bumper Retainers			
	Putty & Spray Paint for Front Complete Bumper			
1.2	Radiator Grill & Front Number Plate:		1	
	Replace Radiator Grill			
	Replace Car Emblem			
	Replace Front Number Plate			
1.3	Front Bumper Reinforcement & Lock Panel:		8	
	Remove & Replace Front Bumper Reinforcement			
	Remove & Replace RHS Front Bumper Reinforcement Bracket			
	Remove & Replace LHS Front Bumper Reinforcement Bracket			

	Remove & Replace Lock Panel			
1.4	Front Support Panel:		6	
	Remove & Replace Front Support Panel			
1.5	Head Lamp & RHS Fog Lamp:		1.5	
	Remove & Replace RHS Head Lamp			
	Remove & Replace LHS Head Lamp			
	Replace RHS Fog Lamp			
	Wiring for RHS Head Lamp			
	Wiring for LHS Head Lamp			
	Wiring for RHS Fog Lamp			
1.6	Air Con Compressor & Air Con Condenser:		8	
	Remove & Replace Air Con Compressor			
	Remove & Replace Air Con Condenser			
	Remove & Replace Air Con Piping			
	Top Up Air Con Gas			
1.7	Radiator:		6	
	Remove & Replace Radiator			
	Remove & Replace Radiator Cowling			
	Remove & Replace Radiator Upper Hose			
	Remove & Replace Radiator Lower Hose			
	Remove & Replace Radiator Fan Blade			
	Remove & Replace Radiator Fan Motor			
	Top Up Coolant			
1.8	Wiper Tank & Battery:		2	
	Remove & Replace Wiper Tank			
	Remove & Replace Battery			
1.9	ABS Pump:		16	
	Remove & Replace ABS Pump			
1.10	Alternator:		4	
	Remove & Replace Alternator			
1.11	Front RH Fender:		4	
	Remove & Replace Front RH Fender			
	Putty & Spray Paint for Front RH Fender			
1.12	Front LH Fender:		4	
	Remove & Replace Front LH Fender			
	Putty & Spray paint for Front LH Fender			
1.13	Bonnet Cover:		10.5	
	Remove & Replace Bonnet Cover			
	Remove & Replace Both Side Bonnet Cover Hinges			
	Remove & Replace Bonnet Cover Insulator			
	Remove & Replace Bonnet Cover Inlet Rubber			
	Remove & Replace Bonnet Cover Lock			
	Replace Bonnet Stand Stopper			
	Replace Bonnet Stand Holder			
	Replace 'POLICE' Wordings Sticker on Bonnet Cover (To be provided by AMED)			
	Putty & Spray Paint for Bonnet Cover			
1.14	Engine Mounting:		10	
	Remove & Replace all Engine Mounting (Front, RHS, LHS & Gear Box)			
	SUB-TOTAL		86	
2	Additional Services			
2.1	Towing Service From Station to Workshop (SOR 10)	176.80	1	176.80
2.2	Return Service From Workshop to Station (SOR 9)	61.20	1	61.20
	SUB-TOTAL		2	238.00
	Labour Total:			
	GRAND TOTAL :			
	Total sum billed under SOR only :			
	Total sum billed under CVR only :			
Contractor shall complete the entire repair within <u>75</u> working days upon approval date . (Include parts awaiting time)				

Verification of Scope of Work					
Contractor QC		Verified By		Approved By:	
Name:	KONG SEW KUI	Name:		Name:	
Date:	30.1.2019	Date:		Date:	
Sign:		Sign:		Sign:	

Verification of Completed Repairs

Contractor QC		Home Team QC / Fleet Manager / Appointed Surveyor		Home Team Contract / Fleet Manager	
Name:		Name:		Name:	
Date:		Date:		Date:	
Sign:		Sign:		Sign:	

All completed repairs must be verified by Home Team Contract Manager / Fleet Manager before payment can be made

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To replace damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:


 15/3/19
 Hwee Lie - LKK
 13/3/19
 L/s 10 days.
 Not Authorise
 Photo After paint
 and replacement part

Registration No. QX 5249P

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	Front Bumper	1	Buckled	\$180.00	\$180.00	
1.2	Front RH Bumper Retainer	1	Cracked	\$24.00	\$24.00	
1.3	Front LH Bumper Retainer	1	Cracked	\$24.00	\$24.00	
1.4	Radiator Grill	1	Missing	\$120.00	\$120.00	
1.5	Car Emblem	1	Necessary	\$18.00	\$18.00	
1.6	Front Number Plate	1	Deformed	\$50.00	\$50.00	
1.7	Front Bumper Reinforcement	1	Dented	\$138.00	\$138.00	
1.8	Front Bumper RH Reinforcement Bracket	1	Bent	\$12.00	\$12.00	
1.9	Front Bumper LH Reinforcement Bracket	1	Bent	\$12.00	\$12.00	
1.10	Lock Panel	1	Bent	\$60.00	\$60.00	
1.11	Front Support Panel	1	Bent	\$660.00	\$660.00	
1.12	RHS Head Lamp	1	Cracked	\$216.00	\$216.00	
1.13	LHS Head Lamp	1	Cracked	\$216.00	\$216.00	
1.14	RHS Fog Lamp	1	Scratched	\$84.00	\$84.00	
1.15	Air Con Compressor	1	Unconfirm	\$468.00	\$468.00	
1.16	Air Con Condenser	1	Bent	\$220.00	\$220.00	
1.17	Air Con Pipe (Discharge Hose)	1	Bent	\$180.00	\$180.00	
1.18	Air Con Pipe (Cooler Hose)	1	Bent	\$342.00	\$342.00	
1.19	Radiator	1	Dented	\$300.00	\$300.00	
1.20	Radiator Cowling	1	Cracked	\$96.00	\$96.00	
1.21	Radiator Fan Blade	1	Cracked	\$48.00	\$48.00	
1.22	Radiator Fan Motor	1	Dented	\$108.00	\$108.00	

1.23	Radiator Upper Hose	1	Bent	\$22.00	\$22.00	
1.24	Radiator Lower Hose	1	Cut	\$22.00	\$22.00	
1.25	Wiper Tank	1	Dented	\$48.00	\$48.00	
1.26	ABS Pump	1	Unconfirm	\$2,280.00	\$2,280.00	
1.27	Alternator	1	Unconfirm	\$384.00	\$384.00	
1.28	Front RH Fender	1	Buckled	\$120.00	\$120.00	
1.29	Front LH Fender	1	Buckled	\$120.00	\$120.00	
1.30	Bonnet Cover	1	Buckled	\$360.00	\$360.00	
1.31	Bonnet Cover RHS Hinges	1	Bent	\$33.00	\$33.00	
1.32	Bonnet Cover LHS Hinges	1	Bent	\$33.00	\$33.00	
1.33	Bonnet Cover Insulator	1	Deformed	\$108.00	\$108.00	
1.34	Bonnet Cover Inlet Rubber	1	Not Necessary	\$14.00		
1.35	Bonnet Cover Lock	1	Missing	\$30.00	\$30.00	
1.36	Bonnet Stand Holder	1	Necessary	\$8.00	\$8.00	
1.37	Bonnet Stand Stopper	1	Bent	\$8.00	\$8.00	
1.38	RHS Engine Mounting	1	Unconfirm	\$84.00	\$84.00	
1.39	LHS Engine Mounting	1	Unconfirm	\$54.00	\$54.00	
1.40	Front Engine Mounting	1	Unconfirm	\$48.00	\$48.00	
1.41	Gear Box Engine Mounting	1	Unconfirm	\$54.00	\$54.00	
1	Scope Of Repairs					
1.1	Front Bumper					5
	Remove & Replace Front Bumper					
	Remove & Replace Both Side Front Bumper Retainers					
	Putty & Spray Paint for Front Complete Bumper					
1.2	Radiator Grill & Front Number Plate					1
	Replace Radiator Grill					
	Replace Car Emblem					
	Replace Front Number Plate					
1.3	Front Bumper Reinforcement & Lock Panel					8

	Remove & Replace Front Bumper Reinforcement						
	Remove & Replace RHS Front Bumper Reinforcement Bracket						
	Remove & Replace LHS Front Bumper Reinforcement Bracket						
	Remove & Replace Lock Panel						6
1.4	Front Support Panel						
	Remove & Replace Front Support Panel						
1.5	Head Lamp & RHS Fog Lamp						1.5
	Remove & Replace RHS Head Lamp						
	Remove & Replace LHS Head Lamp						
	Replace RHS Fog Lamp						
	Wiring for RHS Head Lamp						
	Wiring for LHS Head Lamp						
	Wiring for RHS Fog Lamp						
1.6	Air Con Compressor & Air Con Condenser						8
	Remove & Replace Air Con Compressor						
	Remove & Replace Air Con Condenser						
	Remove & Replace Air Con Piping						
	Top Up Air Con Gas						
1.7	Radiator						6
	Remove & Replace Radiator						
	Remove & Replace Radiator Cowling						
	Remove & Replace Radiator Upper Hose						
	Remove & Replace Radiator Lower Hose						
	Remove & Replace Radiator Fan Blade						
	Remove & Replace Radiator Fan Motor						
	Top Up Coolant						
1.8	Wiper Tank & Battery						2
	Remove & Replace Wiper Tank						

[illegible]



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION			Ref : CS/SPF19004618/Jvd3e2	
ACCIDENT CLAIM SECTION (SPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333 ATTN : WEI YEA LIM			Date : 15-04-2019	
			Code : SPF	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.			Veh. Inspected	QX 5249P
Policy No.			Coverage (\$)	0.00
Claim No.	HOMSPFETQ16000399		Excess (\$)	0.00
Assign From	WEI YEA LIM		Assign Date	12/02/2019
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COROLLA 1.6		c.c	1598
Engine No.	HIDDEN		Year of Reg.	2005
Chassis No.	MR053ZEC107081392		Colour	WHITE
Odometer	-		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/70 R14	FALKEN	6 mm	
L/H Front Tyre	185/70 R14	FALKEN	6 mm	
R/H Rear Tyre	185/70 R14	FALKEN	6 mm	
L/H Rear Tyre	185/70 R14	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date			Inspection Date 13/03/2019	
Survey held at K & S- SUNGAI KADUT DRIVE 2D				
Repairer -				
5a. Remarks				



Registration No. QX 5249P

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	Front Bumper	1	Buckled	\$180.00	\$180.00	
1.2	Front RH Bumper Retainer	1	Cracked	\$24.00	\$24.00	
1.3	Front LH Bumper Retainer	1	Cracked	\$24.00	\$24.00	
1.4	Radiator Grill	1	Missing	\$120.00	\$120.00	
1.5	Car Emblem	1	Necessary	\$18.00	\$18.00	
1.6	Front Number Plate	1	Deformed	\$50.00	\$50.00	
1.7	Front Bumper Reinforcement	1	Dented	\$138.00	\$138.00	
1.8	Front Bumper RH Reinforcement Bracket	1	Bent	\$12.00	\$12.00	
1.9	Front Bumper LH Reinforcement Bracket	1	Bent	\$12.00	\$12.00	
1.10	Lock Panel	1	Bent	\$60.00	\$60.00	
1.11	Front Support Panel	1	Bent	\$660.00	\$660.00	
1.12	RHS Head Lamp	1	Cracked	\$216.00	\$216.00	
1.13	LHS Head Lamp	1	Cracked	\$216.00	\$216.00	
1.14	RHS Fog Lamp	1	Scratched	\$84.00	\$84.00	
1.15	Air Con Compressor	1	Unconfirm	\$468.00	\$468.00	
1.16	Air Con Condenser	1	Bent	\$220.00	\$220.00	
1.17	Air Con Pipe (Discharge Hose)	1	Bent	\$180.00	\$180.00	
1.18	Air Con Pipe (Cooler Hose)	1	Bent	\$342.00	\$342.00	
1.19	Radiator	1	Dented	\$300.00	\$300.00	
1.20	Radiator Cowling	1	Cracked	\$96.00	\$96.00	
1.21	Radiator Fan Blade	1	Cracked	\$48.00	\$48.00	
1.22	Radiator Fan Motor	1	Dented	\$108.00	\$108.00	
1.23	Radiator Upper Hose	1	Bent	\$22.00	\$22.00	
1.24	Radiator Lower Hose	1	Cut	\$22.00	\$22.00	
1.25	Wiper Tank	1	Dented	\$48.00	\$48.00	
1.26	ABS Pump	1	Unconfirm	\$2,280.00	\$2,280.00	
1.27	Alternator	1	Unconfirm	\$384.00	\$384.00	

1.28	Front RH Fender	1	Buckled	\$120.00	\$120.00	
1.29	Front LH Fender	1	Buckled	\$120.00	\$120.00	
1.30	Bonnet Cover	1	Buckled	\$360.00	\$360.00	
1.31	Bonnet Cover RHS Hinges	1	Bent	\$33.00	\$33.00	
1.32	Bonnet Cover LHS Hinges	1	Bent	\$33.00	\$33.00	
1.33	Bonnet Cover Insulator	1	Deformed	\$108.00	\$108.00	
1.34	Bonnet Cover Inlet Rubber	1	Not Necessary	\$14.00		
1.35	Bonnet Cover Lock	1	Missing	\$30.00	\$30.00	
1.36	Bonnet Stand Holder	1	Necessary	\$8.00	\$8.00	
1.37	Bonnet Stand Stopper	1	Bent	\$8.00	\$8.00	
1.38	RHS Engine Mounting	1	Unconfirm	\$84.00	\$84.00	
1.39	LHS Engine Mounting	1	Unconfirm	\$54.00	\$54.00	
1.40	Front Engine Mounting	1	Unconfirm	\$48.00	\$48.00	
1.41	Gear Box Engine Mounting	1	Unconfirm	\$54.00	\$54.00	
1	Scope Of Repairs					
1.1	Front Bumper					5
	Remove & Replace Front Bumper					
	Remove & Replace Both Side Front Bumper Retainers					
	Putty & Spray Paint for Front Complete Bumper					
1.2	Radiator Grill & Front Number Plate					1
	Replace Radiator Grill					
	Replace Car Emblem					
	Replace Front Number Plate					
1.3	Front Bumper Reinforcement & Lock Panel					8
	Remove & Replace Front Bumper Reinforcement					
	Remove & Replace RHS Front Bumper Reinforcement Bracket					
	Remove & Replace LHS Front Bumper Reinforcement Bracket					
	Remove & Replace Lock Panel					
1.4	Front Support Panel					6
	Remove & Replace Front Support Panel					
1.5	Head Lamp & RHS Fog Lamp					1.5
	Remove & Replace RHS Head Lamp					
	Remove & Replace LHS Head Lamp					

	Replace RHS Fog Lamp					
	Wiring for RHS Head Lamp					
	Wiring for LHS Head Lamp					
	Wiring for RHS Fog Lamp					
1.6	Air Con Compressor & Air Con Condenser					8
	Remove & Replace Air Con Compressor					
	Remove & Replace Air Con Condenser					
	Remove & Replace Air Con Piping					
	Top Up Air Con Gas					
1.7	Radiator					6
	Remove & Replace Radiator					
	Remove & Replace Radiator Cowling					
	Remove & Replace Radiator Upper Hose					
	Remove & Replace Radiator Lower Hose					
	Remove & Replace Radiator Fan Blade					
	Remove & Replace Radiator Fan Motor					
	Top Up Coolant					
1.8	Wiper Tank & Battery					2
	Remove & Replace Wiper Tank					
	Remove & Replace Battery					
1.9	ABS Pump					16
	Remove & Replace ABS Pump					
1.10	Alternator					4
	Remove & Replace Alternator					
1.11	Front RH Fender					4
	Remove & Replace Front RH Fender					
	Putty & Spray Paint for Front RH Fender					
1.12	Front LH Fender					4
	Remove & Replace Front LH Fender					
	Putty & Spray paint for Front LH Fender					
1.13	Bonnet Cover					10.5
	Remove & Replace Bonnet Cover					
	Remove & Replace Both Side Bonnet Cover Hinges					
	Remove & Replace Bonnet Cover Insulator					
	Remove & Replace Bonnet Cover Inlet Rubber					
	Remove & Replace Bonnet Cover Lock					
	Replace Bonnet Stand Stopper					
	Replace Bonnet Stand Holder					

	Replace 'POLICE' Wording Sticker on Bonnet Cover					
	(To be provided by AMED)					
	Putty & Spray Paint for Bonnet Cover					
1.14	Engine Mounting					10
	Remove & Replace all Engine Mounting (Front, RHS, LHS & Gear Box)					
		TOTAL PARTS COST			\$7,392.00	
		TOTAL MAN-HOUR				86

Registration No. QX 5249P

Vehicle Inspected By

ONG HWEE JIE
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.