

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ruth Chua Gek Tiang

Date: 19 Mar 2019

Preliminary Advice

Insured Vehicle No	:	SJG1998J			
TP Vehicle No	:	SJF5763Z	Accident Date	:	18/10/2018
Make	:	TOYOTA COROLLA	Assignment Date	:	14/03/2019
Date of Inspection	:	15/03/2019	Est. Duration of Repair	:	2 days
Inspection At	:	Yew Tee Automobile Tech Pte Ltd (HQ) Blk 6 Woodlands Road 399F,, Yew Tee Ind Estate Singapore 678006			

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:	S\$ 4,435.00
Revised Amount	:	S\$ 1,140.00
Check Items (Estimated)	:	S\$ 1,470.00
Total	:	S\$ 2,610.00
Lump Sum Repair		:

Total Loss Consideration

New for Old Value	:	S\$
Pre-Accident Value	:	S\$
COE / PARF Rebate	:	S\$
Salvage Value	:	S\$
Margin for Repair	:	S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP