

ASS. REC. BY:

REF: CS/MSG190046301Ksd3/

Special Instruction:

SAVAJOY
Meimen

Kenneth

ASSIGNMENT (Office)

From (Person): Fivel Foo Winyao

of MSG

Date/Time: 14. Mar. 2019 10:39 AM

Estimated Cost:

Bill to:

OD / (11) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMG 2365T

Insured: GBF 4529K

at Workshop in/a Guan Motor Works (HQ)

Tel: 64536111

of 17L Sin Ming Drive # 02-03 Sin Ming Autocare - 57321 Sin Ming

Policy No: 28846216 mkr

Claim No: 567463

Sum Insured:

Excess:

Make of Vcl:

(Client's Record)

D.O.A: 9.3.2019

CA / REV / REP. / REV 24 HRS

"up"

H.O.D. Endorsement:

Date/Time: 14.3.2019 11.23

Person Contacted: Ah Hung

Vehicle: (IN) / OUT

Date/Time

Action/Instruction (✓) Estimate

SMG 2365T-X

GBF 4529K - CS/MSG17018441 / Dribn 2

D.O.A - 23/04/2019

15/03/19 @ 15:45 p.m. revised IA to Fivel Foo vic
Meimen.

18/4 6/12pm 86200 email

ASS. REC. BY:

REF: MG/Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s Cuan Motor

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 840k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMG 23657 Yr Regn: 04, 11Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mer C180 Komp cc 1587Colour: M. Silver A/C: Insured / Std / NI / NASp. Reading: 195685 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: W00-2040452A526317Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rlm / STD ATRlm orTyre Size: F: 225/458R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

R/Bal. 7 mm

Rear

R/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 9/3/19D.O.I. 14/3/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 26 APR 2019

26/4/2019

Date/Time, File Pass to?

26/04/19

1) Type

Date/Time, File Return to?

2)

☐ : Prell. Report☒ : Final ReportDays Of Repair: 5Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

200

Transportation:

S + RS \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) 7,000/- HS

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Mar 2019		14 Mar 2019 10:39 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	Cat Tech Asia Pacific Pte Ltd, Co. Reg. No.: 199300321N		
Main Claimant:	Tan Chew Yen Cannie, ID: S8412312I		
Vehicle Reg. No.:	SMG2365T	Date of Loss:	09/03/2019 17:00 - :59 [94 Months and 11 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 587463	Policy/Cover Note No.:	28846216MKC (Comprehensive) Coverage: 27/10/2018 - 26/10/2019
Vehicle Reg. No. (Insured):	GBF4529K	Policy No. (Claimant):	
		Excess:	
Repairer:	Guan Motor Works (HQ) 176 Sin Ming Drive #02-03 Sin Ming Autocare, 575721 Sin Ming - Tel: 64536111		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/03/2019]		
Adj Asg. Remarks:	on WP, OI not reported. SJE agree - Kenneth Kong from LKK. Contact : Ah Heng at 6453 6111		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

- Kenneth

Tina: 1123
 person: Ah Heng
 ✓ in
 ✓ ✓

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	23121
Vehicle Details	
Vehicle No.:	SMG2365T
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Mar 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C180K
Primary Colour:	Silver
Manufacturing Year:	2011
Engine No.:	27191031344405
Chassis No.:	WDD2040452A526317
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$30,295.00
Original Registration Date:	26 Apr 2011
First Registration Date:	26 Apr 2011
Transfer Count:	1
Actual ARF Paid:	\$30,295.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Apr 2021
PARF Rebate Amount:	\$18,177.00
Intended COE Rebate Details	
COE Expiry Date:	25 Apr 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$44,000.00
COE Rebate Amount:	\$9,288.00
Total Rebate Amount:	\$27,465.00

The information contained herein is correct as at 15 Mar 2019

OK

LKK Auto Consultants Pte Ltd (Co.Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wenyao

Date: 15 Mar 2019

Preliminary Advice

Insured Vehicle No	: GBF4529K	Accident Date	: 09/03/2019
TP Vehicle No	: SMG2365T	Assignment Date	: 14/03/2019
Make	: MERCEDES-BENZ C180K	Est. Duration of Repair	: 4 - 5 days
Date of Inspection	: 14/03/2019		
Inspection At	: Guan Motor Works (HQ) 176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,699.60
Revised Amount	:S\$	4,920.00
Check Items (Estimated)	:S\$	5,088.00
Total	:S\$	10,008.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/03/2019 17:13
Date Of Accident	09/03/2019 17:55
Exact Location Of Accident	BLK 437 FAJAR ROAD CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMG2365T
Insured/Policyholder	
Name Of Registered Owner	TAN CHEW YEN, CANNIE (CHEN QIUYAN, CANNIE)
NRIC No	S84123121
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91871882
Alternative Phone No	OTHERS-91871882

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C180
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5106671304
Cover Note Number	

Driver

Name of Driver	KOH KWOK LUNG
NRIC No	S8603236H
Date Of Birth	15/01/1986
Occupation	OUTDOOR
Date Of Driving Pass	30/08/2018
Driving Experience	0 YEAR AND 6 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91871882
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 87 DAWSON ROAD #20-17 SINGAPORE
Postcode	141087
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT PANJANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 42 FAJAR ROAD , POSTCODE: 679005 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8929999 - FAX NO: 67673650
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF4529K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

SKETCH PLAN

WITNESS
(video footage)

A - SMG2365T
B - GBF4529K

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer Police Report

DECLARATION

(We declare the foregoing particulars are true in every respect.)

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name:
NRIC/FIN No:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form, and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (c) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190309/2138

1 of 3

Police Station Of Origin:
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

Report No. T/20190309/2138

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 09/03/2019 20:33		Vide Report No.:		Station Diary No: 233	
Informant's Particulars					
Name of Informant: KOH KWOK LUNG			Address: APT BLK 87 DAWSON ROAD #20-17 SINGAPORE 141087		
ID Type / ID No.: NRIC NO / S8603236H			Contact No.: Home/Office: Mobile: 91871882		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 33	Date of Birth: 15/01/1986	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: House Mover			Driving Licence Information: Class: 3A		Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 09/03/2019 16:00	Type of Location: Car Park
Location: Along Road 1 FAJAR ROAD Blk 437 Fajar Road Open Space Carpark Lot No. 254				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
SMG2365T	Car				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190306/2138

2 of 3

Police Station Of Origin:

Bukit Panjang N.P.C

1 Segar Road #01-05 SINGAPORE 677738

Tel No: 1800-8929999

Report No. T/20190306/2138

CONTINUATION OF REPORT

Driver			
Name	KOH KWOK LUNG	ID No.	S8603236H
Related Vehicle	SMG2365T (Car)	Contact No.	91871882
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3A Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 9/3/2019, at 1600hrs, I parked my vehicle on carpark lot 254, a silver Mercedes-Benz (SMG2365T), at the open space carpark of Blk 437 Fajar Rd. everything was intact when I left the vehicle. There was a vehicle parked to the right of mine, at carpark lot 253. At around 1800hrs, I returned to my vehicle and saw that my vehicle had some damages on the right side of it. The vehicle parked at carpark lot 253 was no longer there. My vehicle's front right bumper had scratches and a dent. Additionally, my vehicle's front right headlight had a big crack as well as my front right fender had scratches and a dent. After I discovered this, I called for police. Traffic police came down and discovered that there was an in-car camera of the vehicle (SLF7096B) at carpark lot 252. The traffic police then seized the memory card of said in-car camera. I did not see what or who caused said damages to my vehicle.



**SINGAPORE
POLICE FORCE**



T/20190309/2138

3 of 3

Police Station Of Origin:
Bukit Panjang N.P.C.
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

Report No: T/20190309/2138

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J / FUAD ISKANDAR BIN JUMAT <i>Fg</i>	Signature Of Informant: <i>[Signature]</i>
Signature Of Interpreter: Not applicable	Date/Time: 09/03/2019 20:33
Officer In Charge Of Case: TP / HRT / SS: GOH GEOK LYE Contact No: 65476148	Classification Of Case:
Authentication Stamp AP102 <i>Fg</i> Singapore Police Force	

R001313
14.3.19 16:01
SMG2365T
176-0203



SMG2365T

Mercedes-Benz : 204 (C Class 2007-15) : without 4MATIC : Sedan/Wagon Standard Suspension Europe version/USA : 02/2008-
4-Wheel Total Alignment

Front : Left

Actual	Before	Specified Range
-0°43'	-0°43'	-0°48' -0°05'
10°12'	10°12'	
0°03'	0°03'	0°00' 0°10'
13°40'	13°40'	
12°57'	12°57'	
		-2°12' -1°12'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-2°06'	-2°06'	-0°48' -0°05'
10°06'	10°06'	
-0°13'	-0°11'	0°00' 0°10'
14°50'	14°50'	
12°44'	12°44'	
		-2°12' -1°12'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
1°23'	1°23'	-0°24' 0°24'
0°06'	0°06'	-0°30' 0°30'
-1°10'	-1°10'	
-0°10'	-0°08'	0°00' 0°20'

Rear : Left

Actual	Before	Specified Range
-1°30'	-1°30'	-1°34' -0°34'
0°08'	0°08'	0°05' 0°19'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°15'	-1°14'	-1°34' -0°34'
0°21'	0°21'	0°05' 0°19'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-0°15'	-0°15'	-0°30' 0°30'
0°29'	0°30'	0°17' 0°31'
-0°07'	-0°06'	-0°15' 0°15'

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR SMG2365T

Spare Parts

No.	Qty	List Items		
1	1	Front bumper	1315	\$ Bu 1,596.00 ✓
2	1	Front bumper RH fog lamp cover		\$ Bu 42.00 ✓
3	1	Front bumper RH fog lamp		\$ Sm 295.00 ✓
4	1	Front bumper tow cover		\$ Sm 71.00 X
5	1 set	Front bumper lower side chrome moulding		\$ Bu 190.00 ✓
6	1	Front bumper RH side retainer		\$ Sm 107.00 X
7	1	Front bumper inner foam		\$ Sm 185.00 X
8	1	Front bumper inner reinforcement		\$ R 485.00 X
9	1	Front bumper inner parts		\$ CM 105.00 ✓
10	1 set	Front grille complete	777.00	\$ CM 885.00 ✓
11	1	RH headlamp	1080	\$ CM 1,193.00 ✓
12	1	RH headlamp housing		\$ R 250.00 X
13	1	Front RH fender		\$ Bu 977.00 ✓
14	1	Front RH fender under shield		\$ Di 182.00 ✓
15	1 set	Front fender under shield clips		\$ Bu 40.00 ✓
16	1	Front RH sports rims	850-	\$ Bu 1,180.00 ✓
17	1	Front RH shock absorber		\$ Sm 579.00 3+
18	1	Front RH lower arm		\$ R 585.00 X
19	1	Front RH wheel hub & bearing		\$ 495.00 ✓
20	1	Front RH knuckle arm		\$ A 866.00 ✓
				\$ 10,544.00
			Less 10%	\$ 1,054.40
			Total :	\$ 9,489.60

Special Nett Items

21	1	Front RH tyre	\$ Sm 280.00 X
----	---	---------------	----------------

Labour

1	Labour Charges for remove/refit, panel beating, cutting welding and replacement of damages.	\$ 700.00 4501
2	To putty and spray Spray Paintings charges.	\$ 800.00 6001
3	To remove, refit front RH under carriages.	\$ 250.00 1601
4	To conduct computerise wheel alignment test.	\$ 80.00 601
5	To check wirings and lightings.	\$ 40.00 201
6	To supplied and applied rust proofing treatments.	\$ 60.00 301
		Total : \$ 1,930.00

Total Parts and Labour : \$ 11,699.60

- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No repair modification(s) is allowed
- Supplementary item(s) must be re-surveyed and is subject to final approval from Insurance Company

Authorised by Repairer

Signature

Date

源摩哆廠

GUAN MOTOR WORKS

REPAIR ESTIMATE FOR SMG236

No.	Qty	Spare Parts
		List Items
1	1	Front bumper <i>1375 204</i>
2	1	Front bumper RH fog lamp cover
3	1	Front bumper RH fog lamp
4	1	Front bumper tow cover
5	1 set	Front bumper lower side chrome mol
6	1	Front bumper RH side retainer
7	1	Front bumper inner foam
8	1	Front bumper inner reinforcement
9	1	Front bumper inner parts
10	1 set	Front grille complete <i>204 906</i>
11	1	RH headlamp
12	1	RH headlamp housing
13	1	Front RH fender
14	1	Front RH fender under shield
15	1 set	Front fender under shield clips
16	1	Front RH sports rims <i>204 906</i>
17	1	Front RH shock absorber
18	1	Front RH lower arm
19	1	Front RH wheel hub & bearing
20	1	Front RH knuckle arm

Special Nett Items	
21	1 Front RH tyre

Labour	
1	Labour Charges for remove/refit, painting and replacement of damages
2	To putty and spray Spray Paintings ch
3	To remove, refit front RH under carriage
4	To conduct computerise wheel alignment
5	To check wirings and lightings
6	To supplied and applied rust proofing

EST. AMT	
Part	
Labour	
Tot	

26/04/19
 starting 1,596. +
 42. +
 295. +
 190. +
 105. +
 885. +
 1,193. +
 977. +
 182. +
 40. +
 1,180. +
 731. +
 1,320. +

855. +
 8,282. +
 8,282. +
 90. +
 7,453.8 +
 450. +
 600. +
 160. +
 60. +
 20. +
 30. +
 1,320. +

7,453.8 +
 1,320. +
 8,773.8 +
 8,773.8 +
 80. +
 7,019.04 +

2/5
 \$7,000/-

4501
 6001
 1601
 601
 201
 301

2303570308

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Mar 2019		14 Mar 2019 10:39 Edit Adj Rpt	\$57,000.00 Edit Estimates	\$57,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Cat Tech Asia Pacific Pte Ltd, Co. Reg. No.: 199300321N								
Main Claimant:	Tan Chew Yen Cannie, ID: S84123121								
Vehicle Reg. No.:	SMG2365T	Date of Loss:	09/03/2019 17:00 - :59 [94 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 587463	Policy/Cover Note No.:	28846216MKC (Comprehensive) Coverage: 27/10/2018 - 26/10/2019						
Vehicle Reg. No. (Insured):	GBF4529K	Policy No. (Claimant):							
		Excess:							
Repairer:	Guan Motor Works (HQ) 176 Sin Ming Drive #02-03 Sin Ming Autocare, 575721 Sin Ming - Tel: 64536111								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 13/04/2019]								
Adj Asg. Remarks:	on WP. OI not reported. SJE agree - Kenneth Kong from LKK. Contact : Ah Heng at 6453 6111								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMG2365T (587463)**
[GBF4529K]
TP
Tan Chew Yen Cannie
Mar 9 2019 5:00PM
[Cat Tech Asia Pacific Pte Ltd]
Guan Motor Works

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports					1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print	
1	14/03/19 18:04	Accident Statement From: SC - Reg. No: GBF4529K, Claimant: CAT TECH ASIA PACIFIC PTE LTD		Load HTML		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	15/03/19 15:45	Adjuster Immediate Advice		Load HTML		

Photos/Images					3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	26/04/19 09:59	General View		Load JPG	☒	
2	26/04/19 09:59	General View		Load JPG	☒	
3	26/04/19 09:59	General View		Load JPG	☒	
4	26/04/19 09:59	General View		Load JPG	☒	
5	26/04/19 09:59	General View		Load JPG	☒	
6	26/04/19 09:59	General View		Load JPG	☒	
7	26/04/19 09:59	General View		Load JPG	☒	
8	26/04/19 09:59	General View		Load JPG	☒	
9	26/04/19 09:59	General View		Load JPG	☒	
10	26/04/19 09:59	General View		Load JPG	☒	
11	26/04/19 09:59	General View		Load JPG	☒	
12	26/04/19 09:59	General View		Load JPG	☒	
13	26/04/19 09:59	General View		Load JPG	☒	
14	26/04/19 09:59	General View		Load JPG	☒	
15	26/04/19 09:59	General View		Load JPG	☒	
16	26/04/19 09:59	General View		Load JPG	☒	
17	26/04/19 09:59	General View		Load JPG	☒	
18	26/04/19 10:00	Reinspection Photo		Load JPG	☒	
19	26/04/19 10:00	Reinspection Photo		Load JPG	☒	
20	26/04/19 10:00	Reinspection Photo		Load JPG	☒	
21	26/04/19 10:00	Reinspection Photo		Load JPG	☒	
22	26/04/19 10:00	Reinspection Photo		Load JPG	☒	
23	26/04/19 10:00	Reinspection Photo		Load JPG	☒	
24	26/04/19 10:00	Reinspection Photo		Load JPG	☒	
25	26/04/19 10:00	Reinspection Photo		Load JPG	☒	
26	26/04/19 10:00	Reinspection Photo		Load JPG	☒	
27	26/04/19 10:00	Reinspection Photo		Load JPG	☒	
28	26/04/19 10:00	Reinspection Photo		Load JPG	☒	
29	26/04/19 10:00	Reinspection Photo		Load JPG	☒	
30	26/04/19 10:00	Reinspection Photo		Load JPG	☒	

Documentation					1 per page	☒
---------------	--	--	--	--	------------	-------------------------------------

Assessment Reports				1 per page	☒
No	Finalized On			Thumbnail	Print
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	13/03/19 15:45	PRI from CK Teo & Co		Load PDF	
2	13/03/19 15:45	SMG2365T E-file & police Report		Load PDF	
3	13/03/19 16:15	Survey agree on SJE - Kenneth Kong from LKK		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19004630/KSD3Q2

Date: 06/05/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28846216MKC

Claimant Vehicle No: SMG2365T

Insured Vehicle No: GBF4529K

Date of Loss: 09/03/2019

Nature of Claim: TP

Claim No: 587463

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMG2365T

Make & Model: MERCEDES-BENZ C180K, 1.6 (A)

Reg. Date: 26/04/2011 (Man. Year: 2011)

Colour: Metallic Silver

Engine Capacity: 1597 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 27191031344405

Chassis No: WDD2040452A526317

Odometer: 195685 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45Z R17

Rear Tyre Size: 225/45Z R17

Front Left Side: Continental 7 mm

Rear Left Side: Continental 7 mm

Front Right Side: Continental 7 mm

Rear Right Side: Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,769.60	7,453.80	2,315.80	23.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,930.00	1,320.00	610.00	31.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,699.60	8,773.80	2,925.80	25.01
Approved Total (Overridden) (S\$)		7,000.00		
Nett Amount (S\$)	11,699.60	7,000.00	4,699.60	40.17

INSPECTION

Date of Assignment: 14/03/2019

Date Inspected: 14/03/2019 Inspected At:

Guan Motor Works (HQ)
176 Sin Ming Drive #02-03 Sin Ming
Autocare
Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 06 May 2019)
Parts: 143	MERCEDES-BENZ C180K 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMG2365T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	1,596.00 FL	*1,596.00 FL
2	1		*FRONT BUMPER RH FOG LAMP COVER	Dented	42.00 FL	*42.00 FL
3	1		*FRONT BUMPER RH FOG LAMP	Mtg Cracked	295.00 FL	*295.00 FL
4	1		*FRONT BUMPER TOW COVER	Serviceable	71.00 FL	*- FL
5	1		*SET FRONT BUMPER LOWER SIDE CHROME MOULDING	Necessary	190.00 FL	*190.00 FL
6	1		*FRONT BUMPER RH SIDE RETAINER	Serviceable	107.00 FL	*- FL
7	1		*FRONT BUMPER INNER FOAM	Serviceable	185.00 FL	*- FL
8	1		*FRONT BUMPER INNER REINFORCEMENT	Repair	485.00 FL	*- FL
9	1		*FRONT BUMPER INNER PARTS	Cracked	105.00 FL	*105.00 FL
10	1		*SET FRONT GRILLE COMPLETE	Cracked	885.00 FL	*885.00 FL
11	1		*RH HEADLAMP	Cracked	1,193.00 FL	*1,193.00 FL
12	1		*RH HEADLAMP HOUSING	Repair	250.00 FL	*- FL
13	1		*FRONT RH FENDER	Buckled	977.00 FL	*977.00 FL
14	1		*FRONT RH FENDER UNDER SHIELD	Distorted	182.00 FL	*182.00 FL
15	1		*SET FRONT FENDER UNDER SHIELD CLIPS	Necessary	40.00 FL	*40.00 FL
16	1		*FRONT RH SPORT RIMS	Dented	1,180.00 FL	*1,180.00 FL
17	1		*FRONT RH SHOCK ABSORBER	Serviceable	579.00 FL	*- FL
18	1		*FRONT RH LOWER ARM	Serviceable	585.00 FL	*- FL
19	1		*FRONT RH WHEEL HUB & BEARING	Necessary	731.00 FL	*731.00 FL
20	1		*FRONT RH KNUCKLE ARM	Bent	866.00 FL	*866.00 FL
21	1		*FRONT RH TYRE	Serviceable	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,824.00	8,282.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,054.40	828.20
Total Parts (\$\$)	9,769.60	7,453.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES FOR REMOVE/REFIT ,PANEL BEATING ,CUTTING WELDING AND REPLACEMENT OF DAMAGES	New	700.00	450.00
2	TO PUTTY AND SPRAY PAINTINGS CHARGES	New	800.00	600.00
3	TO REMOVE,REFIT FRONT RH UNDER CARRIAGES	New	250.00	160.00
4	TO CONDUCT COMPUTERISE WHEEL ALIGNMENT TEST	New	80.00	60.00
5	TO CHECK WIRING AND LIGHTINGS	New	40.00	20.00
6	TO SUPPLIED AND APPLIED RUST PROOFING TREATMENTS	New	60.00	30.00
Gross Labour Cost (S\$)			1,930.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >