

SERVE YOU MOTOR SERVICE
 BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2
 #01-265, SINGAPORE 569536
 TEL. NO: 64810555 / FAX NO. 64831654
 E-MAIL: elainesyms@gmail.com

*Not authorized
 L1 Rep @ 1950
 Anthony Alan Paim
 4 days*

INS: AIG ASIA PACIFIC INSURANCE PTE LTD
 COMPANY:AMCOWELD INC PTE LTD
 Registration no.: **GY 7996 R / TOYOTA DYAN 150 D**
 Date : 14-Mar-19

Quotation: CM190304

S/N	Qty	Item	Amount
-----	-----	------	--------

LIST ITEMS

1	1	Rear tailgate	<i>Rn</i> 885.00 ✓
2	4	Rear tailgate hinge \$68 each	<i>R</i> 272.00 X
3	2	Rear tailgate safety lock \$240 each	<i>at 1500</i> <i>disc</i> 480.00 X
4	1	Rear tailgate stop mounting	<i>sn</i> 68.00 X
5	1	Rear end panel	<i>Rn</i> 680.00 ✓
6	2	Side cover \$848 each	<i>R</i> 1,696.00 X
7	2	Side cover safety grille \$480 each	<i>sn</i> 960.00 X
8	2sets	Rear lamp \$325 each	<i>sn</i> 650.00 X
9	1	Rear spare tyre bracket	<i>R</i> 284.00 X
10	1	Exhaust pipe	<i>R</i> 388.00 X
Sub-total:			6,363.00
Less 25 %			1,590.75
			4,772.25

SPECIAL NETT ITEMS

1	1	"70 km/h" sticker	<i>Rn</i> 35.00 <i>15sn</i>
2	1	"Toyota" sticker	<i>Rn</i> 80.00 ✓
3	1	"13 pax" sticker	<i>Rn</i> 35.00 <i>15sn</i>
4	1	Rear number plate	<i>Diy</i> 50.00 <i>20sn</i>
Sub-total:			200.00

LABOUR & MISC CHARGES

1	To dismantle / renew the accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts.	900.00	<i>550/</i>
2	Supply spray paint material and necessary items on the affected areas	900.00	<i>400/</i>

TOTAL

1,800.00

Total Parts and Labour Cost of Repair

\$6,772.25

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: