



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 13/03/2019

User ID : GohKK2

Section A - Accident Details

Registration Number

SMB227Z

Case Reference Number

BUS/03/19/1028

Registration Date

14/12/2011

Company Type

SMRT Buses Ltd

Make

MAN

Model

A22

Name of Driver

Tan Kok Chye

Type of Accident

Open Door Case

Accident Date and Time

10/3/2019 3:28 PM

Accident Reported Date and Time

12/3/2019 10:54 AM

Is Surveyor Required?

No

Survey by

Vehicle is Towed Back?

No

Towed Back Date and Time

Replacement Vehicle issued?

No

Job Card Number

Special Instruction to ARC,if any

SMB227Z - REAR DOOR  
SHA1161L (TP) - COMFORT TAXI. INSURED WITH III. RIGHT PORTION

Prepared Date and Time

12/3/2019 1:26 PM

Chassis Number

WMAA22ZZ1B7001201

Mileage

Work Shop

Repair Completion Date and Time

Section B - Summary of Repair Estimates

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labour Cost

\$2,120.00

\$0.00

Total Spray Cost

\$786.00

\$0.00

Total Spare Part Cost

\$16,560.00

\$0.00

Total Other Cost

\$0.00

\$0.00

TOTAL COST

\$19,466.00

\$0.00

Lump Sum Total

\$19,450.00

\$0.00

Number of Repair Days

5.0

Prepared / Adjusted By

ARC Manager Team

ARC / Surveyor Sign Off Date

13/03/2019 11:12 AM

Signature

Remarks

Section C - Quotation and Accident Invoice Details

Quotation Number

Invoice Number

Quotation Date

Invoice Date

Invoice Amount

Prepared Date



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 13/03/2019

User ID : GohKK2

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope		Quotation from AR				Adjusted by Surveyor, if applicable			
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		\$2,120.00							
Total Labour		\$2,120.00							
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS		\$786.00							
Total Spray Painting & Panel Beating		\$786.00							
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010060	Body	F01001-CW271	COVER:REAR TAIL LAMP,LH,FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repair	
6010457	DOOR		LEAF ASSY:REAR DOOR,FOR MAN A22 BUS	1.00	\$20,700.00	0.00	\$20,700.00	Replace	
6010003	BODY LH	A01001-CW559	PANEL,SIDE:L9,FOR MAN A22 BUS	1.00	\$248.20	100.00	\$0.00	Repair	
6010001	BODY LH	A01001-CW557	PANEL,SIDE:L7,FOR MAN A22 BUS	1.00	\$330.70	100.00	\$0.00	Repair	
6010006	BODY LH	A01001-CW562	PANEL,SIDE:L12,FOR MAN A22 BUS	1.00	\$247.30	100.00	\$0.00	Repair	
Total					\$22,500.90		\$20,700.00		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									