unvagor Korsyl		GNMENT (Office	9		
From (Person). Chong Boor	Sen of	CTL	Di	defring 14 March. 201	13:28 PM
Estimated Cost		Bill to:			
OD (TP) WS/TP RES/OD I	D322 MOTO		Insured:	GBG 647R	
at Workshop m/s Br of 303 Alexandra 1	formance		Tel:		
Policy No. DM CV SN		Claim No.	SNMIA	0201171002	,
Sum lusured:		Haccas:			
Make of Veh; (Client's Record)			D.	D.A. Q.3.2019	
CA / REV / REP. / REV 24 Date/Time: 14. 3. 3619 4.36	HRS "wp"	noted: Caroline		I.O.D. Endocement:	
Date/Fime Action/Instruction SEK 1237K GB GUFR		lmale 202451/R1911	3m2		•
1714/19 101.28m Con		Dr. Cantin	- France	Ga 6 221 20	2 days

Surveyor ( Com	
	SIGNMENT
From Date (9/3/10)	Veh No SLK 1232P Yr Rogn: 2017 / JAN
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD/ TP /WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No: 82K 1237 R	Make: B.M. W 320 I ac 1998
	Colour BLACK A/C Insured / Std / NI / NA
at Workshop m/s PML of 303 Mexandra Road	Sp.Reading 45746 T/Radio: Insured / Std / NI / NA
	opinioning .
Insured:	CINO: WBASA [ GOODN W 3 9.695
Palicy No.	
Claims No.	Gen. Cond: Good (Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Ineffer / Jammed / Leaked / Burnt or
(Client's Record)	Brake: (norder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / SRim / STD A/Rim or
after con	Tyre Size: F: 225 SoR()
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (PIP) SUMI /
repair at the time of Inspection.	TOYO / YOKO or
Bal, or Market Value	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm L/Bal. 6 mm
Est Repairs: 2 days Res.: Yes or No	D.O.A 08/03/19 D.O.I. 20/05/19
Lum Sum: % 3 Val.: Yes or No	Survey held al PERPIRABULE
Con Contract of the Contract o	Des. of Damages : Frt J-Rem / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS Vehicle IN/O	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time Action / Instruction	
arcell.	VED 2 9 APR 2019
KECE	
	(1)
Dute/Time File Pass to? : Preli. Report	Days Of Repair:
1) 28 4 MAST : Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add F	ee: Site Insp (\$ )_5+R5_5I
5 20 30	: Interview (\$ ) Photos
Report Format: MER-91 Lump Sum / I.B.I: (\$ 3306.30)	Tech Invs (\$ ) Others
Lump Sum / I.B.I: (\$ 3306.30)	Weekend (\$

TOTAL

### Nivitha (LKK Auto)

From:

Chong Boon Sen <booksen.chong@sq.cntaiping.com>

Sent:

Thursday, 14 March 2019 3:28 PM

To:

PBSP

Cc:

'assignments'

Subject:

RE: OUR REF: SNM19D201170 - REQUEST FOR DIRECT SETTLEMENT - SLK1232R &

GBG667R ON 08/03/2019 - ANR+PRS

Attachments:

SKM\_558e19031208150.pdf; SLK1232R(MARCH).pdf

Without Prejudice

Dear Sir.

We assign LKK.

Dear LKK,

Pls pri.

Regards.

### Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909 Co. Reg. No. 200208384E

DID: 63896171 Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

#### Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]

Sent: Thursday, 14 March, 2019 2:06 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Re: OUR REF: SNM19D201170 - REQUEST FOR DIRECT SETTLEMENT - SLK1232R & GBG667R ON 08/03/2019

- ANR+PRS

Dear Boon Sen

We are agreeable to use a common surveyor - LKK Auto - as the SJE.

Thank you.

Regards, Caroline

C/o Performance Motors Limited - Body and Paint

7 W 4.70

v - out

FORMALH V

303 Alexandra Road Singapore 159941 DID: 6319 0174 Fax: 6479 4601

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Sent: Thursday, 14 March 2019 10:50:44 AM

To: PBSP

Subject: RE: OUR REF: SNM19D201170 - REQUEST FOR DIRECT SETTLEMENT - SLK1232R & GBG667R ON 08/03/2019

- ANR+PRS

### Without Prejudice

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

DILL EXPELT	
ADRIAN LING	
Kelvin Ang	
SEE CHEW SENG	
MOHD FADHILAH BIN	
OSMAN	
XING QUO QIANG	
KENNETH KONG	
SIMON HO	
CHUA WEIJIE	
MARCUS CHUA	
HENRY NG	

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

### Regards.

### Chong Boon Sen

Claims Executive

Claims

### China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Co. Reg. No. 200208384E DID: 63896171 Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

#### Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]

Sent: Tuesday, March 12, 2019 8:19 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: REQUEST FOR DIRECT SETTLEMENT - SLK1232R & GBG667R ON 08/03/2019

Dear Sirs.

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit <a href="http://www.symanteccloud.com">http://www.symanteccloud.com</a>	
This email has been scanned by the Symantec Email Security.cloud service.  For more information please visit <a href="http://www.symanteccloud.com">http://www.symanteccloud.com</a>	_

## Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Wednesday, 17 April 2019 1:28 PM

To:

PBSP; Rasul (LKKAuto); SUR

Subject:

RE: FINAL REPORT / SLK1232R

Dear Caroline,

WITHOUT PREJUDICE

Confirm final fig \$3,306.30 before GST and 3 repair days.

Kindly send the relevant documents to China Taiping Insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg> Sent: Saturday, 13 April 2019 11:49 AM

To: Rasul (LKKAuto) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: FINAL REPORT / SLK1232R

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour: 2,014.00 Total Parts: 1,292.30

Total Labour & Parts: 3,306.30

Repair days: 3

Thank you.

Regards, Caroline

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

The second second second	ACCIDENT STATEMENT	
Date Of Report	11/03/2019 14:00	
Date Of Accident	08/03/2019 18:00	
Exact Location Of Accident	JALAN BUKIT MERAH	
Country/State of Loss	SINGAPORE	
114 12 13 13 13 13	DETAILS OF OWN VEHICLE	CHARLES AND STREET
Vehicle Registration Number	SLK1232R	
Insured/Policyholder		
Name Of Registered Owner	GOH BEE LAY	
NRIC No	S7232077H	
Email Address	PAM.GOH99@GMAIL.COM	
Mobile Phone No	(LOCAL) +65-91558995	
Alternative Phone No	OTHERS-91558995	

Vehicle Particulars

Manufacturer BMW

Model 320I SPORTS

Exact Purpose for which vehicle was being used at

time of accident

NORMAL USAGE

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken THIRD PARTY Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company LIBERTY INSURANCE PTE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number UNAVAILABLE

Cover Note Number

Driver

Name of Driver GOH BEE LAY NRIC No S7232077H Date Of Birth 04/09/1972 Occupation OUTDOOR Date Of Driving Pass 02/03/1995

**Driving Experience** 24 YEARS AND 0 MONTHS

Gender FEMALE

Mobile Number (LOCAL) +65-91558995

Fax Number

Contact Number OTHERS-91558995

EMail Address PAM,GOH99@GMAIL,COM Address

BLK 515B TAMPINES CENTRAL 7 # 13-18

Postcode

522515

. Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

...

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

VU

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number

GBG667R

Vehicle Make/Model/Colour

TOYOTA SILVER

**Details Of Properties** 

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

SHAHMIL EKNUR BIN EKRAM

NRIC/Passport Number

S9026022G

Contact Number

87529844

Address

SHAH'S COMPANY IS DAYPLUS FOOD PTE LTD

65159948

Postcode

Insurance Company Name

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Nature Of Damage

FRONT

No. Of Passenger (Including Driver)

Page 2 of 11

#### Sketch Plan Pg. 1

#### SKETCH PLAN

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance compenies is not an admission of policy liability on the part of the insurance companies
- Any faise reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (I) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
  - [ii] investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me:
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve discloture of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes"
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Driver's Signature

11.30 GW [If driver is not the policyholder]

Date & Time:

Reporting Centre Personnel's Signature

NRIC/FIN No.:

DESCRIBE	CIRCUMSTAN	programme and the same of the	
OF3CKIBE	STREETINGS LADIN	LEADE THE	AFFIRENT

Red light	soo in option	as if as
car ste	1. der delle	car before my
apologist	rer acknowled	ged his mutalia an
dri	lars are true in every respect.	Char
older's Signature Time:	Oriver's Signature (If driver is not the policyholder) Cate & Time:	Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

BMM Dealer

## Performance Motors Limited

A member of the Sine Durby Group Co. Reg. No. 197401555W GST Neg. No M2-0020081-x

303. Alexandra Road Sime Darby Performance Centre Singapore 159941

Tel. 63190100 (Sales a Admin) 63190111 (AfterSales) Fax. 66767770

180, Kampong Arang Road East Coast Centre Singapore 438180

Tel. 63190888 (AfterSales) Fax. 63449773

315. Alexandra Road Sine Darby Musiness Pentre Singapore 159844 Tel 63190528 AfterSa 63190533/530 Motorra (Afterfales)

(Motorrad) (AfterSales) (Motorrad) FBX: 64796601 64796624

GST REG. NO : M2 - 0020081 - X

ESTIMATE

12 MAR 2019

Page No. : 1 of 5

Estimate No. Date Estimated : b1

50447

: 11/03/2019

Prepared By

: Kevin Leong Wai Kit

- ESTIMATE REPAIR FOR -

Goh Bee Lay

515B Tampines Central 7

#13-18

- ACCOUNT -135

China Taiping Insurance (S) Pte Ltd

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

Singapore 522515

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

SLK1232R

NU39695

06/01/2017

320iA/4Dr

0

DESCRIPTION

To replace rear bumper panel and all attachments cause by

accident.

Painting on rear bumper panel

To check electrical wiring systems at the rear section

for proper function.

Sundries.

Total Labour 1:

PRIC

69.80

32.90

43.25

58.50

58.50

467.95

2,995.00

VALUE

69.80

32.90

80.00

VALUE

1,700.00

DESCRIPTION

RR BUMPER BOTTOM REINFORCEMENT REAR BUMPER CENTRE GUIDE ?

REAR BUMPER TOWING EYE COVER PRIMED A REAR BUMPER LH SIDE GUIDE ?

REAR BUMPER RH SIDE GUIDE 7

REAR BUMPER BLACK TRIM STRIP ?

REAR BUMPER PANEL PRIMED (LINES) SET MOUNTING PDC/PMA SENSOR REAR

DECOUPLING RING PDC TORQUE CONVERTE (DG/SL) ADHESIVE SET K6 A4 -

81.40 1,172.30 66.95 5.05 53.05

QTY

Total Parts

:

467.95 43.25 58.50 58.50 81.40 1,172.30 66.95 20.20

2,124.80

" 53.05

BMN Dealer

## Performance Motors Limited

A number of the Sime Darby Group Co. Reg. No. 197401555W GST Reg. No M2-8828881-x

303. Alexandra Boad Sime Darby Performance Centre Singapore 159941 Tel 62190130 (Sales & Admin) 61390131 (AfterSales) Fax 64747770

280, Kampong Arang Koad East Coast Centre Singapore 438180

Tel. 63190888 (AfterSeles) Fax. 6344977)

315. Alexandra Road Dime Darby Business Centre Singapore 159944 Tel 63190529 (AfterSale 63190533/536 (Motorrad)

AfterSales) Motorrad



Page No. : 2 of 5



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. Date Estimated

50447 : b1

: 11/03/2019

Prepared By

: Kevin Leong Wai Kit

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

REGN. NO. SLK1232R

NU39695

06/01/2017

320iA/4Dr

0





LKK Auto Consultants North nash the Repairer of the following:

• To assure of the following:

• To display changed port(s) during massivey Parts prices are subject to confinuation Third party survey is on a "Without Prepudde" basis. No illegal modification(s) is allowed Supplementary Barr(b) must be assurabled and it subject to final approval from insuration Company Acknowledged by Repairer Signature:

2,995.00 Labour 1 Parts 2,124.80 Labour 2 0.00 0.00 Excess Total GST @ 7% 358.39 Grand Total 5,478.19

<sup>\*\*</sup> PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*



<sup>\*\*</sup> THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

# **Performance Motors Limited**

A member of the Same Darby Group Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



### FINAL REPORT

Estimate No.

: b1 50447

Page No. :

Date Estimated : 11/03/2019

Prepared By

: Kevin Leong Wai Kit

REPAIR FOR -

- ACCOUNT -

Goh Bee Lay

515B Tampines Central 7

#13-18

China Taiping Insurance (S) Pte Ltd

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

GST @7%:

Grand Total:

Singapore 522515

REGN. NO.	CHASSIS NO.	REGN DATE	MODEL		M LEA	VŒ.
SLK1232R	NU39695	06/01/2017	3201A/4Dr		0	
DESCRIPTION	¥		ORIGINA	AL PRICE	DISC. %	NETT
	r bumper panel and atta lents caused by the acci			850.00		850.00
To spray paint	rear bumper			934.00		934.00
To check elect for proper fund	trical wiring systems at t	he rear section		150.00		150.00
Sundries				80.00		80.00
DESCRIPTION	4		UNIT PRICE	QTY	DISC. %	NETT
2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	ER PANEL PRIMED (LIN NG PDC/PMA SENSOR SIVE SET K6	Control P.	1,172.30 66.95 53.05	1,00 1,00 1,00		1,172.30 66.95 53.05
SUPPLEMENTA	RY ITEMS		Total Labour : Total Parts :			2,014.00
			Total Labour & Deduction for E	xcess:	outers.	3,306.30
			Total Repair Co	sts less Exc	:ess:	3,306.30

231.44

3,537.74

## ...CLAIM SUBFOLDER...(Pending for Survey Report)


	OLDER TRA	Est Submitted	Adj Assigned	Adj Rpt	Adi Submitted	Ins Auth'ed	Status	
	17 Apr 2019	Est Submitted	17 Apr 2019 18:08 Edit Adj Rpt	\$\$3,306.30 Edit Estimates	\$\$3,306.30 View Rpt	Ins Auth ed	Pending fo Report Cancel Cas	
	fain	∏ R	eference	Claim De	tails	Document	,	Show All
and distance to the same	FOLDER D	TAILS			[Created	by insurer]		
Insured: Main	GOH BEE	LAY. ID: 57232	2077H					
Claimant: Vehicle Reg. No.:	SLK123	2R		Date of		19 18:00 - :59 hs and <b>2</b> Days Fron	n LTA Reg Date (	(Man Yr))
Claim Type:	TP / SNI	M19D201170C0	2	Policy/ Note N		7704818011		
Vehicle Reg. No. (Insured):	GBG667R			Policy 1	Policy No. (Claimant): UNAVAILABLE			
				Excess				C - COAC
Repairer:		63190174	ted (Alexandra) 3	03 Alexandra Road,	Sime Darby Perfo	rmance Centre, 15	9941 Alexandra	- Teli
Handling Insurer:	China Tai	ping Insurance	(Singapore) Pte. L	td. (HQ) - Tel: 638	9 6111 [Handle	ed by Chong Boor	Sen]	
Claimant's Insurer:	Liberty In	surance Pte Ltd	(HQ) - Tel: (65) 6	221 8611				
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561 [Handle	d by MOHD RAS	UL] [Final Rp	t due 29/04/2	019]
ASSOCIAT	ED MAIL RE	CEIVED				Vie	w All Compo	se Case Mail
There are no	mail for this	case.						
ALL ASSO	CIATED TAS	iks∃			View All	Search Tasks C	Create New Task	Complete
Due Date	Priority	Type Task	Group Subjec	t Handler	Assigned By	Completed On	Created O	n Done

### Claim Documents

\*SLK1232R (SNM19D201170C02)
[GBG667R]
TP
GOH BEE LAY
Mar 8 2019 6:00PM
[-]
Performance Motors Limited

Vid	eo		1 per	page 🔻	V
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	-
1	11/03/19 14:05	Video - Accident  Linked Accident Report Documents	0	Load AVI	
Ass	essment Reports		I per	page V	V
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	-
1	11/03/19 14:09	Accident Statement	0	Load HTM	
Dhe	otos/Images		Parameter		-
No	Finalized On	Budget and the state of the sta	3 per	PINCE TO SERVICE STATE OF THE PERSON NAMED IN COLUMN TO SERVICE STATE OF THE PERSON NAMED STATE OF THE PERSON NAMED STATE OF THE PERSON NAMED STATE OF THE PERSON NAME	S
	1231/140/45310VES	Performance Motors Limited (Alexandra) Accident Photo		Thumbnail	10000
1	11/03/19 14:05	[Linked Accident Report Documents]	0	Load JPG	1
2	11/03/19 14:05	Accident Photo [Linked Accident Report Documents]	0	Load JPG	V
3	11/03/19 14:05	Accident Photo [Linked Accident Report Documents]	0	Load JPG	☑
4	11/03/19 14:05	Accident Photo [Linked Accident Report Documents]	0	Load JPG	V
5	11/03/19 14:05	Accident Photo [Linked Accident Report Documents]	0	Load 3PG	V
6	11/03/19 14:05	Accident Photo [Linked Accident Report Documents]	0	Load JPG	2
7	11/03/19 14:05	Accident Photo [Linked Accident Report Documents]	0	Load 3PG	Ø
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	29/04/19 16:59	Odometer Reading	0	Load JPG	V
2	29/04/19 16:59	Chassis Number	0	Load JPG	V
3	29/04/19 16:59	General View	0	Load 3PG	<b>3</b>
4	29/04/19 16:59	General View	0	Load JPG	V
5	29/04/19 16:59	General View	0	Load JPG	V
6	29/04/19 16:59	General View	0	Load JPG	V
7	29/04/19 16:59	General View	0	Load 3PG	Ø
В	29/04/19 16:59	General View	0	Load JPG	V
9	29/04/19 16:59	General View	0	Load JPG	(Z)
10	29/04/19 16:59	General View	0	Load JPG	(Z)
11	29/04/19 16:59	General View	0	Load JPG	₩.
-				1,000,000,000	-
12	29/04/19 16:59	General View	0	Load JPG	<u>Z</u>
13	29/04/19 16:59	General View	0	Load JPG	V
14	29/04/19 16:59	General View	0	Load JPG	3
Doc	umentation		1 per s	age 🔻	<b>W</b>
No.	Finalized On	China Talping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnall	Print
1	17/04/19 18:09	pri contact	0	Load PDF	
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
t	11/03/19 14:06	Sketch Plan [Linked Accident Report Documents]	0	Load TIF	

### **Linked Accident Report Documents**



### **Documents Checklist**

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

## LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI19004644/R1QD3Q2

Date:

06/05/2019

REFERENCE

Handling Insurer:

China Taiping Insurance

(Singapore) Pte. Ltd.

Policy No:

DMCVSN17704818011

Claimant Vehicle

SLK1232R No:

No:

Insured Vehicle GBG667R

Date of Loss:

08/03/2019

Nature of Claim: TP

Claim No:

SNM19D201170C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

**SLK1232R** 

Make & Model:

BMW 3201, 2.0 LED NAV SHAD, LIGHT (A)

Engine No: Chassis No: 20959694B48B20A

Reg. Date: Colour.

Black

06/01/2017 (Man. Year: 2016)

Odometer:

WBA8A16000NU39695 45740 km

Engine Capacity:

1998 cc Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

225/50 R17

Rear Tyre Size:

225/50 R17

Front Tyre Size: Front Left Side: Front Right Side:

Pirelli 6 mm Pirelli 6 mm. Rear Left Side: Rear Right Side:

Pirelli 6 mm Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,204.80	1,372.30	832.50	37.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,915.00	1,934.00	981.00	33.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,119.80	3,306.30	1,813.50	35.42
+ GST 7.00/7.00% (S\$)	358.39	231.44	126.95	35.42
Nett Amount (S\$)	5,478.19	3,537.74	1,940.45	35.42

INSPECTION

Date of Assignment:

17/04/2019

Date Inspected:

20/03/2019 Inspected At:

Performance Motors Limited (Alexandra)

303 Alexandra Road, Sime Darby

Performance Centre Singapore 159941

Estimated Period of Repair:

3.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 06 May 2019)

Parts:

BMW 320I 2.0 LED NAV SHAD. LIGHT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLK1232R)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*RR BUMPER BOTTOM REINFORCEMENT	Not Necessary	69.80 FS	*-FS
3	1		*REAR BUMPER CENTRE GUIDE	Not Necessary	32.90 FS	*-FS
4	1		*REAR BUMPER CARRIER (ECE)	Not Necessary	467.95 FS	*-FS
5	.1		*REAR BUMPER TOWING EYE COVER PRIMED	Not Necessary	43.25 FS	*-FS
6	1		*REAR BUMPER LH SIDE GUIDE	Not Necessary	58.50 FS	*-FS
7	1		*REAR BUMPER RH SIDE GUIDE	Not Necessary	58.50 FS	*-FS
8	1		*REAR BUMPER BLACK TRIM STRIP	Not Necessary	81.40FS	*-FS
9	1		*REAR BUMPER PANEL PRIMED (LINES)	Deformed	1,172.30 FS	*1,172.30 FS
10	1		*SET MOUNTING PDC/PMA SENSOR REAR	Necessary	66.95 FS	*66.95 FS
11	4		*DECOUPLING RING PDC TORQUE CONVERTE	Not Necessary	20.20 FS	*-FS
12	1		*(DG/SL) ADHESIVE SET K6	Necessary	53.05 FS	*53.05 FS
F=Fra	anchise	part. S=Spc	Nett	A STATE OF THE STA	100000000000000000000000000000000000000	0.0000000000000000000000000000000000000
				Total Parts (S\$)	2,204.80	1,372.30

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REPLACE REAR BUMPER PANEL AND ALL ATTACHMENTS CAUSE BY ACCIDENT	New	1,700.00	850.00
2	PAINTING ON REAR BUMPER PANEL	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
	Gross Labour Cost (S\$)		2,915.00	1,934.00
	Report was unsubmitted during	this print-out.		

< END OF ESTIMATES >