

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: CHINA TAIPING	DATE	: 12/03/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SLV5541P		
MODEL	: HONDA JAZZ 1.4A		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 12-Mar-19
		TIME	: 09:00HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS (REAR)

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL GATE <i>Dented</i>	1	\$ 1,122.00	\$ 1,122.00
2	TAIL GATE LOGO <i>new</i>	1	\$ 45.00	\$ 45.00
3	TAIL GATE EMBLEM 'JAZZ' <i>new</i>	1	\$ 45.00	\$ 45.00
4	TAIL GATE DETECTOR <i>crushed</i>	1	\$ 155.30	\$ 155.30
5	TAIL GATE BUZZEL <i>crushed</i>	1	\$ 180.00	\$ 180.00
6	TAIL GATE INNER LOCK <i>crushed</i>	1	\$ 225.80	\$ 225.80
7	TAIL GATE WEATHER STRIP <i>crushed</i>	1	\$ 128.00	\$ 128.00
8	TAIL GATE INNER TRIM <i>Deformed</i>	1	\$ 118.20	\$ 118.20
9	TAIL GATE WINDSCREEN MOULDING <i>new</i>	1	\$ 190.00	\$ 190.00
10	REAR BUMPER <i>Deformed</i>	1	\$ 730.00	\$ 730.00
11	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 42.00	\$ 84.00
12	TAIL LAMP <i>new new</i>	2	\$ 330.00	\$ 660.00
13	TAIL LAMP LOWER BRACKET <i>3 new</i>	2	\$ 62.00	\$ 124.00
14	TAIL LAMP PANEL <i>new</i>	2	\$ 230.00	\$ 460.00
15	REAR END PANEL <i>Dented</i>	1	\$ 520.00	\$ 520.00
16	REAR END PANEL TOP GARNISH <i>Deformed</i>	1	\$ 190.00	\$ 190.00

2892.3

TOTAL PRICE \$ 4,977.30
LESS 20% \$ 995.46

2313.84

716.

85

530.

435.

SUB TOTAL PRICE \$ 3,981.84

SPECIAL NETT ITEMS (REAR)

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00
2	TAIL GATE SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00
3	TAIL GATE INNER TRIM CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
4	TAIL GATE WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00
5	TAIL GATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00
6	REAR BUMPER CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
7	REAR BUMPER LOWER LID <i>Delud</i>	1	\$ 1,100.00	\$ 1,100.00
8	REAR BUMPER LOWER LID STICKER <i>new</i>	1	\$ 90.00	\$ 90.00
9	TAIL LAMP CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
10	TAIL LAMP PANEL SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00
11	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	1	\$ 20.00	\$ 20.00
12	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 120.00	\$ 120.00
13	REVERSE SENSOR <i>Dangd.</i>	1	\$ 220.00	\$ 220.00

1160

TOTAL \$ 1,960.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,600.00	800	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	800	
3	TUFF COAT	\$ 250.00	60	
4	WIRING CHECK	\$ 80.00	30	
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 180.00	80	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	60	
7	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓	
8	TRANSFER TAILGATE MECHANISM	\$ 80.00	✓	
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X	

TOTAL

\$3,970.00

2030

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,941.84

TOTAL LABOUR COST : \$ 3,970.00
TOTAL REPAIR COST : \$ 9,911.84

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian King.
2/s 13/03/19.
06 days.

total: \$503.84
4/s 4.4K.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: