

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 7803L

CHINA / LKK

DATE 13/3/2019 11:55

FZ

MAKE :

RIGHT REAR

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper ✓			\$ 553.00	
	Rear Bumper Clip 10 pcs ✓			\$ 22.00	
	<i>Rear fender (RH) x repair</i>				
	SUB TOTAL			\$ 575.00	
	LESS 20%			\$ 115.00	
	DISCOUNTED TOTAL			\$ 460.00	
	Rear Bumper Advertisement Logo ✓			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00	Nett
				\$ 250.00	
	Labour Charge				
	Panel Beating-Repair Fender			\$ 400.00 ²⁰⁰	
	Spray Painting Charge			\$ 600.00 ⁴⁰⁰	
	Tuff Kote			\$ 50.00 ^X	
	TOTAL LABOUR			\$ 1,050.00	
	ESTIMATE TOTAL			\$ 1,760.00	
	<i>Ka Ina (LKK)</i>				
	<i>13/3/19 1520hr.</i>				
	<i>2 Pys</i>				
	<i>L/S</i>				
	<i>After Repair photo</i>				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary items must be surveyed and is subject to final approval from the insurance company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.