

ASS. REC. BY:

REF: CS/SPF/900462/ Rlyd302

Special Instruction:

Surveyor

Rahul

ASSIGNMENT (Office)

From (Person):

Hafizul Fuhon

of

SPF

Date/Time:

14/3/19 12:31pm

Estimated Cost:

Bill to:

OD / TV / WS / TR / RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

AJR 6178

Insured:

QX 10318

at Workshop m/s

Mova Automotive

Tel:

62723892

of

Bik 1008 Bkt Merah lane 3 # 01-04

Policy No:

Claim No:

AEMD/105/009/2019/014

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

5/3/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:47pm 14/3/19

Person Contacted:

Nithe

Vehicle IN/OUT

Date/Time

Action/Instruction (-) Estimate

AJR 6178 - X

QX 1031 - X

Do Not Finalise

7/5/19

@ 5.01pm Suanne said vehicle not repair, pending liability

29/5/19

@ 5.01pm Suanne said vehicle not send in for repair, pending liability

27/7/19

Submit LS \$ 2000, 3 days

upper range \$ 2000 - \$ 3000

1/8/19 To re-open and Submit final report. Pls pass to typist *Alvin* 2/8/19

5/8/19 Reopen ref only, 1st Doc 14/1/19

Form

RUE

Form 10/11/12

Vehicle No. **AGR 6178** Date **2014 MAR**

Type ☒ Motor Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Other Motor / ☐ Truck / ☐ Trailer or

Make **TOYOTA CAMRY 2.5V A** Year **2004**

Colour **Grey** Insured / ☐ STD / ☐ HRA

Cap Loading **671/28** HRA Insured / ☐ STD / ☐ HRA

Eng No **PN153AK5007005938**

Chassis No ☒ Good / ☐ Fair / ☐ Poor / ☐ Bunk

Steering ☒ Good / ☐ Jammed / ☐ Leaked / ☐ Bunk or

Brake ☒ Good / ☐ Jammed / ☐ Leaked / ☐ Bunk or

Mod ☒ HRA / ☐ STD / ☐ HRA or

Tyre Size **F: 225/45R18**
R: 225/45R18

BS / ☒ DUH / ☐ EXHOVA / ☐ GY / ☐ HS / ☐ LIZA / ☐ MRC / ☐ OHT / ☐ SUI / ☐ PIR / ☐ SUMU

TOYO / YOKO or

Front	Left	Right
6 mm	6 mm	6 mm
6 mm	6 mm	6 mm
D.O.A. 01/03/19	D.O.A. 20/03/19	

Survey held at **MOVA (G.M.)**

Doc of Damage: ☒ F / ☐ R / ☐ O / ☐ S / ☐ H / ☐ U / ☐ R / ☐ Roof / ☐ or

The URC / Chassis frame / Body Structure affected due to collision.

Location _____ Date _____

Estimated Cost _____

City / TP / WS / TP RES / OD RES / EVA / HV / MV _____

Inspected Vehicle No **AGR 6178**

at Workshop no **MOVA**

at **BUKIT MERAH**

Insured **SPF**

Date of Hire _____

Claim No _____


Claim Insured _____

Excess _____

Policy No _____

Policy Condition _____

Remarks: The veh had commenced its repair at the time of inspection.



Est. or Market Value _____

Insurance: Accident Report _____ Consistent? Yes or No

City / TP / WS _____ Consistent? Yes or No

Est. Reported _____ days _____ Res. Yes or No

Est. Sum _____ % _____ 3 Val. Yes or No

CA / REV / REP / 24 HRS

Date _____ Person Contacted _____

Vehicle: IN / OUT

Date / Time _____ Action / Instruction _____

Range of repair cost - 2K - 4K (EST)

RECEIVED 03 JUN 2019

Time Stamp: File Path: _____

☒ Prel. Report

☐ Final Report

Time Stamp: File Path: _____

3/6 - typist

Report Form: _____

Unrep. Sum (P.O. / C.O.) _____

Days Of Repair: **3**

Recovery No. of Trip _____

Add Fee: ☐ Sub-to: 1K
☐ Inter-city: 1K
☐ Long-haul: 1K
☐ Other: 1K

Survey Fee _____

Transportation _____

Other _____

220

220

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

08/03/2019

SPF ACCIDENT CLAIM SECTION
No. 1 Mount Pleasant Rd
Blk 8 Old Police Academy
Singapore 298333.

Page # :- 1
Veh # :- AJR6178
Veh Model :- TOYOTA CAMRY 2.5
Estimate# :- CK418833
Claim # :-
ACC. Date :- 01/03/19
Terms :- C.O.D Days
Remarks :-

Attention :- XA066

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BUMPER <i>DE</i>	1	PC 769.80	769.80
2.	REAR TAILLAMP LOWER BRACKET L+R <i>X SUC</i>	2	PC 85.70	171.40
3.	REAR BUMPER RETAINER L+R <i>X SUC</i>	2	PC 122.10	244.20
4.	PARKING SENSOR <i>AW</i>	2	PC 418.80	837.60
5.	REAR REINFORCEMENT <i>ST</i>	1	PC 491.80	491.80
6.	SPONGE <i>XAN</i>	1	PC 143.00	143.00
7.	KEYLESS SENSOR <i>~SUC</i>	1	PC 190.80	190.80
8.	END PANEL - REPAIR <i>X</i>	1	PC	
9.	REAR BUMPER LOWER SKIRT - REPAIR <i>X</i>	1	PC	
10.	REAR BOOT - REPAIR <i>X</i>	1	PC	
LIST TOTAL S\$				2,848.60
25% DISCOUNT S\$				-712.15
				2,136.45
LABOUR :				
TO REPAIR REAR BOOT, REAR BUMPER LOWER SKIRTING, TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS & STRAIGHTEN ACCIDENT AFFECTED AREAS				<i>400</i> 600.00
TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS				<i>400</i> 600.00
TO REMOVE & REFIX REAR PARKING SENSOR & CHECK WIRING				<i>60</i> 120.00
TO REMOVE REAR BOOT TRIM, SPARE TYRE COVER AND OTHER ATTACHMENT PARTS				<i>60</i> 120.00
TO RUST PROOF ON ACCIDENT DAMAGED PARTS				<i>40</i> 80.00
TO INSPECT REAR TAILLAMP WATER LEAKAGE TEST				<i>12 X</i> 60.00
LABOUR TOTAL S\$				1,500.00

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/04
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

08/03/2019

SPF ACCIDENT CLAIM SECTION

No. 1 Mount Pleasant Rd
Blk 8 Old Police Academy
Singapore 298333.

Page # :- 1 134313

Veh # :- AJR6178

Veh Model :- TOYOTA CAMRY 2.5

Estimate# :- CK418833

Claim # :-

ACC. Date :- 01/03/19

Terms :- C.O.D Days

Remarks :-

Attention :- XA066

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$

3,716.45

GST @ 7 %

260.15

AMOUNT DUE S\$

3,976.60

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

Rasul
Hp 90110068
21/3/19

3 days

L/S

20/03/19 @ 1200hrs

Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice"
- No illegal modification(s) is allowed
- Survey inventory list must be used and is subject to final approval from Assessor

Acknowledged by Repairer:

Signature:

Date:

Estimate

08/03/2019

SPF ACCIDENT CLAIM SECTION
 No. 1 Mount Pleasant Rd
 Blk 8 Old Police Academy
 Singapore 298333.

Attention :- XA066

Page # :- 1

Veh # :- AJR6178

Veh Model :- TOYOTA CAMRY 2.5

Estimate# :- CK418833

Claim # :-

ACC. Date :- 01/03/19

Terms :- C.O.D Days

Remarks :-

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

Tel: (65) 6272 3892
 Fax: (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BUMPER <i>DE</i>	1 PC	769.80	769.80
2.	REAR TAILLAMP LOWER BRACKET L+R <i>X</i>	2 PC	85.70 <i>RH</i>	171.40
3.	REAR BUMPER RETAINER L+R <i>X</i>	2 PC	122.10 <i>RH</i>	244.20
4.	PARKING SENSOR <i>?</i>	2 PC	418.80	837.60
5.	REAR REINFORCEMENT <i>? b</i>	1 PC	491.80	491.80
6.	SPONGE <i>?</i>	1 PC	143.00	143.00
7.	KEYLESS SENSOR <i>? X</i>	1 PC	190.80	190.80 <i>X</i>
8.	END PANEL - REPAIR	1 PC		
9.	REAR BUMPER LOWER SKIRT - REPAIR <i>/</i>	1 PC		
10.	REAR BOOT - REPAIR <i>X</i>	1 PC		
LIST TOTAL S\$				2,848.60
25% DISCOUNT S\$				-712.15
				2,136.45
LABOUR :				
TO REPAIR REAR BOOT, REAR BUMPER LOWER SKIRTING, TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS & STRAIGHTEN ACCIDENT AFFECTED AREAS				
TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS				
TO REMOVE & REFIX REAR PARKING SENSOR & CHECK WIRING				
TO REMOVE REAR BOOT TRIM, SPARE TYRE COVER AND OTHER ATTACHMENT PARTS				
TO RUST PROOF ON ACCIDENT DAMAGED PARTS				
TO INSPECT REAR TAILLAMP WATER LEAKAGE TEST				
LABOUR TOTAL S\$				60.00
				1,580.00

2099.20
 Parts \$ 2290 - 25%
 \$ 1717.50 1574.40

Labour \$ 960
 2534.40
 total \$ 2677.50 - 20%
 \$ 2150 3044.52 2027.52
 Vep fee \$ 131.70 413-2000 60 120.00
 60 120.00
 40 80.00

Main Office
Mova Building
No. 22, Jalan Klang
Singapore 159419
Tel: (65) 6476 3334
Fax: (65) 6271 5897
www.mova.com.sg

Workshop Dept
Block 1008
Bukit Merah Lane 3
#01-04/06/08/9
Singapore 159721

Tel: (65) 6272 3897
Fax: (65) 6270 8314
Co. Reg. 198904033C
GST Reg. M2-0088864-1

Estimate

08/03/2019

SPF ACCIDENT CLAIM SECTION

No. 1 Mount Pleasant Rd
Blk 8 Old Police Academy
Singapore 298333.

Attention :- XA066

Page # :- 1 134313

Veh # :- AJR6178

Veh Model :- TOYOTA CAMRY 2.5

Estimate# :- CK418833

Claim # :-

ACC. Date :- 01/03/19

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$

3,716.45

GST @ 7 %

260.15

AMOUNT DUE S\$

3,976.60

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

Rasul

Hp 90010068

3 days

4/3

20/03/19 @ 1200hrs

Resuming after repair

1. I/We Auto Consultants hereby certify that the Repairer of the following:

- To return my vehicle after repair
- To display damaged part(s) for my view
- To ensure that the vehicle is safe to drive
- To ensure that the vehicle is in good condition
- To ensure that the vehicle is in good condition
- To ensure that the vehicle is in good condition
- To ensure that the vehicle is in good condition
- To ensure that the vehicle is in good condition

Approved only by:

Signature:

Date:

Click Select button on the right to
choose the transaction for claims

Select All



ERP Payment

02/07/2019 | 07:34 上午

-\$0.50



VEP Payment

01/07/2019 | 07:22 下午

-\$42.40



VEP Payment

28/06/2019 | 06:15 下午

-\$42.40



VEP Payment

27/06/2019 | 06:04 下午


-\$42.40



VEP Payment

25/06/2019 | 06:13 下午

-\$42.40



Add Value

+\$200.00

Click Select button on the right to
choose the transaction for claims

Select All



Add Value

+\$10.00

03/07/2019 | 06:44 下午
NETWOR



ERP Payment

-\$2.00

03/07/2019 | 07:37 上午



VEP Payment

-\$42.40

02/07/2019 | 07:16 下午



Add Value

+\$50.00

02/07/2019 | 06:31 下午
NETWOR



ERP Payment

-\$2.00

02/07/2019 | 07:42 上午



ERP Payment

-\$2.00

Veron Chen (LKKAUTO)

From: Tan Yoong Wei <tanyw@nova.com.sg>
Sent: Saturday, 27 July 2019 9:03 AM
To: Rasul (LKKAUTO)
Subject: RE: FINALISE AJR6178

ok

Best Regards,
Tan Yoong Wei
Estimator
Mova Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

From: Rasul (LKKAUTO) [mailto:Rasul@lkkauto.com]
Sent: Thursday, 25 July 2019 1:52 PM
To: Tan Yoong Wei
Cc: Veron Chen (LKKAUTO)
Subject: RE: FINALISE AJR6178

Hi Yoong Wei,

Refer to attachment

The day I surveyed no damage on keyless sensor. The keyless sensor will not be given.
We will submit on my side amount of \$ 2000 / 3 days lump sum
Finalise amount unconfirmed. As for the VEP, is subject to SPF approval

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

 Auto Consultants Pte Ltd *Save the Earth. Print only when necessary.*

From: Tan Yoong Wei [mailto:tanyw@nova.com.sg]
Sent: Thursday, 25 July, 2019 11:24 AM
To: SUR

Cc: Hsiao Tong (LKKAuto); Rasul (LKKAuto); Veron Chen (LKKAuto)

Subject: FINALISE AJR6178

Hi rasul,

Please advice whether we can finalise cost of repair lumpsum \$2150 3 days

And vep fee for Malaysia car provide receipt \$131.70

TQ

Best Regards,

Tan Yoong Wei

Estimator

Mova Automotive Pte Ltd

Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system.

Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF19004662/R1vd3e2	
ACCIDENT CLAIM SECTION (SPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333		Date : 26-06-2019	
ATTN : HAFIZUL FARHAN		Code : SPF	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	QX 1031B	Veh. Inspected	AJR 6178
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2019/014	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	14/03/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA CAMRY 2.5V (A)	c.c	2494
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	PN153AK5007005938	Colour	GREY
Odometer	67728	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45 R18	MICHELIN	6 mm
L/H Front Tyre	225/45 R18	MICHELIN	6 mm
R/H Rear Tyre	225/45 R18	MICHELIN	6 mm
L/H Rear Tyre	225/45 R18	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	05/03/2019	Inspection Date	20/03/2019
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. AJR 6178

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	769.80	769.80
2	REAR TAILLAMP LOWER BRACKET L+R @\$85.70	SERVICEABLE	171.40	-
2	REAR BUMPER RETAINER L+R @\$122.10	SERVICEABLE	244.20	-
2	PARKING SENSOR @\$418.80	NOT WORKING	837.60	837.60
1	REAR REINFORCEMENT	BENT	491.80	491.80
1	SPONGE	NOT NECESSARY	143.00	-
1	KEYLESS SENSOR	SERVICEABLE	190.80	-
1	END PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR BUMPER LOWER SKIRT (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR BOOT (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 25% DISCOUNT		-712.15	-524.80
			2,136.45	1,574.40
LABOUR				
	TO REPAIR REAR BOOT, REAR BUMPER LOWER SKIRTING, TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS & STRAIGHTEN ACCIDENT AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF END PANEL, REAR BUMPER LOWER SKIRT AND REAR BOOT.		600.00	400.00
	TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS.		600.00	400.00
	TO REMOVE & REFIX REAR PARKING SENSOR & CHECK WIRING.		120.00	60.00
	TO REMOVE REAR BOOT TRIM, SPARE TYRE COVER AND OTHER ATTACHMENT PARTS.		120.00	60.00
	TO RUST PROOF ON ACCIDENT DAMAGED PARTS.		80.00	40.00
	TO INSPECT REAR TAILLAMP WATER LEAKAGE TEST.	NOT NECESSARY	60.00	-
			-	-
			-	-
			-	-
			-	-

Report Ref No. CS/SPF19004662/R1vd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
			-	-
			1,580.00	960.00
GRAND TOTAL			3,716.45	2,534.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,000.00

Report Ref No. CS/SPF19004662/R1vd3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.