

ASS. REC. BY:

REF: cc3/TMI19004665/KISDⁿ²

Special Instruction:

Signature: Kalvin

ASSIGNMENT (Office)

From (Person): Ng Kwai Kay

of TCM

Date/Time: 13/3/19 @

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 3253B

Insured: GBJ 1731R

at Workshop m/s Comfort Delyno

Tel: 0214 8300

of 54 Loxing Drive

Policy No: MS000815

Claim No: M1901606

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 12/03/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 14/3/19 @ 9:37am

Person Contacted:

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SHD 3253B - NS / INCL 017919 / FN D.O.A. 4/9/2010
	GBJ 1731R - X

Surveur: Kalvin

REF: _____

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / IHS / TP RES / OD RES / EVA / INV / MY

To Inspected Vehicle No: _____

at Workshop m/s _____

at _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

NIS	OIS

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Sum Surv: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHO 3253B Tr Regt: 824, 2.6

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai cc 1685

Colour: Blue AJC: Insu / Std / Nil / NA

Sp. Reading: 241161 T/Radio: Ins / Std / Nil / NA

Eng/No: _____

C/No: KM HLB410064091869

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inop / Jammed / Leaked / Burnt or

Brake: Inop / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD Rim or

Tyre Size: F: 205/60 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Caheya

Front: _____ Rear: _____

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. 12/3/19 D.O.I. 13/3/19

Survey held at CDGE (Layang)

Des. of Damages: Frt / Rear / OIS / NIS / UIC / Rooftop or Rear O/S.

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>20/3/19</u>	<u>Check 1 PR \$ 4328.48 / 5 Prp. (\$ 3,483.20 Red - 45%)</u>
	<u>To Kio P/P</u>

RECEIVED 20 MAR 2019

Date/Time, File Pass to? : Prel. Report

1) Typist : Final Report

Date/Time, File Return to? _____

By _____

Signature _____

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: : Site Insp \$ _____

: Interview \$ _____

: Tech Insp \$ _____

: _____ \$ _____

Survey Fee: 250

Transportation: 10

S-RS: _____

Photos: _____

Other: _____

\$ 4,328.48 P/P

260

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Mar 2019 17:03 Sendback Est	13 Mar 2019 17:12 S\$7,707.36	13 Mar 2019 19:00 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	CTPL, Co. Reg. No.: 199303821R		
Main Claimant:	CTPL		
Vehicle Reg. No.:	SHD3253B	Date of Loss:	12/03/2019 18:00 - :59 [32 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M1901606	Policy/Cover Note No.:	MS000815 (Comprehensive) Coverage: 17/01/2019 - 16/01/2020
Vehicle Reg. No. (Insured):	GBJ1731R	Policy No. (Claimant):	
		Excess:	S\$750.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Ng Kwai Kay Francis]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 22/03/2019]		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)

[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/03/2019 11:58
Date Of Accident	12/03/2019 18:00
Exact Location Of Accident	PIE TWDS CHANGI BEFORE LORNIE RD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD3253B
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

Driver

Name of Driver	TEH SIN KIM @ TEE SIN KIN
NRIC No	S2500966E
Date Of Birth	13/10/1946
Occupation	OUTDOOR
Date Of Driving Pass	23/04/1980
Driving Experience	38 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96267978
Fax Number	
Contact Number	
Email Address	SK-TEH@HOTMAIL.COM

Address	BLK 636C SENJA ROAD #06-337
Postcode	673636
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : - GENDER: : MALE
Passenger 2	NAME: : - GENDER: : FEMALE
Passenger 3	NAME: : - GENDER: : MALE
Passenger 4	NAME: : - GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT PANJANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 42 FAJAR ROAD , POSTCODE: 679005 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8929999 - FAX NO: 67673650
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER POLICE REPORT NO: J/20190312/2146

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ1731R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	RAYMOND TAN
NRIC/Passport Number	
Contact Number	97649298
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRONT LH
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	TEH SIN KIM @ TEE SIN KIN
Approximate Age	
Injuries Sustain	NECK
Injured person in which vehicle?	SHD3253B
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this {form} and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)

Date & Time: 13.03.2019
11:25


Reporting Centre Personnel's Signature
Name: Larry Ng
NRIC/FIN No.:

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


* Police Report J/20190312/2146 *

DECLARATION

I/We declare the foregoing particulars are true in every respect.
 COMFORT TRANSPORTATION PTE LTD
 CO. REG. NO. 19530821R

 Policyholder's Signature
 Date & Time:

X 
 Driver's Signature
 (If driver is not the policyholder)


 Reporting Centre Personnel's Signature
 Name: **Lee Ma**



**SINGAPORE
POLICE FORCE**



1 of 2

POLICE REPORT (NP299)

Report No. J/20190312/2146


Police Station Of Origin
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

Date/Time Report Made 12/03/2019 22:16	Vide Report No.	Station Diary No. 176
Name Of Informant TEH SIN KIM	Address APT BLK 636C SENJA ROAD #06-337 SINGAPORE 673636	
ID Type / ID No. NRIC NO / S2500966E	Contact No. Home/Office	Mobile 96267978
Nationality SINGAPORE CITIZEN	Email Address	
Occupation Taxi Driver	Sex Male	Age 72
Institution/School Name	Date of Birth 13/10/1946	Race Chinese
Date/Time Of Incident 12/03/2019 18:00	Location Of Incident PAN-ISLAND EXPRESSWAY SINGAPORE Towards Changi, before Lornie Road exit	

Brief details.

On the 12/03/2019 at about 1800hrs, I was driving my vehicle "SHD3253B" along PIE towards Changi when I arrived at before Lornie Road Exit. I was sending four passenger, a couple and two kids to Bencoolen. At that point in time, I was on the lane 4 of the 6 lane road. Suddenly a truck came from the left of my vehicle and change lane into my lane. I brake my vehicle and managed to avoid collision. At this point in time, the vehicle behind me "GBJ1731R" collided into my vehicle. There is no injuries on all of my passenger. I then took a name card from the driver and left, he is Raymond Tan Hp:97649298. My

Signature Of Officer Recording The Report: J / Sgt 3 CHUA CHUEN LIANG	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 12/03/2019 22:16
Officer In-Charge Of Case: J / Jurong Police Divisional Investigation Branch / Staff Sgt PRATHEEP REHUNATHAN Contact No.: 67910000	Classification Of Case:

Authentication Stamp



SINGAPORE
POLICE FORCE



J/20190312/2146


2 of 2

POLICE REPORT (NP299)


CONTINUATION OF REPORT

Report No. J/20190312/2146

vehicle rear bumper was damaged. I am lodging a report for insurance claims.

Signature Of Officer Recording The Report: J / Sgt 3 CHUA CHUEN LIANG 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 12/03/2019 22:16
Officer In-Charge Of Case: J / Jurong Police Divisional Investigation Branch / Staff Sgt PRATHEEP REHUNATHAN Contact No.: 67910000	Classification Of Case:

Authentication Stamp



ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
 Singapore 508969
 Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	12/03/2019
Vehicle Reg. No.:	SHD3253B	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI I40, 1.7 D CRDI (A)	Vehicle Reg. Date:	08/07/2016
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	D4FDGU655919	Chassis No:	KMHLB41UMGU091869
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	5,567.36
Miscellaneous Items	10.00
Labour	2,130.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	7,707.36
+ GST 7.00% (S\$)	539.52
Nett Amount (S\$)	8,246.88

This claim is handled by: LIM TIEN SIONG

Generated using *Merimen e-Claims Internet Estimation & Adjusting System*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Mar 2019)
 Parts: 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: **ComfortDelGro Engineering Pte Ltd/SHD3253B/13/03/2019 17:12**
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BOOTLID	20.00	0.00	*2,174.90 FL SVC
2	1		*BOOTLID UPR LOCK	20.00	0.00	*102.60 FL SVC
3	1		*BOOTLID LWR LOCK	20.00	0.00	*31.70 FL SVC
4	1		*BOOTLID H EMBLEM	20.00	0.00	*28.70 FL nn
5	1		*BOOTLID CRDI EMBLEM	20.00	0.00	*27.90 FL nn
6	1		*BOOTLID MOULDING	20.00	0.00	*85.00 FL SVC
7	1		*BOOTLID I40 EMBLEM	20.00	0.00	*27.90 FL nn
8	1		*BOOTLID LAMP RH	20.00	0.00	*565.60 FL SVC
9	1		*BOOTLID LOWER GARNISH	20.00	0.00	*85.00 FL SVC
10	1		*REAR BUMPER	20.00	0.00	*553.00 FL OE
11	10		*REAR BUMPER CLIPS	20.00	0.00	*22.00 FL nec
12	1		*REAR BUMPER REFLECTOR RH	20.00	0.00	*30.60 FL cut
13	1		*TAILLAMP RH	20.00	0.00	*697.80 FL cra
14	1		*REAR FENDER RH	20.00	0.00	*2,171.40 FL Buc
15	1		*REAR FENDER SHIELD RH	20.00	0.00	*169.30 FL SVC
16	1		*REAR WINDSCREEN MOULDING	20.00	0.00	*28.30 FL nec
17	1		*BOOTLID COMFORTDELGRO STICKER	0.00	0.00	*20.00 F nn
18	1		*BOOTLID 65221111 STICKER	0.00	0.00	*10.00 F nn
19	1		*REAR BUMPER MAT	0.00	0.00	*50.00 F nec
20	2		*REAR WINDSCREEN SEALANT	0.00	0.00	*46.00 F nec

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	6,927.70
- List Item Discount on L Items (S\$)	1,360.34
Total Parts (S\$)	5,567.36

ComfortDelGro Engineering Pte Ltd/SHD3253B/13/03/2019 17:12. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	800.00 600
2	SPRAY PAINTING	New	900.00 600
3	WIRING CHECK	New	30.00 20
4	TUFF KOTE	New	50.00 20
5	R/I UPHOLSTERY ETC	New	150.00 50
6	R/I REAR WINDSCREEN	New	120.00 100
7	R/I REVERSE SENSOR	New	80.00 30
Gross Labour Cost (S\$)			2,130.00

ComfortDelGro Engineering Pte Ltd/SHD3253B/13/03/2019 17:12. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SHD 3253B

MAKE :

MODEL : HYUNDAI i40

Tokio Marine
C/P/P

DATE 13/3/2019

TS

Merimen

Tyre: Campeon

LKK - Calvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>X su</i>			\$ 2,174.90
	Boot Lid Lock Upper <i>X su</i>			\$ 102.60
	Boot Lid Lock Lower <i>X su</i>			\$ 31.70
	Boot Lid 'H' Emblem <i>X su</i>			\$ 28.70
	Boot Lid CRDI Plate <i>X su</i>			\$ 27.90
	Boot Lid Lamp (RH) <i>X su</i>			\$ 565.60
	Bootlid Moulding <i>X su</i>			\$ 85.00
	Bootlid i40 Emblem <i>X su</i>			\$ 27.90
	Bootlid Lower Garnish <i>X su</i>			\$ 227.90
	Rear Bumper <i>Rehul</i>			\$ 553.00
	Rear Bumper Clip 10 pcs <i>su</i>			\$ 22.00
	Rear Bumper Reflector Lamp (RH) <i>64</i>			\$ 30.60
	Tail Lamp (RH) <i>ca</i>			\$ 697.80
	Rear Fender (RH) <i>Bunkul</i>			\$ 2,171.40
	Rear Fender Inner Lining (RH) <i>X su</i>			\$ 169.30
	Rear Windscreen Moulding <i>su</i>			\$ 28.30
	SUB TOTAL			\$ 6,944.60
	LESS 20%			\$ 1,388.92
	DISCOUNTED TOTAL			\$ 5,555.68
	Boot Lid Comfort Logo & Tel No. Sticker <i>X su</i>			\$ 30.00
	Rear Bumper Rubber Mat <i>su</i>			\$ 50.00
	Rear Windscreen Sealant <i>su</i>			\$ 46.00
				\$ 126.00
	Labour Charge			
	Panel Beating			\$ 800.00 <i>600</i>
	Spray Painting Charge			\$ 900.00 <i>600</i>
	Wiring Charge			\$ 30.00 <i>20</i>
	Tuff Kote			\$ 50.00 <i>20</i>
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 <i>50</i>
	Remove/Refix Rear Windscreen Glass			\$ 120.00 <i>100</i>
	Remove/Refix Reverse Sensor			\$ 80.00 <i>20</i>
	<i>Marina Fee</i>			\$ 60.00 <i>00</i>
	TOTAL LABOUR			\$ 2,130.00
	ESTIMATE TOTAL			\$ 7,811.68

Signature
13/3/19
Kehric Ucky

LKK Auto Consultants hereby notify the Repairer of the following:
 • To resurvey below after spray painting
 • To display damaged parts during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modifications is allowed
 • Supplementary items must be resurveyed
 is subject to final approval from insurance company
 Signatures by Repairer
 Date:

Nett
Nett
Nett

600
20
20
50
100
20

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Workshops

59 Loyang Drive Singapore 508969
 383 Bin Ming Drive Singapore 575717
 45 Pandan Road Singapore 609286

24 Senoko Loop Singapore 758156
 7 Sungei Kadut Way Singapore 728791
 501 Yishun Industrial Park A Singapore 768732

Date/Time: 13.03.2019 14:26 Page : 1

member of COMFORTDELGRO

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:


JC NO.: 305277290

MER COMFORT TRANSPORTATION PTE LTD 7010045 MER NO. 383 SIN MING DRIVE SS Singapore SINGAPORE 575717 65508755 (O) (R) (P) UNT CARD NO.	REGN NO.: SHD3253B	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL I-40	DATE/TIME IN: 12.03.2019 19:30
	YR OF MANH 08.07.2016	TARGET DATE
	CHASSIS CODE KMHLB41UMGU091869	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 12.03.2019
 NATURE: 3P 12.03.19

S/L/J LABOR CODE DESCRIPTION



KEYED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Damage Report / Incident Report / Damage Report Slip

Exit Pass

No.: **SHD3253B** **LIMITS**

Vehicle No.: **SHD3253B**

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305277290
 REGN NO : SHD3253B
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 08.07.2016
 DATE/TIME IN : 12.03.2019 19:30
 ACCIDENT DATE : 12.03.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	REAR BUMPER	1	553.00	20.00	442.40
0002	04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60
0003	04-01-0103-0852-G	REAR BUMPER REFLECTOR RH	1	30.60	20.00	24.48
0004	04-01-0103-0585-A	TAILLAMP RH	1	697.80	20.00	558.24
0005	04-01-0103-0575-G	REAR FENDER RH	1	2,171.40	20.00	1,737.12
0006	04-01-0103-0745-G	REAR WINDSCREEN MOULDING	1	28.30	20.00	22.64
0007	04-01-0103-1150-A	REAR BUMPER MAT	1	50.00		50.00
0008	05-01-0199-0032-A	WINDSCREEN AHESIVE-310MLC	2	46.00		46.00
						SUB-TOTAL : 2,898.48


JOB NATURE

0000	PB	PANEL BEATING				600.00
0001	SP	SPRAYPAINT CHARGE				600.00
0002	17-01	WIRING CHECK				20.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305277290
 REGN NO : SHD3253B
 MILEAGE : 000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 08.07.2016
 DATE/TIME IN : 12.03.2019 19:30
 ACCIDENT DATE : 12.03.2019

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0003 20-00 TUFF COAT ON AFFECTED PARTS.					20.00
0004 L R/I UPHOLSTERY ETC					50.00
0005 L R/I REAR WINDSCREEN					100.00
0006 L R/I REVERSE SENSOR					30.00
0007 L TP MERIMEN					10.00
SUB-TOTAL :					1,430.00
TOTAL :					4,328.48


 MVA NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO
 SURVEYOR NAME & SIGNATURE
 DATE :

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305277290
Date : 19/03/19

FINALIZATION FORM

To : LKK
Attn : KALVIN ANG
Vehicle Reg No. : SHD3253B

Fax : _____
Date of Accident : 12-Mar-19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE --- GBJ1731R
2. The finalized amount shall be:


(a) Spare Parts after List discount	\$2,898.48
(b) Labour Charges	\$1,430.00
Total for Part-By-Part Repair Cost	\$4,328.48
(c) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: <u>20%</u>	_____
Final Lumpsum Repair cost	_____

3. Estimated normal period for repairs: 5 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : LIM T S
Tel : 62148398
Fax : 65468156

Signature : 
Name : KALVIN
Date : 20/3/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	-----			
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI19004665/K1SD3N2

Date: 20/03/2019

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MS000815
Claimant	SHD3253B	Insured Vehicle No :	GBJ1731R
Vehicle No :		Nature of Claim:	TP
Date of Loss:	12/03/2019	Claim No:	M1901606

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD3253B	Engine No:	D4FDGU655919
Make & Model:	HYUNDAI I40, 1.7 D CRDi (A)	Chassis No:	KMHLB41UMGU091869
Reg. Date:	08/07/2016 (Man. Year: 2016)	Odometer:	241161 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Champeon 6 mm	Rear Left Side:	Champeon 6 mm
Front Right Side:	Champeon 6 mm	Rear Right Side:	Champeon 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,567.36	2,898.48	2,668.88	47.94
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	2,130.00	1,420.00	710.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,707.36	4,328.48	3,378.88	43.84
+ GST 7.00/7.00% (S\$)	539.52	302.99	236.53	43.84
Nett Amount (S\$)	8,246.88	4,631.47	3,615.41	43.84

INSPECTION

Date of Assignment:	13/03/2019	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	13/03/2019	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	5.0 days		

Adjuster: KALVIN ANG WEI KUN

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 20 Mar 2019)
Parts: 143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHD3253B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Serviceable	2,174.90 FL	*- FL
2	1		*BOOTLID UPR LOCK	Serviceable	102.60 FL	*- FL
3	1		*BOOTLID LWR LOCK	Serviceable	31.70 FL	*- FL
4	1		*BOOTLID H EMBLEM	Not Necessary	28.70 FL	*- FL
5	1		*BOOTLID CRDI EMBLEM	Not Necessary	27.90 FL	*- FL
6	1		*BOOTLID MOULDING	Serviceable	85.00 FL	*- FL
7	1		*BOOTLID I40 EMBLEM	Not Necessary	27.90 FL	*- FL
8	1		*BOOTLID LAMP RH	Serviceable	565.60 FL	*- FL
9	1		*BOOTLID LOWER GARNISH	Serviceable	85.00 FL	*- FL
10	1		*REAR BUMPER	Deformed	553.00 FL	*553.00 FL
11	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
12	1		*REAR BUMPER REFLECTOR RH	Cut	30.60 FL	*30.60 FL
13	1		*TAILLAMP RH	Cracked	697.80 FL	*697.80 FL
14	1		*REAR FENDER RH	Buckled	2,171.40 FL	*2,171.40 FL
15	1		*REAR FENDER SHIELD RH	Serviceable	169.30 FL	*- FL
16	1		*REAR WINDSCREEN MOULDING	Necessary	28.30 FL	*28.30 FL
17	1		*BOOTLID COMFORTDELGRO STICKER	Not Necessary	20.00 F	*- FS
18	1		*BOOTLID 65221111 STICKER	Not Necessary	10.00 F	*- FS
19	1		*REAR BUMPER MAT	Necessary	50.00 F	*50.00 FS
20	2		*REAR WINDSCREEN SEALANT	Necessary	46.00 F	*46.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,927.70	3,599.10
- List Item Discount on L Items 20.00/20.00% (S\$)	1,360.34	700.62
Total Parts (S\$)	5,567.36	2,898.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	10.00	10.00
Sub Total (S\$)			10.00	10.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	600.00
2	SPRAY PAINTING	New	900.00	600.00
3	WIRING CHECK	New	30.00	20.00
4	TUFF KOTE	New	50.00	20.00
5	R/I UPHOLSTERY ETC	New	150.00	50.00
6	R/I REAR WINDSCREEN	New	120.00	100.00
7	R/I REVERSE SENSOR	New	80.00	30.00
Gross Labour Cost (S\$)			2,130.00	1,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >