



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19004673/Gsd3e2

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 17-07-2020



Code : FCI2

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 9646K	Veh. Inspected	SLM 5355H
Policy No.		Coverage (\$)	0.00
Claim No.	D19001731MFSH	Excess (\$)	0.00
Assign From	KAREN TAN	Assign Date	12/03/2019

#### 2. Vehicle Particulars & Condition

Make & Model	MAZDA 6	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6GL1071H0111517	Colour	GREY
Odometer	77249	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R17	BRIDGESTONE	6 mm
L/H Front Tyre	225/55 R17	BRIDGESTONE	6 mm
R/H Rear Tyre	225/55 R17	BRIDGESTONE	6 mm
L/H Rear Tyre	225/55 R17	BRIDGESTONE	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.

DAMAGES SEE DETAILS.

#### 5. General Information

Accident Date	09/03/2019	Inspection Date	15/03/2019
Survey held at	BEST SOLUTION AUTOCARE PTE LTD 53 UBI AVE 1 #03-01 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

#### 5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.  
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**