



EUROKARS HABITAT PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN.: MOTOR CLAIM DEPT FAX: 68804838 / 68804739		NAME: Ms X Chen ADDRESS: 15 Farrer Drive #05-03 Singapore 259296 TEL: 85712218	WIP: 26518 EXCESS: DATE: 13.03.2019
		VEH NO: SKW9186L CHASSIS NO: WMWXS520002C85659 MODEL: F55	DATE IN: MILEAGE: DATE REG.: 20.11.2015

NATURE OF WORKS

<u>Parts Description</u>				REVISED	PRICES
S/NO	QTY	PARTS	PRICE		
1	1	M51.14.2.755.617	\$ 70.85		
2	1	M51.12.7.380.024	\$ 914.42		
3	1	M51.12.7.403.266	\$ 57.79		
4	1	M51.12.7.403.267	\$ 57.79		
5	1	M51.12.7.380.030	\$ 299.59		
6	4	M07.14.7.411.141	\$ 15.08		
TOTAL PARTS					\$ 1,415.52
					\$ -
TOTAL PARTS COST					\$ 1,415.52
<u>Labour Description</u>					
1	TO REPLACE REAR BUMPER & TO REPAIR TAILGATE AREAS AFFECTED BY THE ACCIDENT.			1900 840	\$ 1,900.00
2	TO RESPRAY REAR BUMPER & TAILGATE.			800	\$ 1,800.00
3	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			150	\$ 250.00
4	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			250	\$ 350.00
5	SUNDRIES.			NETT	\$ 50 100.00
TOTAL LABOUR				\$ -	\$ 4,400.00
TOTAL PARTS				\$ -	\$ 1,415.52
TOTAL				\$ -	\$ 5,815.52
LESS EXCESS				\$ -	\$ -
TOTAL AFTER EXCESS				\$ -	\$ -
GST 7%				\$ -	\$ -
GRAND TOTAL				\$ -	\$ -

REMARKS:
 THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE

BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Paul
44 90010068
3 days
18/03/19 @ 1320

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: