

TP Claims against NTUC Income: Follow-Through Survey

Date : 19/07/2019

s/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate
1	MT/1027613-003	SMRT TAXIS PTE LTD	SHD 6202D	SLK 6202U	12/01/2019	20:50	\$ 21,795.34
2	MT/1029866-003	SMRT TAXIS PTE LTD	SHF 92H	SLC 5120X	27/01/2019	12:30	\$ 12,647.64
3	MT/1035233-002	SMRT TAXIS PTE LTD	SHB 246C	SMC 8115E	09/03/2019	0:50	\$ 8,608.74

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.

Date of Accident

Vehicle No.(For Motor)

Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5102493742		JEN WEI ZUN	S8817780J	GPC	drivo CLASSIC	SMC8115E	SMC8115E	24/07/2018	23/07/2019

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/03/2019 10:37
Date Of Accident	09/03/2019 00:50
Exact Location Of Accident	JUNCTION OF CLIVE STREET AND DUNLOP STREET
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB246C
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	ISMAHARDI BIN MOHAMED SAMUTI
NRIC No	S8011948H
Date Of Birth	28/04/1980
Occupation	OUTDOOR
Date Of Driving Pass	09/06/2000
Driving Experience	18 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG CLIVE STREET TOWARDS KAMPONG KAPOR. SUDDENLY A VEHICLE SMC8115E CAME OUT FROM DUNLOP STREET ON MY RIGHT WITHOUT STOPPING AT THE STOP LINE AND COLLIDED ONTO THE RIGHT PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMC8115E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	JEN WEI ZUN
NRIC/Passport Number	S8817780J
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

CLIVE ST

DUNLOP ST

STOP

A

B

A - SHB 246C

B - SMC 8115E


[Signature]

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. On the left side, there is a vertical margin line, creating a narrow left margin. The paper appears to be from a notebook or a standard ruled sheet of paper. There is no handwriting or other markings on the page.

I/We declare the foregoing particulars are true in every respect.



Driver's Signature 1051
(If driver is not the policyholder)
Date & Time:

 09.03.19

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

9/3/2019

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time: 

Driver's Signature  09.03.19
(If driver is not the policyholder)
Date & Time: 1051 HRS

Reporting Centre Personnel's Signature
Name: 
NRIC/FIN No.:



Case Details

Case Reference Number :

TAX/03/19/2036

Type of Repair : Accident

Repair

Vehicle Registration Number :

SHB246C

Company Type : SMRT Taxis
Pte Ltd

Estimation ID : EST-6033-ID

Assigned By : Taxi Claims
Manager Team

Insurance Company Name : NTUC Income Insurance
Co-operative Ltd

Accident Date and Time : 08/03/2019 04:52 PM

Vehicle Age(In Months) : 65

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Appro		
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)		Surveyor Quantity	Surveyor Final Price(\$)	Repair/
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.5	Repli See
One Time Key In	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	1	57.30	Repli See
One Time Key In	Main			FENDER FRT/RH	1	723.40	723.40	25.00	542.55	Replace	1	542.5	Repli See
One Time Key In	Main			FENDER APRON FRT/RH	1	168.10	168.10	25.00	126.07	Replace	0	0	Not C X See
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Repli See

Total Spare Part Cost 4,488.76

Surveyor Total 2,039.71

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 3,591.01

Final Sur Total 1,631.71

SMRT Recommendation

Surveyor Appro

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/
One Time Key In	Main			FENDER LINER FRT/RH	1	171.70	171.70	25.00	128.77 <i>128.78</i>	Replace	1	128.7	Repli
One Time Key In	Main			WHEEL DISC. FRONT	1	1,484.20	1,484.20	25.00	1,113.15	Replace	1	0	Repa
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not C
One Time Key In	Main			WHEEL HUB FRT	1	549.70	549.70	25.00	412.28	Replace	0	0	Chec
One Time Key In	Main			HEAD LAMP RH	1	945.20	945.20	10.00	850.68	Replace	1	850.6	Repli
One Time Key In	Main			DOOR FRT/RH	1	894.40	894.40	25.00	670.80	Replace	1	0	Repa
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Repli
Total Spare Part Cost									4,488.76		Surveyor Total	2,039.71	
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)	20	
Final Spare Part Cost									3,591.01		Final Sur Total	1,631.71	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH FRONT PORTION	845.00	500	
Total:			845.00	500.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			1,116.00	450.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200.00 ✓	
2	Main	TO RESPRAY FRONT FENDER RH	378.00	200.00 ✓	
3	Main	TO RESPRAY FRONT WHEEL HOUSE RH	180.00	0 X ^{an}	
4	Main	TO RESPRAY RIM	180.00	50 ✓	
Total:			1,116.00	450.00	


Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	56.00	56.00 X ^{an}	receipt?
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30 ✓	
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60 ✓	
4	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	30 ✓	
5	Main	TO WASH AND VACUUM	60.00	0 X ^{an}	
6	Main	TO REPLACE SUNDRY PARTS	100.00	0 X ^{an}	
Total:			536.00	176.00	

Summary



8608.74

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	3,591.01	1,631.78
Total Labour Cost	845.00	500.00
Total Spray Painting	1,116.00	450.00
Other	536.00	176.00

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Overall Total	6,088.01	2,757.78
Lump Sum Repair Option		<input checked="" type="checkbox"/>
Lump Sum Total	0.00	2,750.00
Surveyor Approved Amount		2,750.00
No of Repair Days*	6	5
Remarks	-	RESURVEY AFTER REPAIR / LUMP SUM
Surveyor Name		Rasul
Signature		 15/3/19
Survey Date	11/03/2019	<input type="button" value="Save"/> <input type="button" value="Clear"/>



Section A - Accident Details

Registration Number	SHB246C
Case Reference Number	TAX/03/19/2036
Registration Date	30/10/2013
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	ISMAHARDI BIN MOHAMED SAMUTI
Type of Accident	Head To Side
Accident Date and Time	9/3/2019 12:52 AM
Accident Reported Date and Time	9/3/2019 10:46 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	9/3/2019 1:45 AM
Replacement Vehicle issued?	No
Job Card Number	24100515
Special Instruction to ARC, if any	TOWED \$40/ TP
Prepared Date and Time	11/3/2019 1:11 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Signature

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$500.00
Total Spray Cost	\$1,494.00	\$650.00
Total Spare Part Cost	\$4,488.76	\$2,039.74
Total Other Cost	\$536.00	(\$539.74)
TOTAL COST	\$7,363.76	\$2,650.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	5.0
Prepared / Adjusted By	Kim Ming Chin	RASUL (LKK) / NTUC
ARC / Surveyor Sign Off Date	11/03/2019 5:26 PM	11/03/2019 5:15 PM
Signature		
Remarks		RESURVEY AFTER REPAIR / LUMP SUM

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1907-0275	Invoice Number	
Quotation Date	17.07.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH FRONT PORTION	\$845.00	\$500.00 ✓
Total Labour	\$845.00	\$500.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00 ✓
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00 ✓
TO RESPRAY FRONT WHEEL HOUSE RH	\$160.00	\$0.00
TO RESPRAY RIM	\$180.00	\$50.00 ✓
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00 (S) ✓
Total Spray Painting & Panel Beating	\$1,494.00	\$650.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$0.00 X
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00 ✓
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00 ✓
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$30.00 ✓
TO WASH AND VACUUM	\$60.00	\$0.00 X
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00 X
Lump Sum Adjustment by Surveyor	\$0.00	(\$659.74)
Total Other Costs	\$536.00	(\$539.74)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace ✓
		52115-47040	BUMPER SUPPORT F/RH	1.00	\$76.40	25.00	\$57.30	Replace	Replace ✓
		53801-47050	FENDER FRT/RH	1.00	\$723.40	25.00	\$542.55	Replace	Replace ✓
		53710-12030	FENDER APRON FRT/RH	0.00	\$168.10	0.00	\$0.00	Replace	Not Given X
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace ✓
		53875-47030	FENDER LINER FRT/RH	1.00	\$171.70	25.00	\$128.78	Replace	Replace ✓
		42611-47140(Frt)	WHEEL DISC. FRONT	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair ✓
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given X
		43550-47011	WHEEL HUB FRT	0.00	\$549.70	0.00	\$0.00	Replace	Check X
		81130-47500	HEAD LAMP RH	1.00	\$945.20	10.00	\$850.68	Replace	Replace ✓

		67001-47070	DOOR FRT/RH	1.00	\$894.40	100.00	\$0.00	Replace	Repair <input checked="" type="checkbox"/>
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace <input checked="" type="checkbox"/>
Total					\$5,733.74		\$2,039.74		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

$$\begin{array}{r}
 2039.74 \\
 + \quad 500.00 \\
 + \quad 770.00 \\
 \hline
 3309.74
 \end{array}$$

$$\begin{array}{r}
 - 202 \\
 \hline
 \end{array}$$

$$\begin{array}{r}
 2647.79
 \end{array}$$

$$\begin{array}{r}
 415 \pm 2650/-
 \end{array}$$

$$2608.74$$



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19004692/R1qd3e2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 25-07-2019	
Code: INC4				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMC 8115E	Veh. Inspected	SHB 246C	
Policy No.	5102493742	Coverage (\$)	0.00	
Claim No.	MT/1035233-002	Excess (\$)	0.00	
Assign From		Assign Date	11/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS 1.8A	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	JTDKN36U605692841	Colour	MAROON	
Odometer	458911	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	FALKEN	5 mm	
L/H Front Tyre	195/65 R15	FALKEN	5 mm	
R/H Rear Tyre	195/65 R15	FALKEN	5 mm	
L/H Rear Tyre	195/65 R15	FALKEN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/03/2019	Inspection Date	11/03/2019	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 246C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BUMPER FRT (DISC 25%)	SCRATCHED	482.00	361.50
1	BUMPER SUPPORT F/RH (DISC 25%)	NECESSARY	76.40	57.30
1	FENDER FRT/RH (DISC 25%)	BENT	723.40	542.55
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.93
1	FENDER LINER FRT/RH (DISC 25%)	CUT	171.70	128.78
1	HEAD LAMP RH (DISC 10%)	SCRATCHED	945.20	850.68
1	STICKER DECAL SMRT (DOOR) (SN)	NECESSARY	60.00	60.00
1	FENDER APRON FRT/RH	SERVICEABLE	168.10	-
1	TYRE	SERVICEABLE	126.74	-
1	WHEEL HUB FRT	SERVICEABLE	549.70	-
1	WHEEL DISC. FRONT	TO REPAIR SEE LABOUR	1,484.20	-
1	DOOR FRT/RH	TO REPAIR SEE LABOUR	894.40	-
			5,733.74	2,039.74
<u>LABOUR</u>				
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF WHEEL DISC. FRONT AND DOOR FRT/RH.		845.00	500.00
	SPRAY PAINT.		1,494.00	650.00
	TOWING CHARGE.		56.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	30.00
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.		120.00	60.00
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)		120.00	30.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
			2,875.00	1,270.00
GRAND TOTAL			8,608.74	3,309.74
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				2,650.00

Report Ref No. NS/INC19004692/R1qd3e2

Report Ref No. NS/INC19004692/R1qd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor



K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.