

REF: NS/INC19004693 / R14302

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No: _____

Claims No: _____

Sum Insured _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res: Yes or No

Lump Sum: _____

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

SHB 7744

Yr Equip: _____

2014 / REC

Type: M/Car / M/Cycle / Bus / Van / Lorry / ☒ Prime Mover /

Truck / Trailer or _____

Make: _____

TOYOTA PRIUS 1.8 A

1798

Colour: _____

MAROON

A/C: _____

Insured / Std / Nil / NA

Sp. Reading: _____

461951

T/Radio: _____

Insured / Std / Nil / NA

Eng/No: _____

Ch/No: _____

JTPKN 364805753218

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ Order / Jammed / Leaked / Burnt orBrake: ☒ Order / Jammed / Leaked / Burnt orMod: Nil / ☒ STD A/Rim or

Tyre Size: _____

F: _____

R: _____

198/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

WESTLAKE

Front

Rear

R/Bal: _____

S

mm

R/Bal: _____

S

mm

L/Bal: _____

S

mm

L/Bal: _____

S

mm

D.O.A: _____

08/03/19

D.O.L: _____

11/03/19

Survey held at _____

SMRT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

SHB 7744 - CC3/AIG19002895 / 5f03
 SJL 37505 - Q6/Ax410021616 / Uylf2k2

DOA: 11/2/19 03/19/2034

PUA: 28/10/2010

NTNC

Lump Sum \$2000 Cred: 6584.80, 75%)

SJL 37505

RECEIVED 01 AUG 2019

Enter time, File Pass to?

1/2 Typist

Date/Time, File Return to?



Pref. Report



Final Report

Days Of Repair: 4

Resurvey No. of Trip: -

Add Fee: _____



Site Insp: \$



Interview: \$



Tech. Insp: \$



Weekend: \$

Report Format: _____

Lump Sum / LCU: \$

TP

2100

Survey Fee: _____

Transportation: _____

Fuel: _____

Phone: _____

Other: _____

Total: _____

160

160

Denise Tay (LKKAUTO)

From: MTCL@income.com.sg
Sent: Thursday, 1 August 2019 12:26 PM
To: Denise Tay (LKKAUTO)
Subject: FW: REQUEST CLAIM NUMBER

Hi,

All claims created.

With Regards

Samsia
Senior Admin Assistant,
Motor Insurance
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

in with you

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Thursday, 1 August 2019 11:43 AM
To: MTCL@income.com.sg; mtreg <mtreg@income.com.sg>
Subject: REQUEST CLAIM NUMBER

Dear Sir/Madam,

Request claim number

Date : 1/8/2019

S/No		Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1	MT/1035311-002	SMRT	SHB 774U	SJL 3750S	8/3/2019	23:45	8,684.80	2100
2	MT/1053235-002	SMRT	SHC 4247T	SKB 2998S	11/7/2019	18:10	9,963.14	2750
3	MT/1052883-002	SMRT	SHC 4391J	AY 4532L	10/7/2019	20:05	11,892.10	1900

Denise Tay (LKKAUTO)

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) <YeoPohsuan@smrt.com.sg>
Sent: Tuesday, 30 July 2019 10:10 AM
To: Rasul (LKKAUTO)
Cc: Leong Chee Kwong; Denise Tay (LKKAUTO)
Subject: RE: SHB774U

Hi,

Amount confirmed as per your recommendation, thanks.

Regards
Poh Suan

-----Original Message-----

From: Rasul (LKKAUTO) [mailto:Rasul@lkkauto.com]
Sent: Tuesday, 30 July 2019 9:26 AM
To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)
Cc: Leong Chee Kwong; Denise Tay (LKKAUTO)
Subject: RE: SHB774U

Hi Poh Suan,

Finalised amount confirmed

Best Regards,
Rasul | Assessor
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) Save the Earth. Print only when necessary.

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Monday, 29 July, 2019 4:39 PM
To: Rasul (LKKAUTO)
Cc: SUR; CS A Team; Leong Chee Kwong
Subject: SHB774U

Hi Rasul,

Attached herewith the repair estimate of SHB 774U having Case No: TAX/03/19/2034.

There is no change to the approved amount of \$2,100 @ 4 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Aside Kwong,

Please provide the before / after paint photos as per surveyor's request.

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.

Date of Accident

Vehicle No.(For Motor)

Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5105795878		ORION CARZ PTE LTD	201806193M	GFT	Third Party, Fire & Theft	SJL3750S	SJL3750S	22/11/2018	



Case Details

Case Reference Number :

TAX/03/19/2034

Type of Repair : Accident

Repair

Vehicle Registration Number :

SHB774U

Company Type : SMRT Taxis

Pte Ltd

Estimation ID : EST-6028-ID

Assigned By : Taxi Claims

Manager Team

Insurance Company Name : NTUC Income Insurance

Co-operative Ltd

Accident Date and Time : 08/03/2019 03:45 PM

Vehicle Age(In Months) : 51

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor	
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.5
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08
One Time Key In	Main			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	0	0
One Time Key In	Main			BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	0	0
One Time Key In	Main			ARM SUB-ASSY, FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	0	0

Total Spare Part Cost 6,198.99

Surveyor Total

Lump Sum Discount (%) 20.00

Lump Sum Dis (%)

Final Spare Part Cost 4,959.19

Final Sur Total

SMRT Recommendation

Surveyor

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)
One Time Key In	Main			BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	0	0
One Time Key In	Main			BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	311.10	25.00	233.33	Replace	0	0
One Time Key In	Main			FOG LAMP LH	1	280.10	280.10	10.00	252.09	Replace	0	0
One Time Key In	Main			BRACKET, FR TURN CENTER LH	1	58.20	58.20	25.00	43.65	Replace	0	0
One Time Key In	Main			BRACKET, FR TURN LOWER LH	1	26.00	26.00	25.00	19.50	Replace	0	0
One Time Key In	Main			BRACKET, FR TURN UPPER LH	1	24.40	24.40	25.00	18.30	Replace	0	0
One Time Key In	Main			LENS & BODY, FR TURN LH	1	511.80	511.80	10.00	460.62	Replace	0	0
One Time Key In	Main			BUMPER FRT ABSORBER LOWER	1	127.70	127.70	25.00	95.78	Replace	0	0
One Time Key In	Main			WIRE, ENGINE ROOM, NO.3	1	242.00	242.00	10.00	217.80	Replace	0	0
One Time Key In	Main			SUPPORT SUB-ASSY	1	1,460.40	1,460.40	25.00	1,095.30	Replace	0	0
One Time Key In	Main			HEAD LAMP LH	1	945.20	945.20	10.00	850.68	Replace	1	850.6
One Time Key In	Main			FENDER FRT/LH	1	723.40	723.40	25.00	542.55	Replace	1	0
Total Spare Part Cost									6,198.99	Surveyor Total		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		
Final Spare Part Cost									4,959.19	Final Sur Total		

SMRT Recommendation

Surveyor

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92
One Time Key In	Main			FENDER LINER FRT/LH	1	171.70	171.70	25.00	128.77	Replace	0	0
One Time Key In	Main			FENDER LINER PAD, FR WHEEL LH	1	49.30	49.30	25.00	36.97	Replace	0	0
One Time Key In	Main			WHEEL DISC. FRONT	1	1,484.20	1,484.20	25.00	1,113.15	Replace	0	0
Total Spare Part Cost									6,198.99		Surveyor Total	
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)	
Final Spare Part Cost									4,959.19		Final Sur Total	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT LH PORTION	845.00	300	
Total:			845.00	300.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO SPRAY FRONT BUMPER LOWER SUB GRILLE	180.00	0	
3	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	0	
4	Main	TO RESPRAY FRONT FENDER LH	378.00	200	
Total:			1,296.00	400.00	



S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
5	Main	TO RESPRAY RIM	180.00	0	
Total:			1,296.00	400.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30	
2	Main	TO REMOVE AND REFIT WIRE HARDESS	200.00	0	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	
4	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
5	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0	
6	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	148.44	148.44	
7	Main	TO REPLACE SUNDRY PARTS	100.00	0	
8	Main	TO WASH AND VACUUM	60.00	0	
Total:			928.44	198.44	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	4,959.19	1,010.54
Total Labour Cost	845.00	300.00
Total Spray Painting	1,296.00	400.00
Other	928.44	198.44
Overall Total	8,028.63	1,908.98

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Lump Sum Repair Option	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	8,050.00	1,900.00
Surveyor Approved Amount		1,900.00
No of Repair Days*	6	4
Remarks	-	resurvey after repair / lump sum
Surveyor Name		Rasul
Signature		
Survey Date	11/03/2019	
	<div>Save Clear</div>	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/03/2019 09:18
Date Of Accident	08/03/2019 23:45
Exact Location Of Accident	SIMS AVE AFTER LOR 25 GEYLANG
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB774U
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	SULAIMAN BIN AWANG
NRIC No	S1648535G
Date Of Birth	11/12/1964
Occupation	OUTDOOR
Date Of Driving Pass	16/11/1999
Driving Experience	19 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	NO COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING STRAIGHT ALONG SIMS AVE TOWARDS BEDOK, SUDDENLY A VEHICLE SJL3750S WHICH WAS TRAVELLING ON MY LEFT LANE HAD CUT INTO MY LANE AND COLLIDED ONTO THE LEFT FRONT PORTION OF MY TAXI.

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJL3750S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: 9/3/2019

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 9/3/2019

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

PehSuan

Section A - Accident Details

Registration Number	SHB774U
Case Reference Number	TAX/03/19/2034
Registration Date	2/12/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	SULAIMAN BIN AWANG
Type of Accident	Side Swipe
Accident Date and Time	8/3/2019 11:45 PM
Accident Reported Date and Time	9/3/2019 9:26 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24100511
Special Instruction to ARC, if any	BP
Prepared Date and Time	11/3/2019 10:26 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$300.00
Total Spray Cost	\$1,296.00	\$400.00
Total Spare Part Cost	\$6,659.61	\$1,723.81
Total Other Cost	\$928.44	(\$323.81)
TOTAL COST	\$9,729.05	\$2,100.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Tuck Foo Kok	RASUL (LKK) / NTUC
ARC / Surveyor Sign Off Date	11/03/2019 5:22 PM	11/03/2019 5:09 PM
Signature	<i>[Signature]</i>	<i>Rasul</i>
Remarks		resurvey after repair / lump sum

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1907-0478	Invoice Number	
Quotation Date	27.07.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$845.00	\$300.00
Total Labour	\$845.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO SPRAY FRONT BUMPER LOWER SUB GRILLE	\$180.00	\$0.00 <i>x n n</i>
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00 <i>x n n</i>
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$0.00 <i>x n n</i>
Total Spray Painting & Panel Beating	\$1,296.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00 <i>x n n</i>
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00 <i>x n n</i>
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00 <i>x n n</i>
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$148.44	\$148.44
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00 <i>x n n</i>
TO WASH AND VACUUM	\$60.00	\$0.00 <i>x n n</i>
Lump Sum Adjustment by Surveyor	\$0.00	(\$522.25)
Total Other Costs	\$928.44	(\$323.81)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace <i>de</i>
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace <i>de</i>
		52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Check <i>X</i>
		52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Check <i>X</i>
		57014-47030	ARM SUB-ASSY, FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Check <i>X</i>
		52116-47040	BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	\$0.00	Replace	Check <i>X</i>
		53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	0.00	\$311.10	0.00	\$0.00	Replace	Check <i>X</i>
		81220-12230	FOG LAMP LH	0.00	\$280.10	0.00	\$0.00	Replace	Check <i>X</i>

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number: 63865592
Estimator Telephone Number: 68662623
Accident Reporting Number: 68662672

Date Generated: 29/07/2019

User ID: PohSuan

81529-47060	BRACKET, FR TURN CENTER LH	0.00	\$58.20	0.00	\$0.00	Replace	Check	X
81529-47050	BRACKET, FR TURN LOWER LH	0.00	\$26.00	0.00	\$0.00	Replace	Check	X
81529-47040	BRACKET, FR TURN UPPER LH	0.00	\$24.40	0.00	\$0.00	Replace	Check	X
81521-47050	LENS & BODY, FR TURN LH	0.00	\$511.80	0.00	\$0.00	Replace	Check	X
52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Check	X
82113-47180	WIRE, ENGINE ROOM, NO.3	0.00	\$242.00	0.00	\$0.00	Replace	Not Given	X
53201-47902	SUPPORT SUB-ASSY	0.00	\$1,460.40	0.00	\$0.00	Replace	Not Given	X
81170-47500	HEAD LAMP LH	1.00	\$945.20	10.00	\$850.68	Replace	Replace	X
53802-47050	FENDER FRT/LH	1.00	\$723.40	100.00	\$0.00	Replace	Repair	X
75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	X
53876-47030	FENDER LINER FRT/LH	0.00	\$171.70	0.00	\$0.00	Replace	Not Given	X
53852-47020	FENDER LINER PAD, FR WHEEL LH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given	X
42611-47140 (Frt)	WHEEL DISC. FRONT	0.00	\$1,484.20	0.00	\$0.00	Replace	Not Given	X
Total			\$7,855.01		\$1,263.19			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		81521-47050	LENS & BODY, FR TURN LH	1.00	\$511.80	10.00	\$460.62	Replace	Replace
Total					\$11.80		460.62		

1723.81
+ 300.00
+ 598.44

2622.25
- 20%

2097.80

L/S \$2100/-

11650.44




National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19004693/R1td3e2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 20-08-2019	
Code: INC4				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJL 3750S	Veh. Inspected	SHB 774U	
Policy No.	5105795878	Coverage (\$)	0.00	
Claim No.	MT/1035311-002	Excess (\$)	0.00	
Assign From		Assign Date	11/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS 1.8 A	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JTDKN36U805753218	Colour	MAROON	
Odometer	461951	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WEST LAKE	5 mm	
L/H Front Tyre	195/65 R15	WEST LAKE	5 mm	
R/H Rear Tyre	195/65 R15	WEST LAKE	5 mm	
L/H Rear Tyre	195/65 R15	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/03/2019	Inspection Date	11/03/2019	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 774U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BUMPER FRT (DISC 25%)	DEFORMED	482.00	361.50
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.93
1	HEAD LAMP LH (DISC 10%)	SCRATCHED	945.20	850.68
1	BUMPER ENERGY ABSORBER FRT	SERVICEABLE	78.80	-
1	BUMPER REINFORCEMENT FRT	SERVICEABLE	498.40	-
1	ARM SUB-ASSY, FR BUMPER LH	SERVICEABLE	250.40	-
1	BUMPER SUPPORT F/LH	SERVICEABLE	76.40	-
1	BUMPER GRILLE SUB-ASSY, LOWER	SERVICEABLE	311.10	-
1	FOG LAMP LH	SERVICEABLE	280.10	-
1	BRACKET, FR TURN CENTER LH	SERVICEABLE	58.20	-
1	BRACKET, FR TURN LOWER LH	SERVICEABLE	26.00	-
1	BRACKET, FR TURN UPPER LH	SERVICEABLE	24.40	-
1	LENS & BODY, FR TURN LH	SERVICEABLE	511.80	-
1	BUMPER FRT ABSORBER LOWER	SERVICEABLE	127.70	-
1	WIRE, ENGINE ROOM, NO.3	SERVICEABLE	242.00	-
1	SUPPORT SUB-ASSY	SERVICEABLE	1,460.40	-
1	FENDER LINER FRT / LH	SERVICEABLE	171.70	-
1	FENDER LINER PAD, FR WHEEL. LH	SERVICEABLE	49.30	-
1	WHEEL DISC. FRONT	SERVICEABLE	1,484.20	-
1	FENDER FRT / LH	TO REPAIR SEE LABOUR	723.40	-
1	LENS & BODY, FR TURN LH (DISC 10%)	SCRATCHED	511.80	460.62
			8,381.30	1,723.81
<u>LABOUR</u>				
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF FENDER FRT / LH.		845.00	300.00
	SRRAY PAINT.		1,296.00	400.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	30.00
	TO REMOVE AND REFIT WIRE HARDESS.	NOT NECESSARY	200.00	-

Report Ref No. NS/INC19004693/R1td3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	20.00
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	NOT NECESSARY	120.00	-
	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER.		148.44	148.44
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			3,069.44	898.44
GRAND TOTAL			11,450.74	2,622.25

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			2,100.00
-----------------------------------------------------------------------------------------	--	--	-----------------

Report Ref No. NS/INC19004693/R1td3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.