




Section A - Accident Details

Registration Number	SHB5288Z
Case Reference Number	TAX/03/19/2040
Registration Date	5/3/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	YAM AH YENG
Type of Accident	Side Swipe
Accident Date and Time	9/3/2019 10:30 AM
Accident Reported Date and Time	9/3/2019 12:07 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24100517
Special Instruction to ARC, if any	TP
Prepared Date and Time	11/3/2019 4:42 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$300.00
Total Spray Cost	\$936.00	\$400.00
Total Spare Part Cost	\$2,410.88	\$790.80
Total Other Cost	\$696.88	\$9.20
TOTAL COST	\$4,719.76	\$1,500.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	4.0
Prepared / Adjusted By	Kim Ming Chin	RASUL (LKK) / NTUC
ARC / Surveyor Sign Off Date	11/03/2019 5:35 PM	11/03/2019 5:25 PM
Signature		
Remarks		RESURVEY AFTER REPAIR / LUMP SUM

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1904-0383	Invoice Number	
Quotation Date	27.04.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$676.00	\$300.00
Total Labour	\$676.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00
TO RESPRAY REAR DOOR RH	\$378.00	\$200.00
TO RESPRAY CENTER PILLAR RH	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$936.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$296.88	\$296.88
TO TRANSFER DOOR MECHANISM	\$240.00	\$60.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$347.68)
Total Other Costs	\$696.88	\$9.20

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		67001-47070	DOOR FRT/RH	1.00	\$894.40	25.00	\$670.80	Replace	Replace
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace
		69030-47070	DOOR LOCK FRT/RH	0.00	\$575.80	0.00	\$0.00	Replace	Not Given
		67003-47080	DOOR RR/RH	1.00	\$954.50	100.00	\$0.00	Replace	Repair
		68730-12120	DOOR HINGE UPPER RR/RH	0.00	\$81.70	0.00	\$0.00	Replace	Not Given
		68740-12120	DOOR HINGE LOWER RR/RH	0.00	\$90.10	0.00	\$0.00	Replace	Not Given
		68630-47031	CHECK ASSY, RR DOOR,	0.00	\$150.30	0.00	\$0.00	Replace	Not Given
			PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace
		61311-47030	PILLAR, CTR BODY	0.00	\$307.70	0.00	\$0.00	Replace	Not Given
Total					\$3,174.50		\$790.80		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

790.80
 + 300.00
 + 756.88
 1847.68
 - 208
 1478.14
 415 \$1500/-