

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 21 Mar 2019

Preliminary Advice

Insured Vehicle No : PC4536P
TP Vehicle No : SLK5094X
Make : TOYOTA PRIUS
Date of Inspection : 14/03/2019
Inspection At : Euro Success Services Pte Ltd (HQ)
1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY
Singapore 417883

Accident Date : 12/03/2019
Assignment Date : 15/03/2019
Est. Duration of Repair : 3 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 9,232.54 |
| Revised Amount | :S\$ | 4,072.66 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 4,072.66 |

Lump Sum Repair :S\$

Total Loss Consideration

| | |
|--------------------|------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.