

**Hitachi Capital Asia Pacific Pte
Ltd**
8 Fourth Lok Yang Road
629705

Claim Reference:
Assessment number: SLC1899J
Version: 1810
Date calculated: 04/18/2019 10:21 AM

Full Report
Registration: SLC1899J
Printed: 18/04/2019 10:30 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	Vonnlm Siow	Currency:	SGD
Claim Reference:		Date of Incident:	2019-03-09
Estimated Repair Time:	10	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	HONDA
Model:	VEZEL/HR-V RU1/5
Sub Model:	BASE MODEL
Model Sheet Number:	35 VE 01
Registration:	SLC1899J
VIN number:	
Odometer:	

**Hitachi Capital Asia Pacific Pte
Ltd**
8 Fourth Lok Yang Road
629705

Claim Reference:
Assessment number: SLC1899J
Version: 1810
Date calculated: 04/18/2019 10:21 AM

Full Report
Registration: SLC1899J
Printed: 18/04/2019 10:30 AM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
8411D4	R + R GLOVE BOX CPL		2.0	10.00
710100	R + R BATTERY		3.0	15.00
NN	EDLC MODULE SET R&R / NEW PARTS		5.0*	25.00
NN	HARNESS WIRE LH R&R / NEW PARTS		160.0*	800.00
1004	R+R DASHBOARD R+R DASHBOARD			800.00*
1005	IN-CAR CLEANING IN-CAR CLEANING			600.00*
1006	R+R SEAT R+R SEAT			300.00*
1007	CLAENING FLOORMAT FLOORMAT/CARPET			250.00*
1003	R+R BBC UNIT R+R BBC UNIT			500.00*
1008	VEH CHK &RDTEST VEH CHK &RDTEST		15.0*	75.00

**Hitachi Capital Asia Pacific Pte
Ltd**
8 Fourth Lok Yang Road
629705

Claim Reference:
Assessment number: SLC1899J
Version: 1810
Date calculated: 04/18/2019 10:21 AM

Full Report
Registration: SLC1899J
Printed: 18/04/2019 10:30 AM

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	18.50	185.0	925.00
Fixed Rate			2450.00
Total of Labour			3,375.00

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD
4355	GLOVEBOX CPL	77500T8NT01ZA			160.00
9629	BATTERY	31500TS4T21			0.00
1000	BBC UNIT	BBC UNIT			680.00
1001	A/C FILTER	A/C FILTER			20.00
1009	EDLC MODULE SET	EDLC MODULE SET			700.00
1010	HARNESS WIRE LH	HARNESS WIRE LH			600.00
f: OEM Parts	Savings				0.00
n: Non-OEM Parts	Subtotal				2,160.00
u: Used parts	Addition(+10.00%)				216.00
	Total				2,376.00

Extras

Code	Description	Price SGD
1002	BATTERY BATTERY	130.00*
1011	TOWING TOWING	150.00*
	Total Extras	280.00

**Hitachi Capital Asia Pacific Pte
Ltd
8 Fourth Lok Yang Road
629705**

Claim Reference:
Assessment number: SLC1899J
Version: 1810
Date calculated: 04/18/2019 10:21 AM

Full Report
Registration: SLC1899J
Printed: 18/04/2019 10:30 AM

Final Calculation

	SGD	SGD
Parts	2,160.00	
Addition(+10.00%)	216.00	
Total Parts		2,376.00
Labour Time Base 10 WU/h		
Total 185.0 WU X 50.00 SGD/h	925.00	
Fixed Rate	2,450.00	
Total of Labour		3,375.00
Total Of Extras		280.00
Repair Cost Excludes GST		6,031.00
GST (+7.0%)		422.17
Repair Cost Included GST		6,453.17

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS