

**Hitachi Capital Asia Pacific Pte
Ltd**
8 Fourth Lok Yang Road
629705

Claim Reference:
Assessment number: SLC1899J
Version: 1810
Date calculated: 29/04/2019 3:09 PM

Full Report
Registration: SLC1899J
Printed: 29/04/2019 3:09 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	Vonnlm Siow	Currency:	SGD
Claim Reference:		Date of Incident:	09/03/19
Estimated Repair Time:	10	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	HONDA
Model:	VEZEL/HR-V RU1/5
Sub Model:	BASE MODEL
Model Sheet Number:	35 VE 01
Registration:	SLC1899J
VIN number:	
Odometer:	

Hitachi Capital Asia Pacific Pte Ltd

8 Fourth Lok Yang Road

629705

Claim Reference:
Assessment number: SLC1899J
Version: 1810
Date calculated: 29/04/2019 3:09 PM

Full Report
Registration: SLC1899J
Printed: 29/04/2019 3:09 PM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
8411D4	R + R GLOVE BOX CPL		2.0	10.00
710100	R + R BATTERY		3.0	15.00
NN	EDLC MODULE SET R&R / NEW PARTS		5.0*	25.00
NN	HARNESS WIRE LH R&R / NEW PARTS		80.0*	400.00
1004	R+R DASHBOARD R+R DASHBOARD			400.00*
1005	IN-CAR CLEANING IN-CAR CLEANING			300.00*
1008	VEH CHK &RDTEST VEH CHK &RDTEST		5.0*	25.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		9.50	95.0	475.00
Fixed Rate				700.00
Total of Labour				1,175.00

Spare Parts

prices as at 2015-06-01/01

Hitachi Capital Asia Pacific Pte Ltd

8 Fourth Lok Yang Road

629705

Claim Reference:
 Assessment number: SLC1899J
 Version: 1810
 Date calculated: 29/04/2019 3:09 PM

Full Report
 Registration: SLC1899J
 Printed: 29/04/2019 3:09 PM

Code	Description	Part Number	Supplier	Price SGD
4355	GLOVEBOX CPL	77500T8NT01ZA		160.00
9629	BATTERY	31500TS4T21		0.00
1000	BBC UNIT	BBC UNIT		480.00
1009	EDLC MODULE SET	EDLC MODULE SET		700.00
1010	HARNESS WIRE LH	HARNESS WIRE LH		600.00
f: OEM Parts				Savings 0.00
n: Non-OEM Parts				Subtotal 1,940.00
u: Used parts				Addition(+10.00%) 194.00
Total				2,134.00

Extras

Code	Description	Price SGD
1001	A/C FILTER A/C FILTER	20.00*
1002	BATTERY BATTERY	130.00*
1011	TOWING TOWING	150.00*
Total Extras		300.00

Final Calculation

	SGD	SGD
Parts	1,940.00	
Addition(+10.00%)	194.00	
Total Parts		2,134.00
Labour Time Base 10 WU/h		
Total 95.0 WU X 50.00 SGD/h	475.00	
Fixed Rate	700.00	
Total of Labour		1,175.00
Total Of Extras		300.00
Repair Cost Excludes GST		3,609.00
GST (+7.0%)		252.63
Repair Cost Included GST		3,861.63

**Hitachi Capital Asia Pacific Pte
Ltd
8 Fourth Lok Yang Road
629705**

Claim Reference:

Assessment number: SLC1899J

Version: 1810

Date calculated: 29/04/2019 3:09 PM

Full Report

Registration: SLC1899J

Printed: 29/04/2019 3:09 PM

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS