

**Hitachi Capital Asia Pacific Pte
Ltd**
8 Fourth Lok Yang Road
629705

Claim Reference:
Assessment number: SLC1899J
Version: 1810
Date calculated: 03/13/2019 11:26 AM

Full Report
Registration: SLC1899J
Printed: 13/03/2019 11:26 AM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
8571G3	R + R LEFT LOWER A-PILLAR TRIM		1.0	5.00
8571G4	R + R RIGHT LOWER A-PILLAR TRIM		1.0	5.00
8571B9	R + R LEFT LOWER B-PILLAR TRIM		2.0	10.00
8571C0	R + R RIGHT LOWER B-PILLAR TRIM		2.0	10.00
847100)	R + R FRONT FLOOR CARPET		2.0	10.00
8511E1	R + R L/F SEAT		2.0	10.00
8521D0	R + R R/F SEAT		4.0	20.00
NO NUMBER	R + R COMPLETE REAR SEAT CUSHION		4.0	20.00
NO NUMBER	R + R ENGINE TUNNEL CONSOLE		1.0	5.00
710100	R + R BATTERY		6.0	30.00
1004	R+R DASHBOARD R+R DASHBOARD		3.0	15.00
1005	IN-CAR CLEANING IN-CAR CLEANING			800.00*
1006	R+R SEAT R+R SEAT			600.00*
1007	FLOORMAT/CARPET FLOORMAT/CARPET			300.00*
1003	R+R BBC UNIT R+R BBC UNIT			250.00*
1008	VEH CHK & RDTEST VEH CHK & RDTEST			500.00*
			15.0*	75.00

Hitachi Capital Asia Pacific Pte Ltd
8 Fourth Lok Yang Road
629705

Claim Reference:
 Assessment number: SLC1899J
 Version: 1810
 Date calculated: 03/13/2019 11:26 AM

Full Report
 Registration: SLC1899J
 Printed: 13/03/2019 11:26 AM

Code	Description	WU	Price SGD
	Labour Cost	Hrs	WU
	Panel / Mechanical Labour	4.10	41.0
	Fixed Rate		205.00
			2450.00
	Total of Labour		2,655.00

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD
4873	FRONT FLOOR CARPET	83301T8NT22ZA	X		0.00
9629	BATTERY	31500TS4T21	?		0.00
1000	BBC UNIT	BBC UNIT	/ Unit		680.00
1001	A/C FILTER	A/C FILTER	?		20.00
f: OEM Parts	Savings				0.00
n: Non-OEM Parts	Subtotal				700.00
u: Used parts	Addition(+10.00%)				70.00
	Total				770.00

Extras

Code	Description	Price SGD
1002	BATTERY BATTERY ?	130.00*
	Total Extras	130.00

Steve (LKK) 00- Revert 15/3/19 11:00am
 8322 8813 EXCESS - \$1500

Resurvey before dismantle parts

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

**Hitachi Capital Asia Pacific Pte
Ltd
8 Fourth Lok Yang Road
629705**

Claim Reference:
Assessment number: SLC1899J
Version: 1810
Date calculated: 03/13/2019 11:26 AM

Full Report
Registration: SLC1899J
Printed: 13/03/2019 11:26 AM

Final Calculation

	SGD	SGD
Parts	700.00	
Addition(+10.00%)	70.00	
Total Parts		770.00
Labour Time Base 10 WU/h	205.00	
Total 41.0 WU X 50.00 SGD/h	2,450.00	
Fixed Rate		2,655.00
Total of Labour		130.00
Total Of Extras		3,555.00
Repair Cost Excludes GST		248.85
GST (+7.0%)		3,803.85
Repair Cost Included GST		

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS