

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 21 Mar 2019

## **Preliminary Advice**

Insured Vehicle No : GBC8596E

TP Vehicle No : YN769X

Make : MITSUBISHI FE83BEOSRDEA

Date of Inspection : 15/03/2019

Inspection At : Liu's Brother Auto Engineering Workshop (HQ)  
BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT  
Singapore 417883

Accident Date : 23/02/2019

Assignment Date : 14/03/2019

Est. Duration of Repair : 4 days

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,720.60
Revised Amount	:S\$	7,558.42
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,558.42
Lump Sum Repair	:S\$	6,000.00

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : TP : WP