

ASS. REC. BY:

REF: CS/AWA 19004715/Ktd302 Special Instruction:

Surveyor

Kenneth

ASSIGNMENT (Office)

From (Person):

Stella Goh

of

AWAC

Date/Time:

15/3/19 @ 11:32am.

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YP 677IM

Insured:

at Workshop m/s

cheng hwe motor

Tel:

6755 6142

of

Blk 1019 Yishun Ind. Park e1 # 01374/382

Policy No:

BYFCSB0013291900

Claim No:

NSV1900114/5G

Sum Insured:

Excess:

\$1,000.00

Make of Veh:

D.O.A.

28/2/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:38pm @ 15/3/19

Person Contacted:

sharon

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

Pls take photographs of the front windscreen area from inside to ascertain whether the insured vehicle is equipped with a car camera.

YP 677IM - CS3/AWA 19004105 / Jcd3

D.O.A - 28/2/2019

B6B-

Revert via email.

ASS. REC. BY:

REF: AWA/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to

18/3@

5:19pm - authorize by Stella

18/3@

5:30pm - inform Sharon authorize repair excess \$1000/- P/P

Finalize part by part \$12,631.76, 8days (Red. 2474.80, 16%)

RECEIVED 07 JUN 2019

Date/Time, File Pass to?

11/16 Typist

Date/Time, File Return to?



: Prell. Report



: Final Report

Days Of Repair: 8

Resurvey No. of Trlp: 1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.I: (\$ 12,631.76)

250
250

Nivitha (LKK Auto)

From: Goh, Stella <stella.goh@awac.com> on behalf of Motorsurvey
<Motorsurvey@awac.com>
Sent: Friday, 15 March 2019 11:32 AM
To: assignments@lkkauto.com
Cc: sur@lkkauto.com
Subject: OD survey assignment for YP 6771M - DOA : 28/02/2019

Our Ref:

The above captioned accident refers. Please conduct an "OWN DAMAGE" survey on the following:

Insured Vehicle	:	YP 6771 M		
Policy Number	:	BVFCSB0013291900	Account Code:	0668385
Policy Excess	:	\$ 1,000		
Sum Insured	:	Market Value with COE & PARF		
Make / Model	:	HINO XZU710R-HKFMS3		
Name of Workshop	:	Cheng Hoe Motor Pte Ltd		
Contact Number	:	6755 6142		
Person to Contact	:	Ms Sharon		
Estimated Cost of repairs	:	\$ 16,164.02		
(x)	Please take photographs of the front windscreen area from inside to ascertain whether the insured vehicle is equipped with a car camera. (Compulsory)			
(X)	Please revert with your preliminary survey report with photographs			
Remarks				

Regards,

Claims Division

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail (and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments hereto are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allied World Assurance Company Holdings, GmbH or its subsidiaries or affiliates, either jointly or severally, for any loss or damage arising in any way from its use.

Denise Tay (LKKAUTO)

From: Goh, Stella <stella.goh@awac.com> on behalf of Motorsurvey <Motorsurvey@awac.com>
Sent: Monday, 18 March 2019 5:19 PM
To: Denise Tay (LKKAUTO); Admin-D (LKKAUTO); Motorsurvey; assignments
Cc: SUR
Subject: RE: OD survey assignment for YP 6771M - DOA : 28/02/2019 Our Ref: NSV1900114/SG

Dear Denise.

We refer to your email dated 16.03.2019.

Please authorize repair at \$ 9,026.16 and \$ 5,650.40 check items to be confirmed.

Thank you.

Regards
Stella Goh
Claims Analyst
Claims Group
Global Markets

Allied World Assurance Company, Ltd
60 Anson Road #08-01 Mapletree Anson Singapore 079914
T: +65 6423 0857
F: +65 6423 0864
E: stella.goh@awac.com
W: www.awac.com

From: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Sent: Saturday, 16 March 2019 10:12 AM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>; Motorsurvey <Motorsurvey@awac.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: OD survey assignment for YP 6771M - DOA : 28/02/2019 Our Ref: NSV1900114/SG

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **YP 6771M**.

We did not authorise repair.

Repair on part by part.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Saturday, 16 March 2019 10:12 AM
To: Admin-D (LKKAUTO); 'Motorsurvey'; assignments
Cc: SUR
Subject: RE: OD survey assignment for YP 6771M - DOA : 28/02/2019 Our
Ref: NSV1900114/SG
Attachments: PRELI ADVISED YP 6771M.pdf; YP 6771M photo.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **YP 6771M**.

We did not authorise repair.

Repair on part by part.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 15 March 2019 12:40 PM
To: 'Motorsurvey' <Motorsurvey@awac.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: OD survey assignment for YP 6771M - DOA : 28/02/2019 Our Ref: NSV1900114/SG

Dear Sir/Mdm,

Thank you for the assignment.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Goh, Stella [<mailto:stella.goh@awac.com>] **On Behalf Of** Motorsurvey
Sent: Friday, 15 March 2019 11:32 AM
To: assignments@lkkauto.com

Denise Tay (LKKAUTO)

From: Goh, Stella <stella.goh@awac.com> on behalf of Motorsurvey <Motorsurvey@awac.com>
Sent: Thursday, 6 June 2019 4:16 PM
To: Denise Tay (LKKAUTO); Motorsurvey; Admin-D (LKKAUTO); assignments
Cc: SUR; Goh, Stella
Subject: RE: OD survey assignment for YP 6771M - DOA : 28/02/2019 Our Ref: NSV1900114/SG

Dear Denise,

We refer to your email dated 03.06.2019.

Please authorize repair at \$ 12,631.76 inclusive of check items.

Thank you.

Regards
Stella Goh
Claims Analyst
Claims Group
Global Markets

Allied World Assurance Company, Ltd
60 Anson Road #08-01 Mapletree Anson Singapore 079914
T: +65 6423 0857
F: +65 6423 0864
E: stella.goh@awac.com
W: www.awac.com

From: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Sent: Monday, 3 June 2019 5:01 PM
To: Motorsurvey <Motorsurvey@awac.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: OD survey assignment for YP 6771M - DOA : 28/02/2019 Our Ref: NSV1900114/SG

Dear Sir/Madam,

Enclosed preliminary revised of YP 6771M

Please kindly let us have your approval for the final figure \$12,631.76 inclusive of confirm check item.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DECLARATION

I/We declare the foregoing particulars are true in every respect.

23 MAY 2019

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: NSV1900114/SG

Our Ref: CS/AWA19004715/Ktd3

Date: 15/3/2019

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir,

PRELIMINARY ADVICE OF VEHICLE NO YP 6771M


We thank you for the instruction on 15/3/2019

Please be informed that we had conducted the inspection of the abovementioned vehicle 15/3/2019 at the premises of m/s: Cheng Hoe and have the following to report:-

Workshop Estimate Amount	:	S\$	<u>15,106.50</u>
Revised Estimate Amount	:	S\$	<u>9,026.16</u>
"Check" Items Amount	:	S\$	<u>5,650.40</u>
Market Value	:	S\$	<u>63,000.00</u>
LTA Reimbursement Value	:	S\$	<u>30,678.00</u>
Nett Value	:	S\$	<u>32,322.00</u>

Description of Damage:

The vehicle sustained damages due to
Front o/s portion



Comments/ Present Status:

Damage consistent
Repair Cost economical
Days of repair: 8

Yours faithfully

Kenneth

Automotive Assessor

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	3700E
Vehicle Details	
Vehicle No.:	YP6771M
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Mar 2019
Vehicle Make:	HINO
Vehicle Model:	HINO XZU710R-HKFMS3
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	N04CUS32598
Chassis No.:	JHHUCS3H20K021116
Maximum Power Output:	-
Open Market Value:	\$38,672.00
Original Registration Date:	10 Jul 2017
First Registration Date:	10 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$1,934.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	09 Jul 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$36,879.00
COE Rebate Amount:	\$30,678.00
Total Rebate Amount:	\$30,678.00

The information contained herein is correct as at 14 Mar 2019

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	3700E
Vehicle Details	
Vehicle No.:	YP6771M
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Mar 2019
Vehicle Make:	HINO
Vehicle Model:	HINO XZU710R-HKFMS3
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	N04CUS32598
Chassis No.:	JHHUCS3H20K021116
Maximum Power Output:	-
Open Market Value:	\$38,672.00
Original Registration Date:	10 Jul 2017
First Registration Date:	10 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$1,934.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	09 Jul 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$36,879.00
COE Rebate Amount:	\$30,678.00
Total Rebate Amount:	\$30,678.00

The information contained herein is correct as at 14 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/03/2019 19:29
Date Of Accident	28/02/2019 11:20
Exact Location Of Accident	ALONG WOODLANDS AVE 12
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP6771M
Insured/Policyholder	
Name Of Registered Owner	LEE SAY POULTRY INDUSTRIAL
Co Reg No	44883700E
Email Address	LEESAY@LEESAY.COM
Mobile Phone No	
Alternative Phone No	OFFICE-83993886

Vehicle Particulars

Manufacturer	HINO
Model	XZU710R-HKFMS3
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	ALLIED WORLD ASSURANCE COMPANY, LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	BVFC0013291900
Cover Note Number	N.A

Driver

Name of Driver	YANG MING
Passport No/FIN	G2683067U
Date Of Birth	22/12/1992
Occupation	OUTDOOR
Date Of Driving Pass	15/01/2016
Driving Experience	3 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-82394801
Fax Number	
Contact Number	
Email Address	LEESAY@LEESAY.COM



Address	NA
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was travelling along WOODLANDS AVE 12, when approaching at traffic junction, the front car make a sudden stopped, I couldn't stop in time & my vehicle YP6771M hit onto rear of car SJT5258S. No injuries involved. That's all.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJT5258S
Vehicle Make/Model/Colour	HYUNDAI AVANTE 1.6 AT ABS D/AB 2WD 4DR / WHITE
Details Of Properties	NIL
Vehicle Category	PRIVATE CAR
Name of Driver	CHOO LIAK HUNG
NRIC/Passport Number	S0204021B
Contact Number	93493830
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Sketch Plan

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

6. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARS
REPORTING OFFICER
MOHD FADZLY BIN ISMAIL

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I was travelling along WOODLANDS AVE 12, when approaching at traffic junction, the front car make a sudden stopped, I couldn't stop in time & my vehicle YP6771M hit onto rear of car SJT5258S. No injuries involved. That's all.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHD FADZLY BIN ISMAIL

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

1 March 2019 at 3:55 PM

Date/Time:

1 March 2019 at 3:55 PM



WORK PERMIT
Employment of Foreign Manpower Act (Chapter 91A)
Republic of Singapore

Employer
LEE SAY POULTRY INDUSTRIAL



Name
YANG MING

Work Permit No.
O 7677568D

Sector
MANUFACTURING

YPENIM
8229484
E.1



K0402368

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **G2683067U**
Name: **YANG MING**

Birth Date: **22 Dec 1992**
Issue Date: **09 Nov 2015**
Valid Till **08/11/2020**

002491674E

SG 50

VISIT PASS
Immigration Regulations

21-05-2018

Name
YANG MING

FIN
G2683067U

Date of Birth Sex
22-12-1992 M

Nationality
CHINESE

MULTIPLE JOURNEY VISA ISSUED

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED
OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.

Download SGWorkPass
App to check status



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 MOTOR CARS AND MOTOR TRACTORS THE WEIGHT OF
WHICH UNLADEN DOES NOT EXCEED 2500 KILOGRAMS

15 Jan 2016 5

G2683067U

S / No. 9000231049

NP 428A



Licence No: G2683067U

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

YP6771M
 OD/AWAC

M/S: ALLIED WORLD ASSURANCE COMPANY LTD
 60 Anson Road
 ES1991270/YISHUN
 09-01 Mapletree Anson
 Singapore 079914

Estimate No: ES1991270

Date: 14 Mar 2019
 Policy No: BVFC0013291900
 Veh Reg No: YP6771M
 Make/Model: HINO XZU710R-
 Chassis No: JHHUCS3H20K021116
 Engine No: N04CUS32598
 Reg. Date: 10/07/2017

ATTN: Motor Claim Department
 WS Ref: OD/AWAC/YS
 Claim Type: Own Damage
 Accident Date: 28/02/2019

Estimate Repair Cost to Vehicle No : YP6771M

PAGE:1/2

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 FRONT BUMPER	967.20	1 PC	967.20	✓
2 FRONT BUMPER BRACKETS	285.70	2 PCS	571.40	✓
3 FRONT BUMPER CENTRE INNER BEAM	104.80	1 SET	104.80	✓
4 FRONT BUMPER FOG LAMPS	291.90	2 PCS	583.80	✓
5 FRONT BUMPER FOG LAMP HOUSINGS	90.10	2 PCS	180.20	✓
6 FRONT GRILLE	654.60	1 PC	654.60	✓
7 FRONT PANEL	598.70	1 PC	598.70	✓
8 FRONT PANEL STICKER - HINO	71.90	1 PC	71.90	✓
9 FRONT PANEL STICKER - 300	35.00	1 PC	35.00	✓
10 FRONT WINDSCREEN GLASS	1,598.00	1 PC	1,598.00	✓
11 FRONT WINDSCREEN GLASS LOWER MOULDING	169.80	1 PC	169.80	✓
12 FRONT CORNAL GARNISHS	449.90	2 PCS	899.80	✓
13 HEADLAMPS	1,014.60	2 PCS	2,029.20	✓
14 FRONT WIPER LINKAGE	332.40	1 PC	332.40	✓
15 FRONT WIPER MOTOR	654.10	1 PC	654.10	✓
16 FRONT INNER PANEL	979.70	1 PC	979.70	✓
17 FRONT INNER PANEL CENTRE AIR SCROP GRILLE	99.10	1 PC	99.10	✓
18 FRONT DOOR STICKER - 616	34.90	2 PCS	69.80	✓
19 FRT STEP GARNISHS	373.10	2 PCS	746.20	✓
20 AIR-CON CONDENSER evaporator	1,804.10	1 PC	1,804.10	✓
21 AIR-CON BLOWER	599.10	1 PC	599.10	✓
22 AIR-CON HEATER PIPES	108.50	2 PCS	217.00	✓
23 AIR-CON GAS DISCHARGE	396.90	1 PC	396.90	✓
24 AIR-CON GAS RECEIVER	470.40	1 PC	470.40	✓
			14,833.20	
			Less 10% +10%	
			2,966.64	
			11,866.56	

Special Net

25 FRONT DOOR STICKERS - EURO 5	45.00	2 PCS	90.00	✓
26 FRONT NUMBER PLATE	35.00	1 PC	35.00	✓
27 FRONT WINDSCREEN GLASS GUM	40.00	1 ROLL	40.00	✓
28 ERP BRACKET	25.00	1 PC	25.00	✓
			190.00	190.00

Labour

29 REMOVE AND REFIX FRONT WINDSCREEN GLASS	100.00	1 LA	100.00	✓
30 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
31 REMOVE & REFIX DASHBOARD,METER ASSY & CHECK WIRING	250.00	1 LA	250.00	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S: ALLIED WORLD ASSURANCE COMPANY LTD
 60 Anson Road
ES1991270/YISHUN
 09-01 Mapletree Anson
 Singapore 079914

Estimate No: **ES1991270**

Date: 14 Mar 2019
 Policy No: BVFC0013291900
 Veh Reg No: **YP6771M**
 Make/Model: HINO XZU710R-
 Chassis No: JHHUCS3H20K021116
 Engine No: N04CUS32598
 Reg. Date: 10/07/2017

ATTN: Motor Claim Department
 WS Ref: OD/AWAC/YS
 Claim Type: Own Damage
 Accident Date: 28/02/2019

Estimate Repair Cost to Vehicle No :YP6771M

PAGE:2/2

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
32 PANEL BEATING	1,400.00	1 LA	1,400.00	1100
33 REMOVE & REFIX BRAKE OIL PIPE,AIR PIPE & CHECK SYSTEM	100.00	1 LA	100.00	80
34 PUTTY & RESPRAY ON FRT BOTH DOORS,FRT PANEL,INNER PANEL,FRT CORNAL PANEL,FRT	1,100.00	1 LA	1,100.00	1000
			3,050.00	3,050.00
			Total	S\$ 15,106.56
			Add GST @ 7%	1,057.46
			Total Amount Payable	S\$ 16,164.02

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Parts \$12,302.20
 Less 20% 2460.44
 \$9841.76
 \$160 SN
 \$2630
 \$12,631.76

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

YP6771M
 OD/AWAC

M/S: ALLIED WORLD ASSURANCE COMPANY LTD

60 Anson Road

ES1991270/YISHUN

09-01 Mapletree Anson

Singapore 079914

Estimate No: ES1991270

Date: 14 Mar 2019

Policy No: BVFC0013291900

Veh Reg No: YP6771M

Make/Model: HINO XZU710R-

Chassis No: JHHUCS3H20K021116

Engine No: N04CUS32598

Reg. Date: 10/07/2017

ATTN: Motor Claim Department

WS Ref: OD/AWAC/YS

Claim Type: Own Damage

Accident Date: 28/02/2019

Not witherw
 Repair B4 paint
 Ex 81000/-
 8 days

Estimate Repair Cost to Vehicle No :YP6771M

PAGE:1/2

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 FRONT BUMPER	967.20	1 PC	967.20	✓
2 FRONT BUMPER BRACKETS	285.70	2 PCS	571.40	✓
3 FRONT BUMPER CENTRE INNER BEAM	104.80	1 SET	104.80	✓
4 FRONT BUMPER FOG LAMPS	291.90	2 PCS	583.80	✓
5 FRONT BUMPER FOG LAMP HOUSINGS	90.10	2 PCS	180.20	✓
6 FRONT GRILLE	654.60	1 PC	654.60	✓
7 FRONT PANEL	598.70	1 PC	598.70	✓
8 FRONT PANEL STICKER - HINO	71.90	1 PC	71.90	✓
9 FRONT PANEL STICKER - 300	35.00	1 PC	35.00	✓
10 FRONT WINDSCREEN GLASS	1,598.00	1 PC	1,598.00	✓
11 FRONT WINDSCREEN GLASS LOWER MOULDING	169.80	1 PC	169.80	✓
12 FRONT CORNAL GARNISHS	449.90	2 PCS	899.80	✓
13 HEADLAMPS	1,014.60	2 PCS	2,029.20	✓
14 FRONT WIPER LINKAGE	332.40	1 PC	332.40	✓
15 FRONT WIPER MOTOR	654.10	1 PC	654.10	✓
16 FRONT INNER PANEL	979.70	1 PC	979.70	✓
17 FRONT INNER PANEL CENTRE AIR SCROP GRILLE	99.10	1 PC	99.10	✓
18 FRONT DOOR STICKER - 616	34.90	2 PCS	69.80	✓
19 FRT STEP GARNISHS	373.10	2 PCS	746.20	✓
20 AIR-CON CONDENSER	1,804.10	1 PC	1,804.10	✓
21 AIR-CON BLOWER	599.10	1 PC	599.10	✓
22 AIR-CON HEATER PIPES	108.50	2 PCS	217.00	✓
23 AIR-CON GAS DISCHARGE	396.90	1 PC	396.90	✓
24 AIR-CON GAS RECEIVER	470.40	1 PC	470.40	✓
			14,833.20	
	Less 10% +10%		2,966.64	
			11,866.56	
Special Net				
25 FRONT DOOR STICKERS - EURO 5	45.00	2 PCS	90.00	✓
26 FRONT NUMBER PLATE	35.00	1 PC	35.00	25.00
27 FRONT WINDSCREEN GLASS GUM	40.00	1 ROLL	40.00	✓
28 ERP BRACKET	25.00	1 PC	25.00	✓
			190.00	190.00
Labour				
29 REMOVE AND REFIX FRONT WINDSCREEN GLASS	100.00	1 LA	100.00	✓
30 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
31 REMOVE & REFIX DASHBOARD,METER ASSY & CHECK WIRING	250.00	1 LA	250.00	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : ALLIED WORLD ASSURANCE COMPANY LTD
60 Anson Road
ES1991270/YISHUN
09-01 Mapletree Anson
Singapore 079914

ATTN: Motor Claim Department
WS Ref: OD/AWAC/YS
Claim Type: Own Damage
Accident Date: 28/02/2019

Estimate No: ES1991270

Date: 14 Mar 2019
Policy No: BVFC0013291900
Veh Reg No: **YP6771M**
Make/Model: HINO XZU710R-
Chassis No: JHHUCS3H20K021116
Engine No: N04CUS32598
Reg. Date: 10/07/2017

Estimate Repair Cost to Vehicle No :YP6771M

PAGE:2/2

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
32 PANEL BEATING	1,400.00	1 LA	1,400.00	1100
33 REMOVE & REFIX BRAKE OIL PIPE,AIR PIPE & CHECK SYSTEM	100.00	1 LA	100.00	80
34 PUTTY & RESPRAY ON FRT BOTH DOORS,FRT PANEL,INNER PANEL,FRT CORNAL PANEL,FRT	1,100.00	1 LA	1,100.00	1000
			3,050.00	3,050.00
			Total	S\$ 15,106.56
			Add GST @ 7%	1,057.46
			Total Amount Payable	S\$ 16,164.02

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIED WORLD ASSURANCE COMPANY LTD		Ref : CS/AWA19004715/Ktd3e2		
(SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914		Date : 27-06-2019		
		Code : AWA		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected	YP 6771M	
Policy No.	BVFCB0013291900	Coverage (\$)	0.00	
Claim No.	NSV1900114/SG	Excess (\$)	1,000.00	
Assign From	STELLA GOH	Assign Date	15/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	HINO XZU710R	c.c	4009	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JHHUCS3H20K021116	Colour	WHITE	
Odometer	79186	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	700 R16X10	OHTSU	8 mm	
L/H Front Tyre	700 R16X10	OHTSU	8 mm	
R/H Rear Tyre	700 R16X10 (D)	BRIDGESTONE	2/2 mm	
L/H Rear Tyre	700 R16X10 (D)	BRIDGESTONE	2/2 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/02/2019	Inspection Date	15/03/2019	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A) THE MARKET VALUE IS S\$63,000.00 (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 6771M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	BENT	967.20	967.20
2	FRONT BUMPER BRACKETS @\$285.70	BENT	571.40	571.40
1	SET FRONT BUMPER CENTRE INNER BEAM	BENT	104.80	104.80
2	FRONT BUMPER FOG LAMPS @\$291.90	SERVICEABLE	583.80	-
2	FRONT BUMPER FOG LAMP HOUSINGS @\$90.10	SERVICEABLE	180.20	-
1	FRONT GRILLE	CRACKED	654.60	654.60
1	FRONT PANEL	BENT	598.70	598.70
1	FRONT PANEL STICKER - HINO	NECESSARY	71.90	71.90
1	FRONT PANEL STICKER - 300	NECESSARY	35.00	35.00
1	FRONT WINDSCREEN GLASS	CRACKED	1,598.00	1,598.00
1	FRONT WINDSCREEN GLASS LOWER MOULDING	NECESSARY	169.80	169.80
2	FRONT CORNAL GARNISHS @\$449.90	BUCKLED / DENTED	899.80	899.80
2	HEADLAMPS @\$1014.60	MTG CRACKED	2,029.20	2,029.20
1	FRONT WIPER LINKAGE	DISTORTED	332.40	332.40
1	FRONT WIPER MOTOR	JAMMED	654.10	654.10
1	FRONT INNER PANEL	BENT	979.70	979.70
1	FRONT INNER PANEL CENTRE AIR SCROP GRILLE	SERVICEABLE	99.10	-
2	FRONT DOOR STICKER - 616 @\$34.90	NECESSARY	69.80	69.80
2	FRT STEP GARNISHS @\$373.10	SERVICEABLE	746.20	-
1	AIR-CON EVPORATOR	HOUSING CRACKED	1,804.10	1,804.10
1	AIR-CON BLOWER	CRACKED	599.10	599.10
2	AIR-CON HEATER PIPES @\$108.50	DENTED	217.00	162.60
1	AIR-CON GAS DISCHARGE	SERVICEABLE	396.90	-
1	AIR-CON GAS RECEIVER	SERVICEABLE	470.40	-
	LESS 20% DISCOUNT		-2,966.64	-2,460.44
			11,866.56	9,841.76
SPECIAL NETT ITEMS				
2	FRONT DOOR STICKERS - EURO 5 @\$45.00 (SN)	NECESSARY	90.00	80.00
1	FRONT NUMBER PLATE (SN)	BENT	35.00	15.00
1	ROLL FRONT WINDSCREEN GLASS GUM (SN)	NECESSARY	40.00	40.00
1	ERP BRACKET (SN)	NECESSARY	25.00	25.00
			190.00	160.00

Report Ref No. CS/AWA19004715/Ktd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	REMOVE AND REFIX FRONT WINDSCREEN GLASS.		100.00	100.00
	REMOVE AND REFIX AIRCON, CHECK, VACUUM & REFILL GAS.		100.00	100.00
	REMOVE AND REFIX DASHBOARD, METER ASSY & CHECK WIRING.		250.00	250.00
	PANEL BEATING.		1,400.00	1,100.00
	REMOVE AND REFIX BRAKE OIL PIPE, AIR PIPE & CHECK SYSTEM.		100.00	80.00
	PUTTY & RESPRAY ON FRT BOTH DOORS, FRT PANEL, INNER PANEL, FRT CORNAL PANEL, FRT.		1,100.00	1,000.00
			3,050.00	2,630.00
	GRAND TOTAL		15,106.56	12,631.76

RECOMMENDED COST OF REPAIRS			12,631.76
LESS EXCESS			-1,000.00
NETT LIABILITY			11,631.76

Report Ref No. CS/AWA19004715/Ktd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.