55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sq / claims@premiumauto.com.sq

Telefax

Estimate Accident Repairs Workshop Ubi Road 1 **Contact No** 6366 2323 Fax No 6841 1183

Reference PA/OD/0339/2019/GW

Date 14-Mar-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Telephone

Policy No.

Type of Claim

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name Mr. Kaji Punit Yogesh Address

130 Tanjong Rhu Road

Singapore 436918

#06-01

HP +65 8727 612 Own Damage claims 2100462232-02

Vehicle No **SLC 3699 G**

Model Code Audi A6 1.8 TFSI S Tronic

Model / Year 25/4/2016 **Engine No** CYG 009353

Chassis No WAUZZZ4G1GN076779

Mileage

Date In

Liability **Excess Cost**

Estimated By Johnny Boo / Allan Wu

Accident Date 13-Mar-19

Place of Accident National Gallery Car Park

Premium Automobiles 55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLC 3699 G

| S/n | Nature of Jobs | | Estimated Charges | Surveyor's Recommendation |
|-----|---|----------|--------------------------|------------------------------|
| 1 | To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid. | S/N | \$ 480.00 | <u> </u> |
| 2 | To remove and transfer lhs front door's multi-lock system and power window devices. Inspect for damages. | S/N | \$ 280.00 | /. |
| 3 | To dismantle front bumper, lhs front fender, lhs sill panel trim and lhs front door. To renew lhs front fender, lhs front door and lhs sill panel trim. Reorganise front crash management components reinstall all parts removed. | <i>,</i> | \$ 3,500.00 | 1500 |
| 4 | To respray lhs front fender, lhs front door and lhs sill panel trim. | | \$ 2,800.00 | 1650 |
| 5 | To renew lhs front rim and carry out wheel alignment. | S/N | \$ 280.00 | |
| 6 | To carry out diagnostic check. | 5/N . | \$192.00 | |
| | TOTAL LABOUR CHARGES | : | \$ 7,532.00 | |
| | | | | |

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLC 3699 G

| S/N | Parts Description | <u>Damaged Parts & Prices</u> S/Nett Remark |
|-----|--|--|
| | | No. |
| 1 | FRONT FENDER-LH Peril | \$ 1,269.00 |
| 2 | FRONT FENDER ATTACHMENT PARTS-LH ? | \$ 92.00 ? |
| 3 | FRONT STONE GUARD FILM-LH | \$ 110.00 |
| 4 | FRONT FENDER BRACE-LH | \$ 75.00 <i>k</i> |
| 5 | FRONT FENDER CLOSING ELEMENT-LH | \$ 48.00 7 |
| 6 | FRONT FENDER SEALING ELEMENT-LH | \$ 36.00 ? |
| 7 | FRONT FENDER SEAL -LH | \$ 18.00 - |
| 8 | FRONT WHEEL HOUSING LINER-LH | \$ 256.00 🗸 |
| 9 | FRONT WHEEL HOUISNG LINER ATTACHMENT PARTS-LH? | \$ 66.00 [?] |
| 10 | FRONT WHEEL SPOILER-LH | \$ 242.00 🚜 |
| 11 | FRONT STONE CHIP GUARD-LH ? | \$ 66.00 🛩 🗎 |
| 12 | ADHESIVE TAPE ? | \$ 50.00 |
| 13 | FRONT DOOR-LH Device | \$ 3,374.00 |
| 14 | FRONT STONE GUARD FILM-LH | \$ 110.00 |
| 15 | FRONT DOOR ATTACHMENT PARTS-LH | \$ 173.00 |
| 16 | FRONT OUTER DOOR SEA-LH | \$ 212.00 🖊 ' |
| 17 | BONDING AGENT | \$ 45.00 |
| 18 | CLEAINING SOLUTION 7 | \$ 65.00 \ |
| 19 | FRONT DOOR CATCH-LH | \$ 108.00 * |
| 20 | FRONT DOOR CATCH COVER-LH M L | \$ 16.00 |
| | SUB TOTAL SPARE PARTS : | \$ 6,431.00 |

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLC 3699 G

| | | Damaged Parts & Prices | | |
|-----|---|-----------------------------------|---------------------------------------|--------|
| S/N | Parts Description | | S/Nett | Remark |
| 21 | EDON'T CIDE MEMBER TRIM III & : | _ | | |
| 21 | FRONT SIDE MEMBER TRIM-LH | \$ | ىد 783.00 | ** |
| 22 | FRONT STONE GUARD FILE-LH | \$ | 108.00 ? | |
| 23 | FRONT FENDER BRACKET TRIM-LH | \$ | 15.00 ? | |
| 24 | 1 SET OF ATTACHMENT PARTS FOR CLIP 7 | \$ | 81.00 | |
| 25 | 1 SET OF ATTACHMENT PARTS FOR ADHESIVE TAPE ? | \$ | 15.00 ? | |
| 26 | FRONT ALUMINIUM RIM-LH | \$ | 733.00 | |
| 27 | RUBBER VALVE 4 | \$ | 13.00 Y | |
| 28 | SUNDRIES ? | \$ | 800.00 ? | |
| | TOTAL SPARE PARTS | \$ | 8,979.00 | |
| | TOTAL LABOUR CHARGES | \$ | 7,532.00 | |
| , | GRAND TOTAL | \$ | 16,511.00 | |
| | | | · · · · · · · · · · · · · · · · · · · | |

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name

Ador Li

Surveyed Date

Excess Cost

•

Authorised Date

-

Liability

tv

Remarks

Me Authorised, 05 Days.

Please Note

This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant