



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving 20 2015 VOLVO FM370 42T RAS SC VOVXXX
(XE2686Y)

Date of Loss 12 March 2019

Time of Loss 9.20

Loss Description XE2686Y (INSD) HIT REAR OF YP1186K (TP)

Comment

Workshop Details

Total Rebate Amount 31634

Nett Loss Amount \$62,366.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (OD)

Days of work
completion * 20



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# XE2686Y

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

27/02/2017



Mileage

82068

Age of Vehicle

2

CATEGORY

POLICY INFORMATION

ASSESSMENT
INFORMATIONManufacturing
Year

2015

2015

Make

VOLVO FM370 42T
RAS SC

VOLVO

Model

VOVXXX

FM370 42T RAS SC

Driver Details

CATEGORY

FNOL INFORMATION

POST SURVEY
INFORMATION

Driver Name

MUHAMMAD SAPUAN BIN
SELAMAT

Date of Birth

27 September 1986

dd/mm/



Age

32

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		
Type of Paint		
Chassis No	YV2X1E1A0FB719400	YV2X1E1A0FB719
Engine No	D11346069	D11346069
Engine Capacity		10837
Sum Insured	0	0
Market Value	0	94000

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	
Education Qualification	Other	
Driving Experience	9	
Driver License #		
License Type		
License Issue Date	1 January 2010	dd/mm/ 
License Expiration Date		dd/mm/ 
Address	BLK 807B CHOA CHU KANG AVE 1 #04-532, 682807, Singapore	
Address type	Personal Correspondence	

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Male	
Marital status	Unknown	
Identification #	S8626639C	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

15/03/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

1500

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

315/80R22.5

Rear Tyre Size

315/80R22.5(D)

Front left side

ODY KING8mm

Rear left side

ODY KING8/8mm

Front right side

ODY KING8mm

Rear right side

ODY KING8/8mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No



SERVICE REQUESTS

MESSAGES

CLAIMS

<< Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
		0	1		INSERT	Damaged	0	181	No					181	Reviewing	
		0	1		FRONT PANEL	Bent	0	1289	No					1289	Reviewing	
		0	1		COVER	Cut	0	26	No					26	Reviewing	
		0	1		FRONT PANEL	Cut	0	658	No					658	Reviewing	
		0	1		TRIM PANEL	Cracked	0	180.5	No					180.5	Reviewing	
		0	1		CAP	Deformed	0	82	No					82	Reviewing	
		0	1		CAP	Deformed	0	82	No					82	Reviewing	
		0	1		STEP	Bent	0	369.5	No					369.5	Reviewing	
		0	1		COVER PANEL	Deformed	0	93.5	No					93.5	Reviewing	
		0	1		COVER PANEL	Deformed	0	93.5	No					93.5	Reviewing	
		0	1		UNDERRUN GUARD	Serviceable	0	0	No					0	Deny	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
		0	1		CHARGE AIR COOLER	Dented	0	2026	No					2026	Reviewing	
		0	1		RADIATOR	Serviceable	0	0	No					0	Deny	
		0	1		BUMPER LH	Repair	0	0	No					0	Deny	
		0	1		BUMPER	Deformed	0	95.5	No					95.5	Reviewing	
		0	1		BUMPER RH	Deformed	0	84	No					84	Reviewing	
		0	1		RADIATOR OIL COOLER	Dented	0	1187	No					1187	Reviewing	
		0	8		COOLANT	Necessary	0	34.5	No					276	Reviewing	
		0	1		HEADLAMP	Cut	0	660.5	No					660.5	Reviewing	
		0	1		HEADLAMP PANEL	Dented	0	180.5	No					180.5	Reviewing	
		0	1		CAP LH	Serviceable	0	0	No					0	Deny	
		0	1		HEADLAMP PANEL	Damaged	0	188.5	No					188.5	Reviewing	
		0	1		CAP RH	Deformed	0	12.5	No					12.5	Reviewing	

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
------	-------	-------------------------	-----------	------------------------	------------------------	-----------------------	-----------------------	-----------------	---------	--------

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
 	0		LABOUR TO REMOVE & REPLACE CHARGE COOLER, RADIATOR, GEARBOX OIL COOLER, FRONT PANEL, RH HEADLAMP PANEL & LAMP ASSEMBLY, BUMPER GRILLE, STEPS & BRACKET, UNDER-RUN BUMPER & AFFECTED PARTS	0	4800	0	0	Reviewing		
 	0		TO RE-SPRAY ABOVE MENTIONED WITH 3 COLOURS (METALLIC 2K)	0	3000	0	0	Reviewing		
 	0		PRESSURE TEST ON GEARBOX OIL COOLER & CHARGE COOLER INCLUSIVE RE-INSTALL & RE-PROGRAMME LIGHTING ECU WITH TECH-TOOL	0	900	0	0	Reviewing		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
		0	DAYS OF REPAIR : 8 DAYS	Reviewing	0		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim
Amount

\$0.00

Adjusted Claim Amount

\$14,965.50

CATEGORY

ESTIMATE

ADJUSTED

Spare Parts

\$0.00

\$7,765.50

Labour

\$0.00

\$8,700.00

Excess

-\$1,500.00

[Submit for Review](#)



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

ESTIMATED
AMOUNTADJUSTED
AMOUNT

COMMENT

REMOVE



0

FINAL
LUMP
SUM

Reviewing

13000





SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$11,500.00
------------------------	--------	-----------------------	-------------

CATEGORY	ESTIMATE	ADJUSTED
Miscellaneous	\$0.00	\$13,000.00
Excess		-\$1,500.00

[Submit for Review](#)