

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0296/2019/KN (NK)
Date : 6-Mar-19

Vehicle NOT IN workshop. Please arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Beri Nakul
Address : 130 Tanjong Rhu Road
#05-13
Singapore 436918
Telephone : 98393009
Type of Claim : Own Damage Claims
Policy No. : 1700077975-01
Vehicle No : **SKB 9270 L** ✓
Model Code : Q7 SEDAN 2.0 TFSI QU
Model / Year : 14/11/2017
Engine No : CYR 050611
Chassis No : WAUZZZ4M0JD011389
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Mar-19
Place of Accident : ONE RAFLLES QUEY

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKB 9270 L

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER COVER <i>ok</i>	\$ 2,369.00	✓
2	FIXING PARTS FOR FRONT BUMPER <i>new</i>	\$ 421.00	+
3	COVER FOR TOW EYE ATTACHMENT <i>new</i>	\$ 36.00	+
4	AIR GUIDE - LH <i>new</i>	\$ 60.00	+
5	END CAP - LH <i>new</i>	\$ 32.00	+
6	UPPER CENTER CLOSING ELEMENT <i>3 new</i>	\$ 252.00	X
7	LOWER CENTER GRILLE	\$ 187.00	X
8	UNDERRUN BAR	\$ 735.00	+
9	CLOSING ELEMENT <i>3 new</i>	\$ 191.00	+
10	FRONT SPOILER - LH <i>could</i>	\$ 192.00	✓
11	FRONT SPOILER OUTER - LH ?	\$ 40.00	>
12	AIR GUIDE GRILLE - LH <i>ok</i>	\$ 271.00	✓
13	END CAP - LH <i>new</i>	\$ 30.00	+
14	SPRING CLIP - LH <i>new</i>	4 \$ 3.00	+
15	FRONT INNER SPOILER - LH ?	\$ 55.00	?
16	FOAM FILLER PIECE <i>3 new</i>	\$ 156.00	X
17	BUMPER CARRIER <i>3 new</i>	\$ 791.00	X
18	FRONT BUMPER CARRIER SUPPORT - LH <i>new</i>	\$ 33.00	+
19	AIR GUIDE - LH <i>3 new</i>	\$ 25.00	+
20	AI GUIDE - LOWER <i>3 new</i>	\$ 37.00	+

SUB TOTAL SPARE PARTS

: \$ 5,916.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SKB 9270 L**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	PARKING SENSOR <i>new</i>	2 \$	231.00 P
22	SEAL RING FOR PARKING SENSOR <i>new</i>	4 \$	17.00 X
23	FRONT WHEEL COVER - LH <i>3 new</i>	\$	522.00 ✓
24	FRONT WHEEL COVER - RH	\$	522.00 ✓
25	CLIP <i>new</i>	\$	37.00 ✓
26	SUNDRIES <i>?</i>	\$	500.00 <i>?</i>

TOTAL SPARE PARTS	:	\$ 7,208.00
TOTAL LABOUR CHARGES		\$ 3,872.00
GRAND TOTAL		<u>\$ 11,080.00</u>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 15/03/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Authorised Repairs, 03Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant