

ASS. REC. BY:

REF:

C8/FCS19004733/11vd3¹²

Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person):

Karen ten

of

FCS

Date/Time:

3:27pm 15/3/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLJ 4847C

Insured:

SHC 8736Y

at Workshop m/s

Prime Auto

Tel:

68610908

of

6 Benoi place

Policy No:

Claim No:

D19001834MP84

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14/3/2019

CA / REV / REP. / REV 24 HRS

1Ds

H.O.D. Endorsement:

Date/Time:

4:15pm 15/3/19

Person Contacted:

chrisry

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLJ 4847C - C8 / TMT 7007646 / H/rbn2

DUT: 7/4/17

SHC 8736Y - C83 / FCS 16003186 / Gdp3d1

DUA: 12/2/16

28/3/19

2/4

Final fig \$ 4842.48 confirmed by email (Red 1515.60, 24h)
Karen said OOA put 14/3/2019

Taufik

FC

SALE

Form No. _____ Date _____

Insured's Name _____

Vehicle No. _____

Engine No. _____

Make of Vehicle _____

Model _____

Year _____

Color _____

Registration No. _____

Insured's Name _____

Policy No. _____

Amount Insured _____

Excess _____

Policy Condition _____

Remarks: The veh had commenced its repair at the time of inspection.

Est. of Market Value _____

IDAC Accident Report _____ Consistent? Yes or No _____

GLA / PR Seca _____ Consistent? Yes or No _____

Est. Repair days _____ Res. Yes or No _____

Turn Sum _____ % 3 Val. Yes or No _____

CA / REV / REP / 24 HRS _____

Date _____ Person Contacted _____

Date / Time _____ Action / Instruction _____

Vehicle No. **SLJ 4847C** Date **20/6 Dec**

Type **Wagon / 40 Cycle / Bus / Van / Lorry / Taxi / Prime Mover /**

Truck / Trailer or _____

Make **Honda Vezel Hybrid** 1496

Color **Blue** Insured / Std / HI / NA

Registration No. **130087** License Insured / Std / HI / NA

Engine No. _____

Chassis No. **RU 3113687**

Gen. Cond. **Good** / Fair / Poor / Burnt

Steering: **Knocker** / Jammed / Leaked / Burnt or

Brake: **Knocker** / Jammed / Leaked / Burnt or

Mod. **HR / SD / STD / STD / STD** or

Tyre Size E: **215/60R16**

R: **215/60R16**

BS / DUN / EXROVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **Goodrich**

Front **6** mm Rear **6** mm

R/Ral **6** mm L/Ral **6** mm

D.O.A. **15/3/80 540m**

Survey held at **Bank Prime Auto**

Des. of Damages: Frt / Rear / D / N / U / C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 28 MAR 2019

Date/Time File Entry to: ☐ Prel. Report

File: ☐ Final Report

Days Of Repair: **5**

Resurvey No. of Trip: **1**

28/3- typist

Report Format **CWS**

Lump Sum / LUMP **P/P \$ 4842.48**

Add Fee: ☐ Site Insp. (\$)

☐ Interview (\$)

☐ Transport (\$)

☐ Workshop (\$)

Survey Fee: **149**

Transportation: **50**

Interview: **50**

Workshop: **19**

294

MOTOR SURVEY ASSIGNMENT

Date	14-03-2019	Our Ref No. D19001834MFSH
Accident Date	14-03-2019	Claim Type. Third Party
Insured Vehicle	SHC8736Y	Third Party Vehicle. SLJ4847C
Survey Location	6 BENOI PLACE	
Contact Person.	CHRISSY TEO	
Contact No.	68610908/ 0	Fax No. 65152948
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PRIME AUTO CLAIMS SERVICE PTE. LTD.	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Pei Yee <peiyee@primeautoclaims.com>
Sent: Thursday, 28 March 2019 12:13 PM
To: Veron Chen (LKKAUTO); Taufikh (LKKAUTO)
Cc: 'Alice Leong'; SUR
Subject: RE: FINALIZED TO SLJ4847C

Importance: High

Expires: Tuesday, 24 September 2019 12:00 AM

Dear Veron,

Noted & Confirmed.

Thank you & Best regards,

Pei Yee

Prime Auto Claims Service Pte. Ltd.
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

A member of the Prime Group

Disclaimer: This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Thursday, March 28, 2019 10:14 AM
To: Taufikh (LKKAUTO); peiyee@primeautoclaims.com
Cc: Alice Leong; SUR
Subject: RE: FINALIZED TO SLJ4847C

Dear Pei Yee,

WITHOUT PREJUDICE

Finalize amount \$4842.48 as below:

Right front sport rim-\$600/-

Parts -\$3953.10 (Less 20%)=\$3162.48
Labour-\$1680
Total-\$4842.48

Please check and confirm

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Pei Yee <peiyee@primeautoclaims.com>

Sent: Thursday, 21 March 2019 9:37 AM

To: SUR <sur@lkkauto.com>

Cc: aliceleong@primeautoclaims.com

Subject: FINALIZED TO SLJ4847C

Importance: High

Dear Taufikh,

Enclosed our before & after repair photos & our calculation sheet for your retention. Shall we finalized at P/P \$5,108.48 and 05 working days?

Please revert with your confirmation within three days from our e-mail.

Thank you & Best regards,

Pei Yee

Prime Auto Claims Service Pte. Ltd.

6 Benoi Place Singapore 629927

Tel: 6861 0908 Fax: 6515 2948

A member of the Prime Group

Disclaimer: This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 14.03.2018

MS First Capital Insurance Ltd
36 Robinson Road #16-01
City House
Singapore 068877

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SLJ4847C HONDA VEZEL HYBRID 1.5X (2016)

To Supply

1) 1pc	Right front door	\$	950.00	bt-
2) 1pc	Right front door rubber	\$	50.00	ant-
3) 1pc	Right rear door	\$	930.60	bt-
4) 1pc	Right front fender	\$	580.00	bt-
5) 1pc	Right front fender cowl	\$	130.00	? X
6) 1pc	Right front fender wheel arch garnish	\$	195.00	alt
7) 1pc	Right front fender "Hybrid" emblem	\$	75.00	res
8) 1pc	Right rear fender wheel arch garnish	\$	195.00	alt
9) 1pc	Right lower rocker garnish	\$	377.50	dis
10) 1pc	Right side mirror outer assy.	\$	794.50	R X X
11) 1pc	Right front sport rim	\$	932.50	ant-

Sub total Parts	\$	5,210.10	4,285.60
Less: 20% discount	\$	(1,042.02)	857.12
	\$	4,168.08	3,428.48

L/charges

1) Towing charges	\$	100.00	60.100
2) To tuff kote	\$	50.00	30.
3) To remove right front tyre & sport rim. Replace sport rim & balance tyre.	\$	40.00	30.
4) To transfer right front door & right rear door handles, trim boards, mechanism parts & etc.	\$	200.00	120

5) To remove right front door, right rear door, right front fender, right lower rocker garnish & right side mirror. Replace the above parts. Align & adjust right front door & right rear door.

\$ 900.00 700

6) To putty respray painting right front door & right rear door inlet and outlet & right front fender. To polish.

\$ 900.00 700

Sub total L/charges	\$ 2,190.00	<u>1,680.00</u>
Estimate total	\$ 6,358.08	<u><u>5,108.48</u></u>

(P/P)

supply parts \$ 3,428.48

L/charges \$ 1,680.00

P/P \$ 5,108.48

Taylor 97495749
WP

15/3/19 @ 1740

f sur @ 1/10/2019

5 days

Resurvey before paint



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 14.03.2018

MS First Capital Insurance Ltd
36 Robinson Road #16-01
City House
Singapore 068877

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SLJ4847C HONDA VEZEL HYBRID 1.5X (2016)

To Supply

1) 1pc	Right front door	\$	950.00	bt
2) 1pc	Right front door rubber	\$	50.00	aut
3) 1pc	Right rear door	\$	930.60	bt
4) 1pc	Right front fender	\$	580.00	bt
5) 1pc	Right front fender cowling	\$	130.00	Xnn
6) 1pc	Right front fender wheel arch garnish	\$	195.00	ab
7) 1pc	Right front fender "Hybrid" emblem	\$	75.00	ner
8) 1pc	Right rear fender wheel arch garnish	\$	195.00	aut
9) 1pc	Right lower rocker garnish	\$	377.50	dis
10) 1pc	Right side mirror outer assy.	\$	794.50	Rx
11) 1pc	Right front sport rim	\$	932.50	aut 600
		confirm price		
		Sub total Parts	\$	5,210.10
		Less: 20% discount	\$	(1,042.02)
			\$	4,168.08

L/charges

1) Towing charges	\$	100.00	100
2) To tuff kote	\$	50.00	30
3) To remove right front tyre & sport rim. Replace sport rim & balance tyre.	\$	40.00	30
4) To transfer right front door & right rear door handles, trim boards, mechanism parts & etc.	\$	200.00	120

- 5) To remove right front door, right rear door, right front fender, right lower rocker garnish & right side mirror. Replace the above parts. Align & adjust right front door & right rear door. \$ 900.00 700
- 6) To putty respray painting right front door & right rear door inlet and outlet & right front fender. To polish. \$ 900.00 700

Sub total L/charges \$ 2,190.00
 Estimate total \$ 6,358.08

[Signature]
 26/3/19
 Taylor 97495749
 WP
 15/3/19 @ 1740
 4 sur @ 1/4 hour
 5 days
 Resurvey before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



ISLAND RECOVERY SERVICES

Blk 3026, Ubi Road 1 #04-146 Singapore 408719

Telephone: 6747 7400

Email: islandrecovery@ymail.com

Facsimile: 6844 7233

Web: www.islandrecovery.com.sg

GST Reg.No: M90370499P

Co. Reg. 53120055L

Cash Sales/ Work Order

NO. 1210340

Date: 14-3-18

M/S: PRIME

Vehicle No: SLI 4847C Model: H

From: Gambas Ave Time Start: 12:50

To: 6 Bemo: PL Time End: 2:20

Remarks: _____

☐ Change Tyres / Jump Start

☒ Accident

☐ Use Car Carrier

☐ Basement / Multi Carpark

☐ Crane Up / Winch Out

☐ Open Door

☒ Using King Dolly

☐ Dismantle Shaft / Brake

☐ Loaded

AMOUNT S\$ 100

GST S\$ _____

TOTAL S\$ _____

bizSAFE₃

Important Note:

\$1890

Island Recovery Services

Received By _____

Vehicle is transported at owner's risk. The company accepts no responsibility for damaged or other misdemeanour to your vehicle whilst being transported.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19004733/T1vd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 02-04-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8736Y	Veh. Inspected	SLJ 4847C	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19001834MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	15/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL HYBRID	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	RU31131687	Colour	BLUE	
Odometer	130087	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GOODRICH	6 mm	
L/H Front Tyre	215/60 R16	GOODRICH	6 mm	
R/H Rear Tyre	215/60 R16	GOODRICH	6 mm	
L/H Rear Tyre	215/60 R16	GOODRICH	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/03/2019	Inspection Date	15/03/2019	
Survey held at	PRIME AUTO CLAIMS SERVICE PTE LTD 6 BENOI PLACE SINGAPORE 629927			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 4847C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	RIGHT FRONT DOOR	BENT	950.00	950.00
1	RIGHT REAR DOOR RIBBER	CUT	50.00	50.00
1	RIGHT REAR DOOR	BENT	930.60	930.60
1	RIGHT FRONT FENDER	BENT	580.00	580.00
1	RIGHT FRONT FENDER COWLING	NOT NECESSARY	130.00	-
1	RIGHT FRONT FENDER WHEEL ARCH GARNISH	CUT	195.00	195.00
1	RIGHT FRONT FENDER "HYBRID" EMBLEM	NECESSARY	75.00	75.00
1	RIGHT REAR FENDER WHEEL ARCH GARNISH	CUT	195.00	195.00
1	RIGHT LOWER ROCKER GARNISH	DISTORTED	377.50	377.50
1	RIGHT SIDE MIRROR OUTER ASSY	TO REPAIR SEE LABOUR	794.50	-
1	RIGHT FRONT SPORT RIM	CUT	932.50	600.00
	LESS 20% DISCOUNT		-1,042.02	-790.62
			4,168.08	3,162.48
LABOUR				
	TOWING CHARGES.		100.00	100.00
	TO TUFF KOTE.		50.00	30.00
	TO REMOVE RIGHT FRONT TYRE & SPORT RIM.REPLACE SPORT RIM & BALANCE TYRE.		40.00	30.00
	TO TRANSFER RIGHT FRONT DOOR & RIGHT REAR DOOR HANDLES,TRIM BOARDS,MECHANISM PARTS & ETC.		200.00	120.00
	TO REMOVE RIGHT FRONT DOOR,RIGHT REAR DOOR,RIGHT FRONT FENDER,RIGHT LOWER ROCKER GARNISH & RIGHT SIDE MIRROR.REPKACE THE ABOVE PARTS.ALIGN & ADJUST RIGHT FRONT DOOR & RIGHT REAR DOOR.INCLUSIVE OF THE REPAIR OF RIGHT SIDE MIRROR OUTER ASSY.		900.00	700.00
	TO PUTTY RESPRAY PAINTING RIGHT FRONT DOOR & RIGHT REAR DOOR INLET AND OUTLET & RIGHT FRONT FENDER.TO POLISH.		900.00	700.00
			2,190.00	1,680.00
GRAND TOTAL			6,358.08	4,842.48

Report Ref No. CS/FC19004733/T1vd3n2



RECOMMENDED COST OF REPAIRS			4,842.48
-----------------------------	--	--	----------

Report Ref No. CS/FCI19004733/T1vd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.