

# Allswell Motor Traders

25 Defu Lane 9, Singapore 539266

Tel : +65 6679 1146

email:ben@allswellmotor.com.sg

(3rd party claim against Indun

## Estimate repair

Vehicle No. : SJU4731T

Make & Model : Corolla Altis

Chassis No. : 1-6A

Date of survey :

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during survey
- The prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Submitted by

Acknowledged by Repairer

COE expiry

Engine No.

Bun

25-3-2023

S/No	Part Description	Qty	Unit Price	Price	Disposition by
01	Front bumper X MPax	01	\$890.00	X	
02	LH front repainer / DE	01	\$69.00	35	
03	LH headlamp / Seru	01	\$760.00	399.1	
	Special nutt			434.1	
01	Clips / retainer clips for rear bumper \$25/MCT, MCC.	01	\$25.00	25%	325.58
	Labour Description				
01	Disassemble / Assembly of rear bumper	01	\$260.00	200	
02	Spray painting of rear bumper	01	\$300.00	200	
03	Re-arrang of sensor	01	\$40.00	30	
	3 Days			430	
	Give Quote			780.58	
	15/3/19			20%	600
	Unpainted Repair.				
	After repair photos.				

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.