

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AIG	DATE	: 13/03/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SLV9173S	WBSWD92000PY38626	
MODEL	: BMW M3	Cecilia	
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 13-Mar-19
		TIME	: 13:55HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT DOOR RH <i>Rep</i>	1	\$ 2,550.80	\$ 2,550.80
2	REAR FENDER RH <i>Repld</i>	1	\$ 3,688.50	\$ 3,688.50
3	REAR FENDER QUARTER GLASS MOULDING RH <i>Repl</i>	1	\$ 214.00	\$ 214.00
4	REAR LOWER ARM RH <i>Best</i>	1	\$ 769.50	\$ 769.50
5	REAR UPPER ARM RH <i>Best</i>	1	\$ 550.00	\$ 550.00
6	REAR STAY BAR RH <i>Repl Best</i>	1	\$ 102.10	\$ 102.10
7	REAR STEERING CONTROL ARM RH <i>Repl</i>	1	\$ 486.05	\$ 486.05
8	REAR SHOCK ABSORBER RH <i>Repl</i>	1	\$ 980.00	\$ 980.00
9	REAR KNUCKLE ARM RH <i>Best</i>	1	\$ 1,101.70	\$ 1,101.70
10	REAR KNUCKLE BEARING WITH HUB RH <i>Repl</i>	1	\$ 300.15	\$ 300.15
11	SIDE SKIRT RH <i>Repld</i>	1	\$ 1,050.00	\$ 1,050.00
12	REAR BUMPER <i>Repl ton</i>	1	\$ 1,988.50	\$ 1,988.50
13	REAR BUMPER SIDE RETAINER RH <i>Repl</i>	1	\$ 187.00	\$ 187.00

7265.55

6902.65

TOTAL PRICE \$ 13,968.30

LESS 0% \$ -

SUB TOTAL PRICE \$ 13,968.30

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
-----	-------------	-----	-------------	--------------

1	SIDE SKIRT CLIPS(SET) <i>new</i>	1	\$ 30.00	\$ 30.00	✓
2	REAR BUMPER CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✗
3	REAR WHEEL TYRE RH <i>new</i>	1	\$ 850.00	\$ 850.00	✗
4	REAR WHEEL RIM RH <i>lit</i>	1	\$ 1,600.00	\$ 1,600.00	1000
5	COATING <i>new</i>	1	\$ 1,800.00	\$ 1,800.00	600
1630			TOTAL	\$ 4,300.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,400.00	800 1000	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	750 1000.	
3	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 100.00	50	
4	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 450.00	280	
5	FOUR WHEEL ALIGNMENT	\$ 100.00	80	
6	TUFF COAT	\$ 150.00	80	
7	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 130.00	100	
8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 240.00	x	

TOTAL 2590 \$3,970.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 18,268.30
TOTAL LABOUR COST : \$ 3,970.00
TOTAL REPAIR COST : \$ 22,238.30

Adrian Lj
2/c 15/03/19.

06 days.

total 1111265

1/5: 89K

APPROVED DETAILS

SURVEYOR :

CONTACT NO

PART BY PART / LUMP SUM
NO OF DAYS

: LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FAX

89K