



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE

Our Ref:

Type of Claim : TPVehicle No. : SLV803SMake & Model : HONDA CIVIC 1.6 VTI CVTYear of Manufacture : 2017Chassis No. : MRHFC5650HT000375Ins Company : INDA VS FWDEngine No. : R16B22000740Excess : -Policy No. : -Date of Accident : 14.03.2019Time of Accident : 09:00

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimate**

Case Owner : _____

Signature : _____

Parts (a) Cost / List Price Items \$ -

Plus/Less 20% \$ -

Total of Cost / List \$ -

(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ -

Total Parts Cost (Appendix A) \$ -

Labour (Appendix B) \$ 3,010.00

Total Repair Cost \$ 3,010.00

Contact No

Frnt Counter Operation

63837103 - Patrick Tia

63837730 - Brenda Ng

63837466 - Rohani

braddell_cr@sparkcarcare.com**Workshop Operation**

63837656 - Ngo Toh Wee

63837362 -

63838115 - William Wang

63838115 - Andrew Goh

braddell_operation@sparkcarcare.com

The above total will be subjected to 7% G.S.T.

Name of Surveyor : HenrichCompany : UKICSurvey conducted on : 15/3/19 at _____**Remarks By Surveyor**(a) The repair of this vehicle is authorized / is not authorized until further notice.(b) Recommended Days of Repair : 4-5 day(s)(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Pc Date: 15/3/19

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SLV803S Case Owner : 0

Make & Model : HONDA CIVIC 1.6 VTI CVT Year Manufacture : 2017

Chassis No : MRHFC5650HT000375 Engine No : R16B22000740

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear bumper <i>R₁</i>	1					✓
2	Rear bumper garnish LH <i>S₂</i>	1					X
3	Rear bumper garnish RH <i>S₃</i>	1					X
4	Rear bumper garnish reflector LH <i>S₄</i>	1					X
5	Rear bumper garnish reflector RH <i>S₅</i>	1					X
6	Rear bumper ultra sonic sensor	1					?
7	Rear bumper ultra sonic sensor wire	1					?
8	Rear bumper sponge	1					?
9	Rear bumper reinforcement	1					?
10	Rear bumper retainer LH <i>Dir</i>	1					✓
11	Rear bumper retainer RH	1					?
12	Rear bumper clips <i>Me</i>	1					✓
13	Taillamp LH <i>Gr</i>	1					✓
14	Taillamp RH <i>Gr</i>	1					✓
15	Bootlid <i>R₁</i>	1					✓
16	Bootlid outer garnish	1					?
17	Bootlid badge logo <i>Me</i>	1					?
18	Bootlid emblem - i-VTEC <i>1</i>	1					?
19	Bootlid emblem - CIVIC	1					?
20	Bootlid lamp LH <i>S₂</i>	1					X
21	Bootlid lamp RH <i>S₃</i>	1					X
22	Bootlid upper lock <i>R</i>	1					X
23	Bootlid weatherstrip	1					?
24	Rear end panel	1					?
25	Rear end panel inner garnish	1					?
26	Rear end buzzer	1					?
27	Rear antenna control	1					?
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.