



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE

Our Ref:

Type of Claim : TPVehicle No. : SLV803SMake & Model : HONDA CIVIC 1.6 VTI CVTYear of Manufacture : 2017Chassis No. : MRHFC5650HT000375Ins Company : INDA VS FWDEngine No. : R16B22000740Excess : -Policy No. : -Date of Accident : 14.03.2019Time of Accident : 09:00

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimate**

Case Owner : _____

Signature : _____

Parts (a) Cost / List Price Items \$ -

Plus/Less 20% \$ -

Total of Cost / List \$ -

(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ -

Total Parts Cost (Appendix A) \$ -

Labour (Appendix B) \$ 3,010.00

Total Repair Cost \$ 3,010.00

Contact No

Frnt Counter Operation

63837103 – Patrick Tia

63837730 - Brenda Ng

63837466 – Rohani

braddell_cr@sparkcarcare.com**Workshop Operation**

63837656 - Ngo Toh Wee

63837362 -

63838115 - William Wang

63838115 - Andrew Goh

braddell_operation@sparkcarcare.com*The above total will be subjected to 7% G.S.T.*

Name of Surveyor : _____

Company : _____

Survey conducted on : _____ at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

Spare Parts

Vehicle No : SLV803S Case Owner : 0

Make & Model : HONDA CIVIC 1.6 VTI CVT Year Manufacture : 2017

Chassis No : MRHFC5650HT000375 Engine No : R16B22000740

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear bumper	1					
2	Rear bumper garnish LH	1					
3	Rear bumper garnish RH	1					
4	Rear bumper garnish reflector LH	1					
5	Rear bumper garnish reflector RH	1					
6	Rear bumper ultra sonic sensor	1					
7	Rear bumper ultra sonic sensor wire	1					
8	Rear bumper sponge	1					
9	Rear bumper reinforcement	1					
10	Rear bumper retainer LH	1					
11	Rear bumper retainer RH	1					
12	Rear bumper clips	1					
13	Taillamp LH	1					
14	Taillamp RH	1					
15	Bootlid	1					
16	Bootlid outer garnish	1					
17	Bootlid badge logo	1					
18	Bootlid emblem - i-VTEC	1					
19	Bootlid emblem - CIVIC	1					
20	Bootlid lamp LH	1					
21	Bootlid lamp RH	1					
22	Bootlid upper lock	1					
23	Bootlid weatherstrip	1					
24	Rear end panel	1					
25	Rear end panel inner garnish	1					
26	Rear end buzzer	1					
27	Rear antenna control	1					
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax:62844284,62815767

Year of Manufacture : 2017

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.