# Spark Car Care ComfortDelgro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62815767

**Finalization Form** 

Bill To FWD  Attn to LKK - KENNETH KG		Number -	LV803S TP
A. Spare parts	\$ 2,351.00	F. Total Parts	\$ 1,880.80
B. Supplementary	\$	G. Total Labour	\$ 1,920.00
C. Nett Price	\$	H. Total Repair	\$ 3,800.80
D. Supp Nett Price	\$ -	I. Excess	
E. S/Nett	\$	P/P Total	3,800.80 0
Total Spare Parts Price	\$ 2,351.00		
Cost plus / List Down Total	1,880.80	Lump Sum Less	\$
Total Nett Price	\$ -	Lump Sum Rounding	
Nett Price Less	\$ -		
Total	-	Total Finalized	\$ 3,800.80
N.B. If we DO NOT receive your reply	within 2 weeks, we shall tree	at the above finalized amount as c	confirmed L, correct.
Remarks : Please comfirm and revert by Fax of			
Date in :	Total Repair Day		
Date Survey :	LOU/ Day		
	Total LOU		
Date Out :	1		
Sat/Sun/Ph. :	Rental/Day	and the state of t	
Authorized Repair Day 5	Total Rental		
Submitted By / Date : WILLIAM WANG 07.06.2019	Confirmed By / Date :	_	

# Spark Car Care

### ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62844284,62815767

#### Spare Parts

Vehicle No	:	SLV803S	Case Owner	:	0
Make & Model	:	HONDA CIVIC 1.6 VTI CVT	Year Manufacture	:	2017
Chassis No	1	MRHFC5650HT000375	Engine No	÷	R16B22000740
Sales Order	:		Supplier	;	
Order By			Type of Claim	:	<u>TP</u>

S/No	Part Description	QTY	Cost Price	List Nett Price Price		S/N	Disposition By Surveyor
1	Rear bumper	1		\$ 617.50			
2	Rear bumper garnish LH	1					
3	Rear bumper garnish RH	1					
4	Rear bumper garnish reflector LH	1					
5	Rear bumper garnish reflector RH	1					
6	Rear bumper ultra sonic sensor	2		\$ 267.80			
7	Rear bumper ultra sonic sensor wire	1	333370				
8	Rear bumper sponge	1					
9	Rear bumper reinforcement	1					
10	Rear bumper retainer LH	1		\$ 14.80			
11	Rear bumper retainer RH	1					
12	Rear bumper clips	10		\$ 39.00			
13	Taillamp LH	1		\$ 273.10			
14	Taillamp RH	1		\$ 273.10			
15	Bootlid	1		\$ 572.10			
16	Bootlid outer garnish	1	WOOD W				
17	Bootlid badge logo	1					
18	Bootlid emblem - i-VTEC	1					
19	Bootlid emblem - CIVIC	1					
20	Bootlid lamp LH	1					
21	Bootlid lamp RH	1					
22	Bootlid upper lock	1					
23	Bootlid weatherstrip	1					
	Rear end panel	1		\$ 293.60			
	Rear end panel inner garnish	1					
	Rear end buzzer	1					
27	Rear antenna control	1					
28	0	0					
29	0	0	Wh				
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

# Spark Car Care

## ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62844284,62815767

#### Labour

Vehicle No.	:	SLV803S	Case Owner	:	0	
Make & Model	:	HONDA CIVIC 1.6 VTI CVT	Year of Manufacture	:	2017	

P			
S/No	Labour Description	Esimated Price	Adjusted Price
1	To remove/refit boot compartment trims and garnish to facilitate repairs.	\$180.00	\$ 100.00
2	Labour charges to repair and panel beat the RH rear fender, LH rear fender, rear chassis members, rear floorboard panel, cutting/welding & replacing damaged parts.	\$840.00	\$ 720.00
3	To check wiring functions.	\$40.00	\$ 20.00
4	To putty, apply primer & spray-paint the rear bumper, bootlid, RH rear fender, LH rear fender, rear end panel, taillamp panel LH, taillamp RH, rear chassis members, spare tyre panel and affected areas.	\$1,750.00	\$ 1,000.00
5	To apply rust-proofing on repaired/replaced panels.	\$200.00	\$ 80.00

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.