

ASS. REC. BY:

REF: CS / FC119004845 / Ktd3n2

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): JOANNEY of Pci Date/Time: 15.3.2019

Estimated Cost: Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLS 4151D

Insured: SHC 3517X

at Workshop m/s: Hui Yang Motor Pte Ltd

Tel: 64515152

of Blk 176 Sin Ming Drive # 04-02 Sin Ming Auto Care

Policy No:

Claim No: 4201849RFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 14.3.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement:

Date/Time: 18.3.2019 12:07 p.m. Person Contacted: Bel

Vehicle: IN / (OUT)

Date/Time Action/Instruction (✓) Estimate

SLS 4151 D - X

SHC 3517 - X

20/3 @ 5:02pm - revised via email proti advise.

lump sum \$5000 (Red: 3882.45; 43%)

ASS. REC. BY:

REF:

1021

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

File pass to

RECEIVED 26 MAR 2019

Date/Time, File Pass to?

263 Typst

Date/Time, File Return to?



: Prel. Report



: Final Report

Days Of Repair:

6

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S - RS. \$

Fees

Others

TOTAL

160

50

90+50

23

333

Report Format:

Lump Sum / I.B.I. (\$

5000/-

Veh No:

SLS4151D

Yr Regn:

09, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

74 CHR

c.c.

1787

Colour:

m. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

174253

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ZYX10

2068800

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

215/60R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

DAVANTI

Front

R/Bal.

3

mm

Rear

R/Bal.

2

mm

L/Bal.

3

mm

L/Bal.

2

mm

D.O.A.

14/3/19

D.O.I.

18/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear U/C

The U/C / Chassis frame / Body Structure affected due to collision.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001849MFSH

Date: 20/3/2019

Our Ref: CS/FCI19004845/Ktd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLD 4151D

Please be informed that we had conducted the inspection of the abovementioned vehicle 18/3/2019 at the premises of M/s Hui Yang Motor have the following to report: -

Workshop Estimate Amount	: S\$	<u>8,882.45</u>
Revised Estimate Amount	: S\$	<u>5,533.08</u>
"Check" Items Amount	: S\$	<u>0.00</u>
Market Value	: S\$	<u> </u>
LTA Reimbursement Value	: S\$	<u> </u>
Nett Value	: S\$	<u> </u>

Description of Damage:
The vehicle sustained damages at the
o/s rear and undercarriage portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully
Kenneth
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	15-03-2019	Our Ref No. D19001849MFSH
Accident Date	14-03-2019	Claim Type. Third Party
Insured Vehicle	SHC3517X	Third Party Vehicle. SLS4151D
Survey Location	BLK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE	
Contact Person.	BEL	
Contact No.	6451 5752/ 0	Fax No. 6451 4658
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

Kenneth
Out

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HUI YANG MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 20 March 2019 5:02 PM
To: 'CWS Motor Claims'
Cc: assignments; 'Joanne Yong Lai fong'
Subject: RE: SURVEY ASSESSMENT - D19001849MFSH/1
Attachments: PRELI ADVISED SLS 4151D.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLS 4151D**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 18 March 2019 10:22 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <JoanneYong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19001849MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

辉陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

14/03/2019

Owner: SKYWAY MOTOR PTE LTD

ESTIMATE TO REPAIR TOYOTA C-HR 1.8 - SLS4151D

1pc	rear RH door	Bj	\$ 1,125.85	✓
1pc	rear RH door frame sticker 1	m.	\$ 149.90	✓
1pc	rear RH door frame sticker 2	m.	\$ 149.90	✓
1pc	rear RH door protector	cm	\$ 431.25	✓
1pc	rear RH door inner rubber	pas	\$ 258.50	X
1pc	rear RH door inner lock	n	\$ 285.25	X
1pc	rear RH fender	Bj	\$ 978.85	✓
1pc	rear RH fender protector	cm	\$ 374.45	✓
1pc	rear RH fender inner shield		\$ 381.90	?
1pc	rear bumper	Mg. M	\$ 972.45	✓
1pc	rear bumper RH side retainer	D11	\$ 141.45	✓
1pc	rear RH lower arm		\$ 485.58	?
1pc	rear RH absorber		\$ 450.25	?
1pc	rear RH knuckle arm		\$ 485.50	?
1pc	rear RH knuckle bearing		\$ 358.85	?
			\$ 7,029.93	
			\$ 1,757.48	
			\$ 5,272.45	
1pc	rear RH sport rim		s.nett \$ 750.00	✓
	remove & refit rear RH undercarrage		\$ 380.00	?
	alignment		\$ 80.00	601
	wiring		\$ 80.00	201
	tuffkote		\$ 120.00	601
	spray painting		\$ 1,000.00	6001
	labour charges		\$ 1,200.00	8001
	Total		\$ 8,882.45	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



ms find q

18/03/19

Link, Kennedy

after 11am

Not Notation

L Py 8?

Money After Paint

6 days

辉陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add: SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

14/03/2019

Owner: SKYWAY MOTOR PTE LTD

ESTIMATE TO REPAIR TOYOTA C-HR 1.8 - SLS4151D

1pc	rear RH door	
1pc	rear RH door frame sticker 1	38.90
1pc	rear RH door frame sticker 2	38.90
1pc	rear RH door protector	203.70
1pc	rear RH door inner rubber	
1pc	rear RH door inner lock	
1pc	rear RH fender	
1pc	rear RH fender protector	
1pc	rear RH fender inner shield	
1pc	rear bumper	
1pc	rear bumper RH side retainer	
1pc	rear RH lower arm	
1pc	* rear RH absorber	407.
1pc	* rear RH knuckle arm	
1pc	* rear RH knuckle bearing	

less 25%

Ry	\$	1,125.85	✓
mc	\$	149.90	✓
mc	\$	149.90	✓
cm	\$	431.25	✓
pas	\$	258.50	x
rc	\$	285.25	x
Ry	\$	978.85	✓
cm	\$	374.45	✓
sl	\$	381.90	x
mgm	\$	972.45	✓
oii	\$	141.45	✓
sl	\$	485.58	x
Ry	\$	450.25	✓
Ry	\$	485.50	✓
mc	\$	358.85	✓

\$ 7,029.93

\$ 1,757.48

\$ 5,272.45

1pc rear RH sport rim

mc s.nett \$ 750.00 ✓

remove & refit rear RH undercarrage
alignment
wiring
tuffkote
spray painting
labour charges
Total

\$	380.00	1602
\$	80.00	601
\$	80.00	201
\$	120.00	601
\$	1,000.00	6001
\$	1,200.00	8001
\$	8,882.45	



Work Order: R052996
 License: SLS4151D
 Year: 14
 Date: 18.3.19 14:46

Toyota : C-HR 2017-

Front : Left

Actual	Before	Specified Range
0°12'	0°12'	-0°55' 0°35'
6°06'	6°06'	5°05' 6°35'
0°11'	0°05'	-0°02' 0°07'
14°10'	14°10'	10°40' 12°10'
14°22'	14°22'	9°45' 12°45'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
0°05'	0°05'	-0°55' 0°35'
6°29'	6°29'	5°05' 6°35'
-0°14'	-0°08'	-0°02' 0°07'
13°59'	14°00'	10°40' 12°10'
14°04'	14°04'	9°45' 12°45'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
0°07'	0°07'	
-0°23'	-0°23'	
0°11'	0°11'	
-0°04'	-0°03'	-0°05' 0°14'

Rear : Left

Actual	Before	Specified Range
-1°44'	-1°44'	-1°50' -0°20'
0°29'	0°29'	0°00' 0°09'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-2°29'	-2°25'	-1°50' -0°20'
-0°06'	-0°17'	0°00' 0°09'

Rear

Cross Camber
 Total Toe
 Thrust Angle
 Axle Offset

Actual	Before	Specified Range
0°44'	0°41'	-0°45' 0°45'
0°22'	0°12'	0°00' 0°19'
0°18'	0°23'	
0mm	0mm	

Work Order: R052997
 License: SLS4151D
 Year: 14
 Date: 21.3.19 16:52

Toyota : C-HR 2017-

Front : Left

Actual	Before	Specified Range
-0°07'	0°08'	-0°55' 0°35'
6°07'	6°07'	5°05' 6°35'
-0°01'	0°09'	-0°02' 0°07'
14°32'	14°17'	10°40' 12°10'
14°25'	14°25'	9°45' 12°45'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
0°03'	0°09'	-0°55' 0°35'
6°27'	6°27'	5°05' 6°35'
0°07'	-0°14'	-0°02' 0°07'
14°06'	13°59'	10°40' 12°10'
14°09'	14°09'	9°45' 12°45'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
-0°09'	-0°01'	
-0°20'	-0°20'	
0°26'	0°18'	
0°05'	-0°05'	-0°05' 0°14'

Rear : Left

Actual	Before	Specified Range
-1°44'	-1°47'	-1°50' -0°20'
0°06'	0°06'	0°00' 0°09'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-1°14'	-1°07'	-1°50' -0°20'
0°06'	-0°04'	0°00' 0°09'

Rear

Cross Camber
 Total Toe
 Thrust Angle
 Axle Offset

Actual	Before	Specified Range
-0°30'	-0°40'	-0°45' 0°45'
0°12'	0°02'	0°00' 0°19'
0°00'	0°05'	
0mm	0mm	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19004845/Ktd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 01-04-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3517X	Veh. Inspected	SLS 4151D	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19001849MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	15/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA C-HR (A)	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	ZYX102068800	Colour	METALLIC GREY	
Odometer	174253	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R17	DAVANTI	3 mm	
L/H Front Tyre	215/60 R17	DAVANTI	3 mm	
R/H Rear Tyre	215/60 R17	DAVANTI	2 mm	
L/H Rear Tyre	215/60 R17	DAVANTI	2 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/03/2019	Inspection Date	18/03/2019	
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 4151D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR RH DOOR	BENT	1,125.85	1,125.85
1	REAR RH DOOR FRAME STICKER 1	NECESSARY	149.90	38.90
1	REAR RH DOOR FRAME STICKER 2	NECESSARY	149.90	38.90
1	REAR RH DOOR PROTECTOR	CUT	431.25	203.70
1	REAR RH DOOR INNER RUBBER	SERVICEABLE	258.50	-
1	REAR RH DOOR INNER LOCK	TO REPAIR SEE LABOUR	285.25	-
1	REAR RH FENDER	BENT	978.85	978.85
1	REAR RH FENDER PROTECTOR	CRACKED	374.45	374.45
1	REAR RH FENDER INNER SHIELD	SERVICEABLE	381.90	-
1	REAR BUMPER	MTG CRACKED	972.45	972.45
1	REAR BUMPER RH SIDE RETAINER	DISTORTED	141.45	141.45
1	REAR RH LOWER ARM	SERVICEABLE	485.58	-
1	REAR RH ABSORBER	BENT	450.25	407.00
1	REAR RH KNUCKLE ARM	BENT	485.50	485.50
1	REAR RH KNUCKLE BEARING	NECESSARY	358.85	358.85
	LESS 25% DISCOUNT		-1,757.48	-1,281.48
			5,272.45	3,844.42
SPECIAL NETT ITEMS				
1	REAR RH SPORT RIM (SN)	DENTED	750.00	750.00
			750.00	750.00
LABOUR				
	REMOVE & REFIT REAR RH UNDERCARRIAGE.		380.00	160.00
	ALIGNMENT.		80.00	60.00
	WIRING.		80.00	20.00
	TUFFKOTE.		120.00	60.00
	SPRAY PAINTING.		1,000.00	600.00
	LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF REAR RH DOOR INNER LOCK.		1,200.00	800.00
			2,860.00	1,700.00



GRAND TOTAL		8,882.45	6,294.42
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,000.00

Report Ref No. CS/FCI19004845/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.