

ESTIMATE

Invoice Name & Address		Owner Name & Vehicle Info	
Boey Choi Har		Cust No/Name	/Boey Choi Har
177 Tanjong Rhu Road		Reg No/Reg Date	SGX1249J*CC1/ 16/11/2015
#11-23 Ater Place		Date In/Mileage	/ 0
Singapore 436607		Chassis No	VF73DBHZTFJ745971
Contact No Mobile: 97765200MR TANG		Engine No	10JBHD3011679
		Make/Model	CIT/C4P 1.6 BLUEHDI EAT6 SEDUCTION
		Colour/Trim	1SM / 8MF

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	05/03/2019/ 08:24	TLC	442 / CocoLu	14171

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW REAR BUMPER, TAILGATE LOWER PANEL, REPAIR REAR END PANEL TAILGATE				600 1800.00
E PNT98000 SPRAY PAINT FOR REAR BUMPER, TAILGATE, TAILGATE LOWER PANEL REAR END PANEL				420 1680.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR				60 100.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				50.00
A 54900099 CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM				300.00
M SUNDRY C&C LOGO				40.00 X
M SUNDRY Sundry				20.00
M REAR BUMPER	1.00	898.00	0.00	898.00
M BUMPER BRACKET	1.00	258.00	0.00	258.00
M BUMPER SKIRT	1.00	313.00	0.00	313.00
M BRACKET SET	1.00	58.00	0.00	58.00
M BRACKET	1.00	143.00	0.00	143.00
M LOW RR PAN FIX	1.00	167.00	0.00	167.00
M TLGT EXT PANEL INF	1.00	523.00	0.00	523.00
M BADGE	1.00	40.00	0.00	40.00
M BADGE	1.00	49.00	0.00	49.00
M BADGE	1.00	58.00	0.00	58.00

Steve (LKK) WHL P/TOL
 2/1/20, 2:30pm
 P/P
 Ry Bel SP
 3 days

Confirm & accepted by

Parts	2,507.00
Labour	3,930.00
Standard Menu	0.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	60.00
Total (w/o GST)	6,497.00

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
- To display damaged parts during survey
- Estimated (damaged parts) during survey
- Parts prices are subject to confirmation
- Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, you must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: