

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

JTE6H23B80J024624

MAHAMMED HAFASHAH BIN AHMAD

Date :20.04.2019

BLK659B PUNGGOL EAST

Vehicle no :SGZ 2333 G

#02-765

Make/Model :TOYOTA PICNIC

S 822659

Accident date :12.03.2019

No	DESCRIPTION	Qty	Amount (\$\$)
<u>List Items</u>			
1	Rear windscreen rubber <i>new</i>	1	\$ 132.4 ✓
2	Rear tailgate <i>Dented</i>	1	\$ 1437.6 ✓ 1228
3	Rear tailgate hinges @ \$65.60 <i>new</i>	2	\$ 131.2 x
4	Rear tailgate shock absorber @ \$234.10 <i>new</i>	2	\$ 468.2 x
5	Rear tailgate reflector @ \$171.90 <i>ut</i>	2	\$ 343.8 ✓
6	Rear tailgate centre logo <i>new</i>	1	\$ 78 ✓
7	Rear tailgate handle <i>Dented</i>	1	\$ 164.5 ✓
8	Rear tailgate inner board <i>cracked</i>	1	\$ 340 ✓
9	Rear tailgate upper lock <i>new</i>	1	\$ 259.1 ✓
10	Rear tailgate lower lock <i>new</i>	1	\$ 38.3 x
11	Rear tailgate inner weather strip <i>ut</i>	1	\$ 272.3 ✓
12	Rear tailgate wiper arm <i>new</i>	1	\$ 151.2 x
13	Rear tailgate wiper arm cover <i>new</i>	1	\$ 18.3 x
14	Rear tailgate wiper motor <i>Dented</i>	1	\$ 539.9 ✓
15	Rear number plate lamp <i>new</i>	1	\$ 129.5 x
16	Rear end panel <i>Dented</i>	1	\$ 457.7 ✓
17	Rear end panel top garnish <i>Dented</i>	1	\$ 253.9 ✓
18	Rear bumper <i>Dented</i>	1	\$ 562.3 ✓
19	Rear bumper side holder @ \$41.90 <i>new</i>	2	\$ 83.8 ✓
20	Rear bumper reflector @ \$59.50 <i>new</i>	2	\$ 119 x
21	Rear bumper clips (1set) <i>new</i>	1	\$ 50.30 ✓
22	Floor Panel Surround Trim <i>torn</i>	1	\$ 6031
Less 25% Disc			\$ 1507.75
Total			\$ 4523.25

Special Nett Items

1	Rear number plate <i>new</i>	1	\$ 50 x
2	Rear number plate holder <i>new</i>	1	\$ 50 x
3	Rear bumper reverse sensor <i>Dented</i>	3	\$ 600 250
4	Rear camera <i>new</i>	1	\$ 800 x
5	Floor Panel Insulation Pad <i>new</i>	1	\$ 1500
Total			\$ 1500

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

MAHAMMED HAFASHAH BIN AHMAD
BLK659B PUNGGOL EAST
#02-765
S 822659

Date :20.04.2019
Vehicle no :SGZ 2333 G
Make/Model :TOYOTA PICNIC
Accident date :12.03.2019

No	Description	Qty	Amount (\$\$)
----	-------------	-----	---------------

Labour Cost

1	To supply rear end panel inner sealant		\$ 200-60
2	To supply rear widnscreen sealant		\$ 50 ✓
3	Remove & reinstall rear windscreen		\$ 150-120.
4	Remove & reinstall boot lid inner garnish		\$ 150-82.
5	Remove,replace & repair consistent to the accident	2260	\$ 1800-92
6	Respray painting		\$ 1400-860
7	Tuff kote		\$ 150-60
8	To remove and reinstall upholstery	80	\$ 120-60
9	To replace reverse sensor		
Total			\$ 3900
Grand Total			\$ 9923.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 6527.57
4/5: 521c. 07 days.

5.21c