

MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 # 01-61

SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
78 Shenton Way #07-16
Singapore 079120
Tel : 6419 - 3000
Fax : 6835 - 7416

Quotation

DATE : 04.04.2019
VEH NO : SLU1543R
MODEL : Honda Freed
D O A : 10.03.2019
YR REF : SLJ853K

As per

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLU1543R (HONDA FREED)

Item	Description	Qty	Am't
NO	LIST ITEMS		
1	Front Bumper <i>Repair</i>	1	1,050.80 <i>X</i>
2	Front Bumper Clips <i>new</i>	1 set	30.00 <i>✓</i>
3	Front Bumper Side Holder - RH <i>new</i>	1	35.00 <i>X</i>
4	Front Fender - RH <i>Repair</i>	1	440.70 <i>X</i>
5	Head Lamp - RH <i>ut</i>	1	1,980.00 <i>✓</i>
			3,536.50
	Less 20%		(707.30)
			\$ 2,829.20

S/NETT ITEMS

1	Front Wheel Rim - RH <i>ut</i>	1	850.00 <i>500</i>
Total Parts			\$ 3,679.20

LABOUR CHARGE

1	To knocking & pull out front RH portion & renew above parts	\$ 600.00 <i>300</i>
2	To putty & spray up paint works	\$ 600.00 <i>400</i>
3	To check wiring	\$ 50.00 <i>30</i>
4	To perform wheel alignment	\$ 150.00 <i>80</i>
Total Labour		\$ 1,400.00

Grand Total **\$ 5,079.20**

*total: 2818
c/s: 213K.
04 Days.*

LKR Auto Consultants hereby certify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: