



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLF 6779 Z

Parts	(a) Cost / List Price Items	\$	36,596.58
	Plus/Less 25%	\$	9,149.15
	Total of Cost / List	\$	27,447.44
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	340.00
Total Parts Cost		\$	27,787.44
Labour		\$	6,260.00
Total		\$	34,047.44

Not Authorised
1.3.1
Resurvey Repaint

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items, must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor

:

Kenneth

Company

:

LKK

Survey conducted on

:

18/3/19

at

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 12 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$

(e) Signature of surveyor

:

Lc

Date:

18/3/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLF 6779 Z**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU203531780**

Submit By : **Carmen Lim**
Year Manufacture : **2016**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate <i>Bu</i>	1	\$45.00	S.N	✓
2	Front number plate garnish <i>Pu</i>	1	\$129.00		✓
3	Bonnet <i>Bu</i>	1	\$812.40		✓
4	Bonnet lock <i>D.S</i>	1	\$130.00		✓
5	Bonnet hinge LH	1	\$57.80		?
6	Bonnet hinge RH	1	\$57.80		?
7	Bonnet heat insulator <i>Sm</i>	1	\$440.12		×
8	Bonnet heat insulator clip <i>rm</i>	10	\$35.00		×
9	Front support panel centre <i>Bu</i>	1	\$338.50		✓
10	Front support panel LH	1	\$213.50		?
11	Front support panel RH	1	\$213.50		?
12	Headlamp panel LH	1	\$89.20		?
13	Headlamp panel RH	1	\$89.20		?
14	Support panel lower	1	\$387.95		?
15	Front support panel top garnish <i>D.Y</i>	1	\$285.40		✓
16	Front support panel top garnish clip <i>rm</i>	10	\$35.00		✓
17	Air duct <i>cm</i>	1	\$195.40		✓
18	Air duct - inlet	1	\$109.75		?
19	Brace panel <i>Bu</i>	1	\$105.20		✓
20	Condenser	1	\$1,544.70		?
21	Radiator	1	\$1,841.80		?
22	Radiator fan motor RH	1	\$455.70		?
23	Radiator fan motor LH	1	\$491.79		?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SLF 6779 Z**

Make & Model : **TOYOTA PRIUS**

Chassis No : **JTDKB3FU203531780**

Submit By : **Carmen Lim**

Year Manufacture : **2016**

Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Radiator fan blade LH	1	\$197.80		?
25	Radiator fan blade RH	1	\$219.80		?
26	Radiator fan cowling	1	\$287.67		?
27	Radiator top hose	1	\$49.80		?
28	Radiator bottom hose	1	\$46.95		?
29	Radiator spare tank	1	\$186.70		?
30	Headlamp LH <i>mjc m</i>	1	\$2,531.60		✓
31	Headlamp RH <i>mjc Bu</i>	1	\$2,531.60		✓
32	Headlamp ballast LH	1	\$551.97		?
33	Headlamp ballast LH	1	\$551.97		?
34	Front bumper <i>Tr</i>	1	\$450.80		✓
35	Front bumper clip <i>m</i>	10	\$40.00		✓
36	Front bumper reinforcement - upper <i>B</i>	1	\$711.50		✓
37	Front bumper reinforcement - lower <i>B</i>	1	\$245.30		✓
38	Front bumper side retainer RH <i>D.5</i>	1	\$107.20		✓
39	Front bumper side retainer LH <i>D.5</i>	1	\$107.20		✓
40	Front bumper upper grille <i>C M</i>	1	\$321.90		✓
41	Front bumper lower grille <i>C M</i>	1	\$148.60		✓
42	Front bumper emblem <i>m</i>	1	\$87.10		✓
43	Front bumper tow cover RH <i>C M</i>	1	\$25.70		✓
44	Front bumper tow cover LH <i>m</i>	1	\$25.70		✓
45	Front bumper sponge - upper <i>C M</i>	1	\$89.81		✓
46	Front bumper sponge - lower	1	\$135.70		

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SLF 6779 Z**

Make & Model : **TOYOTA PRIUS**

Chassis No. : **JTDKB3FU203531780**

Submit By : **Carmen Lim**

Year Manufacture : **2016**

Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
47	Fog lamp LH	1	\$910.70		?
48	Fog lamp RH	1	\$910.70		?
49	Engine under cover	1	\$198.30		?
50	Engine under cover clip	10	\$35.00		?
51	Air cleaner box	<i>how old</i> 1	\$967.80		✓
52	Washer tank	1	\$195.60		?
53	Washer tank motor	1	\$196.74		?
54	RH front fender	<i>Br</i> 1	\$868.70		✓
55	RH front fender undershield	1	\$185.64		?
56	RH front fender undershield clip	10	\$25.00		?
57	RHF fender wording "HYBRID"	<i>nu</i> 1	\$44.17		✓
58	RH front fender quarter garnish	<i>Dis</i> 1	\$122.70		✓
59	LH front fender	<i>R</i> 1	\$868.70		X
60	LH front fender undershield	<i>Sh</i> 1	\$195.60		X
61	LH front fender undershield clip	<i>nu</i> 10	\$25.00		X
62	LHF fender wording "HYBRID"	<i>nu</i> 1	\$44.17		X
63	Rear windscreen moulding	<i>nu</i> 1	\$97.70		✓
64	Rear windscreen sealant	<i>nu</i> 1	\$50.00		<i>kosn</i>
65	Rear windscreen moulding	<i>nu</i> 1	\$97.70		✓
66	Rear windscreen sealant	<i>Renew Br</i> 1	\$50.00		<i>kosn</i> X
67	Rear number plate	<i>Sh</i> 1	\$45.00	S.N	X
68	Reverse sensor	<i>nu</i> 1	\$200.00	S.N	✓
69	Rear bumper	<i>Br</i> 1	\$497.50		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SLF 6779 Z**

Make & Model : **TOYOTA PRIUS**

Chassis No : **JTDKB3FU203531780**

Submit By : **Carmen Lim**

Year Manufacture : **2016**

Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
70	Rear bumper clip	10	\$40.00		✓
71	Rear bumper side retainer LH	1	\$112.70		✓
72	Rear bumper side retainer RH	1	\$112.70		✓
73	Rear bumper reinforcement	1	\$398.90		✓
74	Rear bumper lower garnish centre	1	\$582.60		✓
75	Rear bumper lower garnish LH	1	\$149.70		?
76	Rear bumper lower garnish RH	1	\$149.70		✓
77	Rear bumper tow cover	1	\$31.70		✓
78	Rear bumper under cover	1	\$355.20		?
79	Rear bumper under cover LH	1	\$187.60		?
80	Rear bumper under cover RH	1	\$187.60		?
81	Rear bumper under cover clip	4	\$14.00		?
82	Tail door	1	\$1,122.50		✓
83	Tail door lock	1	\$487.70		✓
84	Tail door emblem	1	\$61.70		✓
85	Wording "PRIUS"	1	\$51.90		✓
86	Wording "HYBRID"	1	\$55.47		✓
87	Tail door hinge LH	1	\$87.60		X
88	Tail door hinge RH	1	\$87.60		X
89	Tail door plate garnish	1	\$782.50		✓
90	Tail door inner trim	1	\$278.90		?
91	Tail door inner trim clip	10	\$28.00		?
92	Taildoor spoiler	1	\$1,567.83		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SLF 6779 Z**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU203531780**

Submit By : **Carmen Lim**
Year Manufacture : **2016**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
93	Tail end panel <i>R1</i>	1	\$596.60		✓
94	Tail end panel garnish	1	\$151.60		?
95	Tail end panel garnish clip	10	\$35.00		✓
96	Boot weatherstrip	1	\$353.10		?
97	Spare tyre well panel <i>R1</i>	1	\$793.15		✓
98	Spare tyre board <i>Sm</i>	1	\$566.79		X
99	Spare tyre compartment sponge LH <i>Sm</i>	1	\$297.67		✓
100	Spare tyre compartment sponge RH <i>Sm</i>	1	\$297.67		X
101	Spare tyre compartment centre <i>Sm</i>	1	\$251.70		X
102	Tail lamp LH - UPPER <i>C R1</i>	1	\$498.75		✓
103	Tail lamp RH - UPPER <i>C M</i>	1	\$498.75		✓
104	Tail lamp LH - LOWER	1	\$511.60		?
105	Tail lamp RH - LOWER	1	\$511.60		?
106	Taildoor glass sealant <i>Am</i>	1	\$50.00	S.N	<i>Posn</i>
107					
108					
109					
110					
111					
112					
113					
114					
115					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLF 6779 Z** Submit By : **Carmen Lim**
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2016**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER,BONNET,SUPPORT PANEL, LHF FENDER,RHF FENDER,RHF DOOR,REAR BUMPER, TAILDOOR,END PANEL,SPARE TYRE WELL PANEL,RHR FENDER)	\$2,400.00	1800
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER,BONNET,SUPPORT PANEL, LHF FENDER,RHF FENDER,RHF DOOR,REAR BUMPER, TAILDOOR,END PANEL,SPARE TYRE WELL PANEL,RHR FENDER)	\$2,400.00	1800
3	To check wiring & focus headlamp	\$50.00	40
4	To remove & refit reverse sensor	\$120.00	50
5	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	80
6	To remove & refit rear windscreen.	\$120.00	✓
7	To tuff coat.	\$300.00	120
8	To transfer boot mechanism to new boot	\$120.00	60
9	Towing	\$60.00	50

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Labour

Vehicle No. : **SLF 6779 Z**

Submit By : Carmen Lim

Make & Model : TOYOTA PRIUS

Year of Manufacture : 2016

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.