



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLF 6779 Z

Parts	(a) Cost / List Price Items	\$ 36,596.58
	Plus/Less 25%	\$ 9,149.15
	Total of Cost / List	\$ 27,447.44
	(b) Nett Price Items	
	Less	
	Total of Nett Item	
	(c) Special Nett Items	\$ 340.00
Total Parts Cost		\$ 27,787.44
Labour		\$ 6,260.00
Total		\$ 34,047.44

The above total will be subjected to 7% G.S.T.

Name of Surveyor : _____
Company : _____
Survey conducted on : _____ at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLF 6779 Z**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU203531780**

Submit By : **Carmen Lim**
Year Manufacture : **2016**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate	1	\$45.00	S.N	
2	Front number plate garnish	1	\$129.00		
3	Bonnet	1	\$812.40		
4	Bonnet lock	1	\$130.00		
5	Bonnet hinge LH	1	\$57.80		
6	Bonnet hinge RH	1	\$57.80		
7	Bonnet heat insulator	1	\$440.12		
8	Bonnet heat insulator clip	10	\$35.00		
9	Front support panel centre	1	\$338.50		
10	Front support panel LH	1	\$213.50		
11	Front support panel RH	1	\$213.50		
12	Headlamp panel LH	1	\$89.20		
13	Headlamp panel RH	1	\$89.20		
14	Support panel lower	1	\$387.95		
15	Front support panel top garnish	1	\$285.40		
16	Front support panel top garnish clip	10	\$35.00		
17	Air duct	1	\$195.40		
18	Air duct - inlet	1	\$109.75		
19	Brace panel	1	\$105.20		
20	Condenser	1	\$1,544.70		
21	Radiator	1	\$1,841.80		
22	Radiator fan motor RH	1	\$455.70		
23	Radiator fan motor LH	1	\$491.79		

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SLF 6779 Z**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU203531780**

Submit By : **Carmen Lim**
Year Manufacture : **2016**
Engine No. : _____

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Radiator fan blade LH	1	\$197.80		
25	Radiator fan blade RH	1	\$219.80		
26	Radiator fan cowling	1	\$287.67		
27	Radiator top hose	1	\$49.80		
28	Radiator bottom hose	1	\$46.95		
29	Radiator spare tank	1	\$186.70		
30	Headlamp LH	1	\$2,531.60		
31	Headlamp RH	1	\$2,531.60		
32	Headlamp ballast LH	1	\$551.97		
33	Headlamp ballast LH	1	\$551.97		
34	Front bumper	1	\$450.80		
35	Front bumper clip	10	\$40.00		
36	Front bumper reinforcement - upper	1	\$711.50		
37	Front bumper reinforcement - lower	1	\$245.30		
38	Front bumper side retainer RH	1	\$107.20		
39	Front bumper side retainer LH	1	\$107.20		
40	Front bumper upper grille	1	\$321.90		
41	Front bumper lower grille	1	\$148.60		
42	Front bumper emblem	1	\$87.10		
43	Front bumper tow cover RH	1	\$25.70		
44	Front bumper tow cover LH	1	\$25.70		
45	Front bumper sponge - upper	1	\$89.81		
46	Front bumper sponge - lower	1	\$135.70		

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SLF 6779 Z**

Make & Model : **TOYOTA PRIUS**

Chassis No : **JTDKB3FU203531780**

Submit By : **Carmen Lim**

Year Manufacture : **2016**

Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
47	Fog lamp LH	1	\$910.70		
48	Fog lamp RH	1	\$910.70		
49	Engine under cover	1	\$198.30		
50	Engine under cover clip	10	\$35.00		
51	Air cleaner box	1	\$967.80		
52	Washer tank	1	\$195.60		
53	Washer tank motor	1	\$196.74		
54	RH front fender	1	\$868.70		
55	RH front fender undershield	1	\$185.64		
56	RH front fender undershield clip	10	\$25.00		
57	RHF fender wording "HYBRID"	1	\$44.17		
58	RH front fender quarter garnish	1	\$122.70		
59	LH front fender	1	\$868.70		
60	LH front fender undershield	1	\$195.60		
61	LH front fender undershield clip	10	\$25.00		
62	LHF fender wording "HYBRID"	1	\$44.17		
63	Rear windscreen moulding	1	\$97.70		
64	Rear windscreen sealant	1	\$50.00		
65	Rear windscreen moulding	1	\$97.70		
66	Rear windscreen sealant	1	\$50.00		
67	Rear number plate	1	\$45.00	S.N	
68	Reverse sensor	1	\$200.00	S.N	
69	Rear bumper	1	\$497.50		

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SLF 6779 Z**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU203531780**

Submit By : **Carmen Lim**
Year Manufacture : **2016**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
70	Rear bumper clip	10	\$40.00		
71	Rear bumper side retainer LH	1	\$112.70		
72	Rear bumper side retainer RH	1	\$112.70		
73	Rear bumper reinforcement	1	\$398.90		
74	Rear bumper lower garnish centre	1	\$582.60		
75	Rear bumper lower garnish LH	1	\$149.70		
76	Rear bumper lower garnish RH	1	\$149.70		
77	Rear bumper tow cover	1	\$31.70		
78	Rear bumper under cover	1	\$355.20		
79	Rear bumper under cover LH	1	\$187.60		
80	Rear bumper under cover RH	1	\$187.60		
81	Rear bumper under cover clip	4	\$14.00		
82	Tail door	1	\$1,122.50		
83	Tail door lock	1	\$487.70		
84	Tail door emblem	1	\$61.70		
85	Wording "PRIUS"	1	\$51.90		
86	Wording "HYBRID"	1	\$55.47		
87	Tail door hinge LH	1	\$87.60		
88	Tail door hinge RH	1	\$87.60		
89	Tail door plate garnish	1	\$782.50		
90	Tail door inner trim	1	\$278.90		
91	Tail door inner trim clip	10	\$28.00		
92	Taildoor spoiler	1	\$1,567.83		

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SLF 6779 Z**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU203531780**

Submit By : **Carmen Lim**
Year Manufacture : **2016**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
93	Tail end panel	1	\$596.60		
94	Tail end panel garnish	1	\$151.60		
95	Tail end panel garnish clip	10	\$35.00		
96	Boot weatherstrip	1	\$353.10		
97	Spare tyre well panel	1	\$793.15		
98	Spare tyre board	1	\$566.79		
99	Spare tyre compartment sponge LH	1	\$297.67		
100	Spare tyre compartment sponge RH	1	\$297.67		
101	Spare tyre compartment centre	1	\$251.70		
102	Tail lamp LH - UPPER	1	\$498.75		
103	Tail lamp RH - UPPER	1	\$498.75		
104	Tail lamp LH - LOWER	1	\$511.60		
105	Tail lamp RH - LOWER	1	\$511.60		
106	Taildoor glass sealant	1	\$50.00	S.N	
107					
108					
109					
110					
111					
112					
113					
114					
115					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

> Back to OneMotoring



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 15 Mar 2019 / 09:31:29

Receipt Date/Time : 15 Mar 2019 / 09:31:29

Tax Invoice/Receipt

Receipt No. : ITNET-00000-190315-000497

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SJJ5347X As at 14 Mar 2019/07:49:00 Insurance Co: AXA INSURANCE PTE LTD				
1	Insurance Enquiry - SJJ5347X Enquiry Fee 20190315092859110203	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxx5823	Credit Card: Visa/MasterCard		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.