

AXA

Kh



ESTEE PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLF 6779 Z

Parts	(a) Cost / List Price Items	\$ 36,596.58
	Plus/Less 25%	\$ 9,149.15
	Total of Cost / List	\$ 27,447.44
	(b) Nett Price Items	
	Less	
	Total of Nett Item	
	(c) Special Nett Items	\$ 340.00
Total Parts Cost		\$ 27,787.44
Labour		\$ 6,260.00
Total		\$ 34,047.44

Finalised

18764.70

4691.18

14073.52

Not Withheld
1.31
Penny Bepaint

37K

14398.52

3650

18048.52 ✓ ok

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Kenneth

Company

LKL

Survey conducted on

18/3/19

at

12:30

Remarks By Surveyor

(a) The repair of this vehicle is ☒ authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 12 day(s)

(c) Resurvey : Required / ☒ Not Required

(d) Excess : \$

(e) Signature of surveyor

Lc

Date:

18/3/19



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLF 6779 Z
Make & Model : TOYOTA PRIUS
Chassis No : JTDKB3FU203531780

Submit By : Carmen Lim
Year Manufacture : 2016
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate	1	\$45.00	S.N	✓
2	Front number plate garnish	1	\$129.00	✓	✓
3	Bonnet	1	\$812.40	✓	✓
4	Bonnet lock	1	\$130.00	✓	✓
5	Bonnet hinge LH	1	\$57.80		✗
6	Bonnet hinge RH	1	\$57.80		✗
7	Bonnet heat insulator	1	\$440.12		✗
8	Bonnet heat insulator clip	10	\$35.00		✗
9	Front support panel centre	1	\$338.50	✓	✓
10	Front support panel LH	1	\$213.50	✓	②
11	Front support panel RH	1	\$213.50	✓	②
12	Headlamp panel LH	1	\$89.20		✗
13	Headlamp panel RH	1	\$89.20		✗
14	Support panel lower	1	\$387.95		✗
15	Front support panel top garnish	1	\$285.40	✓	✓
16	Front support panel top garnish clip	10	\$35.00	✓	✓
17	Air duct	1	\$195.40	✓	✓
18	Air duct - inlet NO.2 17752-37120	1	\$109.75	✓	②
19	Brace panel	1	\$105.20	✓	✓
20	Condenser	1	\$1,544.70		✗
21	Radiator	1	\$1,841.80		✗
22	Radiator fan motor RH	1	\$455.70		✗
23	Radiator fan motor LH	1	\$491.79		✗

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

2567.65
SN: 45

Spare Parts

Vehicle No. :

Make & Model :

Chassis No. :

SLF 6779 Z

TOYOTA PRIUS

JTDKB3FU203531780

Submit By :

Year Manufacture :

Engine No. :

Carmen Lim

2016

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Radiator fan blade LH <i>SL</i>	1	\$197.80		<i>?</i>
25	Radiator fan blade RH <i>SL</i>	1	\$219.80		<i>?</i>
26	Radiator fan cowling <i>SL</i>	1	\$287.67		<i>?</i> <i>SL</i>
27	Radiator top hose <i>SL</i>	1	\$49.80		<i>?</i>
28	Radiator bottom hose <i>SL</i>	1	\$46.95		<i>?</i>
29	Radiator spare tank <i>SL</i>	1	\$186.70		<i>?</i>
30	Headlamp LH <i>SL</i>	1	\$2,531.60		<i>?</i>
31	Headlamp RH <i>SL</i>	1	\$2,531.60		<i>?</i>
32	Headlamp ballast LH <i>SL</i>	1	\$551.97		<i>?</i>
33	Headlamp ballast LH <i>SL</i>	1	\$551.97		<i>?</i>
34	Front bumper <i>SL</i>	1	\$450.80		<i>?</i>
35	Front bumper clip <i>SL</i>	10	\$40.00		<i>?</i>
36	Front bumper reinforcement - upper <i>SL</i>	1	\$711.50		<i>?</i>
37	Front bumper reinforcement - lower <i>SL</i>	1	\$245.30		<i>?</i>
38	Front bumper side retainer RH <i>SL</i>	1	\$107.20		<i>?</i>
39	Front bumper side retainer LH <i>SL</i>	1	\$107.20		<i>?</i>
40	Front bumper upper grille <i>SL</i>	1	\$321.90		<i>?</i>
41	Front bumper lower grille <i>SL</i>	1	\$148.60		<i>?</i>
42	Front bumper emblem <i>SL</i>	1	\$87.10		<i>?</i>
43	Front bumper tow cover RH <i>SL</i>	1	\$25.70		<i>?</i>
44	Front bumper tow cover LH <i>SL</i>	1	\$25.70		<i>?</i>
45	Front bumper sponge - upper <i>SL</i>	1	\$89.81		<i>?</i>
46	Front bumper sponge - lower	1	\$135.70		<i>?</i>

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

7424.01

Spare Parts

Vehicle No. :

Make & Model :

Chassis No. :

SLF 6779 Z

TOYOTA PRIUS

JTDKB3FU203531780

Submit By :

Year Manufacture :

Engine No. :

Cost / List

Carmen Lim

2016

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
47	Fog lamp LH <i>Sn</i>	1	\$910.70		<i>X</i>
48	Fog lamp RH <i>Sn</i>	1	\$910.70		<i>X</i>
49	Engine under cover <i>Sn</i>	1	\$198.30		<i>X</i>
50	Engine under cover clip <i>nn</i>	10	\$35.00		<i>X</i>
51	Air cleaner box <i>how old</i>	1	\$967.80	✓	✓
52	Washer tank <i>Sn</i>	1	\$195.60		<i>X</i>
53	Washer tank motor <i>Sn</i>	1	\$196.74		<i>X</i>
54	RH front fender <i>Bu</i>	1	\$868.70	✓	✓
55	RH front fender undershield <i>See</i>	1	\$185.64		<i>X</i>
56	RH front fender undershield clip <i>nn</i>	10	\$25.00		<i>X</i>
57	RHF fender wording "HYBRID" <i>nn</i>	1	\$44.17	✓	✓
58	RH front fender quarter garnish <i>Dry</i>	1	\$122.70	✓	✓
59	LH front fender <i>R</i>	1	\$868.70		<i>X</i>
60	LH front fender undershield <i>Sn</i>	1	\$195.60		<i>X</i>
61	LH front fender undershield clip <i>nn</i>	10	\$25.00		<i>X</i>
62	LHF fender wording "HYBRID" <i>nn</i>	1	\$44.17		✓
63	Rear windscreen moulding <i>nn</i>	1	\$97.70	✓	✓
64	Rear windscreen sealant <i>nn</i>	1	\$50.00		<i>405N</i>
65	Rear windscreen moulding <i>nn</i>	1	\$97.70	✓	✓
66	Rear windscreen sealant <i>Reporal</i>	1	\$50.00		<i>405N X</i>
67	Rear number plate <i>Sn</i>	1	\$45.00	S.N	<i>X</i>
68	Reverse sensor <i>nn</i>	1	\$200.00	S.N	✓
69	Rear bumper <i>Bu</i>	1	\$497.50	✓	✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

2896.27
SN: 240

Spare Parts

Vehicle No. :

Make & Model :

Chassis No. :

SLF 6779 Z

TOYOTA PRIUS

JTDKB3FU203531780

Submit By :

Year Manufacture :

Engine No. :

Carmen Lim

2016

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
70	Rear bumper clip	10	\$40.00	✓	✓
71	Rear bumper side retainer LH	1	\$112.70	✓	✓
72	Rear bumper side retainer RH	1	\$112.70	✓	✓
73	Rear bumper reinforcement	1	\$398.90	✓	✓
74	Rear bumper lower garnish centre	1	\$582.60	✓	✓
75	Rear bumper lower garnish LH	1	\$149.70	✓	X
76	Rear bumper lower garnish RH	1	\$149.70	✓	✓
77	Rear bumper tow cover	1	\$31.70	✓	✓
78	Rear bumper under cover	1	\$355.20	✓ - MISSING	✓
79	Rear bumper under cover LH	1	\$187.60	✓	X
80	Rear bumper under cover RH	1	\$187.60	✓	X
81	Rear bumper under cover clip	4	\$14.00	✓	X
82	Tail door	1	\$1,122.50	✓	✓
83	Tail door lock	1	\$487.70	✓	✓
84	Tail door emblem	1	\$61.70	✓	✓
85	Wording "PRIUS"	1	\$51.90	✓	✓
86	Wording "HYBRID"	1	\$55.47	✓	✓
87	Tail door hinge LH	1	\$87.60	✓	X
88	Tail door hinge RH	1	\$87.60	✓	X
89	Tail door plate garnish	1	\$782.50	✓	✓
90	Tail door inner trim	1	\$278.90	✓	X
91	Tail door inner trim clip	10	\$28.00	✓	X
92	Taildoor spoiler	1	\$1,567.83	✓	X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

4345.27

Spare Parts

Vehicle No. :

SLF 6779 Z

Make & Model :

TOYOTA PRIUS

Chassis No. :

JTDKB3FU203531780

Submit By :

Carmen Lim

Year Manufacture :

2016

Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
93	Tail end panel <i>Rh</i>	1	\$596.60	✓	✓
94	Tail end panel garnish <i>Sn</i>	1	\$151.60		✗
95	Tail end panel garnish clip <i>na</i>	10	\$35.00		✗
96	Boot weatherstrip <i>Sn</i>	1	\$353.10		✗
97	Spare tyre well panel <i>Rh</i>	1	\$793.15		✗
98	Spare tyre board <i>Sn</i>	1	\$566.79		✗
99	Spare tyre compartment sponge LH <i>Sn</i>	1	\$297.67		✗
100	Spare tyre compartment sponge RH <i>Sn</i>	1	\$297.67		✗
101	Spare tyre compartment centre <i>Sn</i>	1	\$251.70		✗
102	Tail lamp LH - UPPER <i>CRA</i>	1	\$498.75	✓	✓
103	Tail lamp RH - UPPER <i>CM</i>	1	\$498.75	✓	✓
104	Tail lamp LH - LOWER <i>Sn</i>	1	\$511.60		✗
105	Tail lamp RH - LOWER <i>Sn</i>	1	\$511.60		✗
106	Taildoor glass sealant <i>na</i>	1	\$50.00	S.N	<i>403N</i>
107					
108					
109					
110					
111					
112					
113					
114					
115					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

1594-10
SN: 40

ESTEEM PERFORMANCE PTE LTD

BLK 5033 ANG MO KIO INDUSTRIAL PARK 2

#01-259 SINGAPORE 569536

Tel:64841221 Fax:64847829

Spare Parts

Vehicle No. :
Make & Model :
Chassis No. :

SLF 6779 Z

TOYOTA PRIUS

JTDKB3FU203531780

Submit By :
Year Manufacture :
Engine No. :
Cost / List

CARMEN LIM

2016

Supplementary

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Radiator Side Guide LH <i>CRA</i>	1	\$68.70		✓
2	Radiator Side Guide RH <i>Dry</i>	1	\$68.70		✓
3					
4					
5					
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

137.40



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6494 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLF 6779 Z** Submit By : **Carmen Lim**
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2018**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER,BONNET,SUPPORT PANEL, LHF FENDER,RHF FENDER,RHF DOOR,REAR BUMPER, TAILDOOR,END PANEL,SPARE TYRE WELL PANEL,RHR FENDER)	\$2,400.00	1400
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER,BONNET,SUPPORT PANEL, LHF FENDER,RHF FENDER,RHF DOOR,REAR BUMPER, TAILDOOR,END PANEL,SPARE TYRE WELL PANEL,RHR FENDER)	\$2,400.00	1800
3	To check wiring & focus headlamp	\$50.00	40
4	To remove & refit reverse sensor	\$120.00	50
5	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	80
6	To remove & refit rear windscreen.	\$120.00	✓
7	To tuff coat.	\$300.00	120
8	To transfer boot mechanism to new boot	\$120.00	60
9	Towing	\$60.00	30

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Vehicle No. : SLF 6779 Z
Make & Model : TOYOTA PRIUS

Submit By : Carmen Lim
Year of Manufacture : 2016

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.