



Cecilia

Case Details

Case Reference Number : TAX/03/19/2070
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHC4210Z

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-6126-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AXA Insurance Singapore Pte Ltd
 Accident Date and Time : 15/03/2019 02:05 PM
 Vehicle Age(In Months) : 64

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace	DEF /
One Time Key In	Main			BUMPER SIDE RETAINER RRLH	1	94.80	94.80	25.00	71.10	Replace	0	0	Check	X NAI
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Check	X NAI
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check	X NAI
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check	X NAI
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check	X NAI
One Time Key In	Main			BUMPER LIP COVER RRLH	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Giv	X un
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Check	X NAI

Total Spare Part Cost 4,888.23

Surveyor Total 815.63

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 3,910.58

Final Sur Total 652.50

SMHT Recommendation

BOM Type	Coasting Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	1	171.68	Replace	SCR
One Time Key In	Main			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0	Check	X NM
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	0	0	Check	X NM
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Check	X NM
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace	shorted
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	rec
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	1	0	Repair	Repair X
One Time Key In	Main			TAILGATE OUTSIDE GARNISH	1	504.90	504.90	25.00	378.67	Replace	0	0	Not Give	X nm
One Time Key In	Main			STICKER SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give	X nm
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give	X nm
One Time Key In	Main			EMBLEM REAR	1	60.30	60.30	25.00	45.22	Replace	0	0	Not Give	X nm
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	0	0	Not Give	X nm
One Time Key In	Main			NAME PLATE (PRIUS)	1	60.80	60.80	25.00	45.60	Replace	0	0	Not Give	X nm
One Time Key In	Main			NAME PLATE (TOYOTA)	1	49.40	49.40	25.00	37.05	Replace	0	0	Not Give	X nm

Total Spare Part Cost	4,888.23	Surveyor Total	815.63
Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	20
Final Spare Part Cost	3,910.58	Final Sur Total	652.50

SMRT Recommendation											Surveyor Approval			Remarks
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			TAIL LAMP BRACKET, LH	1	30.70	30.70	25.00	23.02	Replace	0	0	Check	X M11
One Time Key In	Main			TAIL LAMP BRACKET, RH	1	30.70	30.70	25.00	23.02	Replace	0	0	Check	X M11
One Time Key In	Main			TAIL LAMP LH	1	548.40	548.40	10.00	493.56	Replace	0	0	Check	X M11
One Time Key In	Main			TAIL LAMP RH	1	557.80	557.80	10.00	502.02	Replace	0	0	Check	X M11
One Time Key In	Main			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	29.40	25.00	22.05	Replace	0	0	Not Give	X M11
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	29.40	25.00	22.05	Replace	0	0	Not Give	X M11
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	29.40	25.00	22.05	Replace	0	0	Not Give	X M11
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	0	0	Not Give	X M11
Total Spare Part Cost									4,888.23	Surveyor Total		815.63		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									3,910.58	Final Sur Total		652.50		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	1,014.00	400 /	
Total:			1,014.00	400.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200 /	
2	Main	TO RESPRAY REAR PANEL	180.00	0	
Total:			1,116.00	400.00	

V19/2019

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
3	Main	TO RESPRAY TAIL GATE	378.00	200	
4	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0	
Total:			1,116.00	400.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	APC
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0	
3	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	APC
4	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0	
5	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	40	APC
6	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	0	
7	Main	TO REMOVE / REFIT WINDSCREEN	120.00	0	
8	Main	TO WASH AND VACUUM	60.00	0	
9	Main	TO REPLACE SUNDRY PARTS	100.00	0	
Total:			1,040.00	80.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	3,910.58	652.50
Total Labour Cost	1,014.00	400.00
Total Spray Painting	1,116.00	400.00
Other	1,040.00	80.00
Overall Total	7,080.58	1,532.50
Lump Sum Repair Option	-	-
Lump Sum Total	7,100.00	1,550.00

2019

Estimator Assessment(\$)

Surveyor Assessment(\$)

Surveyor Approved Amount

1,550.00

No of Repair Days*

6

4

Remarks

L/S REPAIR, PHOTO AFTER PAINT.

Surveyor Name

Hwee Jie

Signature



Save Clear

Survey Date

19/03/2019

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Contractor	WEGA ENGINEERING PTE LTD		
Accident Case Number	7AX/03/19/2070	Date of Collection	20/3/19
Vehicle No	SHC 4210 Z	Date of Request	20/3/19
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend	17 DAYS

REQUEST FOR SUPPLYMENT PARTS

S/N	Number photos	Part Description	Quantity	Unit Price
1	8286, 87, 193, 194 8295	Arm Sub Assy RR Bumper LH		#139.60 ✓
2	8288, 89, 196, 197	Arm Sub Assy RR Bumper RH		#139.60 ✓
3	8280, 81, 82, 183 8284, 185	Bumper Reinforcement Rear		#205.70 ✓
4	8290, 91, 92	To Repair End Panel		#250.00
5		To Respray End Panel		#150.00
6				
7				
8				

BT 104.70
BT 104.70
DD 154.28
#100
#100

<<<Please submit photographs for damaged parts>>>

21/3/19

I, (Name) CHIA

(Position) ADVISOR

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Chia
.....
Signature of person making this declaration

Signature of person making this declaration



[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff

Section A - Accident Details	
Registration Number	SHC4210Z
Case Reference Number	TAX/03/19/2070
Registration Date	29/11/2013
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	CHAN CHIN TIONG
Type of Accident	Head to Rear
Accident Date and Time	15/3/2019 10:05 PM
Accident Reported Date and Time	16/3/2019 8:46 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24100642
Special Instruction to ARC, if any	TSS
Prepared Date and Time	18/3/2019 1:19 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Toyota

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,264.00	\$500.00
Total Spray Cost	\$1,296.00	\$500.00
Total Spare Part Cost	\$4,201.52	\$943.45
Total Other Cost	\$1,040.00	\$80.00
TOTAL COST	\$7,801.52	\$2,023.45
Lump Sum Total	\$7,350.00	\$2,000.00 (L/S)
Number of Repair Days	7.0	5.0
Prepared / Adjusted By	Kim Ming Chin	Hwee Jie (LKK) / AXA
ARC / Surveyor Sign Off Date	19/03/2019 3:30 PM	19/03/2019 1:32 PM
Signature		
Remarks		L/S REPAIR, PHOTO AFTER PAINT.



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 60 Woodlands Industrial Park E4, Singapore 757705
 FAX Number 63665692
 Estimator Telephone Number 68692623
 Accident Reporting Number 66662672

Date Generated : 14/09/2019
 User ID : PehSuen

Section C - Quotation and Accident Invoice Details			
Quotation Number	QN-1908-0141	Invoice Number	
Quotation Date	13.08.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates		
Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$1,014.00	\$400.00
TO REPAIR RR END PANEL	\$250.00	\$100.00
Total Labour	\$1,264.00	\$500.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR PANEL	\$180.00	\$100.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,296.00	\$500.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	\$120.00	\$40.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$0.00
TO REMOVE / REFIT WINDSCREEN	\$120.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$1,040.00	\$80.00

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace
		52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Check X
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Check X
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check X
		52015-47050	ARM SUB-ASSY, RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Check X
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check X
		76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given X



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
35 Woodlands Industrial Park EA, Singapore 757705
FAX Number: 63685582
Estimator Telephone Number: 68652623
Accident Reporting Number: 68962672

Date Generated: 14/08/2019
User ID: PuhDuan

Main repair estimate table with columns for Part Number, Portion, Stock Number, Part Name, Quantity, List Price \$, Discount (%), Final Price (\$), ARC Check, and Surveyor Check. Includes items like BUMPER LIP COVER, BUMPER LIP REAR, UNDER COVER SUB-ASSY, etc.

Added Spare Parts / Material Usage After Surveyor Signed off

Table for added spare parts with columns: Part Number, Portion, Stock Number, Part Name, Quantity, List Price \$, Discount (%), Final Price (\$), ARC Check, Surveyor Check. Includes items like ARM SUB-ASSY, BUMPER LH, BUMPER RH, BUMPER REINFORCEMENT REAR.

Handwritten calculations: 1179.31 - 202 = 943.45 + 500.00 + 580.00 = 2023.45. Note: L/S \$2000/-