



## Case Details

Case Reference Number :

TAX/03/19/2070

Type of Repair : Accident Repair

Vehicle Registration Number :

SHC4210Z

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-6126-ID

Assigned By : Taxi Claims Manager  
TeamInsurance Company Name : AXA Insurance Singapore Pte  
Ltd

Accident Date and Time : 15/03/2019 02:05 PM

Vehicle Age(In Months) : 64

## Documents / Photographs

View Documents / Photographs

Total Documents: 1

## Estimation Details

### Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				Remarks
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.9	Replace ▾	DEF
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	0	0	Check ▾	
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Check ▾	
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check ▾	
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check ▾	
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check ▾	
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give ▾	un
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Check ▾	

Total Spare Part Cost 4,888.23

Surveyor Total 815.63

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 3,910.58

Final Sur Total 652.50

SMRT Recommendation											Surveyor Approval			Remarks
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	1	171.6	Replace	SCR
One Time Key In	Main			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0	Check	
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	0	0	Check	
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Check	
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.0	Replace	shorted
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.0	Replace	nee
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	1	0	Repair	Repair
One Time Key In	Main			TAILGATE OUTSIDE GARNISH	1	504.90	504.90	25.00	378.67	Replace	0	0	Not Give	nu
One Time Key In	Main			STICKER SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give	nu
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give	nu
One Time Key In	Main			EMBLEM REAR	1	60.30	60.30	25.00	45.22	Replace	0	0	Not Give	nu
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	0	0	Not Give	nu
One Time Key In	Main			NAME PLATE (PRIUS)	1	60.80	60.80	25.00	45.60	Replace	0	0	Not Give	nu
One Time Key In	Main			NAME PLATE (TOYOTA)	1	49.40	49.40	25.00	37.05	Replace	0	0	Not Give	nu

Total Spare Part Cost	4,888.23	Surveyor Total	815.63
Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	20
Final Spare Part Cost	3,910.58	Final Sur Total	652.50

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TAIL LAMP BRACKET, LH	1	30.70	30.70	25.00	23.02	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	Check	
One Time Key In	Main			TAIL LAMP BRACKET, RH	1	30.70	30.70	25.00	23.02	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	Check	
One Time Key In	Main			TAIL LAMP LH	1	548.40	548.40	10.00	493.56	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	Check	
One Time Key In	Main			TAIL LAMP RH	1	557.80	557.80	10.00	502.02	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	Check	
One Time Key In	Main			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	29.40	25.00	22.05	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	Not Give	
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	29.40	25.00	22.05	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	Not Give	
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	29.40	25.00	22.05	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	Not Give	
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	Not Give	
<b>Total Spare Part Cost</b>									<b>4,888.23</b>		<b>Surveyor Total</b>		<b>815.63</b>	
<b>Lump Sum Discount (%)</b>									<b>20.00</b>		<b>Lump Sum Dis (%)</b>		<input type="text" value="20"/>	
<b>Final Spare Part Cost</b>									<b>3,910.58</b>		<b>Final Sur Total</b>		<b>652.50</b>	

**Labour's Cost Detail**

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	<input type="text" value="1,014.00"/>	<input type="text" value="400"/>	
<b>Total:</b>			<b>1,014.00</b>	<b>400.00</b>	

**Spray Cost Detail**

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	<input type="text" value="378.00"/>	<input type="text" value="200"/>	
2	Main	TO RESPRAY REAR PANEL	<input type="text" value="180.00"/>	<input type="text" value="0"/>	
<b>Total:</b>			<b>1,116.00</b>	<b>400.00</b>	

1/19/2019

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
3	Main	TO RESPRAY TAIL GATE	378.00	200	
4	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0	
<b>Total:</b>			<b>1,116.00</b>	<b>400.00</b>	

**Other Cost Detail**

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0	
3	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	
4	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0	
5	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	40	
6	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	0	
7	Main	TO REMOVE / REFIT WINDSCREEN	120.00	0	
8	Main	TO WASH AND VACUUM	60.00	0	
9	Main	TO REPLACE SUNDRY PARTS	100.00	0	
<b>Total:</b>			<b>1,040.00</b>	<b>80.00</b>	

**Summary**

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	3,910.58	652.50
Total Labour Cost	1,014.00	400.00
Total Spray Painting	1,116.00	400.00
Other	1,040.00	80.00
Overall Total	7,080.58	1,532.50
Lump Sum Repair Option	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	7,100.00	1,550.00

2019

Estimator Assesment(\$)		Surveyor Assesment(\$)	1,550.00
Surveyor Approved Amount			
No of Repair Days*	6		4
Remarks	-		L/S REPAIR, PHOTO AFTER PAINT.
Surveyor Name			Hwee jie
Signature			
		<input type="button" value="Save"/> <input type="button" value="Clear"/>	
Survey Date	19/03/2019		

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	7AX/03/19/2070	Date of Collection	20/3/19
Vehicle No	SHC 4210 Z	Date of Request	20/3/19
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend	17 DAYS

**REQUEST FOR SUPPLYMENT PARTS**

S/N	Number photos	Part Description	Quantity	Unit Price	
1	8286, 87, 93, 94 8295	Arm Sub Assy RR Bumper LH		\$139.60	BT
2	8288, 89, 96, 97	Arm Sub Assy RR Bump RH		\$139.60	BT
3	8280, 81, 82, 83 8284, 85	Bumper Reinforcement Rear		\$205.70	DD
4	8290, 91, 92	To Repair End Panel		<del>\$250.00</del>	\$100
5		To Respray End Panel		<del>\$150.00</del>	\$100
6					
7					
8					

<<<Please submit photographs for damaged parts>>>

21/3/19

I. (Name) CHIA

(Position) ADVISOR

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

*Chia*

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff