

F-1 AUTOCLINIC PTE LTD

Block 25 Kaki Bukit Road 4, #05-26 Synergy @ KB Singapore 417800
 HP: 96583371 TEL: (65) 67022915 FAX: 67022916

13th MARCH 2019

KOH HEE KEEN
 Bk 25 Kaki Bukit Rd 4
 # 05-26 SYNERGY @KB
 Singapore 417800

TPEQ.
 VIC

Accident date: 27th February 2019
 Estimated repair cost for vehicle no: SKR7426J HONDA STREAM 1.8 A

S/n	Qty	Items	U/price	Amount
				\$977.00 +
1	1	Front bumper <i>Rep</i>		\$96.80 +
2	2	Front bumper side bracket <i>new</i>	\$48.40	\$255.00 +
3	1	Front bumper fog lamp-LH <i>2 NP</i>		\$155.00 +
4	1	Front Bumper fog lamp cover - LH <i>new</i>	\$5.00	\$50.00 30
5	10	Front bumper clips <i>new</i>		\$320.20 +
6	1	Front bumper reinforcement <i>new</i>		\$752.00 ✓
7	2	Front head lamp-LH <i>ut</i>		\$53.20 x
8	1	Front head lamp lower bracket <i>new</i>		\$532.00 +
9	1	Front L/H fender <i>Rep</i>		\$176.00 ✓
10	1	Front L/H fender cowling <i>Deband</i>		\$50.00 30
11	10	Front L/H fender cowling clips <i>new</i>	\$5.00	\$155.00 +
12	1	Front mud shield-LH <i>new</i>	\$5.00	\$20.00 +
13	4	Front mud shield clips <i>new</i>		\$806.90 x
14	1	Front sport rim - LH <i>new</i>		\$350.00 +
15	1	Front tyre - LH <i>new</i>		\$490.80 +
16	1	Front shock absorber - LH <i>new</i>		\$315.50 +
17	1	Front lower arm - LH <i>new</i>		\$257.00 +
18	1	Front knuckle arm - LH <i>new</i>		\$130.30 +
19	1	Front wheel bearing - LH		

Subtotal :- \$5,942.70

988

79040

Labour charges

To Check Wiring System

\$60.00 30

To remove & re-fix front undercarriage

\$250.00 +

WHEEL alignment (computer)

\$120.00 +

Tuff kote

630

\$120.00 +

Panel beating

\$800.00 210

Spray painting

\$800.00 400

Subtotal :- \$2,150.00

Total:- \$8,092.70

Total: 1420.40

4/5: 1.1K.5

03 Pays.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: