

Steve


REF:

ASSIGNMENT

From _____ Date: _____
 Estimated Cost _____
 QD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: _____
 of _____
 Insured _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 14 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SDS 1666 A Vi Regn: 24/10/12
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or
 Make: Bentley Continental
 Colour: Black A/C Insured / Std / NI / NA
 Sp. Reading: 37547 T/Rvlin: Insured / Std / NI / NA

Eng/No: _____
 C/No: SCBFE 63W 9D C 082090

Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/35 ZR 21
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Firelli

Front		Rear
R/Bal. 7 mm		R/Bal. 7 mm
L/Bal. 7 mm		L/Bal. 7 mm
D.O.A. 7/3/18		D.O.A. 14/3/19

Survey held at Chuan Ho

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

HS \$ 113,000.00 (Real) \$ 22,000 / 41%.

Date/Time: File Pass to?

☐ : Prel. Report
☐ : Final Report

41

Date/Time: File Return to?

21

Report Format :

Lump Sum / I.B.F. (\$) :

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation

) 2 + R.T. 21

) Phone

) Index

)

2014

CHUAN HO AUTO SERVICE

SIN MING AUTO CITY

160 SIN MING DRIVE #07-09

SINGAPORE 575722

Steve (LXX) wil papu
14 repair Days ? 14 days

ESTIMATE : SDS 1666 A

Vehicle & Document Information

Date: 27/03/2019

Vehicle No: SDS 1666 A

Make/Model: BENTLEY CONTINENTAL

S/N	Description	Qty	Repairer's Est	Revised Est
1	HEADLAMP LH / OR	1	\$ 13,356.00	\$ 9,600 / 13,356.00
2	HEADLAMP RH / OR	1	\$ 13,356.00	\$ 7,600 / 13,356.00
3	FRONT RE-INFORCEMENT BAR / DD	1	\$ 2,912.00	\$ 2,912.00
4	FRONT BUMPER / OR	1	\$ 8,792.00	\$ 8,792.00
5	FRONT BUMPER SIDE BRACKET LH / OR	1	\$ 252.00	\$ 252.00
6	FRONT BUMPER SIDE BRACKET RH / OR	1	\$ 252.00	\$ 252.00
7	FRONT BUMPER BRACKET OUTER LH / OR	1	\$ 112.00	\$ 112.00
8	FRONT BUMPER BRACKET OUTER RH / OR	1	\$ 112.00	\$ 112.00
9	FRONT BUMPER BRACKET INNER LH / OR	1	\$ 308.00	\$ 308.00
10	FRONT BUMPER BRACKET INNER RH / OR	1	\$ 308.00	\$ 308.00
11	FRONT BUMPER LOWER GRILLE LH / OR (VT)	1	\$ 1,932.00	\$ 1,932.00
12	FRONT BUMPER LOWER GRILLE RH / OR	1	\$ 1,932.00	\$ 1,932.00
13	FRONT BUMPER LOWER GRILLE LH (SMALL) / CMT	1	\$ 1,092.00	\$ 1,092.00
14	FRONT BUMPER LOWER GRILLE RH (SMALL) / CMT	1	\$ 1,092.00	\$ 1,092.00
15	FRONT BUMPER CLIPS / ORC	23	\$ 1,288.00	\$ 300 / 1,288.00
16	FRONT BUMPER CLIPS X NM	2	\$ 56.00	\$ 56.00 X
17	FRONT BUMPER CLIPS X NM	6	\$ 336.00	\$ 336.00 X
18	FRONT BUMPER CLIPS X NM	4	\$ 112.00	\$ 112.00 X
19	FRONT RADIATOR GRILLE BASE / OR	1	\$ 4,620.00	\$ 4,620.00
20	FRONT RADIATOR GRILLE TOP GARNISH / OR	1	\$ 336.00	\$ 336.00
21	FRONT RADIATOR GRILLE TOP GARNISH STRIP / CMT	1	\$ 280.00	\$ 280.00
22	FRONT RADIATOR GRILLE BRACKET LH / MIS	1	\$ 140.00	\$ 140.00
23	FRONT RADIATOR GRILLE BRACKET RH / MIS	1	\$ 140.00	\$ 140.00
24	FRONT RADIATOR GRILLE LOWER BRACKET LH / MIS	1	\$ 84.00	\$ 84.00
25	FRONT RADIATOR GRILLE LOWER BRACKET RH / MIS	1	\$ 84.00	\$ 84.00
26	FRONT RADIATOR GRILLE SEAL / MIS	1	\$ 336.00	\$ 336.00
27	FRONT RADIATOR GRILLE TRIM / MIS	1	\$ 2,156.00	\$ 2,156.00
28	FRONT RADIATOR GRILLE / OR	1	\$ 1,652.00	\$ 1,652.00
29	FRONT GRILLE BADGE (TOP) / MIS	1	\$ 168.00	\$ 168.00
30	FRONT GRILLE BADGE / MIS	1	\$ 1,232.00	\$ 1,232.00
31	FRONT GRILLE BADGE SEAL / MIS	1	\$ 140.00	\$ 140.00
32	FRONT RADIATOR GRILLE MIDDLE BRACKET LH / MIS	1	\$ 224.00	\$ 224.00
33	FRONT RADIATOR GRILLE MIDDLE BRACKET RH / MIS	1	\$ 224.00	\$ 224.00
34	FRONT RADIATOR GRILLE RIVET X NM	20	\$ 280.00	\$ 280.00 X
35	FRONT RADIATOR GRILLE RIVET X NM	12	\$ 336.00	\$ 336.00 X
36	FRONT RADIATOR GRILLE RIVET / ORC	16	\$ 896.00	\$ 200 / 896.00
37	FRONT RADIATOR GRILLE RIVET X NM	10	\$ 840.00	\$ 840.00 X
38	FRONT RADIATOR GRILLE RIVET X NM	10	\$ 560.00	\$ 560.00 X
39	FRONT RADIATOR GRILLE RIVET X NM	10	\$ 840.00	\$ 840.00 X
40	FRONT RADIATOR GRILLE SPACER X NM	2	\$ 280.00	\$ 280.00 X
41	FRONT RADIATOR GRILLE HEXAGON SOCKET X NM	10	\$ 840.00	\$ 840.00 X
42	FRONT RADIATOR GRILLE FOAM FILTER / OR	2	\$ 252.00	\$ 252.00

43	FRONT RADIATOR GRILLE CLIPS	X	NN	2	\$	504.00	\$	504.00	X
44	FRONT BONNET	X	R	1	\$	2,500.40	\$	2,500.40	X
45	FRONT BONNET SEAL	X	NN	1	\$	2,352.00	\$	2,352.00	X
46	FRONT FENDER LH	/	DD	1	\$	18,424.00	\$	16,698	18,424.00
47	FRONT FENDER RH	/	DD	1	\$	18,424.00	\$	16,698	18,424.00
48	FRONT HEADLAMP TRIM LH (BIG)	/	MEC	1	\$	420.00	\$	420.00	/
49	FRONT HEADLAMP TRIM RH (BIG)	/	MEC	1	\$	420.00	\$	420.00	/
50	FRONT HEADLAMP TRIM LH (SMALL)	/	MEC	1	\$	392.00	\$	392.00	/
51	FRONT HEADLAMP TRIM RH (SMALL)	/	MEC	1	\$	392.00	\$	392.00	/
52	FRONT FENDER BRACKET LH	X	NN	1	\$	420.00	\$	420.00	/
53	FRONT FENDER BRACKET RH	X	NN	1	\$	420.00	\$	420.00	X
54	FRONT FENDER TOP BRACKET LH (BIG)	X	NN	1	\$	42.00	\$	42.00	X
55	FRONT FENDER TOP BRACKET RH (BIG)	X	NN	1	\$	42.00	\$	42.00	X
56	FRONT FENDER TOP BRACKET LH (SMALL)	X	NN	1	\$	28.00	\$	28.00	X
57	FRONT FENDER TOP BRACKET RH (SMALL)	X	NN	1	\$	28.00	\$	28.00	X
58	FRONT FENDER CLIPS	X	NN	2	\$	448.00	\$	448.00	X
59	FRONT FENDER CLIPS	/	MEC	28	\$	3,136.00	\$	100	3,136.00
60	FRONT FENDER CLIPS	/	MEC	28	\$	2,352.00	\$	100	2,352.00
61	FRONT FENDER CLIPS	X	NN	4	\$	336.00	\$	336.00	X
62	FRONT FENDER CLIPS	X	NN	10	\$	840.00	\$	840.00	X
63	FRONT AIRGUIDE	X	NN	1	\$	140.00	\$	140.00	X
64	FRONT BUMPER SENSOR	X	NN	8	\$	28,000.00	\$	28,000.00	X
65	FRONT SUPPORT FRAME	X	NN	1	\$	11,088.00	\$	11,088.00	X
66	FRONT CROSS MEMBER	X	NN	1	\$	1,736.00	\$	1,736.00	X
67	FRONT GEARBOX SUPPORT	X	NN	1	\$	1,204.00	\$	1,204.00	X
68	FRONT SUPPORT PANEL SCREW / CLIPS / RIVET	X	NN	2	\$	560.00	\$	560.00	X
69	FRONT SUPPORT PANEL SCREW / CLIPS / RIVET	X	NN	2	\$	112.00	\$	112.00	X
70	FRONT SUPPORT PANEL SCREW / CLIPS / RIVET	X	NN	3	\$	168.00	\$	168.00	X
71	FRONT SUPPORT PANEL SCREW / CLIPS / RIVET	X	NN	1	\$	28.00	\$	28.00	X
72	FRONT SUPPORT PANEL SCREW / CLIPS / RIVET	X	NN	3	\$	84.00	\$	84.00	X
73	FRONT SUPPORT PANEL SCREW / CLIPS / RIVET	X	NN	4	\$	224.00	\$	224.00	X
74	FRONT SUPPORT PANEL SCREW / CLIPS / RIVET	X	NN	4	\$	224.00	\$	224.00	X
75	FRONT SUPPORT PANEL SCREW / CLIPS / RIVET	X	NN	4	\$	448.00	\$	448.00	X
76	FRONT SUPPORT PANEL SCREW / CLIPS / RIVET	X	NN	4	\$	1,008.00	\$	1,008.00	X
77	FRONT SUPPORT PANEL SCREW / CLIPS / RIVET	X	NN	3	\$	168.00	\$	168.00	X
78	REAR BUMPER UNDER COVER (BIG)	/	MEC	1	\$	1,288.00	\$	1,288.00	/
79	REAR BUMPER UNDER COVER LH	/	MEC	1	\$	868.00	\$	868.00	/
80	REAR BUMPER UNDER COVER RH	/	MEC	1	\$	868.00	\$	868.00	/
81	REAR BUMPER UNDER COVER BRACKET LH	/	MEC	1	\$	168.00	\$	168.00	/
82	REAR BUMPER UNDER COVER BRACKET RH	/	MEC	1	\$	168.00	\$	168.00	/
83	REAR BUMPER UNDER COVER SIDE BRACKET LH	/	MEC	1	\$	112.00	\$	112.00	/
84	REAR BUMPER UNDER COVER SIDE BRACKET RH	/	MEC	1	\$	112.00	\$	112.00	/
85	FRONT BUMPER UNDER COVER	X	NN	1	\$	2,660.00	\$	2,660.00	X
86	FRONT BUMPER UNDER COVER LH	X	NN	1	\$	252.00	\$	252.00	X
87	FRONT BUMPER UNDER COVER RH	X	NN	1	\$	280.00	\$	280.00	X
88	FRONT BUMPER UNDER COVER SUPPORT BRACKET	X	NN	1	\$	252.00	\$	252.00	X
89	BUMPER UNDER COVER CLIPS	X	NN	31	\$	868.00	\$	868.00	X
90	BUMPER UNDER COVER CLIPS	X	NN	2	\$	56.00	\$	56.00	X
91	BUMPER UNDER COVER CLIPS	X	NN	6	\$	336.00	\$	336.00	X
92	REAR WIRING SET	/	MEC	1	\$	588.00	\$	588.00	X
93	FRONT WIRING SET	X	NN	1	\$	364.00	\$	364.00	X
94	REAR BOOTLID REVERSE CAMERA	X	NN	1	\$	1,596.00	\$	1,596.00	X
95	REAR BOOTLID REVERSE CAMERA WIRING SET	X	NN	1	\$	420.00	\$	420.00	X
96	REAR BUMPER LAMP (Lower)	/	MEC	1	\$	5,880.00	\$	4,900	5,880.00
97	REAR BOOTLID	/	DD	1	\$	18,424.00	\$	15,650	18,424.00
98	REAR BOOTLID TOP LOCK	/	MEC	1	\$	1,512.00	\$	1,512.00	X

99	REAR BOOTLID LOCK	BT	1	\$	336.00	\$	336.00
100	REAR BOOTLID CLOSING ELEMENT	NN	1	\$	112.00	\$	112.00
101	REAR BOOTLID CLIPS / RIVET	MC	10	\$	280.00	\$	280.00
102	REAR BOOTLID LOCK FRAME	BT	1	\$	112.00	\$	112.00
103	REAR BOOTLID HANDLE SHELL	NN	1	\$	392.00	\$	392.00
104	REAR BOOTLID SEAL	CRH	1	\$	1,008.00	\$	1,008.00
105	REAR BOOTLID DAMPER	NN	2	\$	784.00	\$	784.00
106	REAR BOOTLID HEXAGON NUT	NN	3	\$	84.00	\$	84.00
107	REAR BOOTLID TRIM	DD	1	\$	532.00	\$	532.00
108	REAR BOOTLID REVERSE CAM GARNISH	NN	1	\$	168.00	\$	168.00
109	REAR BOOTLID LED LICENSE PLATE LAMP	NN	2	\$	1,008.00	\$	1,008.00
110	REAR BODY PANEL	DD	1	\$	12,796.00	\$	12,796.00
111	REAR BODY PANEL LH	X NN	1	\$	6,972.00	\$	6,972.00
112	REAR BODY PANEL RH	X NN	1	\$	6,972.00	\$	6,972.00
113	REAR BODY PANEL COVER LH	MTS	1	\$	196.00	\$	196.00
114	REAR BODY PANEL COVER RH	MTS	1	\$	196.00	\$	196.00
115	REAR SPARE WHEEL COMPARTMENT PANEL	OR	1	\$	2,016.00	\$	2,016.00
116	REAR FENDER LH	R	1	\$	19,264.00	\$	19,264.00
117	REAR FENDER RH	R	1	\$	19,264.00	\$	19,264.00
118	REAR FENDER PANEL	X R	1	\$	532.00	\$	532.00
119	REAR FENDER SOUND PANEL LH (BIG)	X NN	1	\$	252.00	\$	252.00
120	REAR FENDER SOUND PANEL RH (BIG)	X NN	1	\$	252.00	\$	252.00
121	REAR FENDER SOUND PANEL LH (SMALL)	X NN	1	\$	252.00	\$	252.00
122	REAR FENDER SOUND PANEL RH (SMALL)	X NN	1	\$	252.00	\$	252.00
123	REAR END PANEL	DD	1	\$	644.00	\$	644.00
124	REAR TAIL LAMP MOUNTING LH	X NN	1	\$	336.00	\$	336.00
125	REAR TAIL LAMP MOUNTING RH	X NN	1	\$	336.00	\$	336.00
126	REAR TAIL LAMP INNER BRACKET LH	X NN	1	\$	532.00	\$	532.00
127	REAR TAIL LAMP INNER BRACKET RH	X NN	1	\$	644.00	\$	644.00
128	REAR PANEL GARNISH LH	OR	1	\$	364.00	\$	364.00
129	REAR PANEL GARNISH RH	OR	1	\$	364.00	\$	364.00
130	REAR PANEL CENTER GARNISH	CRH	1	\$	420.00	\$	420.00
131	REAR PANEL SIDE GARNISH LH	NN	1	\$	1,316.00	\$	1,316.00
132	REAR PANEL SIDE GARNISH RH	NN	1	\$	1,316.00	\$	1,316.00
133	REAR HEAT SHIELD (UPPER)	MTS	1	\$	728.00	\$	728.00
134	REAR HEAT SHIELD (LOWER)	MTS	1	\$	196.00	\$	196.00
135	REAR HEAT SHIELD (CENTER)	MTS	1	\$	224.00	\$	224.00
136	REAR HEAT SHIELD CLIPS	MC	22	\$	1,848.00	\$	1,848.00
137	REAR SILENCER LH	DD	1	\$	5,964.00	\$	5,964.00
138	REAR SILENCER RH	DD	1	\$	5,964.00	\$	5,964.00
139	REAR EXHAUST TRIM LH	DD	1	\$	1,120.00	\$	1,120.00
140	REAR EXHAUST TRIM RH	MTS	1	\$	1,120.00	\$	1,120.00
141	REAR EXHAUST BRACKET LH	DD	1	\$	112.00	\$	112.00
142	REAR EXHAUST BRACKET RH	MTS	1	\$	84.00	\$	84.00
143	REAR EXHAUST SCREW	NN	4	\$	112.00	\$	112.00
144	REAR EXHAUST SCREW	NN	20	\$	2,240.00	\$	2,240.00
145	AIR SUPPLY UNIT	X NN	1	\$	13,804.00	\$	13,804.00
146	AIR SUPPLY UNIT VALVE	X NN	1	\$	504.00	\$	504.00
147	AIR SUPPLY VALVE UNIT	X NN	1	\$	3,640.00	\$	3,640.00
148	AIR SUPPLY INTAKE HOSE	X NN	1	\$	56.00	\$	56.00
149	AIR SUPPLY PRESSURE ACCUM	NN	1	\$	2,548.00	\$	2,548.00
150	AIR SUPPLY AIR LINE	NN X	1	\$	700.00	\$	700.00
151	AIR SUPPLY AIR LINE	NN X	1	\$	420.00	\$	420.00
152	AIR SUPPLY AIR LINE	X NN	1	\$	28.00	\$	28.00
153	AIR SUPPLY AIR LINE	X NN	1	\$	672.00	\$	672.00
154	AIR SUPPLY AIR LINE	X NN	1	\$	756.00	\$	756.00

155	AIR SUPPLY AIR LINE	X NN	1	\$	784.00	\$	X 784.00
156	AIR SUPPLY CLIPS	X NN	10	\$	560.00	\$	X 560.00
157	AIR SUPPLY SPRING BAND	X NN	2	\$	56.00	\$	X 56.00
158	AIR SUPPLY HEXAGON SCREW	X NN	2	\$	56.00	\$	X 56.00
159	AIR SUPPLY HEXAGON SCREW	X NN	3	\$	84.00	\$	X 84.00
160	AIR SUPPLY HEXAGON SCREW	X NN	10	\$	560.00	\$	X 560.00
161	AIR SUPPLY CLIPS	X NN	4	\$	448.00	\$	X 448.00
162	AIR SUPPLY CLIPS	X NN	1	\$	196.00	\$	X 196.00
163	REAR BUMPER	OR	1	\$	14,056.00	\$	11,985 X 14,056.00
164	REAR BUMPER SPOILER	OR	1	\$	9,240.00	\$	7,397 X 9,240.00
165	REAR BUMPER TOWING COVER	OR	1	\$	336.00	\$	336.00
166	REAR BUMPER SENSOR BRACKET	OR	2	\$	168.00	\$	168.00
167	REAR BUMPER SENSOR BRACKET (SPOILER) LH	OR	1	\$	84.00	\$	84.00
168	REAR BUMPER SENSOR BRACKET (SPOILER) RH	OR	1	\$	84.00	\$	84.00
169	REAR BUMPER RE-INFORCEMENT BAR	DD	1	\$	2,380.00	\$	2,380.00
170	REAR PANEL CAP	X NN	1	\$	784.00	\$	784.00 X
171	REAR PANEL CAP	X NN	1	\$	784.00	\$	784.00 X
172	REAR BUMPER BRACKET FLAP	X NN	1	\$	112.00	\$	X 112.00
173	REAR BUMPER HEAT SHIELD LH	MS	1	\$	224.00	\$	224.00
174	REAR BUMPER HEAT SHIELD RH	MS	1	\$	224.00	\$	224.00
175	REAR BUMPER BRACKET LH	X NN	1	\$	224.00	\$	224.00 X
176	REAR BUMPER BRACKET RH	X NN	1	\$	224.00	\$	224.00 X
177	REAR BUMPER INNER BRACKET LH	OR	1	\$	420.00	\$	420.00
178	REAR BUMPER INNER BRACKET RH	OR	1	\$	420.00	\$	420.00
179	REAR BUMPER RIVET / NUT / CLIPS / SCREWS	MC	18	\$	1,008.00	\$	300 1,008.00
180	REAR BUMPER RIVET / NUT / CLIPS / SCREWS	X NN	4	\$	112.00	\$	112.00 X
181	REAR BUMPER RIVET / NUT / CLIPS / SCREWS	X NN	20	\$	2,240.00	\$	2,240.00 X
182	REAR BUMPER RIVET / NUT / CLIPS / SCREWS	X NN	4	\$	224.00	\$	224.00 X
183	REAR BUMPER RIVET / NUT / CLIPS / SCREWS	X NN	4	\$	224.00	\$	224.00 X
184	REAR BUMPER RIVET / NUT / CLIPS / SCREWS	X NN	22	\$	1,232.00	\$	1,232.00 X
185	REAR BUMPER RIVET / NUT / CLIPS / SCREWS	X NN	4	\$	224.00	\$	224.00 X
186	REAR BUMPER RIVET / NUT / CLIPS / SCREWS	X NN	4	\$	224.00	\$	224.00 X
187	REAR BUMPER RIVET / NUT / CLIPS / SCREWS	X NN	1	\$	56.00	\$	56.00 X
188	REAR BUMPER RIVET / NUT / CLIPS / SCREWS	X NN	2	\$	112.00	\$	112.00 X
189	REAR BUMPER RIVET / NUT / CLIPS / SCREWS	X NN	2	\$	112.00	\$	112.00 X
190	REAR BUMPER RIVET / NUT / CLIPS / SCREWS	X NN	2	\$	112.00	\$	112.00 X

168,421.00
- 306
134,736.80

Total :	\$	257,326.00
-20%	\$	51,465.20
Parts Total :	\$	205,860.80

1	FRONT NUMBER PLATE	\$	40 80.00
2	REAR NUMBER PLATE	\$	40 80.00
SPECIAL NETT :		\$	160.00

1	ELECTRICAL CHECKS ON WIRING, AIR SUPPLY UNIT (SUSPENSION), FRONT & REAR RADAR SENSOR, ANTI-COLLISION PREVENTION SYSTEM, AUTO TAILGATE LIFTER, AUTO TAILGATE RELEASE BUTTON, HEADLAMPS & TAILLAMPS, EXHAUST OUTPUT AIR-FLOW, REAR BUMPER LAMP, REVERSE CAMERA, BATTERY SUPPLY UNIT.	\$	4,500.00
1	PROGRAMMING RESET & RE-CALIBRATE AIR REGULATED SUSPENSION. HEIGHT & COMPRESSION REGULATIONS FOR ALL 4 X SUSPENSIONS.	\$	X 2,600.00
1	PROGRAMMING RESET & RE-CALIBRATE LIGHTING ELECTRONICS (LAMPS)	\$	2,800.00

1200
300

ETC), REVERSE RADAR SENSOR PARKING DISTANCE, REVERSE CAMERA TO HEADUNIT CAN BUS READING, FRONT RADAR SENSING COLLISION PREVENTION, BOOT LID COMFORT ACCESS.

1	LABOUR TO DISMANTLE, REPAIR & REPLACE PARTS AS STATED. WHOLE EXTERIOR SHELL REMOVAL FROM CHASSIS FOR PANEL BEATING OF REAR LH & RH FENDER. 300 7500	\$	2400 / 3,500.00 800 1500
1	LABOUR FOR CHASSIS & BODY ALIGNMENT, PARTS FITMENT	\$	X 5,500.00
1	LABOUR TO REPLACE REAR END PANEL.	\$	X 850.00
1	LABOUR TO REMOVE & REPLACE EXHAUST MUFFLER LH & RH, ALIGN TO REAR BUMPER LOWER DIFFUSER EXHAUST DUCT, EXHAUST MOUNTINGS. 300	\$	300 1,200.00 800
1	ANTI-RUST PROOFING & GALVANISE ON REAR END PANEL, REAR LH & RH FENDER (OUTER SHELL WHOLE PIECE), REAR LOWER FLOOR PANEL (SPARE TYRE TANK), FRONT REINFORCEMENT	\$	200 1,800.00 1000
1	TO PRIMED, GALVANISE ZINC PUTTY, SPRAY-PAINTING (WATER-BORNE PAINT AS PER BENTLEY SPECIFICATION) FRONT BUMPER, FRONT LH & RH FENDER, FRONT RADIATOR GRILLE BASE, REAR LH & RH FENDER, REAR BOOTLID INNER, REAR BOOTLID OUTER, REAR BUMPER, REAR BUMPER LOWER DIFFUSER CENTER TRIM, REAR END PANEL INNER, REAR END PANEL OUTER, REAR BODY PANEL INNER, REAR BODY PANEL OUTER, FRONT & REAR 8 X RADAR SENSORS. 300 2800	\$	9,000.00 5500 2800 / 6400

P - 134,736.80
 NI - 80
 L - 6400
 141,216.80
 C/S - 112,973.44
 = 113,000.00

CHUAN HO AUTO SERVICE

Labour Total :	\$	31,750.00
Parts Total :	\$	205,860.80
Total :	\$	237,610.80
-20%	\$	47,522.16
Grand Total :	\$	190,088.64
Special Nett :	\$	160.00
Lump Sum :	\$	190,000.00

LKH Auto Consultants hence notify the Repairer of the following:

- To resurvey & re-spray after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Cheap Car Insurance Renewal

Is your car insurance expiring soon?

Receive best quotations from multiple insurers in as little as 2 hours.

Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

2009 Toyota Vellfire 3.5A Z G-Edition selling@S\$2999



Powerful & Smooth V6 engine
Interior and exterior in
immaculate condition
Starting

Deposited 60K per year

- Free VICOM evaluation
- Free grooming and 6 months maintenance
- In-house workshop ensures quality service
- Member of SYTA and hire purchase association
- 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

[Browse by Category](#)
[Sort by Date Posted](#)
[20 results/page](#)

8 vehicles

Bentley Continental

[Advanced Search](#)

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Bentley Continental	Any	Any	2012	Any	Any	Any	Available
	Bentley Continental GT 6.0A	\$338,000	\$70,060 /yr	01-Sep-2012	5,998 cc	57,000 km	Sports	Available
Well Maintained By Agent. Easy In-House Financing Available. Call Our Friendly Sales Consultants For More Information! Price Inclusive Of GST, Motor-Way Credit Pte Ltd								
Posted: 10-Mar-2019 Tags: 2012 Bentley Continental, 2012 bentley continental, Bentley Continental, bentley continental, Bentley, Continental, continental, Used Bentley								
	Bentley Continental GT 4.0A V8	\$308,000	\$61,030 /yr	02-Nov-2012	3,993 cc	17,000 km	Sports	Available
1 Owner With Low Mileage Beautiful White With Blue Interior Leather With White Stitching. Beautiful Condition. Serviced And Maintained By Bentley Agent. Owner Consignment Car.								
Posted: 06-Mar-2019 Tags: 2012 Bentley Continental, 2012 bentley continental, Bentley Continental, bentley continental, Bentley, Continental, continental, Used Bentley								
	Bentley Continental GT Convertible 4.0A V8	\$359,000	\$72,390 /yr	06-Nov-2012	3,993 cc	21,900 km	Sports	Available
Luxurious And Powerful Bentley GTC V8 Twin Turbocharged In Town. Wearnas Automotive Unit. Low Mileage, Includes Paddle Shifters, Reverse Camera, Navigations System, Bi-Xenon Headlights With Signature ...								
Motor-Way Credit Pte Ltd								
Posted: 02-Mar-2019 Tags: 2012 Bentley Continental, 2012 bentley continental, Bentley Continental, bentley continental, Bentley, Continental, continental, Used Bentley								
	Bentley Continental GT 6.0A	\$318,000	\$71,140 /yr	24-Apr-2012	5,998 cc	45,000 km	Sports	Available
Low Mileage. Excellent Condition. Well Maintained. Easy In House Financing Available. Call Our Friendly Sales Consultant For Viewing. Price Inclusive Of GST,								
Motor-Way Credit Pte Ltd								
Posted: 01-Mar-2019 Tags: 2012 Bentley Continental, 2012 bentley continental, Bentley Continental, bentley continental, Bentley, Continental, continental, Used Bentley								
	Bentley races into its centenary year							
Bentley Motorsport embarks on a landmark racing campaign as it competes in the season-opening Bathurst 12 Hour for the fifth time.								
Read this article								
	Bentley Continental GT 4.0A V8	\$269,800	\$50,350 /yr	28-Sep-2012	3,993 cc	88,000 km	Sports	Available
Cheapest In Singapore! Agent Unit. Maintained By 9Degree Workshop, Original Black, Resprayed To Blue, Call Now!								
AMS Motors Pte Ltd								
Posted: 26-Feb-2019 Tags: 2012 Bentley Continental, 2012 bentley continental, Bentley Continental, bentley continental, Bentley, Continental, continental, Used Bentley								
	Bentley Continental GT 6.0A	\$250,000	\$50,330 /yr	12-Mar-2012	5,998 cc	36,000 km	Sports	Available
Well Maintenance, Must View. Wearnas Agent Car.								

[Compare](#)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0189B
Vehicle Details	
Vehicle No.:	SDS1666A
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Mar 2019
Vehicle Make:	BENTLEY
Vehicle Model:	CONTINENTAL GT 6.0 AUTO ABS D/AB 4WD HID
Primary Colour:	Black
Manufacturing Year:	2012
Engine No.:	CKH014441
Chassis No.:	SCBFE63W9DC082090
Maximum Power Output:	423.0 kW (567 bhp)
Open Market Value:	\$199,387.00
Original Registration Date:	24 Oct 2012
First Registration Date:	24 Oct 2012
Transfer Count:	3
Actual ARF Paid:	\$199,387.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Oct 2022
PARF Rebate Amount:	\$129,601.00
Intended COE Rebate Details	
COE Expiry Date:	23 Oct 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$92,050.00
COE Rebate Amount:	\$33,207.00
Total Rebate Amount:	\$162,808.00

The information contained herein is correct as at 14 Mar 2019

OK

MV- 315,000
 PV- 162,808
 NV- 152,192

60,000 p.a. year

3 year 7 month = 215,000

ARF + 100,000

= 315,000

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	18 Mar 2019 21:13	Clm Dtl Modified	Claimant's Name: -> KHNG THIAN HUAT, Claimant's ID: -> S0100189B.	[A] HOW MEI KWAN
2	18 Mar 2019 21:13	Clm Veh Model Changed	(205900) BENTLEY CONTINENTAL GT SPEED 6.0 (A).	[A] HOW MEI KWAN
3	18 Mar 2019 21:13	Clm Created	Reg No: SDS1666A, Acct Date: 2019/03/07, Claim Type: TP, Insurer: India International Insurance Pte Ltd (HQ), TP Insurer: AXA Insurance Pte Ltd (HQ), Workshop: Chuan Ho Auto Service (Sin Ming)	[A] HOW MEI KWAN
4	18 Mar 2019 21:13	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] HOW MEI KWAN
5	18 Mar 2019 21:13	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/03/27	[A] HOW MEI KWAN
6	18 Mar 2019 21:13	Adj Mandate Set	Approved:0.00,Reinsp:Adj decides.	[A] HOW MEI KWAN
7	18 Mar 2019 21:14	Label Added	(30653):Direct Settlement.	[A] HOW MEI KWAN
8	18 Mar 2019 21:14	Adj Adjuster Assigned	[None] -> XING GUO QIANG	[A] HOW MEI KWAN
9	26 Mar 2019 16:31	Adj Mandate Request	Cur.Reg:0.00:PODS LIABILITY: 100% REMARKS: BOLA 28 - 4 veh.c.c.; OID 3rd car	[A] VIC ALPEH
10	29 Mar 2019 10:50	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/03/27	[I] Lalitha Krishnan
11	29 Mar 2019 10:50	Adj Mandate Set	Approved:0.00.	[I] Lalitha Krishnan
12	29 Mar 2019 15:11	Clm Registration Modified	Acct Time:15:00:00->14:00:00.	[I] Stanley Lai
13	21 May 2019 13:42	Adj Adjuster Assigned	XING GUO QIANG -> CHEN TSUE YEE	[A] HOW MEI KWAN
14	25 Jun 2019 10:01	Video Downloaded	Downloaded Video - Accident	[A] Chong Poh Kin
15	25 Jun 2019 10:26	Adj Mandate Request	Cur.Reg:113000.00:PODS MARKET VALUE: \$315,000.00 - REBATE:\$162,808.00 = Net Value:\$152,192.00 Surveyor recommended COR at \$113,000.00 (BEFORE GST) For yo ur comments/instruction/approval on COR only	[A] Chong Poh Kin
16	25 Jun 2019 10:28	Video Downloaded	Downloaded Video - Accident	[I] Sherini Pillai
17	25 Jun 2019 16:20	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2019/03/27, Mandate Remarks: Please advice on rental as well as we have to seek approval	[I] Sherini Pillai
18	25 Jun 2019 16:20	Adj Mandate Set	Maintained:Please advice on rental as well as we have to seek approval	[I] Sherini Pillai
19	05 Aug 2019 17:02	Adj Mandate Request	Cur.Reg:131000.00:PODS Liability: 100% MARKET VALUE: \$ 315,000.00 - REBATE: \$ 162,808.00 = Net Value: \$ 152,192.00. We have yet to finalize COR with TP repairer, S urveyor recommended COR at \$113,000.00 (BEFORE GST) + LOSS OF USE (\$180.00 x 100 d	[A] Chong Poh Kin
20	08 Aug 2019 16:11	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2019/03/27, Mandate Remarks: Please offer LOU \$2,5 20.00 (14 days as recommended x \$180).	[I] Sherini Pillai
21	08 Aug 2019 16:11	Adj Mandate Set	Maintained:Please offer LOU \$2,520.00 (14 days as recommended x \$180).	[I] Sherini Pillai
22	03 Oct 2019 13:53	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
23	03 Oct 2019 13:53	Clm Dtl Modified	Insured Name: -> -, Insured ID: -> -.	[A] JOANNE LEE KHANG MIN
24	03 Oct 2019 13:53	Clm Dtl Modified	JPJ Reg. Date: -> 2012/10/24.	[A] JOANNE LEE KHANG MIN

AUDIT TRAIL				
No.	On	Audit	Remarks	By
25	03 Oct 2019 13:53	Cim Details Notified		[A] JOANNE LEE KHANG MIN
26	03 Oct 2019 16:17	Adj Mandate Request	Cur.Reg:131000.00:PODS Liability: 100% *Quantum: (a)COR \$113,000.00 + (b)LOU(90days x \$200.00): \$18,000.00 = Total: \$131,000.00 *Vehicle Model: Bentley Continental (5998cc) *14 recommendation repair days + 76days(waiting parts) = 90days *For you	[A] CHEW HSIAO TONG
<div> Date From <div> Date To <div> Audit Type None Go </div> </div> </div>				

ACTIVITY

[04/04/2019 11:19] VIC ALPEH:

PENDING COR FINALIZATION

[04/04/2019 11:14] VIC ALPEH:

Alert - Adj Mandate Approved (\$0.00) - SDS1666A - Claim Handler: Sherini Pillai

Approved:0.00.

[26/03/2019 16:31] VIC ALPEH:

Adj Mandate Request Cur.Reg:0.00:PODS LIABILITY: 100% REMARKS: BOLA 28 - 4 veh.c.c.; OID 3rd car

[26/03/2019 16:30] VIC ALPEH:

FILE REVIEWED. OID involved in a 4 veh.c.c. and was the 3rd car and was pushed forward from behind. Seek liability mandate to III by merimen

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2100172	29 Mar 2019 15:21:51	Video Upload	Motor	India International Insurance Pte Ltd (HQ)	India International Insurance Pte Ltd (HQ)	SDS1666A	Stanley Lai	xx.xx
2301295	03 Oct 2019 13:53:05	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SDS1666A	SHC8802P	11.77

Hsiao Tong (LKKAuto)

From: Sherini Pillai <sherini@iii.com.sg>
Sent: Tuesday, 5 November 2019 3:40 PM
To: Hsiao Tong (LKKAuto)
Subject: MCT19030186

Hi Hsiao Tong,

We spoke on this matter before. Now we need your help.

Meka wants a chronology of this case up to the delay in parts so we can explain to our auditors next time.

Are you able to help? Tks

Best Regards,

Sherini Pillai

Motor & Work Injury Claims Department

64 Cecil Street, #04/#05 IOB Building, Singapore 049711

☎ 6347 6128 Fax: 6224 4174

Company Registration No. 198703792K



This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

23
24
20
29
82 days.

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Wednesday, 6 November 2019 7:56 AM
To: 'Sherini Pillai'
Subject: RE: MCT19030186

Hi Sherini,

Please refer to the below: -

07/03/2019 (Thursday)	Date of accident.	
08/03/2019 (Friday)	Third party repairer placed order for parts at KBS Motorsports Pte Ltd.	82days
14/03/2019 (Thursday)	LKK conducted survey.	
07/05/2019 (Tuesday)	Rec'd parts (Pls refer to the KBS tax invoice W.I.P No. 13834)	
29/05/2019 (Wednesday)	- Rec'd parts (Pls refer to the KBS tax invoice W.I.P No. 14042) - Start repair work.	
14/06/2019 (Friday)	- Repair done.	14 repair days
Total		96days

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sherini Pillai <sherini@iii.com.sg>
Sent: Tuesday, 5 November 2019 3:40 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: MCT19030186

Hi Hsiao Tong,

We spoke on this matter before. Now we need your help.

Meka wants a chronology of this case up to the delay in parts so we can explain to our auditors next time.

Are you able to help? Tks

Best Regards,

Sherini Pillai

Motor & Work Injury Claims Department

64 Cecil Street, #04/#05 IOB Building, Singapore 049711

☎ 6347 6128 Fax: 6224 4174

Company Registration No. 198703792K



This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Hsiao Tong (LKKAUTO)

From: Mekavathanan Sarangapani <mekavathanan@iii.com.sg>
Sent: Friday, 8 November 2019 4:31 PM
To: KKLau; Hsiao Tong (LKKAUTO); Olivia Lau (LKKAUTO)
Cc: Sherini Pillai
Subject: FW: MCT19030186

LKK Team,

Approving this claim via email for S\$ 126,500.00

Best Regards,

Sherini Pillai

Motor & Work Injury Claims Department

64 Cecil Street, #04/#05 IOB Building, Singapore 049711

☎ 6347 6128 Fax: 6224 4174

Company Registration No. 198703792K



This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Hsiao Tong (LKKAuto)

From: Sherini Pillai <sherini@iii.com.sg>
Sent: Thursday, 14 November 2019 9:31 AM
To: Hsiao Tong (LKKAuto)
Subject: FW: SDS1666A (Invoices) DOA: 07.03.2019 //LKK REF: CC6/III19004918/Epa3

Hi Hsiao Tong,

We have agreed settlement at \$130,000.00 (all-in).

Please send DV to Chuan Ho.

Best Regards,

Sherini Pillai

Motor & Work Injury Claims Department

64 Cecil Street, #04/#05 IOB Building, Singapore 049711

☎ 6347 6128 Fax: 6224 4174

Company Registration No. 198703792K



From: Sherini Pillai
Sent: Thursday, November 14, 2019 9:30 AM
To: CHUAN HO AUTO SERVICE <chuanhoautoservice@gmail.com>
Subject: RE: SDS1666A (Invoices) DOA: 07.03.2019 //LKK REF: CC6/III19004918/Epa3

Hi Justin,

Thank you for your email.

We appreciate your patience in settling this matter amicably.

We are pleased to make a global offer of **\$130,000.00** (all-in).

Please confirm acceptance.

Best Regards,

Sherini Pillai

Motor & Work Injury Claims Department

64 Cecil Street, #04/#05 IOB Building, Singapore 049711

☎ 6347 6128 Fax: 6224 4174

Company Registration No. 198703792K



From: CHUAN HO AUTO SERVICE [mailto:chuanhoautoservice@gmail.com]
Sent: Thursday, November 14, 2019 9:24 AM
To: Sherini Pillai <sherini@iii.com.sg>
Subject: Re: SDS1666A (Invoices) DOA: 07.03.2019 //LKK REF: CC6/III19004918/Epa3

Hi Miss Sherini,

My client's reply to the offer is as follows:

"" Past average closing of bentley continental gt 6.0 is @ \$60k per year, which is \$163 (round up dollar) per day

Insurance per month is about \$800 per month, which is \$27 (round up dollar) per day

Road Tax is \$7074 per year which is \$20 (round up dollar) per day.

Depreciation consist of coe, hence all added up will be \$210 per day.

Date of accident: 07/03/2019

Police investigation results out, and able to proceed with survey: 14/03/2019

Repairing done: 25/06/2019

Total of 108 Days for this whole procedure,

$\$210 \times 108 \text{ Days} = \$22\,680$ ""

So sorry for the trouble and I hope we can close this matter soon. Please let me have an ALL-IN sum offer so that I can show him to satisfy his queries and close this matter as soon as possible, thank you so much!!

Best Regards,

Justin Ho

+65 9189 2365

Chuan Ho Auto Service

160 Sin Ming Drive, #07-09, Sin Ming Auto City, S 575722

On Tue, Nov 12, 2019 at 1:46 PM Sherini Pillai <sherini@iii.com.sg> wrote:

Hi Justin,

We have reviewed the matter and we can go up to a max of \$180/- per day totaling up to \$16,200.00 for LOU.

Please reconsider so we can wrap up the matter. Thank you.

Best Regards,

Sherini Pillai

Motor & Work Injury Claims Department

64 Cecil Street, #04/#05 IOB Building, Singapore 049711

☎ 6347 6128 Fax: 6224 4174



From: CHUAN HO AUTO SERVICE [mailto:chuanhoautoservice@gmail.com]

Sent: Monday, November 11, 2019 9:55 AM

To: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; Sherini Pillai <sherini@iii.com.sg>

Subject: Re: SDS1666A (Invoices) DOA: 07.03.2019 //LKK REF: CC6/III19004918/Epa3

Hi Miss Sherini,

My clients is requesting for minimum \$200 per day for the 3months LOU, as the currently offer works out to be \$150 per day LOU which is lesser than the depreciation of a 6 Litres Bentley Conti Gt.

Please assist for a new offer, thank you so much!

So sorry for the inconvenience caused and we hope to close this case as soon as possible, thanks thanks!

Best Regards,

Justin Ho

+65 9189 2365

Chuan Ho Auto Service

160 Sin Ming Drive, #07-09, Sin Ming Auto City, S 575722

On Sat, Nov 9, 2019 at 1:22 PM Hsiao Tong (LKKAUTO) <chewht@lkkauto.com> wrote:

Without Prejudice

(save as to costs)

Dear Sirs/Mdm,

Thank you for your patience.

We have our principal instruction to offer at **\$126,500.00(all-in).**

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CHUAN HO AUTO SERVICE <chuanhoautoservice@gmail.com>

Sent: Friday, 4 October 2019 10:12 AM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: Fwd: SDS1666A (Invoices) DOA: 07.03.2019

Hi Hsiao Tong,

Please provide us an update for the LOU.

Thank you.

Best Regards,

Sharin Lim

+65 9069 1985



----- Forwarded message -----

From: **CHUAN HO AUTO SERVICE** <chuanhoautoservice@gmail.com>

Date: Mon, Sep 23, 2019 at 2:17 PM

Subject: Fwd: SDS1666A (Invoices) DOA: 07.03.2019

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Hi Hsiao Tong,


Please provide us an update for the LOU for this case ASAP.

Thank you.

Best Regards,

Sharin Lim

+65 9069 1985



----- Forwarded message -----

From: **CHUAN HO AUTO SERVICE** <chuanhoautoservice@gmail.com>

Date: Tue, Aug 27, 2019 at 9:48 AM

Subject: Fwd: SDS1666A (Invoices) DOA: 07.03.2019

To: Poh Kin (LKKAuto) <pohkin@lkkauto.com>

Hi Poh Kin,

My boss is looking at, at least 3 months of LOU at \$240/Day.


Please help us push for the amount.

Thank you!

Best Regards,

Sharin Lim

+65 9069 1985



----- Forwarded message -----

From: **CHUAN HO AUTO SERVICE** <chuanhoautoservice@gmail.com>

Date: Mon, Aug 26, 2019 at 10:51 AM

Subject: Fwd: SDS1666A (Invoices) DOA: 07.03.2019

To: Poh Kin (LKKAuto) <pohkin@lkkauto.com>

Hi Poh Kin,

Any updates on the LOU?

Thank you.

Best Regards,

Sharin Lim

+65 9069 1985



----- Forwarded message -----

From: **CHUAN HO AUTO SERVICE** <chuanhoautoservice@gmail.com>

Date: Wed, Aug 21, 2019 at 11:30 AM

Subject: Re: SDS1666A (Invoices) DOA: 07.03.2019

To: Poh Kin (LKKAuto) <pohkin@lkkauto.com>

Hi Poh Kin,

Noted please finalize at \$113k.

Have attached our Final Repair Bill, please process this for us.

Do let us know who to speak to regarding the nego of the LOU.

Many Thanks!

Best Regards,

Sharin Lim

+65 9069 1985



On Wed, Aug 21, 2019 at 10:40 AM Poh Kin (LKKAuto) <pohkin@lkkauto.com> wrote:

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Our Ref: CC6/III19004918/Epa3

Your Ref: SDS 1666A

Dear Ms Sharin,

We refer to the above matter.

For COR, our surveyor had recommended amount at L/S \$113,000.00 (before GST) with 14 repair days.

In the meantime, please be informed that we have instruction from our principal to offer Loss of Use at \$180.00 per day x 14 days.

*** Kindly forward your LOD with all the relevant documents(ie: final repair bill, authorisation to act, rental receipt) to us (LKK) for our necessary action.

Thank you.

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

64 Cecil Street, #04/#05 IOB Building, Singapore 049711
☎ 6347 6128 Fax: 6224 4174

Company Registration No. 198703792K

From: CHUAN HO AUTO SERVICE [<mailto:chuanhoautoservice@gmail.com>]

Sent: Tuesday, August 20, 2019 1:24 PM

To: Sherini Pillai <sherini@iii.com.sg>

Subject: Fwd: SDS1666A (Invoices)

Hi Ms Sherini,

Can I check if there are any updates on this?


Please provide us the offer for LOU and the breakdown.

Many thanks!

Best Regards,

Sharin Lim

+65 9069 1985



----- Forwarded message -----

From: **CHUAN HO AUTO SERVICE** <chuanhoautoservice@gmail.com>

Date: Fri, Aug 16, 2019 at 6:16 PM

Subject: Re: SDS1666A (Invoices)

To: Sherini Pillai <sherini@iii.com.sg>

Hi Sherini,

Oh so do we followup with the surveyor side?

By the way, how much is your offer? Able to have a breakdown?

Thanks thanks! :) :)

Best Regards,

Justin Ho | Company Director

+65 9069 1985



On Fri, Aug 16, 2019 at 5:16 PM Sherini Pillai <sherini@iii.com.sg> wrote:

Hi Justin,

I have given mandate to our surveyor on 8 August 2019.

While we appreciate your intend to lower our exposure, we are not able to offer \$18K for LOU.

You may liaise with our surveyor with regards to this.

Have a great weekend!

Regards,

Sherini Pillai

Motor Claims Department



64 Cecil Street, #04/#05 IOB Building, Singapore 049711
DID: 6347 6128 Fax: 6224 4174

Company Registration No. 198703792K

From: CHUAN HO AUTO SERVICE [mailto:chuanhoautoservice@gmail.com]
Sent: Thursday, August 15, 2019 10:56 AM
To: Sherini Pillai <sherini@iii.com.sg>
Subject: Re: SDS1666A (Invoices)

Hi Sherini,

Is there any updates on the loss of use amount?

Thanks thanks! :)

Best Regards,

Justin Ho | Company Director

+65 9069 1985



On Tue, Aug 6, 2019 at 6:27 PM CHUAN HO AUTO SERVICE <chuanhoautoservice@gmail.com> wrote:

Hi Sherini,

The client initially demand to either get a same category 6.0Litres Bentley Coupe or to get his loss of usage.

We tried looking for companies that does Bentley 6.0Litres rental and the rental fees are about \$15000 (lowest) average for monthly rental fees. Which covers the insurance (considered , road tax, maintenances) etc. His car is a coupe variant with 3year plus left and a W12 engine, hence will be different than 4 door 4.0Litres vehicles.

Given \$15000 rental per month, each day is average to about \$500. If we choose per day rental is about \$800.

Hence we managed to talk thru to our client to opt for loss of usage, which if we calculate depreciation, road tax and insurance premium inside, cost about \$300 per day only. This will save a huge sum from the claims.

Therefore rather than incurring about \$45000 (for 3mths rental of same category), its better to be given as loss of usage from our deduction. Hope you understand that we are trying to help rather than drown the matter further

Best Regards,

Justin Ho | Company Director

+65 9189 2365



On Tue, Aug 6, 2019 at 5:19 PM Sherini Pillai <sherini@iii.com.sg> wrote:

Hi Justin,

Sorry I have a question.

In this 3 months, your client was not given a replacement vehicle?

Regards,

Sherini Pillai

Motor Claims Department

India International Insurance Pte Ltd

64 Cecil Street, #04/#05 IOB Building, Singapore 049711
DID: 6347 6128 Fax: 6224 4174



From: CHUAN HO AUTO SERVICE [<mailto:chuanhoautoservice@gmail.com>]

Sent: Monday, August 05, 2019 10:16 AM

To: Sherini Pillai <sherini@iii.com.sg>

Subject: SDS1666A (Invoices)

Hi Ms Sherini,

Good morning to you, as attached are the invoices from KBS that we ordered the parts for our client SDS1666A (Bentley Continental GT 6.0 Coupe).


Thank you! :)

--

Best Regards,

Justin Ho | Company Director

+65 9189 2365



This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the

content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Hsiao Tong (LKKAuto)

From: CHUAN HO AUTO SERVICE <chuanhoautoservice@gmail.com>
Sent: Tuesday, 27 August 2019 9:49 AM
To: Poh Kin (LKKAuto)
Subject: Fwd: SDS1666A (Invoices) DOA: 07.03.2019
Attachments: SDS 1666 A - FINAL REPAIR BILL.pdf

Hi Poh Kin,

My boss is looking at, at least 3 months of LOU at \$240/Day.
Please help us push for the amount.
Thank you!

Best Regards,
Sharin Lim
+65 9069 1985



----- Forwarded message -----

From: CHUAN HO AUTO SERVICE <chuanhoautoservice@gmail.com>
Date: Mon, Aug 26, 2019 at 10:51 AM
Subject: Fwd: SDS1666A (Invoices) DOA: 07.03.2019
To: Poh Kin (LKKAuto) <pohkin@lkkauto.com>

Hi Poh Kin,

Any updates on the LOU?
Thank you.

Best Regards,
Sharin Lim
+65 9069 1985



----- Forwarded message -----

From: CHUAN HO AUTO SERVICE <chuanhoautoservice@gmail.com>
Date: Wed, Aug 21, 2019 at 11:30 AM
Subject: Re: SDS1666A (Invoices) DOA: 07.03.2019
To: Poh Kin (LKKAuto) <pohkin@lkkauto.com>

Hi Poh Kin,

Noted please finalize at \$113k.
Have attached our Final Repair Bill, please process this for us.
Do let us know who to speak to regarding the nego of the LOU.
Many Thanks!

Best Regards,
Sharin Lim
+65 9069 1985



On Wed, Aug 21, 2019 at 10:40 AM Poh Kin (LKKAuto) <pohkin@lkkauto.com> wrote:

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

Our Ref: CC6/III19004918/Epa3

Your Ref: SDS 1666A

Dear Ms Sharin,

We refer to the above matter.

For COR, our surveyor had recommended amount at **L/S \$113,000.00 (before GST)** with **14** repair days.

In the meantime, please be informed that we have instruction from our principal to offer Loss of Use at \$180.00 per day x 14 days.

*** Kindly forward your LOD with all the relevant documents(ie: final repair bill, authorisation to act, rental receipt) to us (LKK) for our necessary action.

Thank you.

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

64 Cecil Street, #04/#05 IOB Building, Singapore 049711

☎ 6347 6128 Fax: 6224 4174

From: CHUAN HO AUTO SERVICE [<mailto:chuanhoautoservice@gmail.com>]
Sent: Tuesday, August 20, 2019 1:24 PM
To: Sherini Pillai <sherini@iii.com.sg>
Subject: Fwd: SDS1666A (Invoices)

Hi Ms Sherini,

Can I check if there are any updates on this?

Please provide us the offer for LOU and the breakdown.

Many thanks!

Best Regards,

Sharin Lim

+65 9069 1985



----- Forwarded message -----

From: CHUAN HO AUTO SERVICE <chuanhoautoservice@gmail.com>
Date: Fri, Aug 16, 2019 at 6:16 PM
Subject: Re: SDS1666A (Invoices)
To: Sherini Pillai <sherini@iii.com.sg>

Hi Sherini,

Oh so do we followup with the surveyor side?

By the way, how much is your offer? Able to have a breakdown?

Thanks thanks! :) :)

Best Regards,

Justin Ho | Company Director

+65 9069 1985



On Fri, Aug 16, 2019 at 5:16 PM Sherini Pillai <sherini@iii.com.sg> wrote:

Hi Justin,

I have given mandate to our surveyor on 8 August 2019.

While we appreciate your intend to lower our exposure, we are not able to offer \$18K for LOU.

You may liaise with our surveyor with regards to this.

Have a great weekend!

Regards,

Sherini Pillai

Motor Claims Department



64 Cecil Street, #04/#05 IOB Building, Singapore 049711
DID: 6347 6128 Fax: 6224 4174

Company Registration No. 198703792K

From: CHUAN HO AUTO SERVICE [mailto:chuanhoautoservice@gmail.com]
Sent: Thursday, August 15, 2019 10:56 AM
To: Sherini Pillai <sherini@iii.com.sg>
Subject: Re: SDS1666A (Invoices)

Hi Sherini,

Is there any updates on the loss of use amount?

Thanks thanks! :)

Best Regards,

Justin Ho | Company Director

+65 9069 1985



On Tue, Aug 6, 2019 at 6:27 PM CHUAN HO AUTO SERVICE <chuanhoautoservice@gmail.com> wrote:

Hi Sherini,

The client initially demand to either get a same category 6.0Litres Bentley Coupe or to get his loss of usage.

We tried looking for companies that does Bentley 6.0Litres rental and the rental fees are about \$15000 (lowest) average for monthly rental fees. Which covers the insurance (considered , road tax, maintenences) etc. His car is a coupe variant with 3year plus left and a W12 engine, hence will be different than 4 door 4.0Litres vehicles.

Given \$15000 rental per month, each day is average to about \$500. If we choose per day rental is about \$800.

Hence we managed to talk thru to our client to opt for loss of usage, which if we calculate depreciation, road tax and insurance premium inside, cost about \$300 per day only. This will save a huge sum from the claims.

Therefore rather than incurring about \$45000 (for 3mths rental of same category), its better to be given as loss of usage from our deduction. Hope you understand that we are trying to help rather than drown the matter further

Best Regards,

Justin Ho | Company Director

+65 9189 2365



On Tue, Aug 6, 2019 at 5:19 PM Sherini Pillai <sherini@iii.com.sg> wrote:

Hi Justin,

Sorry I have a question.

In this 3 months, your client was not given a replacement vehicle?

Regards,

Sherini Pillai

Motor Claims Department

India International Insurance Pte Ltd

64 Cecil Street, #04/#05 IOB Building, Singapore 049711
DID: 6347 6128 Fax: 6224 4174



From: CHUAN HO AUTO SERVICE [mailto:chuanhoautoservice@gmail.com]

Sent: Monday, August 05, 2019 10:16 AM

To: Sherini Pillai <sherini@iii.com.sg>

Subject: SDS1666A (Invoices)

Hi Ms Sherini,

Good morning to you, as attached are the invoices from KBS that we ordered the parts for our client SDS1666A (Bentley Continental GT 6.0 Coupe).

Thank you! :)

Best Regards,

Justin Ho | Company Director

+65 9189 2365



This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

CHUAN HO AUTO SERVICE
SIN MING AUTO CITY
160 SIN MING DRIVE #07-09
SINGAPORE 575722

FINAL REPAIR BILL : SDS 1666 A

Vehicle & Document Information

Date: 21/08/2019
 Vehicle No: SDS 1666 A
 Make/Model: BENTLEY CONTINENTAL

S/N	Description	Qty	Repairer's Est	Revised Est
1	HEADLAMP LH	1	\$ 9,600.00	\$ 9,600.00
2	HEADLAMP RH	1	\$ 9,600.00	\$ 9,600.00
3	FRONT RE-INFORCEMENT BAR	1	\$ 2,912.00	\$ 2,912.00
4	FRONT BUMPER	1	\$ 8,792.00	\$ 8,792.00
5	FRONT BUMPER SIDE BRACKET LH	1	\$ 252.00	\$ 252.00
6	FRONT BUMPER SIDE BRACKET RH	1	\$ 252.00	\$ 252.00
7	FRONT BUMPER BRACKET OUTER LH	1	\$ 112.00	\$ 112.00
8	FRONT BUMPER BRACKET OUTER RH	1	\$ 112.00	\$ 112.00
9	FRONT BUMPER BRACKET INNER LH	1	\$ 308.00	\$ 308.00
10	FRONT BUMPER BRACKET INNER RH	1	\$ 308.00	\$ 308.00
11	FRONT BUMPER LOWER GRILLE LH	1	\$ 1,932.00	\$ 1,932.00
12	FRONT BUMPER LOWER GRILLE RH	1	\$ 1,932.00	\$ 1,932.00
13	FRONT BUMPER LOWER GRILLE LH (SMALL)	1	\$ 1,092.00	\$ 1,092.00
14	FRONT BUMPER LOWER GRILLE RH (SMALL)	1	\$ 1,092.00	\$ 1,092.00
15	FRONT BUMPER CLIPS	23	\$ 300.00	\$ 300.00
19	FRONT RADIATOR GRILLE BASE	1	\$ 4,620.00	\$ 4,620.00
20	FRONT RADIATOR GRILLE TOP GARNISH	1	\$ 336.00	\$ 336.00
21	FRONT RADIATOR GRILLE TOP GARNISH STRIP	1	\$ 280.00	\$ 280.00
22	FRONT RADIATOR GRILLE BRACKET LH	1	\$ 140.00	\$ 140.00
23	FRONT RADIATOR GRILLE BRACKET RH	1	\$ 140.00	\$ 140.00
24	FRONT RADIATOR GRILLE LOWER BRACKET LH	1	\$ 84.00	\$ 84.00
25	FRONT RADIATOR GRILLE LOWER BRACKET RH	1	\$ 84.00	\$ 84.00
26	FRONT RADIATOR GRILLE SEAL	1	\$ 336.00	\$ 336.00
27	FRONT RADIATOR GRILLE TRIM	1	\$ 2,156.00	\$ 2,156.00
28	FRONT RADIATOR GRILLE	1	\$ 1,652.00	\$ 1,652.00
29	FRONT GRILLE BADGE (TOP)	1	\$ 168.00	\$ 168.00
30	FRONT GRILLE BADGE	1	\$ 1,232.00	\$ 1,232.00
31	FRONT GRILLE BADGE SEAL	1	\$ 140.00	\$ 140.00
32	FRONT RADIATOR GRILLE MIDDLE BRACKET LH	1	\$ 224.00	\$ 224.00
33	FRONT RADIATOR GRILLE MIDDLE BRACKET RH	1	\$ 224.00	\$ 224.00
36	FRONT RADIATOR GRILLE RIVET	16	\$ 200.00	\$ 200.00
42	FRONT RADIATOR GRILLE FOAM FILTER	2	\$ 252.00	\$ 252.00
46	FRONT FENDER LH	1	\$ 16,698.00	\$ 16,698.00
47	FRONT FENDER RH	1	\$ 16,698.00	\$ 16,698.00
48	FRONT HEADLAMP TRIM LH (BIG)	1	\$ 420.00	\$ 420.00
49	FRONT HEADLAMP TRIM RH (BIG)	1	\$ 420.00	\$ 420.00
50	FRONT HEADLAMP TRIM LH (SMALL)	1	\$ 392.00	\$ 392.00
51	FRONT HEADLAMP TRIM RH (SMALL)	1	\$ 392.00	\$ 392.00
59	FRONT FENDER CLIPS	28	\$ 100.00	\$ 100.00
60	FRONT FENDER CLIPS	28	\$ 100.00	\$ 100.00
78	REAR BUMPER UNDER COVER (BIG)	1	\$ 1,288.00	\$ 1,288.00
79	REAR BUMPER UNDER COVER LH	1	\$ 868.00	\$ 868.00

80	REAR BUMPER UNDER COVER RH	1	\$	868.00	\$	868.00
81	REAR BUMPER UNDER COVER BRACKET LH	1	\$	168.00	\$	168.00
82	REAR BUMPER UNDER COVER BRACKET RH	1	\$	168.00	\$	168.00
83	REAR BUMPER UNDER COVER SIDE BRACKET LH	1	\$	112.00	\$	112.00
84	REAR BUMPER UNDER COVER SIDE BRACKET RH	1	\$	112.00	\$	112.00
92	REAR WIRING SET	1	\$	588.00	\$	588.00
96	REAR BUMPER LAMP	1	\$	4,900.00	\$	4,900.00
97	REAR BOOTLID	1	\$	15,650.00	\$	15,650.00
98	REAR BOOTLID TOP LOCK	1	\$	1,512.00	\$	1,512.00
99	REAR BOOTLID LOCK	1	\$	336.00	\$	336.00
101	REAR BOOTLID CLIPS / RIVET	10	\$	50.00	\$	50.00
102	REAR BOOTLID LOCK FRAME	1	\$	112.00	\$	112.00
104	REAR BOOTLID SEAL	1	\$	1,008.00	\$	1,008.00
107	REAR BOOTLID TRIM	1	\$	532.00	\$	532.00
110	REAR BODY PANEL	1	\$	10,236.00	\$	10,236.00
113	REAR BODY PANEL COVER LH	1	\$	196.00	\$	196.00
114	REAR BODY PANEL COVER RH	1	\$	196.00	\$	196.00
115	REAR SPARE WHEEL COMPARTMENT PANEL	1	\$	2,016.00	\$	2,016.00
123	REAR END PANEL	1	\$	644.00	\$	644.00
128	REAR PANEL GARNISH LH	1	\$	364.00	\$	364.00
129	REAR PANEL GARNISH RH	1	\$	364.00	\$	364.00
130	REAR PANEL CENTER GARNISH	1	\$	420.00	\$	420.00
133	REAR HEAT SHIELD (UPPER)	1	\$	728.00	\$	728.00
134	REAR HEAT SHIELD (LOWER)	1	\$	196.00	\$	196.00
135	REAR HEAT SHIELD (CENTER)	1	\$	224.00	\$	224.00
136	REAR HEAT SHIELD CLIPS	22	\$	100.00	\$	100.00
137	REAR SILENCER LH	1	\$	5,964.00	\$	5,964.00
138	REAR SILENCER RH	1	\$	5,964.00	\$	5,964.00
139	REAR EXHAUST TRIM LH	1	\$	1,120.00	\$	1,120.00
140	REAR EXHAUST TRIM RH	1	\$	1,120.00	\$	1,120.00
141	REAR EXHAUST BRACKET LH	1	\$	112.00	\$	112.00
1	REAR EXHAUST BRACKET RH	1	\$	84.00	\$	84.00
163	REAR BUMPER	1	\$	14,056.00	\$	11,985.00
164	REAR BUMPER SPOILER	1	\$	9,240.00	\$	1,392.00
165	REAR BUMPER TOWING COVER	1	\$	336.00	\$	336.00
166	REAR BUMPER SENSOR BRACKET	2	\$	168.00	\$	168.00
167	REAR BUMPER SENSOR BRACKET (SPOILER) LH	1	\$	84.00	\$	84.00
168	REAR BUMPER SENSOR BRACKET (SPOILER) RH	1	\$	84.00	\$	84.00
169	REAR BUMPER RE-INFORCEMENT BAR	1	\$	2,380.00	\$	2,380.00
173	REAR BUMPER HEAT SHIELD LH	1	\$	224.00	\$	224.00
174	REAR BUMPER HEAT SHIELD RH	1	\$	224.00	\$	224.00
177	REAR BUMPER INNER BRACKET LH	1	\$	420.00	\$	420.00
178	REAR BUMPER INNER BRACKET RH	1	\$	420.00	\$	420.00
179	REAR BUMPER RIVET / NUT / CLIPS / SCREWS	18	\$	300.00	\$	300.00
				Total :	\$	168,421.00
				-20%	\$	33,684.20
				Parts Total :	\$	134,736.80
1	FRONT NUMBER PLATE				\$	40.00
2	REAR NUMBER PLATE				\$	40.00
				SPECIAL NETT :	\$	80.00

1	ELECTRICAL CHECKS ON WIRING, AIR SUPPLY UNIT (SUSPENSION), FRONT & REAR RADAR SENSOR, ANTI-COLLISION PREVENTION SYSTEM, AUTO TAILGATE LIFTER, AUTO TAILGATE RELEASE BUTTON, HEADLAMPS &	\$	400.00
---	---	----	--------

TAILLAMPS, EXHAUST OUTPUT AIR-FLOW, REAR BUMPER LAMP, REVERSE CAMERA, BATTERY SUPPLY UNIT.

1	PROGRAMMING RESET & RE-CALIBRATE LIGHTING ELECTRONICS (LAMPS ETC), REVERSE RADAR SENSOR PARKING DISTANCE, REVERSE CAMERA TO HEADUNIT CAN BUS READING, FRONT RADAR SENSING COLLISION PREVENTION, BOOT LID COMFORT ACCESS.	\$	300.00
1	LABOUR TO DISMANTLE, REPAIR & REPLACE PARTS AS STATED. WHOLE EXTERIOR SHELL REMOVAL FROM CHASSIS FOR PANEL BEATING OF REAR LH & RH FENDER.	\$	2,400.00
1	LABOUR TO REMOVE & REPLACE EXHAUST MUFFLER LH & RH, ALIGN TO REAR BUMPER LOWER DIFFUSER EXHAUST DUCT, EXHAUST MOUNTINGS.	\$	300.00
1	ANTI-RUST PROOFING & GALVANISE ON REAR END PANEL, REAR LH & RH FENDER (OUTER SHELL WHOLE PIECE), REAR LOWER FLOOR PANEL (SPARE TYRE TANK), FRONT REINFORCEMENT	\$	200.00
1	TO PRIMED, GALVANISE ZINC PUTTY, SPRAY-PAINTING (WATER-BORNE PAINT AS PER BENTLEY SPECIFICATION) FRONT BUMPER, FRONT LH & RH FENDER, FRONT RADIATOR GRILLE BASE, REAR LH & RH FENDER, REAR BOOTLID INNER, REAR BOOTLID OUTER, REAR BUMPER, REAR BUMPER LOWER DIFFUSER CENTER TRIM, REAR END PANEL INNER, REAR END PANEL OUTER, REAR BODY PANEL INNER, REAR BODY PANEL OUTER, FRONT & REAR 8 X RADAR SENSORS.	\$	2,800.00

Labour Total :	\$	6,400.00
Parts Total :	\$	134,736.80
Total :	\$	141,136.80
-20%	\$	28,227.36
Grand Total :	\$	112,909.44
Special Nett :	\$	80.00
Lump Sum :	\$	113,000.00

CHUAN HO AUTO SERVICE





Reg: 200504627K

DELIVERY ORDER

Date of order: 08.03.2019
Date of delivery: 03.06.2019
Name: Choon Chuan Ho Auto Service
Contact: 9069 1985

Address (for Part to be delivered): 160 Sin Ming Drive, #07-09, Singapore 575722.

ITEM	DESCRIPTION	Singapore	QTY
01.	ORIGINAL BENTLEY CONTI GT REPAIR SETS (*PLEASE REFER TO INVOICE)		1 SET

The above items are received in good order and condition, checked by

RECEIVER SIGNATURE

NAME:

DATE:



PREPARED BY

NAME: *Ben Tan*

DATE: *2/6/2019*



TAX INVOICE

Chuan Ho Auto Service
160 Sin Ming Drive
#07-09

Singapore 575722

Contact No.: 90691985

Account No. K1000	Service Advisor Rex Tan	Invoiced By Rex Tan	Invoice/Credit Note No. 21004792	W.I.P. No. 13834
Reg. No. NC#DC08209	Make & Model Bentley Conti GT	Chassis No. SCBFE63W9DC082090	Engine No.	Reg. Date --/--
Date & Time In --/-- 0.00	Date & Time Out --/-- 0.00	Mileage 0	Invoice Date & Time	

Attending Service Advisor: Rex Tan
Should you require further explanation, please reach me at 86886288

Next Service Date & Mileage:

--/-- 0

Description of Goods / Services	Qty.	Price	Disc %	Net Tot
Additional sockets				
BENTLEY FLAT CONTACT HOUSING 2 P ✓	1.00PC			
BENTLEY FLAT CONTACT HOUSING 8 P ✓	1.00PC			
BENTLEY FLAT CONTACT HOUSING 10 ✓	1.00PC			
Subtotal				
Air duct radiator (page 121-090)				
BENTLEY AIR DUCT RADIATOR LH	1.00PC			
BENTLEY AIR DUCT RADIATOR RH	1.00PC			
Subtotal				
Wiring harness (page 971-020)				
BENTLEY HARNESS FOR REAR BUMPER	1.00PC			
Subtotal				
Parking assist (page 919-020)				
BENTLEY PARKING SENSOR	2.00PC			
BENTLEY SEAL RING FOR SENSOR	2.00PC			
BENTLEY SENSOR BRACKET	2.00PC			
Subtotal				
Underbody lining (page 825-012)				
BENTLEY UNDERBODY TRIM REAR	1.00PC			
BENTLEY UNDERBODY TRIM LH REAR	1.00PC			
BENTLEY UNDERBODY TRIM RH REAR	1.00PC			

PAID
07 MAY 2018

BY: #2313 LL

Customer's Signature

Cashier's Signature

KBS Motorsports Pte

Inquiries to invoice must be lodged within 7 days from
invoice date.

160 Sin Ming
#06-03 Sin Ming Au
Singapore 57
T 6262 8888 | F 6452
www.kbsmotorsports.com
Company Registration Number: 200504
GST Registration Number: M90366



TAX INVOICE

uan Ho Auto Service
0 Sin Ming Drive
7-09

ngapore 575722

ntact No.: 90691985

Account No.	Service Advisor	Invoiced By	Invoice/Credit Note No.	W.I.P. No.
000	Rex Tan	Rex Tan	21004792	13834
g. No.	Make & Model	Chassis No.	Engine No.	Reg. Date
#DC08209	Bentley Conti GT	SCBFE63W9DC082090		---
te & Time In	Date & Time Out	Mileage	Invoice Date & Time	
--- 0.00	--- 0.00	0		

tending Service Advisor: Rex Tan
ould you require further explanation, please reach me at 86886288

Next Service Date & Mileage:
--- 0

Description of Goods / Services	Qty.	Price	Disc %	Net Total
BENTLEY BRACKET UNDERBODY LINING	1.00PC			
BENTLEY BRACKET UNDERBODY LINING	1.00PC			
BENTLEY BRACKET LH REAR	1.00PC			
BENTLEY BRACKET RH REAR	1.00PC			
				Subtotal
ish panel (page 813-010)				
BENTLEY REPAIR PLATE REAR	1.00PC			
				Subtotal
imper front (page 807-010)				
BENTLEY GRILLE LH INNER CHROME	1.00PC			
BENTLEY GRILLE RH INNER CHROME	1.00PC			
BENTLEY GRILLE LH OUTER CHROME	1.00PC			
BENTLEY GRILLE RH OUTER CHROME	1.00PC			
				Subtotal
are wheel well (page 803-010)				
BENTLEY SPARE WHEEL WELL	1.00PC			
				Subtotal
haust (page 253-080)				
BENTLEY EXHAUST BRACKET	2.00PC			
BENTLEY EXHAUST BRACKET	2.00PC			

ustomer's Signature

Cashier's Signature

KBS Motorsports Pte Ltd

nquiries to invoice must be lodged within 7 days from
nvoice date.

160 Sin Ming Drive
#06-03 Sin Ming Autocity
Singapore 575722
T 6262 8888 | F 6452 5333
www.kbsmotorsports.com.sg
Company Registration Number: 200504627K
GST Registration Number: M903684461



TAX INVOICE

Chuan Ho Auto Service
160 Sin Ming Drive
#07-09

Singapore 575722

Contact No.: 90691985

Account No.	Service Advisor	Invoiced By	Invoice/Credit Note No.	W.I.P. No.
K1000	Rex Tan	Rex Tan	21004792	13834
Reg. No.	Make & Model	Chassis No.	Engine No.	Reg. Date
NC#DC08209	Bentley Conti GT	SCBFE63W9DC082090		--/--
Date & Time In	Date & Time Out	Mileage	Invoice Date & Time	
--/-- 0.00	--/-- 0.00	0		

Attending Service Advisor: Rex Tan
Should you require further explanation, please reach me at 86886288

Next Service Date & Mileage:
--/-- 0

Description of Goods / Services	Qty.	Price	Disc %	Net Tc
BENTLEY SHEILD	2.00PC			
BENTLEY VACUUM UNIT	2.00PC			

Subtotal

Bumper rear (page 807-020)

BENTLEY GUIDE PIECE, LH INNER	1.00PC
BENTLEY GUIDE PIECE, RH INNER	1.00PC
BENTLEY EXPANDING NUT	20.00PC
BENTLEY COUNTERSUNK BOLT	4.00PC
BENTLEY HEXAGON SOCKET	22.00PC
BENTLEY SEAL LH	1.00PC
BENTLEY SEAL RH	1.00PC
BENTLEY RETAINING PLATE	1.00PC

Subtotal

Radiator grille (page 853-020)

BENTLEY RADIATOR GRILLE COVER	1.00PC
BENTLEY SUPPORT BRACKET LH	1.00PC
BENTLEY SUPPORT BRACKET RH	1.00PC
BENTLEY BRACKET FOR DIST MEASURE	1.00PC
BENTLEY BRACKET FOR DIST MEASURE	1.00PC
BENTLEY TRIM FOR RADIA GRILLE	1.00PC
BENTLEY RADIATOR GRILL LH	1.00PC
BENTLEY RADIATOR GRILL RH	1.00PC

Customer's Signature

Cashier's Signature

Inquiries to invoice must be lodged within 7 days from
invoice date.

KBS Motorsports Pte

160 Sin Ming
#06-03 Sin Ming Ave
Singapore 575722
T 6262 8888 | F 6457

www.kbsmotorsports.com

Company Registration Number: 200504
GST Registration Number: M90361



TAX INVOICE

Shuan Ho Auto Service
60 Sin Ming Drive
07-09

Singapore 575722

Contact No.: 90691985

Account No. 1000	Service Advisor Rex Tan	Invoiced By Rex Tan	Invoice/Credit Note No. 21004792	W.I.P. No. 13834
Eq. No. C#DC08209	Make & Model Bentley Conti GT	Chassis No. SCBFE63W9DC082090	Engine No.	Reg. Date --/--
Start & Time In --/-- 0.00	Date & Time Out --/-- 0.00	Mileage 0	Invoice Date & Time	

Attending Service Advisor: Rex Tan
Should you require further explanation, please reach me at 86886288

Next Service Date & Mileage:
--/-- 0

Description of Goods / Services	Qty.	Price	Disc %	Net Total
ENTLEY BADGE (SELF-AD)	1.00PC			
ENTLEY BADGE	1.00PC			
ENTLEY SEAL	1.00PC			
ENTLEY OVAL HEXAGON SOCKET	12.00PC			
ENTLEY OVAL HEAD SCREW	16.00PC			
ENTLEY OVAL HEAD SCREW	10.00PC			
ENTLEY OVAL HEXAGON SOCKET	10.00PC			
ENTLEY HEXAGON NUT	10.00PC			
ENTLEY BRACKET LH	1.00PC			
ENTLEY BRACKET RH	1.00PC			
ENTLEY SPACER PIECE	2.00PC			
ENTLEY HEXAGON SOCKET	10.00PC			
ENTLEY FOAM FILLER RADIA GRILLE	2.00PC			
ENTLEY RETAINING CLIP	2.00PC			

Subtotal

Vehicle tools (page 011-020)

ENTLEY RETAINING CLIP	1.00
ENTLEY OVAL HEXAGON SOCKET	3.00
ENTLEY OVAL HEAD PNAEL SCREW	4.00
ENTLEY OVAL HEXAGON SOCKET	30.00

Customer's Signature

Cashier's Signature

KBS Motorsports Pte Ltd

Enquiries to invoice must be lodged within 7 days from
invoice date.

160 Sin Ming Drive
#06-03 Sin Ming Autocity
Singapore 575722
T 6262 8888 | F 6452 5333
www.kbsmotorsports.com.sg
Company Registration Number: 200504637K



TAX INVOICE

Chuan Ho Auto Service
160 Sin Ming Drive
#07-09

Singapore 575722

Contact No.: 90691985

Account No. K1000	Service Advisor Rex Tan	Invoiced By Rex Tan	Invoice/Credit Note No. 21004792	W.I.P. No. 13834
Reg. No. NC#DC08209	Make & Model Bentley Conti GT	Chassis No. SCBFE63W9DC082090	Engine No.	Reg. Date --/--
Date & Time In --/-- 0.00	Date & Time Out --/-- 0.00	Mileage 0	Invoice Date & Time	

Attending Service Advisor: Rex Tan
Should you require further explanation, please reach me at 86886288

Next Service Date & Mileage:
--/-- 0

Description of Goods / Services	Qty.	Price	Disc %	Net To
Package				
				Subtotal
Exhaust vacuum (page 253-090)				
BENTLEY VACUUM TANK	1.00PC			
BENTLEY SOLENOID VALVE	1.00PC			
BENTLEY VACUUM PIPE	1.00PC			
				Subtotal

Currency SGD

Net	
Add GST @7%	
Discount	0.
Total	
Paid/Deposit	
Balance	

Customer's Signature

Cashier's Signature

KBS Motorsports Pte L

Inquiries to invoice must be lodged within 7 days from
invoice date.

160 Sin Ming D
#06-03 Sin Ming Auto
Singapore 575
T 6262 8888 | F 6452 5
www.kbmotorsports.com
Company Registration Number: 2005046
GST Registration Number: M905684



TAX INVOICE

Chuan Ho Auto Service
160 Sin Ming Drive
#07-09

575722

Contact No.: 90691985		Invoice/Credit Note No. 21004952		W.I.P. No. 14042
Account No. K1000	Service Advisor	Invoiced By Rex Tan		
Reg. No. NC#DC08209	Make & Model Bentley Conti GT	Chassis No. SCBFE63W9DC082090	Engine No.	Reg. Date
Date & Time In	Date & Time Out	Mileage 0	Invoice Date & Time	
0.00	0.00		Next Service Date & Mileage: 0	

Attending Service Advisor:
Should you require further explanation, please reach me at

Description of Goods / Services	Qty.	Price	Disc %	Net Total
Dash panel (page 813-010) BENTLEY REPAIR PLATE	1.00PC			Subtotal
Heat shield (page 825-020) BENTLEY HEAT SHIELD	1.00PC			
BENTLEY HEAT SHIELD	1.00PC			Subtotal

PAID
29 MAY 2019

BY: #231837

Currency SG

Net	
Add GST @7%	
Discount	0.00
Total	
Paid/Deposit	(0.00)
Balance	

Customer's Signature

Cashier's Signature

KBS Motorsports Pte L

Inquiries to invoice must be lodged within 7 days from
invoice date.

160 Sin Ming T
#06-03 Sin Ming Ave
Singapore 57
T 6262 8888 F 6452
www.kbsmotorsports.co
Company Registration Number: 2003046
GST Registration Number: M90368

Print Received Message

This mail is associated with :

***SDS1666A (MCT19030186)**
[SHC8802P]

TP

KHNG THIAN HUAT

Mar 7 2019 2:00PM

[-]

Chuan Ho Auto Service

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 22/11/2019 13:55 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - SDS1666A - Claim Handler: Sherini Pillai

Approved:0.00:Please go ahead & offer a global sum of \$130,000.00 as agreed.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement










































CLAIM SUBFOLDER TRACKING






















































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Mar 2019 Edit Reg		14 Mar 2019 00:00 Edit Adj Rpt	S\$113,000.00 Edit Estimates	S\$113,000.00 View Rpt		Pending for Survey Report Cancel Case























































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	KHNG THIAN HUAT, ID: S0100189B								
Vehicle Reg. No.:	SDS1666A	Date of Loss:	07/03/2019 14:00 - :59 [76 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19030186	Policy/Cover Note No.:	MCOM0015 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	SHC8802P	Policy No. (Claimant):	CN036457						
		Excess:							
Repairer:	Chuan Ho Auto Service (Sin Ming) 160 Sin Ming Drive, #07-09, Sin Ming AutoCity, S75722 Sin Ming - Tel: 91892365								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 27/03/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (22/11/2019): Alert - Adj Mandate Approved (S\$0.00) - SDS1666A - Claim Handler: Sherini Pillai III_SG (08/11/2019): Alert - Adj Mandate Maintained - SDS1666A - Claim Handler: Sherini Pillai III_SG (08/08/2019): Alert - Adj Mandate Maintained - SDS1666A - Claim Handler: Sherini Pillai III_SG (25/06/2019): Alert - Adj Mandate Maintained - SDS1666A - Claim Handler: Sherini Pillai III_SG (29/03/2019): Alert - Adj Mandate Approved (S\$0.00) - SDS1666A - Claim Handler: Sherini Pillai 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									























































Claim Documents
























































*SDS1666A (MCT19030186)
[SHC8802P]
TP
KHNG THIAN HUAT
Mar 7 2019 2:00PM
[COMFORT TRANSPORTATION PTE LTD]
Chuan Ho Auto Service


Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Video									1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	India International Insurance Pte Ltd (HQ)							Thumbnail			Print		
1	29/03/19 15:21	Video - Accident										Load MP4		
Photos/Images									3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail			Print		
1	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
2	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
3	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
4	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
5	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
6	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
7	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
8	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
9	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
10	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
11	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
12	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
13	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
14	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
15	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
16	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
17	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
18	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
19	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
20	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
21	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
22	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
23	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
24	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
25	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
26	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
27	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
28	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
29	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
30	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
31	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
32	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
33	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
34	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
35	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
36	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
37	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
38	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
39	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		
40	20/06/19 18:35	General View										<input checked="" type="checkbox"/>		

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
41	20/06/19 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
42	20/06/19 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
43	20/06/19 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
44	20/06/19 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
45	20/06/19 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
46	20/06/19 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
47	20/06/19 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
48	20/06/19 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
49	20/06/19 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
50	20/06/19 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
51	20/06/19 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
52	20/06/19 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
53	20/06/19 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
54	20/06/19 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
55	20/06/19 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
56	20/06/19 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
57	20/06/19 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
58	20/06/19 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
59	20/06/19 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
60	20/06/19 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
61	20/06/19 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
62	20/06/19 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
63	20/06/19 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
64	20/06/19 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
65	20/06/19 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
66	20/06/19 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
67	20/06/19 18:35	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
68	20/06/19 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
69	20/06/19 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
70	20/06/19 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
71	20/06/19 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
72	20/06/19 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
73	20/06/19 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
74	20/06/19 18:35	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
75	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	20/06/19 18:36	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
95	20/06/19 18:36	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
96	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
97	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
98	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
99	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
100	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
101	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
102	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
103	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
104	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
105	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
106	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
107	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
108	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
109	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
110	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
111	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
112	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
113	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
114	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
115	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
116	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
117	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
118	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
119	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
120	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
121	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
122	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
123	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
124	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
125	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
126	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
127	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
128	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
129	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
130	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
131	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
132	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
133	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
134	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
135	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
136	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
137	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
138	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
139	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
140	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
141	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
142	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
143	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
144	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
145	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
146	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
147	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
148	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
149	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
150	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
151	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
152	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
153	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
154	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
155	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
156	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
157	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
158	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
159	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
160	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
161	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
162	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
163	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
164	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
165	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
166	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
167	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
168	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
169	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
170	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
171	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
172	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
173	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
174	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
175	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
176	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
177	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
178	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
179	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
180	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
181	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
182	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
183	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
184	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
185	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
186	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
187	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
188	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
189	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
190	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
191	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
192	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
193	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
194	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
195	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
196	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
197	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
198	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
199	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
200	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
201	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
202	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
203	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
204	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
205	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
206	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
207	20/06/19 18:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
208	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
209	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
210	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
211	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
212	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
213	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
214	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
215	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
216	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
217	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
218	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
219	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
220	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
221	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
222	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
223	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
224	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
225	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
226	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
227	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
228	20/06/19 18:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
229	20/06/19 18:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
230	20/06/19 18:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
231	20/06/19 18:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
232	20/06/19 18:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
233	20/06/19 18:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
234	20/06/19 18:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
235	20/06/19 18:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
236	20/06/19 18:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
237	20/06/19 18:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
238	20/06/19 18:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
239	20/06/19 18:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
240	20/06/19 18:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
241	20/06/19 18:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
242	20/06/19 18:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
243	20/06/19 18:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
244	20/06/19 18:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
245	20/06/19 18:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/03/19 21:15	TP DOCS	 Load PDF	
2	23/03/19 16:38	TP GIA REPORT	 Load PDF	
3	04/04/19 11:12	TP ESTIMATE - MARKED	 Load PDF	
4	25/06/19 10:16	Market value+PRAF and COE rebate form	 Load PDF	
5	25/06/19 10:16	TP Estimate-Marked revise	 Load PDF	
6	19/07/19 16:42	Indent order documents	 Load PDF	
7	05/08/19 16:44	INDENT ORDER - KBS INVOICES	 Load PDF	
8	03/10/19 15:37	FINAL REPAIR BILL	 Load PDF	
9	06/11/19 07:54	KBS Tax Invoice W.I.P No.13834	 Load PDF	
10	06/11/19 07:54	KBS Tax Invoice W.I.P No.14042	 Load PDF	
11	22/11/19 13:59	III APPROVAL	 Load PDF	
12	29/11/19 09:16	WORKSHOP INVOICE	 Load PDF	
13	29/11/19 09:16	AUTHORISATION TO ACT FORM	 Load PDF	
14	29/11/19 09:16	DISCHARGE VOUCHER	 Load PDF	
15	29/11/19 09:16	LOD	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	19/03/19 09:18	Singapore Accident Statement	 Load PDF	
2	29/03/19 15:18	Singapore Accident Statement SKDB204A SAS	 Load PDF	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
3	29/03/19 15:18	Singapore Accident Statement SLF5877E SAS	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III19004918/EPA3Q2

Date: 29/11/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant Vehicle No: SDS1666A Insured Vehicle No: SHC8802P
 Date of Loss: 07/03/2019 Nature of Claim: TP Claim No: MCT19030186

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDS1666A
 Make & Model: BENTLEY CONTINENTAL GT SPEED, 6.0 (A) Engine No: CKH014441
 Reg. Date: 24/10/2012 (Man. Year: 2012) Chassis No: SCBFE63W9DC082090
 Colour: Black Odometer: 37547 km
 Engine Capacity: 5998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 275/35Z R21 Rear Tyre Size: 275/35Z R21
 Front Left Side: Firelli 7 mm Rear Left Side: Firelli 7 mm
 Front Right Side: Firelli 7 mm Rear Right Side: Firelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	288,365.12	134,816.80	153,548.32	53.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	31,750.00	6,400.00	25,350.00	79.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	320,115.12	141,216.80	178,898.32	55.89
Approved Total (Overridden) (S\$)		113,000.00		
Nett Amount (S\$)	320,115.12	113,000.00	207,115.12	64.70
+ Loss of Use (85.0 x S\$200.00/day) (S\$)		17,000.00		
Nett Liability (S\$)		130,000.00		
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 14/03/2019
 Date Inspected: 14/03/2019 Inspected At: Chuan Ho Auto Service (Sin Ming)
 160 Sin Ming Drive, #07-09, Sin Ming
 AutoCity
 Singapore 575722

Estimated Period of Repair: 14.0 days

Adjuster: CHEN TSUE YEE

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Oct 2019)
Parts:	M1-COUPE	BENTLEY CONTINENTAL GT SPEED 6.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDS1666A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP LH	Broken	13,356.00 FL	*9,600.00 FL
2	1		*HEADLAMP RH	Broken	13,356.00 FL	*9,600.00 FL
3	1		*FRONT REINFORCEMENT BAR	Dented	2,912.00 FL	*2,912.00 FL
4	1		*FRONT BUMPER	Broken	8,792.00 FL	*8,792.00 FL
5	1		*FRONT BUMPER SIDE BRACKET LH	Broken	252.00 FL	*252.00 FL
6	1		*FRONT BUMPER SIDE BRACKET RH	Broken	252.00 FL	*252.00 FL
7	1		*FRONT BUMPER BRACKET OUTER LH	Broken	112.00 FL	*112.00 FL
8	1		*FRONT BUMPER BRACKET OUTER RH	Broken	112.00 FL	*112.00 FL
9	1		*FRONT BUMPER BRACKET INNER LH	Broken	308.00 FL	*308.00 FL
10	1		*FRONT BUMPER BRACKET INNER RH	Broken	308.00 FL	*308.00 FL
11	1		*FRONT BUMPER LOWER GRILLE LH	Cut	1,932.00 FL	*1,932.00 FL
12	1		*FRONT BUMPER LOWER GRILLE RH	Broken	1,932.00 FL	*1,932.00 FL
13	1		*FRONT BUMPER LOWER GRILLE LH (SMALL)	Cut	1,092.00 FL	*1,092.00 FL
14	1		*FRONT BUMPER LOWER GRILLE RH (SMALL)	Cut	1,092.00 FL	*1,092.00 FL
15	1		*FRONT BUMPER CLIPS (23 PCS)	Necessary	1,288.00 FL	*300.00 FL
16	2		*FRONT BUMPER CLIPS	Not Necessary	56.00 FL	*- FL
17	6		*FRONT BUMPER CLIPS	Not Necessary	336.00 FL	*- FL
18	4		*FRONT BUMPER CLIPS	Not Necessary	112.00 FL	*- FL
19	1		*FRONT RADIATOR GRILLE BASE	Broken	4,620.00 FL	*4,620.00 FL
20	1		*FRONT RADIATOR GRILLE TOP GARNISH	Broken	336.00 FL	*336.00 FL
21	1		*FRONT RADIATOR GRILLE TOP GARNISH STRIP	Crushed	280.00 FL	*280.00 FL
22	1		*FRONT RADIATOR GRILLE BRACKET LH	Missing	140.00 FL	*140.00 FL
23	1		*FRONT RADIATOR GRILLE BRACKET RH	Missing	140.00 FL	*140.00 FL
24	1		*FRONT RADIATOR GRILLE BRACKET LH	Missing	84.00 FL	*84.00 FL
25	1		*FRONT RADIATOR GRILLE BRACKET RH	Missing	84.00 FL	*84.00 FL
26	1		*FRONT RADIATOR GRILLE SEAL	Missing	336.00 FL	*336.00 FL
27	1		*FRONT RADIATOR GRILLE TRIM	Missing	2,156.00 FL	*2,156.00 FL
28	1		*FRONT RADIATOR GRILLE	Broken	1,652.00 FL	*1,652.00 FL
29	1		*FRONT GRILLE BADGE (TOP)	Missing	168.00 FL	*168.00 FL
30	1		*FRONT GRILLE BADGE	Missing	1,232.00 FL	*1,232.00 FL
31	1		*FRONT GRILLE BADGE SEAL	Missing	140.00 FL	*140.00 FL
32	1		*FRONT RADIATOR GRILLE MIDDLE BRACKET LH	Missing	224.00 FL	*224.00 FL
33	1		*FRONT RADIATOR GRILLE MIDDLE BRACKET RH	Missing	224.00 FL	*224.00 FL
34	20		*FRONT RADIATOR GRILLE RIVET	Not Necessary	280.00 FL	*- FL
35	12		*FRONT RADIATOR GRILLE RIVET	Not Necessary	336.00 FL	*- FL
36	16		*FRONT RADIATOR GRILLE RIVET	Necessary	896.00 FL	*200.00 FL
37	10		*FRONT RADIATOR GRILLE RIVET	Not Necessary	840.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	10		*FRONT RADIATOR GRILLE RIVET	Not Necessary	560.00 FL	*- FL
39	10		*FRONT RADIATOR GRILLE RIVET	Not Necessary	840.00 FL	*- FL
40	2		*FRONT RADIATOR GRILLE SPACER	Not Necessary	280.00 FL	*- FL
41	10		*FRONT RADIATOR GRILLE HEXAGON SOCKET	Not Necessary	840.00 FL	*- FL
42	2		*FRONT RADIATOR GRILLE FOAM FILTER	Broken	252.00 FL	*252.00 FL
43	2		*FRONT RADIATOR GRILLE CLIPS	Not Necessary	504.00 FL	*- FL
44	1		*FRONT BONNET	Repair	2,500.40 FL	*- FL
45	1		*FRONT BONNET SEAL	Not Necessary	2,352.00 FL	*- FL
46	1		*FRONT FENDER LH	Dented	18,424.00 FL	*16,698.00 FL
47	1		*FRONT FENDER RH	Dented	18,424.00 FL	*16,698.00 FL
48	1		*FRONT HEADLAMP TRIM LH (BIG)	Necessary	420.00 FL	*420.00 FL
49	1		*FRONT HEADLAMP TRIM RH (BIG)	Necessary	420.00 FL	*420.00 FL
50	1		*FRONT HEADLAMP TRIM LH (SMALL)	Necessary	392.00 FL	*392.00 FL
51	1		*FRONT HEADLAMP TRIM RH (SMALL)	Necessary	392.00 FL	*392.00 FL
52	1		*FRONT FENDER BRACKET LH	Not Necessary	420.00 FL	*- FL
53	1		*FRONT FENDER BRACKET RH	Not Necessary	420.00 FL	*- FL
54	1		*FRONT FENDER TOP BRACKET LH (BIG)	Not Necessary	42.00 FL	*- FL
55	1		*FRONT FENDER TOP BRACKET RH (BIG)	Not Necessary	42.00 FL	*- FL
56	1		*FRONT FENDER TOP BRACKET LH (SMALL)	Not Necessary	28.00 FL	*- FL
57	1		*FRONT FENDER TOP BRACKET RH (SMALL)	Not Necessary	28.00 FL	*- FL
58	2		*FRONT FENDER CLIPS	Not Necessary	448.00 FL	*- FL
59	1		*FRONT FENDER CLIPS (28 PCS)	Necessary	3,136.00 FL	*100.00 FL
60	1		*FRONT FENDER CLIPS (28 PCS)	Necessary	2,352.00 FL	*100.00 FL
61	4		*FRONT FENDER CLIPS	Not Necessary	336.00 FL	*- FL
62	10		*FRONT FENDER CLIPS	Not Necessary	840.00 FL	*- FL
63	1		*FRONT AIRGUIDE	Not Necessary	140.00 FL	*- FL
64	8		*FRONT BUMPER SENSOR	Not Necessary	28,000.00 FL	*- FL
65	1		*FRONT SUPPORT FRAME	Not Necessary	11,088.00 FL	*- FL
66	1		*FRONT CROSS MEMBER	Not Necessary	1,736.00 FL	*- FL
67	1		*FRONT GEARBOX SUPPORT	Not Necessary	1,204.00 FL	*- FL
68	2		*FRONT SUPPORT PANEL SCREW /CLIPS /RIVET	Not Necessary	560.00 FL	*- FL
69	2		*FRONT SUPPORT PANEL SCREW /CLIPS /RIVET	Not Necessary	112.00 FL	*- FL
70	3		*FRONT SUPPORT PANEL SCREW /CLIPS /RIVET	Not Necessary	168.00 FL	*- FL
71	1		*FRONT SUPPORT PANEL SCREW /CLIPS /RIVET	Not Necessary	28.00 FL	*- FL
72	3		*FRONT SUPPORT PANEL SCREW /CLIPS /RIVET		84.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Not Necessary		
73	4		*FRONT SUPPORT PANEL SCREW /CLIPS /RIVET	Not Necessary	224.00 FL	*- FL
74	4		*FRONT SUPPORT PANEL SCREW /CLIPS /RIVET	Not Necessary	224.00 FL	*- FL
75	4		*FRONT SUPPORT PANEL SCREW /CLIPS /RIVET	Not Necessary	448.00 FL	*- FL
76	4		*FRONT SUPPORT PANEL SCREW /CLIPS /RIVET	Not Necessary	1,008.00 FL	*- FL
77	3		*FRONT SUPPORT PANEL SCREW /CLIPS /RIVET	Not Necessary	168.00 FL	*- FL
78	1		*REAR BUMPER UNDER COVER (BIG)	Missing	1,288.00 FL	*1,288.00 FL
79	1		*REAR BUMPER UNDER COVER LH	Missing	868.00 FL	*868.00 FL
80	1		*REAR BUMPER UNDER COVER RH	Missing	868.00 FL	*868.00 FL
81	1		*REAR BUMPER UNDER COVER BRACKET LH	Missing	168.00 FL	*168.00 FL
82	1		*REAR BUMPER UNDER COVER BRACKET RH	Missing	168.00 FL	*168.00 FL
83	1		*REAR BUMPER UNDER COVER SIDE BRACKET LH	Missing	112.00 FL	*112.00 FL
84	1		*REAR BUMPER UNDER COVER SIDE BRACKET RH	Missing	112.00 FL	*112.00 FL
85	1		*FRONT BUMPER UNDER COVER	Not Necessary	2,660.00 FL	*- FL
86	1		*FRONT BUMPER UNDER COVER LH	Not Necessary	252.00 FL	*- FL
87	1		*FRONT BUMPER UNDER COVER RH	Not Necessary	280.00 FL	*- FL
88	1		*FRONT BUMPER UNDER COVER SUPPORT BRACKET	Not Necessary	252.00 FL	*- FL
89	1		*BUMPER UNDER COVER CLIPS (31 PCS)	Not Necessary	868.00 FL	*- FL
90	2		*BUMPER UNDER COVER CLIPS	Not Necessary	56.00 FL	*- FL
91	6		*BUMPER UNDER COVER CLIPS	Not Necessary	336.00 FL	*- FL
92	1		*SET REAR WIRING	Broken	588.00 FL	*588.00 FL
93	1		*SET FRONT WIRING	Not Necessary	364.00 FL	*- FL
94	1		*REAR BOOTLID REVERSE CAMERA	Not Necessary	1,596.00 FL	*- FL
95	1		*SET REAR BOOTLID REVERSE CAMERA WIRING	Not Necessary	420.00 FL	*- FL
96	1		*REAR BUMPER LAMP (LOWER)	Broken	5,880.00 FL	*4,900.00 FL
97	1		*REAR BOOTLID	Dented	18,424.00 FL	*15,650.00 FL
98	1		*REAR BOOTLID TOP LOCK	Jammed	1,512.00 FL	*1,512.00 FL
99	1		*REAR BOOTLID LOCK	Bent	336.00 FL	*336.00 FL
100	1		*REAR BOOTLID CLOSING ELEMENT	Not Necessary	112.00 FL	*- FL
101	10		*REAR BOOTLID CLIPS /RIVET	Necessary	280.00 FL	*50.00 FL
102	1		*REAR BOOTLID LOCK FRAME	Bent	112.00 FL	*112.00 FL
103	1		*REAR BOOTLID HANDLE SHELL	Not Necessary	392.00 FL	*- FL
104	1		*REAR BOOTLID SEAL	Crushed	1,008.00 FL	*1,008.00 FL
105	2		*REAR BOOTLID DAMPER	Not Necessary	784.00 FL	*- FL
106	3		*REAR BOOTLID HEXAGON NUT	Not Necessary	84.00 FL	*- FL
107	1		*REAR BOOTLID TRIM	Dented	532.00 FL	*532.00 FL
108	1		*REAR BOOTLID REVERSE CAM GARNISH	Not Necessary	168.00 FL	*- FL
109	2		*REAR BOOTLID LED LICENSE PLATE LAMP	Not Necessary	1,008.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
110	1		*REAR BODY PANEL	Dented	12,796.00 FL	*10,236.00 FL
111	1		*REAR BODY PANEL LH	Not Necessary	6,972.00 FL	*- FL
112	1		*REAR BODY PANEL RH	Not Necessary	6,972.00 FL	*- FL
113	1		*REAR BODY PANEL COVER LH	Missing	196.00 FL	*196.00 FL
114	1		*REAR BODY PANEL COVER RH	Missing	196.00 FL	*196.00 FL
115	1		*REAR SPARE WHEEL COMPARTMENT PANEL	Broken	2,016.00 FL	*2,016.00 FL
116	1		*REAR FENDER LH	Repair	19,264.00 FL	*- FL
117	1		*REAR FENDER RH	Repair	19,264.00 FL	*- FL
118	1		*REAR FENDER PANEL	Repair	532.00 FL	*- FL
119	1		*REAR FENDER SOUND PANEL LH (BIG)	Not Necessary	252.00 FL	*- FL
120	1		*REAR FENDER SOUND PANEL RH (BIG)	Not Necessary	252.00 FL	*- FL
121	1		*REAR FENDER SOUND PANEL RH (SMALL)	Not Necessary	252.00 FL	*- FL
122	1		*REAR FENDER SOUND PANEL LH (SMALL)	Not Necessary	252.00 FL	*- FL
123	1		*REAR END PANEL	Dented	644.00 FL	*644.00 FL
124	1		*REAR TAIL LAMP MOUNTING LH	Not Necessary	336.00 FL	*- FL
125	1		*REAR TAIL LAMP MOUNTING RH	Not Necessary	336.00 FL	*- FL
126	1		*REAR TAIL LAMP INNER BRACKET LH	Not Necessary	532.00 FL	*- FL
127	1		*REAR TAIL LAMP INNER BRACKET RH	Not Necessary	644.00 FL	*- FL
128	1		*REAR PANEL GARNISH LH	Broken	364.00 FL	*364.00 FL
129	1		*REAR PANEL GARNISH RH	Broken	364.00 FL	*364.00 FL
130	1		*REAR PANEL GARNISH GARNISH	Crushed	420.00 FL	*420.00 FL
131	1		*REAR PANEL SIDE GARNISH LH	Not Necessary	1,316.00 FL	*- FL
132	1		*REAR PANEL SIDE GARNISH RH	Not Necessary	1,316.00 FL	*- FL
133	1		*REAR HEAT SHIELD (UPPER)	Missing	728.00 FL	*728.00 FL
134	1		*REAR HEAT SHIELD (LOWER)	Missing	196.00 FL	*196.00 FL
135	1		*REAR HEAT SHIELD (CENTER)	Missing	224.00 FL	*224.00 FL
136	1		*REAR HEAT SHIELD CLIPS (22 PCS)	Necessary	1,848.00 FL	*100.00 FL
137	1		*REAR SILENCER LH	Dented	5,964.00 FL	*5,964.00 FL
138	1		*REAR SILENCER RH	Dented	5,964.00 FL	*5,964.00 FL
139	1		*REAR EXHAUST TRIM LH	Dented	1,120.00 FL	*1,120.00 FL
140	1		*REAR EXHAUST TRIM RH	Missing	1,120.00 FL	*1,120.00 FL
141	1		*REAR EXHAUST BRACKET LH	Dented	112.00 FL	*112.00 FL
142	1		*REAR EXHAUST BRACKET RH	Missing	84.00 FL	*84.00 FL
143	4		*REAR EXHAUST SCREW	Not Necessary	112.00 FL	*- FL
144	20		*REAR EXHAUST SCREW	Not Necessary	2,240.00 FL	*- FL
145	1		*AIR SUPPLY UNIT	Not Necessary	13,804.00 FL	*- FL
146	1		*AIR SUPPLY UNIT VALVE	Not Necessary	504.00 FL	*- FL
147	1		*AIR SUPPLY UNIT UNIT	Not Necessary	3,640.00 FL	*- FL
148	1		*AIR SUPPLY INTAKE HOSE	Not Necessary	56.00 FL	*- FL
149	1		*AIR SUPPLY PRESSURE ACCUM	Not Necessary	2,548.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
150	1		*AIR SUPPLY AIR LINE	Not Necessary	700.00 FL	*- FL
151	1		*AIR SUPPLY AIR LINE	Not Necessary	420.00 FL	*- FL
152	1		*AIR SUPPLY AIR LINE	Not Necessary	28.00 FL	*- FL
153	1		*AIR SUPPLY AIR LINE	Not Necessary	672.00 FL	*- FL
154	1		*AIR SUPPLY AIR LINE	Not Necessary	756.00 FL	*- FL
155	1		*AIR SUPPLY AIR LINE	Not Necessary	784.00 FL	*- FL
156	10		*AIR SUPPLY CLIPS	Not Necessary	560.00 FL	*- FL
157	2		*AIR SUPPLY SPRING BAND	Not Necessary	56.00 FL	*- FL
158	2		*AIR SUPPLY HEXAGON SCREW	Not Necessary	56.00 FL	*- FL
159	3		*AIR SUPPLY HEXAGON SCREW	Not Necessary	84.00 FL	*- FL
160	10		*AIR SUPPLY HEXAGON SCREW	Not Necessary	560.00 FL	*- FL
161	4		*AIR SUPPORT CLIPS	Not Necessary	448.00 FL	*- FL
162	1		*AIR SUPPORT CLIPS	Not Necessary	196.00 FL	*- FL
163	1		*REAR BUMPER	Broken	14,056.00 FL	*11,985.00 FL
164	1		*REAR BUMPER SPOILER	Broken	9,240.00 FL	*7,392.00 FL
165	1		*REAR BUMPER TOWING COVER	Broken	336.00 FL	*336.00 FL
166	2		*REAR BUMPER SENSOR BRACKET	Broken	168.00 FL	*168.00 FL
167	1		*REAR BUMPER SENSOR BRACKET (SPOILER) LH	Broken	84.00 FL	*84.00 FL
168	1		*REAR BUMPER SENSOR BRACKET (SPOILER) RH	Broken	84.00 FL	*84.00 FL
169	1		*REAR BUMPER REINFORCEMENT BAR	Dented	2,380.00 FL	*2,380.00 FL
170	1		*REAR PANEL CAP	Not Necessary	784.00 FL	*- FL
171	1		*REAR PANEL CAP	Not Necessary	784.00 FL	*- FL
172	1		*REAR BUMPER BRACKET FLAP	Not Necessary	112.00 FL	*- FL
173	1		*REAR BUMPER HEAT SHIELD LH	Missing	224.00 FL	*224.00 FL
174	1		*REAR BUMPER HEAT SHIELD RH	Missing	224.00 FL	*224.00 FL
175	1		*REAR BUMPER BRACKET LH	Not Necessary	224.00 FL	*- FL
176	1		*REAR BUMPER BRACKET RH	Not Necessary	224.00 FL	*- FL
177	1		*REAR BUMPER INNER BRACKET LH	Broken	420.00 FL	*420.00 FL
178	1		*REAR BUMPER INNER BRACKET RH	Broken	420.00 FL	*420.00 FL
179	1		*REAR BUMPER RIVET /NUT/CLIPS/SCREWS (18 PCS)	Necessary	1,008.00 FL	*300.00 FL
180	4		*REAR BUMPER RIVET /NUT/CLIPS/SCREWS	Necessary	112.00 FL	*- FL
181	20		*REAR BUMPER RIVET /NUT/CLIPS/SCREWS	Not Necessary	2,240.00 FL	*- FL
182	4		*REAR BUMPER RIVET /NUT/CLIPS/SCREWS	Not Necessary	224.00 FL	*- FL
183	4		*REAR BUMPER RIVET /NUT/CLIPS/SCREWS	Not Necessary	224.00 FL	*- FL
184	1		*REAR BUMPER RIVET /NUT/CLIPS/SCREWS (22 PCS)	Not Necessary	1,232.00 FL	*- FL
185	4		*REAR BUMPER RIVET /NUT/CLIPS/SCREWS	Not Necessary	224.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
186	4		*REAR BUMPER RIVET /NUT/CLIPS/SCREWS	Not Necessary	224.00 FL	*- FL
187	1		*REAR BUMPER RIVET /NUT/CLIPS/SCREWS	Not Necessary	56.00 FL	*- FL
188	2		*REAR BUMPER RIVET /NUT/CLIPS/SCREWS	Not Necessary	112.00 FL	*- FL
189	2		*REAR BUMPER RIVET /NUT/CLIPS/SCREWS	Not Necessary	112.00 FL	*- FL
190	2		*REAR BUMPER RIVET /NUT/CLIPS/SCREWS	Not Necessary	112.00 FL	*- FL
191	1		*FRONT NUMBER PLATE	Necessary	80.00 FS	*40.00 FS
192	1		*REAR NUMBER PLATE	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	360,416.40	168,501.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	72,051.28	33,684.20
Total Parts (\$\$)	288,365.12	134,816.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ELECTRICAL CECKS ON WIRING ,AIR SUPPLY UNIT (SUSPENSION) ,FRONT & REAR RADAR SENSOR ,ANTI-COLLISIO PREVENTION SYSTEM ,AUTO TAILGATE LIFTER ,AUTO TAILGATE RELEASE BUTTON ,HEADLAMPS & TAILLAMPS,EXHAUST OUTPUT AIR-FLOW ,REAR BUMPER LAMP ,REVERSE CAMERA ,BATTERY SUPPLY UNIT	New	4,500.00	400.00
2	PROGRAMMING RESET & RE-CALIBRATION AIR REGULATED SUSPENSION ,HEIGHT & COMPRESSION REGULATIONS FOR ALL 4 X SUSPENSIONS	New	2,600.00	0.00
3	PROGRAMMING RESET & RE-CALIBRATE LIGHTING ELECTRONICS (LAMPS ETC),REVERSE RADAR SENSOR PARKING DISTANCE ,REVERSE CAMERA TO HEADUNIT CAN BUS READING ,FRONT RADAR SENSING COLLISION PREVENTION ,BOOT LID COMFORT ACCESS	New	2,800.00	300.00
4	LABOUR TO DISMANTLE ,REPAIR & REPLACE PARTS AS STATED .WHOLE EXTERIOR SHELL REMOVAL FROM CHASSIS FOR PANEL BEATING OF REAR LH & RH FENDER	New	3,500.00	2,400.00
5	LBOUR FOR CHASSIS & BODY ALIGNMENT ,PARTS FITMENT	New	5,500.00	0.00
6	LABOUR TO REPLACE REAR END PANEL	New	850.00	0.00
7	LABOUR TO REMOVE & REPLACE EXHAUST MUFFLER LH & RH ,ALIGN TO REAR BUMPER LOWER DIFFUSER EXHAUST DUCT ,EXHAUST MOUNTINGS	New	1,200.00	300.00
8	ANTI RUST PROOFING & GALVANISE ON REAR END PANEL,REAR LH & RH FENDER (OUTER SHELL WHOLE PIECE),REAR LOWER FLOOR PANEL (SPARE TYRE TANK) ,FRONT REINFORCEMENT	New	1,800.00	200.00
9	TO PRIMED ,GALVANISE ZINC PUTTY ,SPRAY -PAINTING (WATER-BORNE PAINT AS PER BENTLEY SPECIFICATION) FRONT BUMPER ,FRONT LH & RH FENDER ,FRONT RADIATOR GRILLE BASE ,REAR LH & RH FENDER ,REAR BOOTLID INNER ,REAR BOOTLID OUTER,REAR BUMPER,REAR BUMPER LOWER DIFFUSER CENTER TRIM ,REAR END PANEL INNER ,REAR END PANEL OUTER ,REAR BODY PANEL INNER ,REAR BODY PANEL OUTER,FRONT & REAR 8 X RADAR SENSORS	New	9,000.00	2,800.00
Gross Labour Cost (\$\$)			31,750.00	6,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >