

India International Insurance Pte Ltd
64 Cecil Street
#04-00/#05-00 IOB Building
Singapore 049711

Attn: Motor Claims Dept

Dear Sir/ Madam

ACCIDENT INVOLVING VEHICLE NO SDS1666A AND SHC8802P ALONG PIE
(LP 730) ON 07/03/2019

We understand that you are the insurer of SHC8802P vehicle.

We are instructed by the owner of motor vehicle SDS1666A to write, negotiate and settle the claim on their behalf for the abovementioned accident. We therefore propose to claim from you as follows: -

1.	Cost of repair	S\$ 113,000.00
2.	Loss of Use/ Rental (90days x \$200.00)	S\$ 18,000.00
3.	LTA/GIA Search fee	S\$ -
4.	Towing Fee	S\$ -
TOTAL		<u>S\$ 131,000.00</u>

Please let us have your reply soonest possible.

Thank you.

Yours faithfully



Signed by "the workshop"
(with chop)

(Visão Temp)

LETTER OF AUTHORITY

**CHUAN HO AUTO SERVICE
160 SIN MING DRIVE #07-09
SIN MING AUTO CITY
SINGAPORE 575722**

Re : Vehicle : SDS 1666 A , SLF 5877 E , SHC 8802 P AND SKD 8204 A
Date/Time Of Accident : 07/03/2019 1500HRS
Location : PIE (LP 730)

I hereby authorize Chuan Ho Auto Service to seek repair cost for accident occurred as above.

Thank you.

Best Regards,



KHNG THIAN HUAT
S0100189B
9631 4060

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III- Direct Settlement (PODS)

India Ref: MCT19030186
Claimant Ref: SDS 1666A

We/I, CHUAN HO AUTO SERVICE ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 130,000.00 (Global Sum) ~~(Global Sum)~~ S\$ ~~(Global Sum)~~, vehicle no. SDS 1666A that was damaged pursuant to the accident which occurred on 07/03/2019 (date) at PIE (LP 730) (location) involving vehicle no. SHC 8802P (insured vehicle). This is pursuant to the inspection conducted on 14/03/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner KHNG THIAN HUAT ("the third party claimant") of vehicle no. SDS 1666A to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SDS 1666A (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 130,000.00 to CHUAN HO AUTO SERVICE

Dated this 14 day of November 20 19

CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

Chuan Ho Auto Service

NRIC:

52833755J

Address:

160 Sin Ming Drive
#07-04

Nationality:

Occupation:

WITNESS:

Signature:

Signed by appointed Surveyor

Name:

LKK Auto Consultants Pte Ltd

NRIC:

199607198R

Address:

51 Ubi Avenue 1
#01-25 Paya Ubi Ind. Park S(408933)

Nationality:

Occupation:



CTY

CHUAN HO AUTO SERVICE
SIN MING AUTO CITY
160 SIN MING DRIVE #07-09
SINGAPORE 575722

FINAL REPAIR BILL : SDS 1666 A

To : M/s India International Insurance Pte Ltd

Vehicle & Document Information

Date: 21/08/2019
 Vehicle No: SDS 1666 A
 Make/Model: BENTLEY CONTINENTAL

S/N	Description	Qty		Repairer's Est	Revised Est
1	HEADLAMP LH	1	\$	9,600.00	9,600.00
2	HEADLAMP RH	1	\$	9,600.00	9,600.00
3	FRONT RE-INFORCEMENT BAR	1	\$	2,912.00	2,912.00
4	FRONT BUMPER	1	\$	8,792.00	8,792.00
5	FRONT BUMPER SIDE BRACKET LH	1	\$	252.00	252.00
6	FRONT BUMPER SIDE BRACKET RH	1	\$	252.00	252.00
7	FRONT BUMPER BRACKET OUTER LH	1	\$	112.00	112.00
8	FRONT BUMPER BRACKET OUTER RH	1	\$	112.00	112.00
9	FRONT BUMPER BRACKET INNER LH	1	\$	308.00	308.00
10	FRONT BUMPER BRACKET INNER RH	1	\$	308.00	308.00
11	FRONT BUMPER LOWER GRILLE LH	1	\$	1,932.00	1,932.00
12	FRONT BUMPER LOWER GRILLE RH	1	\$	1,932.00	1,932.00
13	FRONT BUMPER LOWER GRILLE LH (SMALL)	1	\$	1,092.00	1,092.00
14	FRONT BUMPER LOWER GRILLE RH (SMALL)	1	\$	1,092.00	1,092.00
15	FRONT BUMPER CLIPS	23	\$	300.00	300.00
19	FRONT RADIATOR GRILLE BASE	1	\$	4,620.00	4,620.00
20	FRONT RADIATOR GRILLE TOP GARNISH	1	\$	336.00	336.00
21	FRONT RADIATOR GRILLE TOP GARNISH STRIP	1	\$	280.00	280.00
22	FRONT RADIATOR GRILLE BRACKET LH	1	\$	140.00	140.00
23	FRONT RADIATOR GRILLE BRACKET RH	1	\$	140.00	140.00
24	FRONT RADIATOR GRILLE LOWER BRACKET LH	1	\$	84.00	84.00
25	FRONT RADIATOR GRILLE LOWER BRACKET RH	1	\$	84.00	84.00
26	FRONT RADIATOR GRILLE SEAL	1	\$	336.00	336.00
27	FRONT RADIATOR GRILLE TRIM	1	\$	2,156.00	2,156.00
28	FRONT RADIATOR GRILLE	1	\$	1,652.00	1,652.00
29	FRONT GRILLE BADGE (TOP)	1	\$	168.00	168.00
30	FRONT GRILLE BADGE	1	\$	1,232.00	1,232.00
31	FRONT GRILLE BADGE SEAL	1	\$	140.00	140.00
32	FRONT RADIATOR GRILLE MIDDLE BRACKET LH	1	\$	224.00	224.00
33	FRONT RADIATOR GRILLE MIDDLE BRACKET RH	1	\$	224.00	224.00
36	FRONT RADIATOR GRILLE RIVET	16	\$	200.00	200.00
42	FRONT RADIATOR GRILLE FOAM FILTER	2	\$	252.00	252.00
46	FRONT FENDER LH	1	\$	16,698.00	16,698.00
47	FRONT FENDER RH	1	\$	16,698.00	16,698.00
48	FRONT HEADLAMP TRIM LH (BIG)	1	\$	420.00	420.00
49	FRONT HEADLAMP TRIM RH (BIG)	1	\$	420.00	420.00
50	FRONT HEADLAMP TRIM LH (SMALL)	1	\$	392.00	392.00
51	FRONT HEADLAMP TRIM RH (SMALL)	1	\$	392.00	392.00
59	FRONT FENDER CLIPS	28	\$	100.00	100.00
60	FRONT FENDER CLIPS	28	\$	100.00	100.00
78	REAR BUMPER UNDER COVER (BIG)	1	\$	1,288.00	1,288.00
79	REAR BUMPER UNDER COVER LH	1	\$	868.00	868.00

80	REAR BUMPER UNDER COVER RH	1	\$	868.00	\$	868.00
81	REAR BUMPER UNDER COVER BRACKET LH	1	\$	168.00	\$	168.00
82	REAR BUMPER UNDER COVER BRACKET RH	1	\$	168.00	\$	168.00
83	REAR BUMPER UNDER COVER SIDE BRACKET LH	1	\$	112.00	\$	112.00
84	REAR BUMPER UNDER COVER SIDE BRACKET RH	1	\$	112.00	\$	112.00
92	REAR WIRING SET	1	\$	588.00	\$	588.00
96	REAR BUMPER LAMP	1	\$	4,900.00	\$	4,900.00
97	REAR BOOTLID	1	\$	15,650.00	\$	15,650.00
98	REAR BOOTLID TOP LOCK	1	\$	1,512.00	\$	1,512.00
99	REAR BOOTLID LOCK	1	\$	336.00	\$	336.00
101	REAR BOOTLID CLIPS / RIVET	10	\$	50.00	\$	50.00
102	REAR BOOTLID LOCK FRAME	1	\$	112.00	\$	112.00
104	REAR BOOTLID SEAL	1	\$	1,008.00	\$	1,008.00
107	REAR BOOTLID TRIM	1	\$	532.00	\$	532.00
110	REAR BODY PANEL	1	\$	10,236.00	\$	10,236.00
113	REAR BODY PANEL COVER LH	1	\$	196.00	\$	196.00
114	REAR BODY PANEL COVER RH	1	\$	196.00	\$	196.00
115	REAR SPARE WHEEL COMPARTMENT PANEL	1	\$	2,016.00	\$	2,016.00
123	REAR END PANEL	1	\$	644.00	\$	644.00
128	REAR PANEL GARNISH LH	1	\$	364.00	\$	364.00
129	REAR PANEL GARNISH RH	1	\$	364.00	\$	364.00
130	REAR PANEL CENTER GARNISH	1	\$	420.00	\$	420.00
133	REAR HEAT SHIELD (UPPER)	1	\$	728.00	\$	728.00
134	REAR HEAT SHIELD (LOWER)	1	\$	196.00	\$	196.00
135	REAR HEAT SHIELD (CENTER)	1	\$	224.00	\$	224.00
136	REAR HEAT SHIELD CLIPS	22	\$	100.00	\$	100.00
137	REAR SILENCER LH	1	\$	5,964.00	\$	5,964.00
138	REAR SILENCER RH	1	\$	5,964.00	\$	5,964.00
139	REAR EXHAUST TRIM LH	1	\$	1,120.00	\$	1,120.00
140	REAR EXHAUST TRIM RH	1	\$	1,120.00	\$	1,120.00
141	REAR EXHAUST BRACKET LH	1	\$	112.00	\$	112.00
1	REAR EXHAUST BRACKET RH	1	\$	84.00	\$	84.00
163	REAR BUMPER	1	\$	14,056.00	\$	11,985.00
164	REAR BUMPER SPOILER	1	\$	9,240.00	\$	1,392.00
165	REAR BUMPER TOWING COVER	1	\$	336.00	\$	336.00
166	REAR BUMPER SENSOR BRACKET	2	\$	168.00	\$	168.00
167	REAR BUMPER SENSOR BRACKET (SPOILER) LH	1	\$	84.00	\$	84.00
168	REAR BUMPER SENSOR BRACKET (SPOILER) RH	1	\$	84.00	\$	84.00
169	REAR BUMPER RE-INFORCEMENT BAR	1	\$	2,380.00	\$	2,380.00
173	REAR BUMPER HEAT SHIELD LH	1	\$	224.00	\$	224.00
174	REAR BUMPER HEAT SHIELD RH	1	\$	224.00	\$	224.00
177	REAR BUMPER INNER BRACKET LH	1	\$	420.00	\$	420.00
178	REAR BUMPER INNER BRACKET RH	1	\$	420.00	\$	420.00
179	REAR BUMPER RIVET / NUT / CLIPS / SCREWS	18	\$	300.00	\$	300.00

Total :	\$	168,421.00
-20%	\$	33,684.20
Parts Total :	\$	134,736.80

1	FRONT NUMBER PLATE	\$	40.00
2	REAR NUMBER PLATE	\$	40.00
SPECIAL NETT :		\$	80.00

1	ELECTRICAL CHECKS ON WIRING, AIR SUPPLY UNIT (SUSPENSION), FRONT & REAR RADAR SENSOR, ANTI-COLLISION PREVENTION SYSTEM, AUTO TAILGATE LIFTER, AUTO TAILGATE RELEASE BUTTON, HEADLAMPS &	\$	400.00
---	---	----	--------

TAILLAMPS, EXHAUST OUTPUT AIR-FLOW, REAR BUMPER LAMP, REVERSE CAMERA, BATTERY SUPPLY UNIT.

1	PROGRAMMING RESET & RE-CALIBRATE LIGHTING ELECTRONICS (LAMPS ETC), REVERSE RADAR SENSOR PARKING DISTANCE, REVERSE CAMERA TO HEADUNIT CAN BUS READING, FRONT RADAR SENSING COLLISION PREVENTION, BOOT LID COMFORT ACCESS.	\$	300.00
1	LABOUR TO DISMANTLE, REPAIR & REPLACE PARTS AS STATED. WHOLE EXTERIOR SHELL REMOVAL FROM CHASSIS FOR PANEL BEATING OF REAR LH & RH FENDER.	\$	2,400.00
1	LABOUR TO REMOVE & REPLACE EXHAUST MUFFLER LH & RH, ALIGN TO REAR BUMPER LOWER DIFFUSER EXHAUST DUCT, EXHAUST MOUNTINGS.	\$	300.00
1	ANTI-RUST PROOFING & GALVANISE ON REAR END PANEL, REAR LH & RH FENDER (OUTER SHELL WHOLE PIECE), REAR LOWER FLOOR PANEL (SPARE TYRE TANK), FRONT REINFORCEMENT	\$	200.00
1	TO PRIMED, GALVANISE ZINC PUTTY, SPRAY-PAINTING (WATER-BORNE PAINT AS PER BENTLEY SPECIFICATION) FRONT BUMPER, FRONT LH & RH FENDER, FRONT RADIATOR GRILLE BASE, REAR LH & RH FENDER, REAR BOOTLID INNER, REAR BOOTLID OUTER, REAR BUMPER, REAR BUMPER LOWER DIFFUSER CENTER TRIM, REAR END PANEL INNER, REAR END PANEL OUTER, REAR BODY PANEL INNER, REAR BODY PANEL OUTER, FRONT & REAR 8 X RADAR SENSORS.	\$	2,800.00

Labour Total :	\$	6,400.00
Parts Total :	\$	134,736.80
Total :	\$	141,136.80
-20%	\$	28,227.36
Grand Total :	\$	112,909.44
Special Nett :	\$	80.00
Lump Sum :	\$	113,000.00

CHUAN HO AUTO SERVICE

