

TP QBE
Jasper.

Tekson.

Subject: GBC13425.

Date:

Mitsubishi Canter
FB70BBA20324

CC6/QBE19004919 / A593

Front Windscreen <i>cracked</i>	1413.40 ✓
Front Windscreen Moulding <i>2 new</i>	285.30 ✓
Front Windscreen Sealant <i>2 new</i>	60(SN) ✓
ERP Bracket. <i>new</i>	26(SN) ✓
Front Wiper Barnish. <i>Rehd</i>	562 ✓
Center Sticker <i>new</i>	96 ✓
Front Wiper Arm LH <i>Best</i>	89.90 ✓
Front Wiper Blade LH <i>lt</i>	33.90 ✓
Front Wing Mirror (Round) <i>Missing</i>	112.50 ✓
Front Wing Mirror (Rectangular) <i>2 new</i>	126.20 +
Front Wing Mirror Stay. <i>1 new</i>	378 +

2593 S.N: 86.
1944.75

Panel Bending	200 100
Spray Painting	250 X
To replace front windscreen.	180 120.

220.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 2250.75
L/S: 1.8K.
03 Days.