

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 18 March 2019

To : LKK

By Fax: 6256-4315

Attn : Bryan Ang

Tel: 97237799

VEHICLE NO : FBN 3796U

Sniper 150

ACCIDENT DATE: 10 March 2019

Description	Qty	Quotation \$
1 Handle Bar <i>bst</i>	1	195.00 ✓
2 Balancer <i>new cut</i>	1 set	135.00 ✓ ✓
3 Head Lamp <i>cut</i>	1	235.00 ✓
4 Front Top Cover <i>cut</i>	1	125.00 ✓
5 Front Panel <i>cut</i>	1	185.00 ✓
6 Front Left Signal <i>cut</i>	1	95.00 ✓
7 Front Inner Garnish Panel <i>cut</i>	1	135.00 ✓
8 Front LH Side Fairing <i>cut</i>	1	135.00 ✓
9 Head Light Switch Cover <i>new</i>	1	165.00 ✗
10 Gear Pedal <i>bst cut</i>	1	65.00 ✓
11 Footrest Bracket LH <i>bst</i>	1	75.00 ✓
12 Foot Peg LH <i>cut</i>	1	75.00 ✓
13 Engine Casing LH <i>new</i>	1	145.00 ✗
14 Rear LH Fairing <i>cut</i>	1	195.00 ✓
15 Front Fork <i>new</i>	1 set	480.00 ✗
16 Swing Arm <i>bst</i>	1	380.00 ✓
<i>Ren</i> 17 Rim <i>distorted</i>	1 set	350.00 ✓
18 Rear Wheel Hub <i>new</i>	1	165.00 ✗
19 Rear Wheel Shaft <i>bst bst</i>	1	125.00 ✗ ✓
20 Rear Wheel Bearing <i>new</i>	1	75.00 ✗
21 Chain Sprocket Assy <i>new</i>	1	79.00 ✗
22 Rear LH Signal <i>broken</i>	1	65.00 ✓
23 Rear Mudguard <i>cut</i>	1	178.00 ✓
24 Brake Pedal <i>new</i>	1	95.00 ✗
25 Exhaust Pipe <i>cut Distorted</i>	1	580.00 ✓
	Sub-Total	4,532.00
	Less 10%	453.20
	Sub-Total	4,078.80

3328.00

2995.20

VEHICLE NO : FBN 3796U

Sniper 150

Nett Items

1 Towing fee <i>hlc</i>	50.00 30/-
2 Remove & replace necessary parts, align & etc	280.00 150/-
3 Remove & replace fork assy, swing arm, rim, shaft, sprocket chain assy & etc	280.00 125/-
4 Supply body decal sticker	200.00 100/-
5 Touch up, respray paint work	250.00 150/-
6 Re-align rear body frame	200.00 120/-

Sub-Total 1,260.00

Nett Total 5,338.80

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion. Thank you

SG 98 MOTOR PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

19/03/2019 e 1100ms

Not Author

2/3m 4 days.

nyar

2 Kk Auto