



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FWD SINGAPORE PTE LTD			Ref : CS3/FWD18019250/Bqd3s2-1	
6 TEMASEK BOULEVARD #18-01 SUNTEC TOWER 4SINGAPORE 038986			Date : 27-03-2019	
			Code : FWD	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLE 2743H	Veh. Inspected	SKW 2727Y	
Policy No.	PNPV2017-00005247-01	Coverage (\$)	0.00	
Claim No.	1201800013412	Excess (\$)	0.00	
Assign From	CLARA LI	Assign Date	15/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA HRV 1.5 DX CVT	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JHMRU1810GX204092	Colour	RED	
Odometer	78805	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60R16	DUNLOP	7 mm	
L/H Front Tyre	215/60R16	DUNLOP	7 mm	
R/H Rear Tyre	215/60R16	DUNLOP	7 mm	
L/H Rear Tyre	215/60R16	DUNLOP	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/10/2018	Inspection Date	23/10/2018	
Survey held at	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		