



Section A - Accident Details

Registration Number	SHB388B
Case Reference Number	TAX/03/19/2072
Registration Date	24/10/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	TAN KOK SENG
Type of Accident	Head to Rear
Accident Date and Time	16/3/2019 12:00 AM
Accident Reported Date and Time	16/3/2019 10:53 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24100626
Special Instruction to ARC, if any	TP
Prepared Date and Time	18/3/2019 11:42 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	


Section B - Summary of Repair Estimates
Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,095.00	\$300.00
Total Spray Cost	\$1,494.00	\$500.00
Total Spare Part Cost	\$3,257.64	\$1,163.19
Total Other Cost	\$636.88	(\$163.19)
TOTAL COST	\$6,483.52	\$1,800.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	4.0
Prepared / Adjusted By	Zhi Yang Phua	Hwee Jie (LKK) / NTUC
ARC / Surveyor Sign Off Date	18/03/2019 3:20 PM	18/03/2019 3:01 PM
Signature		
Remarks	Initial estimates = 5 days Request number of days to extend 2 days	L/S REPAIR, PHOTO AFTER PAINT.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1903-0645	Invoice Number	
Quotation Date	29.03.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$845.00	\$200.00
TO REPAIR REAR END PANEL	\$250.00	\$100.00
Total Labour	\$1,095.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$100.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$1,494.00	\$500.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$480.07)
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$296.88	\$296.88
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$636.88	(\$163.19)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace ✓
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check X
		52015-47050	ARM SUB-ASSY, RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Check X
		52016-47030	ARM SUB-ASSY, RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given X
		52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Check X
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Check X
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace ✓
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace ✓
		76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given X
		76087-47020	BUMPER LIP COVER RR/RH	1.00	\$118.10	25.00	\$88.58	Replace	Replace ✓

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 29/03/2019

User ID : PohSuan

	76891-47020	BUMPER LIP REAR	1.00	\$228.90	25.00	\$171.68	Replace	Replace	✓
	58307-47060	END PANEL	0.00	\$602.10	0.00	\$0.00	Replace	Check	X
		SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Check	X
	61604-47090	FENDER RR/RH	0.00	\$766.80	0.00	\$0.00	Replace	Not Given	X
		STICKER SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	✓
		STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	X
	52562-47010	TAIL LAMP BRACKET, RH	0.00	\$30.70	0.00	\$0.00	Replace	Check	X
	81551-47180	TAIL LAMP RH	0.00	\$557.80	0.00	\$0.00	Replace	Check	X
Total				\$3,816.10		\$904.21			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	1.00	\$139.60	25.00	\$104.70	Replace	Replace
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace
Total					345.30		258.98		

1163.19
+ 300.00
+ 816.88

2280.07
- 207

1824.06
L/s \$1800/-