

ASS. REC. BY:

REF: CS/AWA1904934/A20302

Special Instruction:

Surveior

Adrian

## ASSIGNMENT (Office)

From (Person):

Wong Kin

of

AWAC

Date/Time:

18/3/19 @ 5:11pm

Estimated Cost:

Bill to:

TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCG 1262

Insured:

at Workshop m/s

CompuAdelegro

Tel:

6848 5726

of

330 Ubi Rd 3

Policy No:

BVP18B0045881804

Claim No:

NSV1900136/B1

Sum Insured:

Excess:

\$500.00 WAIVED

Make of Veh:

(Client's Record)

D.O.A.

13/3/19

CA /  REV /

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:40am @ 19/3/19

Person Contacted:

Johni

Vehicle  IN /  OUT

Date/Time

Action/Instruction (✓) Estimate

take photographs of the front windscreen area from inside to ascertain whether the insured vehicle is equipped with a car camera.

SCG 1262 - X

20/3/19 @

11:04am revert to kin wong by email.

20/3/19 @

1:17pm been returned ~~via~~ by email. (cost +10%)

ASSIGNMENT

From: \_\_\_\_\_ Date: 19/03/19  
 Estimated Cost: \_\_\_\_\_  
 OD /  TP /  WS /  TP RES /  OD RES /  EVA /  INV /  MV  
 To inspect Vehicle No: SCG1262  
 at Workshop m/s: Comfort Delgro  
 of: 330 ubi Rd 3  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \$500.00  
 (Client's Record)  
 Make of Veh: Johari

(Policy Condition)  
 Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 8 days Res: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No  
 CA /  REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: 82 SCG126Z Yr Regn: 2013, Nov  
 Type:  M.Car /  M.Cycle /  Bus /  Van /  Lorry /  Taxi /  Prime Mover /  Truck /  Trailer or  
 Make: Mercedes Benz c.c. 1991  
 Colour: Brown A/C:  Insured /  Std /  NI /  NA  
 Sp. Reading: 103658 T/Radio:  Insured /  Std /  NI /  NA  
 Eng/No: \_\_\_\_\_  
 C/No: WDD2120362A796679  
 Gen. Cond:  Good /  Fair /  Poor /  Burnt  
 Steering:  Inorder /  Jammed /  Leaked /  Burnt or  
 Brake:  Inorder /  Jammed /  Leaked /  Burnt or  
 Modi:  Nil /  S/Rim /  STD A/Rim or  
 Tyre Size: F: 245/45R17  
 R: 245/45R17  
 BS /  DUN /  EXNOVA /  GY /  FS /  LIZA /  MIC /  OHTSU /  PIR /  SUMI /  TOYO /  YOKO or  

Front	Rear
R/Bal. <u>06</u> mm	R/Bal. <u>06</u> mm
L/Bal. <u>06</u> mm	L/Bal. <u>06</u> mm
D.O.A. _____	D.O.I. <u>19/03/19</u>

 Survey held at: Comfort Ubi  
 Des. of Damages:  Frt /  Rear /  O/S /  N/S /  U/C /  Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<b>Pls take photographs of the front windscreen area from inside to ascertain whether the insured vehicle is equipped with a car camera</b>
27/3/19 @ 1.29pm	Informed Tina Chh & EX = WAIVED by email.
26/4/19 @ 1.20pm	2nd visit to Ben Tang by email - Complementary
26/4/19 @ 4.21pm	Ben Tang informed can proceed repair on supplementary
16/5/19 @ 7pm	confirmed with Tina final fig of 11964.50, 8 days
	(Lied to 737.60, 39%)
	no lump sum. RECEIVED 16 MAY 2019

Date/Time, File Pass to?  Prel. Report  
 Final Report  
 Date/Time, File Return to?  
 2)  
 Report Format: OD  
 Lump Sum / I.B.I: (\$) 11964.50

Days Of Repair: 8  
 Resurvey No. of Trip: 1  
 Add Fee:  Site Insp (\$) )  
 Interview (\$) )  
 Tech. Invs (\$) )  
 Weekend (\$) )  
 Survey Fee: 250  
 Transportation: \_\_\_\_\_ )  
 Photos \_\_\_\_\_ )  
 Others \_\_\_\_\_ )  
 TOTAL: 250

*[Handwritten Signature]*  
 16/5/19

**Nivitha (LKK Auto)**

**From:** Wong, Kin <Kin.Wong@awac.com> on behalf of Motorsurvey <Motorsurvey@awac.com>  
**Sent:** Monday, 18 March 2019 5:11 PM  
**To:** 'assignments@lkkauto.com'  
**Cc:** 'sur@lkkauto.com'  
**Subject:** OD survey assignment for SCG 126 Z - DOA : 13/03/2019  
Our Ref: NSV1900136/BT

The above captioned accident refers. Please conduct an "OWN DAMAGE" survey on the following:

Insured Vehicle	:	SCG 126 Z		
Policy Number	:	BVPISB0045881804	Account Code:	B900SD6
Policy Excess	:	\$ 500	(Allied World waived \$ 500 ) (Insured to pay \$ 0 )	
Voluntary Excess	:	\$ NA	(No waiver)	
Sum Insured	:	Market Value with COE & PARF		
Make / Model	:	Mercedes Benz E 250 Sedan (R17) / 2013		
Name of Workshop	:	Comfortdelgro Engineering Pte Ltd / Ubi		
Contact Number	:	6848 5725/26		
Person to Contact	:	Johari		
Estimated Cost of repairs	:	\$17,264		
( x )	Please take photographs of the front windscreen area from inside to ascertain whether the insured vehicle is equipped with a car camera. (Compulsory)			
( x )	Please revert with your preliminary survey report with photographs			
Remarks				

Regards,

Claims Division

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail (and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments hereto are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no

## Shiau Chan (LKKAuto)

---

**From:** CDGE Ubi Private Cars Crash Repair Counter <ubi\_cr@sparkcarcare.com>  
**Sent:** Thursday, 16 May 2019 2:00 PM  
**To:** Shiau Chan (LKKAuto)  
**Cc:** SUR  
**Subject:** Re: ( REMINDER ) TO FINALIZE OD VEHICLE SCG 126Z (DOA: 13/03/2019)

Dear Ms Chan,

Sorry for the delay.

Yes COR \$11,964.50 before excess WAIVED & GST and 8 repair days.

Thks & Regards,

Tinie

Crash Repair

ComfortDelGro Engineering Pte Ltd

320 Ubi Road 3 S (408649)

Tel: +65 6848 5725/26

Email: Ubi\_CR@sparkcarcare.com



---

**From:** Shiau Chan (LKKAuto) <siewsc@lkkauto.com>  
**Sent:** Thursday, 16 May 2019 1:47 PM  
**To:** CDGE Ubi Private Cars Crash Repair Counter  
**Cc:** SUR  
**Subject:** RE: ( REMINDER ) TO FINALIZE OD VEHICLE SCG 126Z (DOA: 13/03/2019)

Dear Tinie,

Can confirm?

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Friday, 10 May 2019 10:56 AM  
**To:** CDGE Ubi Private Cars Crash Repair Counter <ubi\_cr@sparkcarcare.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: ( REMINDER ) TO FINALIZE OD VEHICLE SCG 126Z (DOA: 13/03/2019)

Dear Tinie,

## Shiau Chan (LKKAuto)

---

**From:** Tang, Ben <Ben.Tang@awac.com> on behalf of Motorsurvey <Motorsurvey@awac.com>  
**Sent:** Thursday, 9 May 2019 3:21 PM  
**To:** Shiau Chan (LKKAuto); Motorsurvey; assignments  
**Cc:** SUR  
**Subject:** RE: OD survey assignment for SCG 126 Z - DOA : 13/03/2019 Our Ref: NSV1900136/BT

Dear Shiau Chan

As spoken, please proceed to finalize repair costs of \$11,964.50 all in inclusive check items and supplementary.

Thank you.

Best Regards  
Ben Tang  
Claims Analyst  
Claims Group  
Global Markets

Allied World Assurance Company, Ltd  
60 Anson Road #08-01 Mapletree Anson Singapore 079914  
T: +65 6423 0816  
F: +65 6423 0864  
E: [ben.tang@awac.com](mailto:ben.tang@awac.com)  
W: [www.awac.com](http://www.awac.com)

---

**From:** Shiau Chan (LKKAuto) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>  
**Sent:** Thursday, 9 May 2019 10:27 AM  
**To:** Motorsurvey <[Motorsurvey@awac.com](mailto:Motorsurvey@awac.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: OD survey assignment for SCG 126 Z - DOA : 13/03/2019 Our Ref: NSV1900136/BT

Dear Ben,

Re-send.

Please be informed that the final repair cost of above vehicle is \$11,964.50 inclusive check items and supplementary.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Thursday, 2 May 2019 2:47 PM  
**To:** Motorsurvey <[Motorsurvey@awac.com](mailto:Motorsurvey@awac.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>

## Shiau Chan (LKKAuto)

---

**From:** Tang, Ben <Ben.Tang@awac.com> on behalf of Motorsurvey <Motorsurvey@awac.com>  
**Sent:** Friday, 26 April 2019 4:21 PM  
**To:** Shiau Chan (LKKAuto); Motorsurvey; assignments  
**Cc:** SUR  
**Subject:** RE: OD survey assignment for SCG 126 Z - DOA : 13/03/2019 Our Ref: NSV1900136/BT

Dear Shiau Chan

Reference to above matter.

Please proceed repair \$11,962.30 inclusive of supplementary items.

No more supplementary is allowed.

Thank you.

Best Regards  
Ben Tang  
Claims Analyst  
Claims Group  
Global Markets

Allied World Assurance Company, Ltd  
60 Anson Road #08-01 Mapletree Anson Singapore 079914  
T: +65 6423 0816  
F: +65 6423 0864  
E: [ben.tang@awac.com](mailto:ben.tang@awac.com)  
W: [www.awac.com](http://www.awac.com)

---

**From:** Shiau Chan (LKKAuto) <siewsc@lkkauto.com>  
**Sent:** Friday, 26 April 2019 1:20 PM  
**To:** Motorsurvey <Motorsurvey@awac.com>; assignments <assignments@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: OD survey assignment for SCG 126 Z - DOA : 13/03/2019 Our Ref: NSV1900136/BT

Dear Ben,

Enclosed herewith 2<sup>nd</sup> preliminary advice of SCG 126Z.  
Kindly approve on supplementary.

Best Regards,  
**Shiau Chan (Ms) | Case Handler**  
**LKK Auto Consultants Pte Ltd**  
Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Friday, 26 April 2019 1:20 PM  
**To:** Motorsurvey; assignments  
**Cc:** SUR  
**Subject:** RE: OD survey assignment for SCG 126 Z - DOA : 13/03/2019 Our  
Ref: NSV1900136/BT  
**Attachments:** CSAWA19004934Aqd3(2).pdf; SCG126 SUPP-.pdf

Dear Ben,

Enclosed herewith 2<sup>nd</sup> preliminary advice of SCG 126Z.  
Kindly approve on supplementary.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Tang, Ben <Ben.Tang@awac.com> **On Behalf Of** Motorsurvey  
**Sent:** Friday, 22 March 2019 1:17 PM  
**To:** Shiau Chan (LKKAuto) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>; Motorsurvey <[Motorsurvey@awac.com](mailto:Motorsurvey@awac.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: OD survey assignment for SCG 126 Z - DOA : 13/03/2019 Our Ref: NSV1900136/BT

Hi Shiau Chan

Please proceed on costs +10% as discussed.

To authorize repair \$11,564.10 , checked items of \$2,864.80 subject to verification again.

Thank you.

Best Regards  
Ben Tang  
Claims Analyst  
Claims Group  
Global Markets

Allied World Assurance Company, Ltd  
60 Anson Road #08-01 Mapletree Anson Singapore 079914  
T: +65 6423 0816  
F: +65 6423 0864  
E: [ben.tang@awac.com](mailto:ben.tang@awac.com)  
W: [www.awac.com](http://www.awac.com)

---

**From:** Shiau Chan (LKKAuto) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>  
**Sent:** Thursday, 21 March 2019 11:32 AM



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UHI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: NSV1900136/BT

Date: 26<sup>th</sup> April 2019

Our Ref: CS/AWA19004934/Aqd3

The Motor Claims Department  
Allied World Assurance Company Ltd

Attn: Kin

Dear Sirs/Mdm


**PRELIMINARY ADVICE OF VEHICLE NO. SCG 126Z .**

We thank you for the instruction on 18/03/2019.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 19/03/2019 at the premises of M/s COMFORTDELGRO and have the following to report:-

Workshop Estimate Amount	: <u>S\$19,002.10 (ESTIMATE \$18,603.90 + SUPP \$398.20)</u>
Revised Estimate Amount	: <u>S\$ 11,962.30</u>
"Check" Items Amount	: <u>S\$ 2,864.80</u>
Market Value	: <u>S\$ 93,000.00</u>
Salvage Value	: <u>S\$ 77,299.00</u>
Nett Value	: <u>S\$ 15,701.00</u>

Description of Damage:  
The vehicle sustained damages at the front portion.



Comments/ Present Status:  
Damages consistent.  
Repair cost economical.  
Kindly approve on supplementary.  
Days of repair: 8 days.

Yours faithfully

ADRIAN LING WAI PING  
*B.Eng, AMSOE, AMIRTE, AMSAE-A, MMATAI*  
Licensed Appraiser



## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Friday, 22 March 2019 1:29 PM  
**To:** ubi\_cr@sparkcarcare.com  
**Cc:** SUR  
**Subject:** OD VEHICLE SCG 126Z (DOA: 13/03/2019)

Dear Tinie,

As spoken with you.

As instructed by our client, please proceed to repair the **insured vehicle SCG 126Z (Excess WAIVED)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Shiau Chan (LKKAuto)

---

**From:** Tang, Ben <Ben.Tang@awac.com> on behalf of Motorsurvey <Motorsurvey@awac.com>  
**Sent:** Friday, 22 March 2019 1:17 PM  
**To:** Shiau Chan (LKKAuto); Motorsurvey; assignments  
**Cc:** SUR  
**Subject:** RE: OD survey assignment for SCG 126 Z - DOA : 13/03/2019 Our Ref: NSV1900136/BT

Hi Shiau Chan

Please proceed on costs +10% as discussed.

To authorize repair \$11,564.10 , checked items of \$2,864.80 subject to verification again.

Thank you.

Best Regards  
Ben Tang  
Claims Analyst  
Claims Group  
Global Markets

Allied World Assurance Company, Ltd  
60 Anson Road #08-01 Mapletree Anson Singapore 079914  
T: +65 6423 0816  
F: +65 6423 0864  
E: [ben.tang@awac.com](mailto:ben.tang@awac.com)  
W: [www.awac.com](http://www.awac.com)

---

**From:** Shiau Chan (LKKAuto) <siewsc@lkkauto.com>  
**Sent:** Thursday, 21 March 2019 11:32 AM  
**To:** Motorsurvey <Motorsurvey@awac.com>; assignments <assignments@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: OD survey assignment for SCG 126 Z - DOA : 13/03/2019 Our Ref: NSV1900136/BT

Dear Ben,

We have checked with repairer, they insist cost + 10% instead of 5%.

Kindly advise.

Best Regards,  
**Shiau Chan (Ms)** | Case Handler  
**LKK Auto Consultants Pte Ltd**  
Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Tang, Ben <Ben.Tang@awac.com> On Behalf Of Motorsurvey  
**Sent:** Thursday, 21 March 2019 11:05 AM

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Wednesday, 20 March 2019 11:04 AM  
**To:** 'Motorsurvey'; assignments  
**Cc:** SUR  
**Subject:** RE: OD survey assignment for SCG 126 Z - DOA : 13/03/2019 Our Ref: NSV1900136/BT  
**Attachments:** CSAWA19004934Aqd3.pdf; SCG126 Photo.pdf

Dear Kin,

Enclosed herewith preliminary advice of SCG 126Z.  
Repairer asking for part by part basis due to no second hand parts available.  
Repair cost economical.

We have not authorise repair.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Tuesday, 19 March 2019 9:43 AM  
**To:** 'Motorsurvey' <[Motorsurvey@awac.com](mailto:Motorsurvey@awac.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: OD survey assignment for SCG 126 Z - DOA : 13/03/2019 Our Ref: NSV1900136/BT

Dear Sir/Mdm,

Thank you for the assignment.

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Wong, Kin [<mailto:Kin.Wong@awac.com>] On Behalf Of Motorsurvey  
**Sent:** Monday, 18 March 2019 5:11 PM  
**To:** 'assignments@lkkauto.com' <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'sur@lkkauto.com' <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** OD survey assignment for SCG 126 Z - DOA : 13/03/2019 Our Ref: NSV1900136/BT

The above captioned accident refers. Please conduct an "OWN DAMAGE" survey on the following:



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: NSV1900136/BT

Date: 20<sup>th</sup> March 2019

Our Ref: CS/AWA19004934/Aqd3

The Motor Claims Department  
Allied World Assurance Company Ltd

Attn: Kin

Dear Sirs/Mdm

**PRELIMINARY ADVICE OF VEHICLE NO. SCG 126Z .**


We thank you for the instruction on 18/03/2019.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 19/03/2019 at the premises of M/s COMFORTDELGRO and have the following to report:-

Workshop Estimate Amount	: S\$ <u>18,603.90</u> .
Revised Estimate Amount	: S\$ <u>11,564.10</u> .
"Check" Items Amount	: S\$ <u>2,864.80</u> .
Market Value	: S\$ <u>93,000.00</u> .
Salvage Value	: S\$ <u>77,299.00</u> .
Nett Value	: S\$ <u>15,701.00</u> .

Description of Damage:

The vehicle sustained damages at the front portion.



Comments/ Present Status:

Damages consistent.

Repair cost economical.

Repairer asking for part by part basis due to no second hand parts available.

Days of repair: 8 days.

Yours faithfully

ADRIAN LING WAI PING

*B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI*

Licensed Appraiser

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	9277Z
<b>Vehicle Details</b>	
Vehicle No.:	SCG126Z
Vehicle to be Exported:	Yes
Intended Deregistration Date:	19 Mar 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E 250 SEDAN (R17)
Primary Colour:	Brown
Manufacturing Year:	2013
Engine No.:	27492030059953
Chassis No.:	WDD2120362A796679
Maximum Power Output:	155.0 kW (207 bhp)
Open Market Value:	\$46,610.00
Original Registration Date:	07 Nov 2013
First Registration Date:	07 Nov 2013
Transfer Count:	0
Actual ARF Paid:	\$52,254.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Nov 2023
PARF Rebate Amount:	\$36,577.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	06 Nov 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$87,910.00
COE Rebate Amount:	\$40,722.00
<b>Total Rebate Amount:</b>	<b>\$77,299.00</b>

The information contained herein is correct as at 19 Mar 2019

OK

**Save More Than 30% on Bills**  
PacificLight Now

Stand to win a smart phone X  
and other attractive lucky draw

**FOR SALE BY OWNER**

**Post an Advertisement**  
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

**New 5 Years Coe Renewal Toyota Estima 2.4A**

2.88% P.A. Low Interest @ GV Finance. 2 Years Warranty. \$4800 Down Monthly From \$98

[Go to Credit Plan Ltd](#) [StarAd](#)

- Free VICOM evaluation
- Free grooming and 8 months maintenance
- In-house workshop ensures quality service
- Member of SVTA and hire purchase association
- 100% deposit refund for unapproved loan

**YONG LEE SENG MOTOR PTE LTD**

Browse by Category Save Search Print Sort by Date Posted 20 results/page

6 vehicles **Search e250** [Advanced Search](#) [Search](#) [View All](#)

Search Selection	e250	Any	Any	2013	Any	Any	Any	Available
------------------	------	-----	-----	------	-----	-----	-----	-----------



**Mercedes-Benz E-Class E250 CGI** **\$81,800** **\$14,450 /yr** **02-Jan-2013** **1,796 cc** **79,000 km** **Luxury** **Available**

Original Condition, Well Maintained By Previous Owner, Low Mileage, 90% Loan Available. Elegant Silver Colour With Brown Leather Upholstery, Car In Tip Top Condition, Clean & Neat Interior. High OMV & Hig...

[Public](#) [14-Feb-2013](#) [Tags: 2013 Mercedes-Benz E250, 2013 Mercedes-Benz E250, Mercedes-Benz E250, Mercedes-Benz E250, Mercedes-Benz E250, Mercedes-Benz E250, Used Mercedes-Benz](#)



**Mercedes-Benz E-Class E250 CGI** **\$89,700** **\$14,120 /yr** **25-Mar-2013** **1,796 cc** **99,800 km** **Luxury** **Available**

1 Careful Owner. C&C Unit With Original AMG KIT, Full C&C Service Records. Highest ARF Value Of \$65,989, Low Depreciation Of \$13K Yearly Only. Comes With Nice Number Plate 1177, Well Maintained. Accid...

[Public](#) [23-Jan-2013](#) [Tags: 2013 Mercedes-Benz E250, 2013 Mercedes-Benz E250, Mercedes-Benz E250, Mercedes-Benz E250, Mercedes-Benz E250, Mercedes-Benz E250, Used Mercedes-Benz](#)



**Mercedes-Benz E-Class E250 CGI Avantgarde** **\$89,000** **\$13,200 /yr** **12-Apr-2013** **1,796 cc** **114,808 km** **Luxury** **Available**

Car Panoramic Sun Roof, Avantgarde Model. Low Depreciation. Always Park Under Shelter. No Obligation For Loan And Insurance. View After Office Hours At 1 Lew Lian Vale. Contact Me To Arrange For View...

[Public](#) [23-Mar-2013](#) [Tags: 2013 Mercedes-Benz E250, 2013 Mercedes-Benz E250, Mercedes-Benz E250, Mercedes-Benz E250, Mercedes-Benz E250, Mercedes-Benz E250, Used Mercedes-Benz](#)



**Mercedes-Benz E-Class E250 AMG Line** **\$96,800** **\$15,640 /yr** **18-Jun-2013** **1,991 cc** **118,000 km** **Luxury** **Available**

Cheapest AMG Model In The Market! High Paper Value + Body Already \$90K+! 1 Year Warranty! 1 Owner Only, Fully Serviced And Maintained By C&C, 100% Accident-Free, Tip Top Condition, View To Believe, Up...

[Public](#) [04-Mar-2013](#) [Tags: 2013 Mercedes-Benz E250, 2013 Mercedes-Benz E250, Mercedes-Benz E250, Mercedes-Benz E250, Mercedes-Benz E250, Mercedes-Benz E250, Used Mercedes-Benz](#)



**E-Class coupe returns with an attitude**

We are duly impressed with what Mercedes has done to the latest E-Class sedans. But how will the facelift fit the coupes?

[Read this article](#)



**Mercedes-Benz E-Class E250** **\$99,800** **\$16,060 /yr** **29-Aug-2013** **1,991 cc** **75,000 km** **Luxury** **Available**

1 Owner Only. Agent Maintained. Call Or Visit Us Now For Further Details.

[Public](#) [05-Mar-2013](#) [Tags: 2013 Mercedes-Benz E250, 2013 Mercedes-Benz E250, Mercedes-Benz E250, Mercedes-Benz E250, Mercedes-Benz E250, Mercedes-Benz E250, Used Mercedes-Benz](#)



**Mercedes-Benz E-Class E250 CGI** **\$95,800** **\$14,270 /yr** **15-Nov-2013** **1,796 cc** **68,000 km** **Luxury** **Available**

Low Mileage And Well Maintain By Owner, High Loan And Trade In Available.

[Public](#) [10-Mar-2013](#) [Tags: 2013 Mercedes-Benz E250, 2013 Mercedes-Benz E250, Mercedes-Benz E250, Mercedes-Benz E250, Mercedes-Benz E250, Mercedes-Benz E250, Used Mercedes-Benz](#)

Save this search criteria, to get email alerts whenever a match is found. [Save Search](#)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	14/03/2019 08:45
Date Of Accident	13/03/2019 11:20
Exact Location Of Accident	JUNCTION OF AIRPORT RD TURNING TO UPP PAYA LABAR
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCG126Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SOON KONG ANN
NRIC No	S1169277Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96336622
Alternative Phone No	OFFICE-96336622

### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E250
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	PRIVATE CAR
------------------	-------------

### Insurance Company

Name of Insurance Company	ALLIED WORLD ASSURANCE COMPANY, LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	BVPISB0045881804
Cover Note Number	

### Driver

Name of Driver	SOON KONG ANN
NRIC No	S1169277Z
Date Of Birth	13/10/1956
Occupation	INDOOR
Date Of Driving Pass	03/07/1976
Driving Experience	42 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96336622
Fax Number	
Contact Number	OFFICE-96336622
EMail Address	NOEMAIL

Address	28 JALAN RIMAU
Postcode	418724
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHMENT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBA7216U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (including Driver)	







ComfortDrive Engineering

320 UBI ROAD 3 SINGAPORE 408649

**ACCIDENT REPAIR ESTIMATES**

Our Ref:

Type of Claim : OD

Vehicle No. : SCG126Z

Make & Model : MERCEDES BENZ E250

Year of Manufacture : 2013

Chassis No. : WDD2120362A796679

Ins Company : \_\_\_\_\_

Engine No. : 27492030059953

Excess : \_\_\_\_\_

Policy No. : \_\_\_\_\_

Date of Accident : 13.03.2019

Time of Accident : 11.20

Suggested Days of Repair : \_\_\_\_\_

In-house Vehicle Assessor

**Repair Estimates**

Case Owner : JOHARI

Signature : \_\_\_\_\_

Contact No \_\_\_\_\_

Parts (a) Cost / List Price Items **\$ 13,399.00**

Plus/Less # \_\_\_\_\_

Total of Cost / List \_\_\_\_\_

(b) Nett Price Items **\$ -**

Less \_\_\_\_\_

Total of Nett Item \_\_\_\_\_

(c) Special Nett Items **\$ 125.00**

**Total Parts Cost (Appendix A)** \_\_\_\_\_

**Labour (Appendix B)** **\$ 3,740.00**

**Total Repair Cost** \_\_\_\_\_

- Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_

The above total will be subjected to 7% G.S.T.

15603.90  
12622.00

Name of Surveyor : Adrian King

Company : UIC

Survey conducted on : 19/03/19 at 1:30pm

Remarks By Surveyor

(a) The repair of this vehicle is authorized  is not authorized until further notice.

(b) Recommended Days of Repair : 08 days day(s)

(c) Resurvey :  Required  Not Required

(d) Excess : \$ 500

(e) Signature of surveyor : [Signature] Date: \_\_\_\_\_

## Spark Car Care

ComfortDelGro Engineering Pte Ltd

320 UBI ROAD 3 S (408649)

Tel: 6843 8723 68438736 Fax : 67436072

### Spare Parts 1

Vehicle No : SCG126Z Type of Claim : OD

Make & Model : MERCEDES BENZ Year Manufacture : 2013

Chassis No : WDD2120362A796679 Engine No : 27492030059953

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	BONNET <i>Distorted.</i>	1	\$ 1,250.00	✓			
2	BONNET HINGE RH <i>2nd</i>	1	\$ 80.00	+			
3	BONNET HINGE LH <i>1st</i>	1	\$ 80.00	+			
4	BONNET CENTER CATCH <i>Best</i>	1	\$ 40.00	✓			
5	BONNET SIDE LOCK RH <i>2nd</i>	1	\$ 36.00	✓			
6	BONNET SIDE LOCK LH	1	\$ 36.00	✓			
7	BONNET ABSORBER RH <i>2nd</i>	1	\$ 64.00	+			
8	BONNET ABSORBER LH	1	\$ 64.00	+			
9	BONNET INSULATOR <i>crumpled</i>	1	\$ 140.00	✓			
10	BONNET INSULATOR CLIPS <i>new</i>	12	\$ 4.00	✓			
11	BONNET UPPER SIDE CATCH RH <i>Best</i>	1	\$ 20.00	✓			
12	BONNET UPPER SIDE CATCH LH	1	\$ 20.00	✓			
13	BONNET STOPPER SPRING RH <i>2nd</i>	1	\$ 16.00	✓			
14	BONNET STOPPER SPRING LH	1	\$ 16.00	✓			
15	BONNET EMBLEM <i>new</i>	1	\$ 54.00	✓			
16	BONNET RUBBER RH <i>2nd</i>	1		+			
17	BONNET RUBBER LH	1		+			
18	BONNET CENTER CATCH BAR <i>Best</i>	1	\$ 140.00	✓			
19	FRONT GRILLE WITH CHROME <i>cracked</i>	1	\$ 520.00	✓			
20	FRONT BUMPER <i>Delivered</i>	1	\$ 750.00	✓			
21	FRONT BUMPER SIDE RETAINER RH <i>2nd</i>	1	\$ 39.00	+			
22	FRONT BUMPER SIDE RETAINER LH <i>1st</i>	1	\$ 39.00	+			
21	FRONT BUMPER LOWER GRILLE <i>new</i>	1	\$ 49.00	+			
24	FRONT BUMPER LOWER CHROME MOULDING <i>new</i>	1	\$ 100.00	+			
25	FRONT BUMPER REINFORCEMENT <i>Best</i>	1	\$ 280.00	✓			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

## Spark Car Care

ComfortDelGro Engineering Pte Ltd

320 UBI ROAD 3 S (408649)  
Tel: 6843 8723 68438736 Fax : 67436072

**Spare Parts 2**

Vehicle No : SCG126Z Case Owner : JOHARI  
 Make & Model : MERCEDES BENZ Year Manufacture : 2013  
 Chassis No : WDD2120362A796679 Engine No : 27492030059953  
 Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_  
 Order By : \_\_\_\_\_ Type of Claim : OD

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
11	FRONT REINFORCEMENT BRACKET RH <i>2H Mer</i>	1	\$ 30.00	→ X			
12	FRONT REINFORCEMENT BRACKET LH <i>2H Mer</i>	1	\$ 30.00	→ X			
13	FRONT BUMPER SPONGE <i>Distorted</i>	1		+ ES			
14	FRONT BUMPER BASE <i>Distorted</i>	1	\$ 50.00				
15	BRASE PANEL <i>Best</i>	1	\$ 64.00	✓			
16	GRILLE EMBLEM <i>per</i>	1	\$ 42.00	✓ <i>Thin</i>			
17	FRONT BUMPER TOW COVER <i>Missing</i>	1	\$ 32.00	✓			
18	FRONT BUMPER SENSOR RH OUTER <i>2H Mer</i>	1	\$ 90.00	+			
19	FRONT BUMPER SENSOR RH INNER <i>2H Mer</i>	1	\$ 90.00	? X			
20	FRONT BUMPER SENSOR RH CENTER <i>2H Mer</i>	1	\$ 90.00	+			
21	FRONT BUMPER SENSOR LH OUTER <i>2H Mer</i>	1	\$ 90.00	+			
22	FRONT BUMPER SENSOR LH INNER <i>2H Mer</i>	1	\$ 90.00	+			
23	FRONT BUMPER SENSOR LH CENTER <i>2H Mer</i>	1	\$ 90.00	+			
24	FRONT FENDER RH <i>2 Buckled</i>	1	\$ 520.00	✓			
25	FRONT FENDER LH	1	\$ 520.00	✓			
26	FRONT HEADLAMP RH <i>cont'd</i>	1	\$ 1,720.00	✓			
27	FRONT HEADLAMP LH <i>Bot</i>	1	\$ 1,720.00	✓			
28	FRONT HEADLAMP CONTROL UNIT RH <i>2H Mer</i>	1	\$ 495.00	+			
29	FRONT HEADLAMP CONTROL UNIT LH <i>2H Mer</i>	1	\$ 495.00	+			
30	FRONT FENDER CHROME MOULDING RH <i>2H Mer</i>	1	\$ 26.00	✓			
31	FRONT FENDER CHROME MOULDING LH <i>2H Mer</i>	1	\$ 26.00	✓			
32	HEADLAMP SUPPORT PANEL RH <i>2 Distorted</i>	1	\$ 138.00	✓			
33	HEADLAMP SUPPORT PANEL LH	1	\$ 138.00	✓			
34	RADIATOR SUPPORT PANEL <i>Distorted</i>	1	\$ 82.00	✓			
35	RADIATOR SUPPORT PANEL BOTTOM <i>2H Mer</i>	1		? X			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**Spark Car Care**

**ComfortDelGro Engineering Pte Ltd**  
 320 UBI ROAD 3 S (408649)  
 Tel: 6843 8723 68438736 Fax : 67436072

**Spare Parts 3**

Vehicle No : SCG126Z Case Owner : JOHARI

Make & Model : MERCEDES BENZ Year Manufacture : 2013

Chassis No : WDD2120362A796679 Engine No : 27492030059953

Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_

Order By : \_\_\_\_\_ Type of Claim : OD

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
36	RADIATOR SUPPOPT TOP GARNISH <i>Del'd</i>	1	\$ 72.00	✓			
37	TOP GARNISH CLIP'S <i>u</i>	2	\$ 2.00	4 ✓			
38	FRONT INTER COOLER <i>Me no</i>	1	\$ 650.00	x			
39	FRONT INTER COOLER COVER <i>Del'd</i>	1	\$ 45.00	x			
40	A/C CONDENSER ASSY <i>Not Nec</i>	1	\$ 650.00	?x			
41	RADIATOR ASSY <i>Not Nec</i>	1	\$ 700.00	?x			
42	RADIATOR AIR GUIDE RH <i>Not Nec</i>	1	\$ 24.00	?x			
43	RADIATOR AIR GUIDE LH <i>Not Nec</i>	1	\$ 24.00	?x			
44	RADIATOR FAN MOTOR COMPLET <i>Not Nec</i>	1	\$ 620.00	?x			
45	RADIATOR FAN MOTOR CONTROL UNIT <i>u</i>	1		.			
46	HEADLAMP LOWER BEAM RH <i>Not Nec</i>			?x			
47	HEADLAMP LOWER BEAM LH <i>Not Nec</i>	1		?x			
48	AIR DUCT FRONT <i>Del'd</i>	1	\$ 107.00	✓			
49	AIR DUCT REAR <i>Not Nec</i>	1		?x			
50	NUMBER PLATE GARNISH <i>Garnish Del'd</i>	1		✓			
51	NUMBER PLATE GARNISH <i>Bent</i>	1				\$ 45.00	✓
52	COOLANT <i>u</i>					\$ 80.00	So
53							
54							
55							
56							
57							
58							
59							
60							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.  
 18/03/2019



## Spark Car Care

ComfortDelGro Engineering Pte Ltd  
320 UBI ROAD 3 SINGAPORE 408649  
Tel: 68438723/68438736 Fax:67436072

### Supplementary 1

Vehicle No : SCG 126Z \_\_\_\_\_

Make & Model : MERCEDES BENZ E250 \_\_\_\_\_

Chassis No : WDD2120362A796679 \_\_\_\_\_

Sales Order : \_\_\_\_\_

Order By : \_\_\_\_\_ Type of Claim **OD**

S/No	Part Description	QTY	Cost Price	Nett Item	S/N	Disposition By Surveyor
1	FRONT BUMPER SUPPORT BRACKET LH	1	\$22.00	SPM		
2	FRONT BUMPER SUPPORT BRACKET RH	1	\$22.00	SPM		
3	FRONT BUMPER SPONGE	1	\$82.00	SPM		
4	BONNET LATCH SUPPORT BRACKET	1	\$26.00	SPM		
5	U-SHAPED STRIKER	1	\$29.00	SPM		
6	WIPER TANK	1	\$85.00	SPM		
7	FRONT BUMPER INNER BASE LH	1	\$42.00	SPM		
8	FRONT BUMPER INNER BASE RH	1	\$42.00	SPM		
9	FRONT BUMPER RIVET	6	\$12.00	SPM		
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						

*Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.*

SCG126Z Mercedes E250.

FRT Bumper Support Bracket <sup>Byd</sup> X 2PCS LH&RH \$22 X 2 ✓

FRT Bumper Sponge <sup>culd</sup> \$82.

Bonnet Latch Support Bracket <sup>Bent</sup> \$26.

U-Shaped Striker <sup>Bent</sup> \$ 29. ✓

Attn: Johari. Supp. items.

S/O: 3/08815. Done.

Add: Wiper Tank <sup>culd</sup> - \$85. ✓

FRT Bumper inner base LH - \$42 ✓  
- - - - - RH - \$42 ✓

FRT Bumper Rivet \$2 X 6PCS ✓

xc



320 UBI ROAD 3 S (408649)  
Tel: 6843 8723 68438736 Fax : 67436072

**Spare Parts** 2

Vehicle No : SCG126Z Case Owner : JOHARI  
 Make & Model : MERCEDES BENZ Year Manufacture : 2013  
 Chassis No : WDD2120362A796679 Engine No : 27492030059953  
 Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_  
 Order By : \_\_\_\_\_ Type of Claim : OD

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
11	FRONT REINFORCEMENT BRACKET RH <i>2x</i>	1	\$ 30.00	X			
12	FRONT REINFORCEMENT BRACKET LH <i>2x</i>	1	\$ 30.00	X			
13	FRONT BUMPER SPONGE <i>Delud</i>	1		X			
14	FRONT BUMPER BASE <i>Disturbed</i>	1	\$ 50.00	-			
15	BRASE PANEL <i>Best</i>	1	\$ 64.00	✓			
16	GRILLE EMBLEM <i>per</i>	1	\$ 42.00	✓			
17	FRONT BUMPER TOW COVER <i>Missing</i>	1	\$ 32.00	✓			
18	FRONT BUMPER SENSOR RH OUTER <i>2x</i>	1	\$ 90.00	X			
19	FRONT BUMPER SENSOR RH INNER <i>?</i>	1	\$ 90.00	?			
20	FRONT BUMPER SENSOR RH CENTER <i>2x</i>	1	\$ 90.00	X			
21	FRONT BUMPER SENSOR LH OUTER <i>?</i>	1	\$ 90.00	X			
22	FRONT BUMPER SENSOR LH INNER <i>2x</i>	1	\$ 90.00	X			
23	FRONT BUMPER SENSOR LH CENTER <i>?</i>	1	\$ 90.00	X			
24	FRONT FENDER RH <i>3 Buckled</i>	1	\$ 520.00	✓			
25	FRONT FENDER LH	1	\$ 520.00	✓			
26	FRONT HEADLAMP RH <i>crackd</i>	1	\$ 1,720.00	✓			
27	FRONT HEADLAMP LH <i>Bot</i>	1	\$ 1,720.00	✓			
28	FRONT HEADLAMP CONTROL UNIT RH <i>not</i>	1	\$ 495.00	X			
29	FRONT HEADLAMP CONTROL UNIT LH <i>not</i>	1	\$ 495.00	X			
30	FRONT FENDER CHROME MOULDING RH <i>not</i>	1	\$ 28.00	✓			
31	FRONT FENDER CHROME MOULDING LH <i>not</i>	1	\$ 28.00	✓			
32	HEADLAMP SUPPORT PANEL RH <i>3 Disturbed</i>	1	\$ 138.00	✓			
33	HEADLAMP SUPPORT PANEL LH	1	\$ 138.00	✓			
34	RADIATOR SUPPORT PANEL <i>Delud</i>	1	\$ 82.00	✓			
35	RADIATOR SUPPORT PANEL BOTTOM <i>not</i>	1		X			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

ComfortDelGro Engineering Pte Ltd  
 320 UBI ROAD 3 S (408649)  
 Tel: 6843 8723 68438736 Fax : 67436072

**Spare Parts 3**

Vehicle No : SCG126Z Case Owner : JOHARI  
 Make & Model : MERCEDES BENZ Year Manufacture : 2013  
 Chassis No : WDD2120362A796679 Engine No : 27492030059953  
 Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_  
 Order By : \_\_\_\_\_ Type of Claim : OD

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
36	RADIATOR SUPPOPT TOP GARNISH <i>Del'd</i>	1	\$ 72.00	✓			
37	TOP GARNISH CLIP'S <i>h</i>	2	\$ 2.00	✓			
38	FRONT INTER COOLER <i>Neu</i>	1	\$ 650.00	✗			
39	FRONT INTER COOLER COVER <i>Neu h</i>	1	\$ 45.00	✗			
40	A/C CONDENSER ASSY <i>Neu</i>	1	\$ 650.00	✗			
41	RADIATOR ASSY <i>Neu</i>	1	\$ 700.00	✗			
42	RADIATOR AIR GUIDE RH <i>Neu</i>	1	\$ 24.00	✗			
43	RADIATOR AIR GUIDE LH <i>Neu</i>	1	\$ 24.00	✗			
44	RADIATOR FAN MOTOR COMPLET <i>Neu</i>	1	\$ 620.00	✗			
45	RADIATOR FAN MOTOR CONTROL UNIT <i>Neu</i>	1		*			
46	HEADLAMP LOWER BEAM RH <i>Neu</i>	1		✗			
47	HEADLAMP LOWER BEAM LH <i>Neu</i>	1		✗			
48	AIR DUCT FRONT <i>Del'd</i>	1	\$ 107.00	—			
49	AIR DUCT REAR <i>Neu</i>	1		✗			
50	NUMBER PLATE GARNISH <i>Del'd</i>	1		✓			
51	NUMBER PLATE GARNISH <i>Best</i>	1					
52	COOLANT <i>Neu</i>				\$ 45.00		✓
53					\$ 80.00		So
54							
55							
56							
57							
58							
59							
60							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.  
 18/03/2019

**Spark Car Care**  
 ComfortDelgro Engineering Pte Ltd  
 320 UBI ROAD 3 SINGAPORE 408649  
 Tel: 68438723/68438736 FAX : 67438072

Finalization Form

Bill : ALLIED WORLD                      Vehicle Number : SCG 126Z  
 Attn to : MR ADRIAN LING                      Type Of Claim : OD

<b>A. Spare parts</b>	<u>\$8,583.00</u>	<b>F. Total Parts</b>	<u>\$9,839.50</u>
<b>B. Supplementary</b>	<u>\$362.00</u>	<b>G. Total Labour</b>	<u>\$2,030.00</u>
<b>C. Nett Price</b>	<u>\$95.00</u>	<b>H. Total Repair</b>	<u>\$11,869.50</u>
<b>D. Supp Nett Price</b>	<u>\$-</u>	<b>I. Excess</b>	<u>                    </u>
<b>E. S/Nett</b>	<u>\$-</u>	<b>P/P Total</b>	<u>11,869.50</u>

Total Spare Parts Price		\$8,945.00
Cost plus / List Down	10%	894.50
Total		9,839.50

Lump Sum Less                      \$-

Lump Sum Rounding                     

**Total Finalized**                     

Total Nett Price		
Nett Price Less		\$-
Total		-

*N.B. If we DO NOT receive your reply within 2 weeks, we shall treat the above finalized amount as confirmed & correct.*

Remarks : Please confirm and revert by Fax or Email

Date In : _____	Total Repair Day <u>8</u>
Date Survey : _____	LOU/ Day _____
Date Out : _____	Total LOU _____
Sat/Sun/Ph. : _____	Rental/Day _____
Authorized Repair Day _____	Total Rental _____
Submitted By / Date : _____	Confirmed By / Date : _____

## Spark Car Care

ComfortDelGro Engineering Pte Ltd  
320 UBI ROAD 3 SINGAPORE 408649  
TEL :68438723/68438736 Fax:67436072

### Spare Parts

Vehicle No : SCG 126Z Case Owner : \_\_\_\_\_

Make & Model : MERCEDES BENZ E250 Year Manufacture : 2013

Chassis No : WDD2120362A796679 Engine No : \_\_\_\_\_

Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_

Order By : \_\_\_\_\_ Type of Claim : OD

S/N	Part Description	QTY	Cost Price	List Price	Nett Price	S/N
1	FRONT BONNET	1	\$1,250.00			
2	BONNET LOCK	1	\$40.00			
3	ENGINE HOOD CATCH	2	\$72.00			
4	INSULATION	1	\$140.00			
5	BONNET INSULATOR CLIPS	12	\$48.00			
6	BONNET UPP SIDE CATCH RH	1	\$20.00			
7	BONNET UPP SIDE CATCH LH	1	\$20.00			
8	BONNET STOPPER SPRING RH	1	\$16.00			
9	BONNET STOPPER SPRING LH	1	\$16.00			
10	BONNET EMBLEM	1	\$54.00			
11	BONNET CENTER CATCH BAR	1	\$140.00			
12	FRONT GRILLE WITH CHROME	1	\$520.00			
13	FRONT BUMPER REINFORCEMENT	1	\$280.00			
14	FRONT BUMPER SPONGE	1	\$64.00			
15	FRONT FENDER RH	1	\$520.00			
16	FRONT FENDER LH	1	\$520.00			
17	FRT FENDER CHROME MOULDING RH	1	\$26.00			
18	FRT FENDER CHROME MOULDING LH	1	\$26.00			
19	HEADLAMP SUPPORT PANEL RH	1	\$138.00			
20	HEADLAMP SUPPORT PANEL LH	1	\$138.00			
21	RADIATOR SUPPORT PANEL	1	\$82.00			
22	RADIATOR SUPPORT TOP GARNISH	1	\$72.00			
23	AIR DUCT FRONT	1	\$107.00			
24	FRONT BUMPER	1	\$750.00			
25	BASE MOUNTING	1	\$48.00			
26	FRONT BUMPER TOW COVER	1	\$32.00			
27	FRONT HEADLAMP RH	1	\$1,720.00			
28	FRONT HEADLAMP LH	1	\$1,720.00			
29	TOP GARNISH CLIPS	2	\$4.00			
30	NUMBER PLATE & GARNISH	1			\$45.00	
31	COOLANT	1			\$50.00	

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

## Spark Car Care

ComfortDelGro Engineering Pte Ltd  
320 UBI ROAD 3 SINGAPORE 408649  
Tel: 68438723/68438736 Fax:67436072

### Supplementary 1

Vehicle No : SCG 126Z \_\_\_\_\_

Make & Model : MERCEDES BENZ E250 \_\_\_\_\_

Chassis No : WDD2120362A796679 \_\_\_\_\_

Sales Order : \_\_\_\_\_

Order By : \_\_\_\_\_ Type of Claim OD

S/No	Part Description	QTY	Cost Price	Nett Item	S/N	Disposition By Surveyor
1	FRONT BUMPER SUPPORT BRACKET LH	1	\$22.00			
2	FRONT BUMPER SUPPORT BRACKET RH	1	\$22.00			
3	FRONT BUMPER SPONGE	1	\$82.00			
4	BONNET LATCH SUPPORT BRACKET	1	\$26.00			
5	U-SHAPED STRIKER	1	\$29.00			
6	WIPER TANK	1	\$85.00			
7	FRONT BUMPER INNER BASE LH	1	\$42.00			
8	FRONT BUMPER INNER BASE RH	1	\$42.00			
9	FRONT BUMPER RIVET	6	\$12.00			
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						

*Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.*



# 平治汽车零部件供应商私人有限公司

## AUTOMEXIM SUPPLIES & PARTS HOUSE PTE LTD

580, SERANGOON ROAD SINGAPORE 218194  
TEL : 6295 5593 (4 LINES) FAX : 6295 8503  
GST REG NO : M2-0125450-7 RCB Reg No : 199404347N  
Email : automexi@singnet.com.sg

### DELIVERY ORDER

COMFORTDELGRO ENG PTE LTD(UBI) DELIVER TO :  
205 BRADDELL ROAD UBI  
SCG126Z  
ZHANG ZHUO  
REMARK : 4500808449 /

✓  
D/O NO : D617904  
DATE : 26/03/2019  
PAGE : 1 OF 1

ITEM	DESCRIPTION	QTY	UNIT	UNIT PRICE	TOTAL AMT.
1	212-880-0357DB / F BONET	1	PC	1,250.00	1,250.00
2	212-880-0064DB / LOCK	1	PC	40.00	40.00
3	212-880-0160DB / ENGINE HOOD CATCH	2	PC	36.00	72.00
4	112-682-0126DB / INSULATION	1	PC	140.00	140.00
5	001-988-0325DB / PLUG-IN MOUNTING	12	PC	4.00	48.00
6	212-880-0060DB / ENGINE HOOD CATCH	2	PC	20.00	40.00
7	204-880-0227DB / HOOK	2	PC	16.00	32.00
8	222-810-1200DB / BONET STAR	1	PC	54.00	54.00
9	212-880-1403DB / BEAM	1	PC	140.00	140.00
10	212-880-1483DB / RADIATOR GRILL	1	PC	520.00	520.00
11	212-620-1500DB / CROSS MEMBER	1	PC	280.00	280.00
12	212-885-4065DB / F BUMPER SPONGE	1	PC	64.00	64.00
13	212-880-1218DB / FRONT FENDER RH	1	PC	520.00	520.00
14	212-880-1118DB / FENDER	1	PC	520.00	520.00
15	212-690-4482DB / F FENDER MOULDING RH	1	PC	26.00	26.00
16	212-690-4382DB / F FENDER MOULDING LH	1	PC	26.00	26.00
17	112-620-4700DB / H/LAMP PANEL RH	1	PC	138.00	138.00
18	212-620-4600DB / H/LAMP PANEL LH	1	PC	138.00	138.00
19	212-620-1100DB / STIFFENING	1	PC	82.00	82.00
20	212-500-0455DB / COLD AIR	1	PC	72.00	72.00
21	274-090-0400DB / AIR INTAKE HOSE 274-090-0882	1	PC	107.00	107.00

ISSUED BY : BERNARD

COMFORTDELGRO ENGINEERING PTE LTD  
SCM, UBI BRANCH

NAME & SIGNATURE: *Zhang Zhuo*

DESIGNATION: \_\_\_\_\_

DATE: *26/03/19*

SUB-TOTAL : S\$ 4,309.00  
ADD. 7% GST : S\$ 301.63  
TOTAL : S\$ 4,610.63

GOODS SOLD CANNOT BE RETURNED OR EXCHANGED.

E & O.E



平治汽车零部件供应商私人有限公司

AUTOMEXIM SUPPLIES & PARTS HOUSE PTE LTD

580, SERANGOON ROAD SINGAPORE 218194  
 TEL : 6295 5593 (4 LINES) FAX : 6295 8503  
 GST REG NO : M2-0125450-7 RCB Reg No : 199404347N  
 Email : automexi@singnet.com.sg

**DELIVERY ORDER**

COMFORTDELGRO ENG PTE LTD(UBI) DELIVER TO :  
 205 BRADDELL ROAD UBI  
 - ZHANG ZHUO  
 - SCG126Z  
 REMARK : 4500808449 /

D/O NO : D617919  
 DATE : 27/03/2019  
 PAGE : 1 OF 1

ITEM	DESCRIPTION	QTY	UNIT	UNIT PRICE	TOTAL AMT.
1	212-880-2547DB / TRIM BUMPER	1	PC	750.00	750.00
2	212-885-3965DB / BASE MOUNTING	1	PC	48.00	48.00
3	212-885-0526DB / CAP	1	PC	32.00	32.00
4	212-820-1939DB / HEAD LAMP LH	1	PC	1,720.00	1,720.00
5	212-820-2039DB / HEAD LAMP RH	1	PC	1,720.00	1,720.00
6	000-991-9540DB / EXPANSION RIVET	2	PC	2.00	4.00

ISSUED BY : BERNARD  
 COMFORTDELGRO ENGINEERING PTE LTD  
 SCN, UBI BRANCH  
 NAME & SIGNATURE: *Zhang Zhuo*  
 DESIGNATION: \_\_\_\_\_ DATE: \_\_\_\_\_

27/03/19

SUB-TOTAL : S\$ 4,274.00  
 ADD. 7% GST : S\$ 299.18  
 TOTAL : S\$ 4,573.18

GOODS SOLD CANNOT BE RETURNED OR EXCHANGED.

E & O.E



平治汽车零部件供应商私人有限公司

AUTOMEXIM SUPPLIES & PARTS HOUSE PTE LTD

580, SERANGOON ROAD SINGAPORE 218194  
 TEL : 6295 5593 (4 LINES) FAX : 6295 8503  
 GST REG NO : M2-0125450-7 RCB Reg No : 199404347N  
 Email : automexi@singnet.com.sg

*DELIVERY ORDER*

COMFORTDELGRO ENG PTE LTD(UBI)  
 205 BRADDELL ROAD

DELIVER TO :  
 UBI  
 ZHANG ZHUO  
 SCG126Z

*Sup*  
 D/O NO : D617935  
 DATE : 28/03/2019  
 PAGE : 1 OF 1

REMARK : 4500808624 /

*506101726*

ITEM	DESCRIPTION	QTY	UNIT	UNIT PRICE	TOTAL AMT.
1	212-620-0028DB / BRACING	2	PC	22.00	44.00 ✓
2	212-880-0135DB / IMPACT ABSORBER	1	PC	82.00	82.00 ✓
3	212-620-0900DB / BONET LATCH SUPPORT BRACKET	1	PC	26.00	26.00 ✓
4	212-898-0232DB / U-SHAPED STRIKER	1	PCE	29.00	29.00 ✓

ISSUED BY : BERNARD

COMFORTDELGRO ENGINEERING PTE LTD  
 SCM, UBI BRANCH

NAME & SIGNATURE: *Zhang Zhuo*

DESIGNATION: \_\_\_\_\_ DATE: *28/03/19*

SUB-TOTAL : S\$ 181.00  
 ADD. 7% GST : S\$ 12.67  
 TOTAL : S\$ 193.67

GOODS SOLD CANNOT BE RETURNED OR EXCHANGED

E & O.E





# 平治汽车零部件供应商私人有限公司

## AUTOMEXIM SUPPLIES & PARTS HOUSE PTE LTD

580, SERANGOON ROAD SINGAPORE 218194  
 TEL : 6295 5593 (4 LINES) FAX : 6295 8503  
 GST REG NO : M2-0125450-7 RCB Reg No : 199404347N  
 Email : automexi@singnet.com.sg

### DELIVERY ORDER

COMFORTDELGRO ENG PTE LTD(UBI) DELIVER TO :  
 205 BRADDELL ROAD

UBI  
 ZHANG ZHUO  
 SCG126Z

D/O NO : D617947  
 DATE : 28/03/2019  
 PAGE : 1 OF 1

REMARK : 4500808716

5001017254

ITEM	DESCRIPTION	QTY	UNIT	UNIT PRICE	TOTAL AMT.
1	204-869-0200DB / WATER CONT 204-869-1420	1	PC	85.00	85.00
2	212-885-3765DB / F BUMPER BASIC MOUNTING LH	1	PC	42.00	42.00
3	212-885-3865DB / F BUMPER FRAME RH	1	PC	42.00	42.00
4	03-990-9497DB / BLIND RIVET	6	PC	2.00	12.00

ISSUED BY: BERNARD  
 COMFORTDELGRO ENGINEERING PTE LTD  
 320 UBI ROAD SINGAPORE 408649  
 TEL: 6748 7586 FAX: 6748 1422

SUB-TOTAL : S\$ 181.00  
 ADD. 7% GST : S\$ 12.67  
 TOTAL : S\$ 193.67

GOODS SOLD CANNOT BE RETURNED OR EXCHANGED

E & O.E




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ALLIED WORLD ASSURANCE COMPANY LTD		Ref : CS/AWA19004934/Aqd3e2	
(SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914		Date : 03-06-2019	
		Code : AWA	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SCG 126Z
Policy No.	BVPISB0045881804	Coverage (\$)	0.00
Claim No.	NSV1900136/BT	Excess (\$)	0.00
Assign From	WONG KIN	Assign Date	18/03/2019
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ E250 SEDAN (R17)	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	WDD2120362A796679	Colour	BROWN
Odometer	103658	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/45 R17	BRIDGESTONE	6 mm
L/H Front Tyre	245/45 R17	BRIDGESTONE	6 mm
R/H Rear Tyre	245/45 R17	BRIDGESTONE	6 mm
L/H Rear Tyre	245/45 R17	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	13/03/2019	Inspection Date	19/03/2019
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD NO : 330 UBI ROAD 3 SINGAPORE 408649		
5a. Remarks			
A)THE MARKET VALUE IS S\$93,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>8 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCG 126Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BONNET (WCP)	DISTORTED	1,250.00	1,250.00
1	BONNET HINGE RH (WCP)	NOT NECESSARY	80.00	-
1	BONNET HINGE LH (WCP)	NOT NECESSARY	80.00	-
1	BONNET CENTER CATCH (WCP)	BENT	40.00	40.00
1	BONNET SIDE LOCK RH (WCP)	DAMAGED	36.00	36.00
1	BONNET SIDE LOCK LH (WCP)	DAMAGED	36.00	36.00
1	BONNET ABSORBER RH (WCP)	NOT NECESSARY	64.00	-
1	BONNET ABSORBER LH (WCP)	NOT NECESSARY	64.00	-
1	BONNET INSULATOR (WCP)	CRUMPLED	140.00	140.00
12	BONNET INSULATOR CLIPS @\$4.00(WCP)	NECESSARY	48.00	48.00
1	BONNET UPPER SIDE CATCH RH (WCP)	BENT	20.00	20.00
1	BONNET UPPER SIDE CATCH LH (WCP)	BENT	20.00	20.00
1	BONNET STOPPER SPRING RH (WCP)	DAMAGED	16.00	16.00
1	BONNET STOPPER SPRING LH (WCP)	DAMAGED	16.00	16.00
1	BONNET EMBLEM (WCP)	NECESSARY	54.00	54.00
1	BONNET RUBBER RH (NPA)	NOT NECESSARY	-	-
1	BONNET RUBBER LH (NPA)	NOT NECESSARY	-	-
1	BONNET CENTER CATCH BAR (WCP)	BENT	140.00	140.00
1	FRONT GRILLE WITH CHROME (WCP)	CRACKED	520.00	520.00
1	FRONT BUMPER (WCP)	DEFORMED	750.00	750.00
1	FRONT BUMPER SIDE RETAINER RH(WCP)	NOT NECESSARY	39.00	-
1	FRONT BUMPER SIDE RETAINER LH(WCP)	NOT NECESSARY	39.00	-
1	FRONT BUMPER LOWER GRILLE (WCP)	NOT NECESSARY	49.00	-
1	FRONT BUMPER LOWER CHROME MOULDING (WCP)	NOT NECESSARY	100.00	-
1	FRONT BUMPER REINFORCEMENT (WCP)	BENT	280.00	280.00
1	FRONT REINFORCEMENT BRACKET RH (WCP)	NOT NECESSARY	30.00	-
1	FRONT REINFORCEMENT BRACKET LH (WCP)	NOT NECESSARY	30.00	-
1	FRONT BUMPER SPONGE (NPA)	NOT NECESSARY	-	-
1	FRONT BUMPER BASE (WCP)	DISTORTED	50.00	48.00
1	BRACE PANEL (WCP)	BENT	64.00	64.00
1	GRILLE EMBLEM (WCP)	NOT NECESSARY	42.00	-
1	FRONT BUMPER TOW COVER (WCP)	MISSING	32.00	32.00
1	FRONT BUMPER SENSOR RH OUTER (WCP)	NOT NECESSARY	90.00	-
1	FRONT BUMPER SENSOR RH INNER (WCP)	NOT NECESSARY	90.00	-

Report Ref No. CS/AWA19004934/Aqd3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER SENSOR RH CENTER (WCP)	NOT NECESSARY	90.00	-
1	FRONT BUMPER SENSOR LH OUTER (WCP)	NOT NECESSARY	90.00	-
1	FRONT BUMPER SENSOR LH INNER (WCP)	NOT NECESSARY	90.00	-
1	FRONT BUMPER SENSOR LH CENTER (WCP)	NOT NECESSARY	90.00	-
1	FRONT FENDER RH (WCP)	BUCKLED	520.00	520.00
1	FRONT FENDER LH (WCP)	BUCKLED	520.00	520.00
1	FRONT HEADLAMP RH (WCP)	CRACKED	1,720.00	1,720.00
1	FRONT HEADLAMP LH (WCP)	CUT	1,720.00	1,720.00
1	FRONT HEADLAMP CONTROL UNIT RH (WCP)	NOT NECESSARY	495.00	-
1	FRONT HEADLAMP CONTROL UNIT LH (WCP)	NOT NECESSARY	495.00	-
1	FRONT FENDER CHROME MOULDING RH (WCP)	NECESSARY	26.00	26.00
1	FRONT FENDER CHROME MOULDING LH (WCP)	NECESSARY	26.00	26.00
1	HEADLAMP SUPPORT PANEL RH (WCP)	DISTORTED	138.00	138.00
1	HEADLAMP SUPPORT PANEL LH (WCP)	DISTORTED	138.00	138.00
1	RADIATOR SUPPORT PANEL (WCP)	DEFORMED	82.00	82.00
1	RADIATOR SUPPORT PANEL BOTTOM (NPA)	NOT NECESSARY	-	-
1	RADIATOR SUPPORT TOP GARNISH (WCP)	DEFORMED	72.00	72.00
2	TOP GARNISH CLIPS @\$2.00 (WCP)	NECESSARY	4.00	4.00
1	FRONT INTER COOLER (WCP)	NOT NECESSARY	650.00	-
1	FRONT INTER COOLER COVER (WCP)	NOT NECESSARY	45.00	-
1	A/C CONDENSER ASSY (WCP)	NOT NECESSARY	650.00	-
1	RADIATOR ASSY (WCP)	NOT NECESSARY	700.00	-
1	RADIATOR AIR GUIDE RH (WCP)	NOT NECESSARY	24.00	-
1	RADIATOR AIR GUIDE LH (WCP)	NOT NECESSARY	24.00	-
1	RADIATOR FAN MOTOR COMPLET (WCP)	NOT NECESSARY	620.00	-
1	RADIATOR FAN MOTOR CONTROL UNIT (NPA)	NOT NECESSARY	-	-
1	HEADLAMP LOWER BEAM RH (NPA)	NOT NECESSARY	-	-
1	HEADLAMP LOWER BEAM LH (NPA)	NOT NECESSARY	-	-
1	AIR DUCT FRONT (WCP)	DEFORMED	107.00	107.00
1	AIR DUCT REAR (NPA)	NOT NECESSARY	-	-
1	NUMBER PLATE GARNISH (NPA)	DEFORMED	-	-
1	FRONT BUMPER SUPPORT BRACKET LH (WCP) (ADDITIONAL)	DAMAGED	22.00	22.00
1	FRONT BUMPER SUPPORT BRACKET RH (WCP) (ADDITIONAL)	DAMAGED	22.00	22.00
1	FRONT BUMPER SPONGE (WCP)(ADDITIONAL)	CRACKED	82.00	82.00

Report Ref No. CS/AWA19004934/Aqd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET LATCH SUPPORT BRACKET (WCP) (ADDITIONAL)	BENT	26.00	26.00
1	U-SHAPED STRIKER (WCP)(ADDITIONAL)	BENT	29.00	29.00
1	WIPER TANK (WCP)(ADDITIONAL)	DEFORMED	85.00	85.00
1	FRONT BUMPER INNER BASE LH (WCP)(ADDITIONAL)	DEFORMED	42.00	42.00
1	FRONT BUMPER INNER BASE RH (WCP)(ADDITIONAL)	DEFORMED	42.00	42.00
6	FRONT BUMPER RIVET (WCP)(ADDITIONAL)	NECESSARY	12.00	12.00
	COST PLUS 10%		-	894.50
			13,807.00	9,839.50
	<b>SPECIAL NETT ITEMS</b>			
1	NUMBER PLATE (SN)	BENT	45.00	45.00
1	COOLANT (SN)	NECESSARY	80.00	50.00
			125.00	95.00
	<b>LABOUR</b>			
	PUTTY & SPRAY PAINT BONNET, BUMPER, FRONT BOTH FENDER, FENDER TOP BEAM BOTH SIDE, A-PILLAR AND AFFECTED AREA.		1,700.00	1,000.00
	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKET AND ETC.		100.00	30.00
	TO REMOVE AND REPLACE A/C CONDENSER PIPES AND RADIATOR, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.		240.00	120.00
	TO REPLACE & REINSTALL FRONT DISTANCE SENSOR.		220.00	80.00
	TO REPROGRAMMING HEADLAMP.	NOT NECESSARY	480.00	-
	CUT & WELD RADIATOR SUPPORT PANEL, KNOCK REPAIR FRONT FENDER TOP BEAM BOTH SIDE, A-PILLAR AND AFFECTED AREA.		1,000.00	800.00
			3,740.00	2,030.00
<b>GRAND TOTAL</b>			<b>17,672.00</b>	<b>11,964.50</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>11,964.50</b>

Report Ref No. CS/AWA19004934/Aqd3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.