

15/5/2010

INS. CASE OWNER:

Sailha

CC 3/AIG1900

4928, J. 18/2/14

LKK:

IDAC:

Surveyor:

M. J

DOI:

ASSIGNMENT

18/2/14

Date / Time:

18/2/14

Registered in Merimen:

19/2/14

Pre-assign / CCU / FTE



Insured Vehicle No.:

SGK 572T

Name of Insured:

Tom Munn KET

Insured Tel No.:

HP:

Excess Sec II :\$

D.O.A:

15/3/14

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

055202119054

Policy No.:

1010653039-12

Make / Model:

DUMMATION

Place of Accident:

PAPER KO

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SGK 8773L

SGK 572T

SGK 4705M

SLT 7422T

INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

01

INSRS:  
WSP: SMRT  
Tel:  
Liability:  
RMKS: TPINSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

| Date/ Time                                                                                                                                               | STAGE                                                                                                                                                                             | DATE / PIC                                                              |
|----------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------|
|                                                                                                                                                          | Non-Reporting ltr (1st):                                                                                                                                                          |                                                                         |
|                                                                                                                                                          | Non-Reporting ltr (2nd):                                                                                                                                                          |                                                                         |
|                                                                                                                                                          | Non-Reporting ltr (Final):                                                                                                                                                        |                                                                         |
|                                                                                                                                                          | Notification ltr (if non-pickup):                                                                                                                                                 |                                                                         |
|                                                                                                                                                          | Call OE: 4/4/2014                                                                                                                                                                 |                                                                         |
|                                                                                                                                                          | After call ltr to OI:                                                                                                                                                             |                                                                         |
|                                                                                                                                                          | Documentation Check List:                                                                                                                                                         | Handler Typist                                                          |
|                                                                                                                                                          | Notification ltr (if non-pickup)                                                                                                                                                  | <input type="checkbox"/>                                                |
|                                                                                                                                                          | After call ltr to OE:                                                                                                                                                             | <input checked="" type="checkbox"/>                                     |
|                                                                                                                                                          | Authorisation To Act:                                                                                                                                                             | <input checked="" type="checkbox"/>                                     |
|                                                                                                                                                          | Release Voucher:                                                                                                                                                                  | <input checked="" type="checkbox"/>                                     |
|                                                                                                                                                          | Final Repair Bill:                                                                                                                                                                | <input checked="" type="checkbox"/>                                     |
|                                                                                                                                                          | Car Rental Invoice:                                                                                                                                                               | <input checked="" type="checkbox"/>                                     |
|                                                                                                                                                          | Towing Invoice:                                                                                                                                                                   | <input type="checkbox"/>                                                |
|                                                                                                                                                          | LTA/ GIA:                                                                                                                                                                         | <input checked="" type="checkbox"/>                                     |
|                                                                                                                                                          | Medical Bill:                                                                                                                                                                     | <input type="checkbox"/>                                                |
|                                                                                                                                                          | PIR:                                                                                                                                                                              | <input type="checkbox"/>                                                |
|                                                                                                                                                          | Mandate/Reject Instruction:                                                                                                                                                       | <input type="checkbox"/>                                                |
|                                                                                                                                                          | LOD:                                                                                                                                                                              | <input checked="" type="checkbox"/>                                     |
|                                                                                                                                                          | Payment Breakdown Form:                                                                                                                                                           | <input type="checkbox"/>                                                |
|                                                                                                                                                          | Post-Repair Photos:                                                                                                                                                               | <input type="checkbox"/>                                                |
|                                                                                                                                                          | Others:                                                                                                                                                                           | <input type="checkbox"/>                                                |
| 4/4/2014                                                                                                                                                 | Spoke to OI, confirmed BOLA 28, 4 car chain collision, OI is 3rd, 7P is 2nd, explain 19CF, OI agree to settle and cover MCD will be withheld for the time being send letter to OI |                                                                         |
| 24/10/14                                                                                                                                                 | File pass to Shaqilah to close                                                                                                                                                    |                                                                         |
|                                                                                                                                                          | After paint photo                                                                                                                                                                 |                                                                         |
| PRELIMINARY ADVICE                                                                                                                                       | Date/Time: 19/1/2014                                                                                                                                                              | Sent By: LSP                                                            |
| FINALIZATION                                                                                                                                             | Date/Time: Confirm with:                                                                                                                                                          | Confirm by:                                                             |
| Repair Cost:                                                                                                                                             | \$S 4,450.00 (6 days) Reduction: 7528 %                                                                                                                                           | Email <input type="checkbox"/> Call <input type="checkbox"/>            |
| FINAL SETTLEMENT                                                                                                                                         | Date/Time: 4/7/2014 Confirm with Lee Gek                                                                                                                                          | Email <input checked="" type="checkbox"/> Call <input type="checkbox"/> |
| Final Liability:                                                                                                                                         | % 100 (Agreed / Assessed) BOLA S/N No.: 28                                                                                                                                        | If NO or B 28, Ass. Lia: 0%                                             |
| Repair Cost:                                                                                                                                             | \$S 4,450.00                                                                                                                                                                      |                                                                         |
| Loss of Rental (LOR):                                                                                                                                    | \$S 982.26 (9 days) X 109.14                                                                                                                                                      |                                                                         |
| Loss of Use (LOU):                                                                                                                                       | \$S - (5 x days)                                                                                                                                                                  |                                                                         |
| Loss of Income (LOI):                                                                                                                                    | \$S 450.00 (\$50.00 x 9 days)                                                                                                                                                     |                                                                         |
| LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LO <input type="checkbox"/> [Tick only one] |                                                                                                                                                                                   |                                                                         |
| GIA/LTA Search                                                                                                                                           | \$S 7.00                                                                                                                                                                          |                                                                         |
| Medical:                                                                                                                                                 | \$S -                                                                                                                                                                             |                                                                         |
| Disbursement:                                                                                                                                            | \$S - (e.g. Tow/ Independent)                                                                                                                                                     |                                                                         |
| Legal Cost                                                                                                                                               | \$S -                                                                                                                                                                             |                                                                         |
| Total:                                                                                                                                                   | \$S 5,889.26 Global Sum \$S: 5,880.00                                                                                                                                             |                                                                         |
| FINAL PAYMENT                                                                                                                                            | Date/Time: Confirm with:                                                                                                                                                          | Email <input type="checkbox"/> Call <input type="checkbox"/>            |
| Payee 1:                                                                                                                                                 | \$S 5,880.00 Name 1: SMRT TAXIS PTE LTD                                                                                                                                           |                                                                         |
| Payee 2: (Strike if N.A.)                                                                                                                                | \$S Name 2:                                                                                                                                                                       |                                                                         |
| Payee 3: (Strike if N.A.)                                                                                                                                | \$S Name 3:                                                                                                                                                                       |                                                                         |

4 car chain collision, OI is third vehicle and was pushed by behind.

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee:

\$320.00





## Case Details

Case Reference Number : TAX/03/19/2063  
 Type of Repair : Accident Repair  
 Vehicle Registration Number : SHC4705M

Company Type : SMRT Taxis Pte Ltd  
 Estimation ID : EST-6106-ID  
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd  
 Accident Date and Time : 15/03/2019 01:00 AM  
 Vehicle Age(In Months) : 51

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

## Estimation Details

### Spare Part's Cost Detail

| BOM Type        | Costing Type | Portion | Material Number | SMRT Recommendation        |     |                         |                |        |                 | Surveyor Approval |                   |                          |                |   | Remarks   |
|-----------------|--------------|---------|-----------------|----------------------------|-----|-------------------------|----------------|--------|-----------------|-------------------|-------------------|--------------------------|----------------|---|-----------|
|                 |              |         |                 | Part Name                  | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace   | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace |   |           |
| One Time Key In | Main         |         |                 | BUMPER REAR                | 1   | 458.60                  | 458.60         | 25.00  | 343.95          | Replace           | 1                 | 343.95 ✓                 | Replace        | * | BUC ✓     |
| One Time Key In | Main         |         |                 | BUMPER REINFORCEMENT REAR  | 1   | 205.70                  | 205.70         | 25.00  | 154.27          | Replace           | 0                 | 0 154.28                 | Check          | * | ✓ DT ✓    |
| One Time Key In | Main         |         |                 | ARM SUB-ASSY, RR BUMPER LH | 1   | 139.60                  | 139.60         | 25.00  | 104.70          | Replace           | 0                 | 0 104.70                 | Check          | * | ✓ GRS ✓   |
| One Time Key In | Main         |         |                 | ARM SUB-ASSY, RR BUMPER RH | 1   | 139.60                  | 139.60         | 25.00  | 104.70          | Replace           | 0                 | 0 104.70                 | Check          | * | ✓ COM ✓   |
| One Time Key In | Main         |         |                 | BUMPER SIDE RETAINER RR/LH | 1   | 94.80                   | 94.80          | 25.00  | 71.10           | Replace           | 0                 | 0 71.10                  | Check          | * | ✓ COM ✓   |
| One Time Key In | Main         |         |                 | BUMPER SIDE RETAINER RR/RH | 1   | 94.80                   | 94.80          | 25.00  | 71.10           | Replace           | 0                 | 0                        | Check          | * | X 201     |
| One Time Key In | Main         |         |                 | SENSOR REVERSE             | 1   | 180.00                  | 180.00         | 0.00   | 180.00          | Replace           | 1                 | 180.00 ✓                 | Replace        | * | Shorted ✓ |
| One Time Key In | Main         |         |                 | PIXEL STICKER              | 2   | 60.00                   | 120.00         | 0.00   | 120.00          | Replace           | 2                 | 120.00 ✓                 | Replace        | * | rec ✓     |
| One Time Key In | Main         |         |                 | BUMPER LIP REAR            | 1   | 228.90                  | 228.90         | 25.00  | 171.68          | Replace           | 1                 | 171.68 ✓                 | Replace        | * | DEF ✓     |
| One Time Key In | Main         |         |                 | BUMPER LIP COVER RR/LH     | 1   | 72.20                   | 72.20          | 25.00  | 54.15           | Replace           | 1                 | 54.15 ✓                  | Replace        | * | DEF ✓     |

Total Spare Part Cost 10,486.84

Surveyor Total 2,114.08

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 8,391.07

Final Sur Total 1,691.26

| SMRT Recommendation   |              |         |                 |                                   |     |                         |                |        |                 |                          | Surveyor Approval |                          |                |         |
|-----------------------|--------------|---------|-----------------|-----------------------------------|-----|-------------------------|----------------|--------|-----------------|--------------------------|-------------------|--------------------------|----------------|---------|
| BOM Type              | Costing Type | Portion | Material Number | Part Name                         | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace          | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In       | Main         |         |                 | BUMPER LIP COVER RR/RH            | 1   | 118.10                  | 118.10         | 25.00  | 88.57           | Replace                  | 1                 | 88.57<br>88.58           | Replace        | DEF ✓   |
| One Time Key In       | Main         |         |                 | UNDER COVER SUB-ASSY, RR FLOOR    | 1   | 514.50                  | 514.50         | 25.00  | 385.88          | Replace                  | 0                 | 0                        | Check          | NN      |
| One Time Key In       | Main         |         |                 | END PANEL                         | 1   | 602.10                  | 602.10         | 25.00  | 451.58          | Replace                  | 0                 | 0                        | Check          |         |
| One Time Key In       | Main         |         |                 | SEALANT SIKAFLEX                  | 1   | 37.00                   | 37.00          | 0.00   | 37.00           | Replace                  | 0                 | 0                        | Check          |         |
| One Time Key In       | Main         |         |                 | TAILGATE ASY                      | 1   | 1,007.90                | 1,007.90       | 25.00  | 755.92          | Replace                  | 1                 | 755.92<br>755.93         | Replace        | BUC ✓   |
| One Time Key In       | Main         |         |                 | TAILGATE OUTSIDE GARNISH          | 1   | 504.90                  | 504.90         | 25.00  | 378.67          | Replace                  | 1                 | 0                        | Repair         | R ✓     |
| One Time Key In       | Main         |         |                 | EMBLEM REAR                       | 1   | 60.30                   | 60.30          | 25.00  | 45.22           | Replace                  | 1                 | 45.22<br>45.23           | Replace        | rec ✓   |
| One Time Key In       | Main         |         |                 | NAME PLATE (HYBRID)               | 1   | 51.90                   | 51.90          | 25.00  | 38.92           | Replace                  | 1                 | 38.92<br>38.93           | Replace        | rec ✓   |
| One Time Key In       | Main         |         |                 | NAME PLATE (PRIUS)                | 1   | 60.80                   | 60.80          | 25.00  | 45.60           | Replace                  | 1                 | 45.60                    | Replace        | rec ✓   |
| One Time Key In       | Main         |         |                 | NAME PLATE (TOYOTA)               | 1   | 51.90                   | 51.90          | 25.00  | 38.92           | Replace                  | 1                 | 38.92<br>38.93           | Replace        | rec ✓   |
| One Time Key In       | Main         |         |                 | NUMBER PLATE                      | 1   | 15.00                   | 15.00          | 0.00   | 15.00           | Replace                  | 1                 | 15.00                    | Replace        | DEF ✓   |
| One Time Key In       | Main         |         |                 | NUMBER PLATE FRAME                | 1   | 12.00                   | 12.00          | 0.00   | 12.00           | Replace                  | 1                 | 12.00                    | Replace        | CRA ✓   |
| One Time Key In       | Main         |         |                 | TAIL GATE DOOR GLASS MOULDING, LH | 1   | 29.40                   | 29.40          | 25.00  | 22.05           | Replace                  | 1                 | 22.05                    | Replace        | rec ✓   |
| One Time Key In       | Main         |         |                 | TAIL GATE DOOR GLASS MOULDING, RH | 1   | 29.40                   | 29.40          | 25.00  | 22.05           | Replace                  | 1                 | 22.05                    | Replace        | rec ✓   |
| One Time Key In       | Main         |         |                 | MOULDING BACK WINDOW, LOWER NO.1  | 1   | 29.40                   | 29.40          | 25.00  | 22.05           | Replace                  | 1                 | 22.05                    | Replace        | rec ✓   |
| One Time Key In       | Main         |         |                 | SEALANT W/SCREEN                  | 3   | 37.00                   | 111.00         | 0.00   | 111.00          | Replace                  | 3                 | 111.00                   | Replace        | rec ✓   |
| Total Spare Part Cost |              |         |                 |                                   |     |                         |                |        | 10,488.84       | Surveyor Total 2,114.08  |                   |                          |                |         |
| Lump Sum Discount (%) |              |         |                 |                                   |     |                         |                |        | 20.00           | Lump Sum Dis (%) 20      |                   |                          |                |         |
| Final Spare Part Cost |              |         |                 |                                   |     |                         |                |        | 8,391.07        | Final Sur Total 1,691.26 |                   |                          |                |         |

| SMRT Recommendation   |              |         |                 |                                 |     |                         |                |                        |                 |                  |                   | Surveyor Approval        |                |         |  |
|-----------------------|--------------|---------|-----------------|---------------------------------|-----|-------------------------|----------------|------------------------|-----------------|------------------|-------------------|--------------------------|----------------|---------|--|
| BOM Type              | Costing Type | Portion | Material Number | Part Name                       | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%)                 | Final Price(\$) | Repair/ Replace  | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |  |
| One Time Key In       | Main         |         |                 | SPOILER REAR                    | 1   | 953.70                  | 953.70         | 25.00                  | 715.28          | Replace          | 0                 | 0                        | Not Give       | mm      |  |
| One Time Key In       | Main         |         |                 | 3RD BRAKE LAMP                  | 1   | 231.30                  | 231.30         | 25.00                  | 173.48          | Replace          | 0                 | 0                        | Check          | mm      |  |
| One Time Key In       | Main         |         |                 | TAILGATE TRIM, LH               | 1   | 85.90                   | 85.90          | 25.00                  | 64.43           | Replace          | 0                 | 0                        | Check          |         |  |
| One Time Key In       | Main         |         |                 | TAILGATE TRIM, LOWER            | 1   | 180.70                  | 180.70         | 25.00                  | 135.52          | Replace          | 0                 | 0                        | Check          |         |  |
| One Time Key In       | Main         |         |                 | TAILGATE TRIM, RH               | 1   | 88.30                   | 88.30          | 25.00                  | 66.22           | Replace          | 0                 | 0                        | Check          |         |  |
| One Time Key In       | Main         |         |                 | TAILGATE TRIM, UPPER            | 1   | 49.60                   | 49.60          | 25.00                  | 37.20           | Replace          | 0                 | 0                        | Check          |         |  |
| One Time Key In       | Main         |         |                 | TAILGATE, BOARD ASSY            | 1   | 246.90                  | 246.90         | 25.00                  | 185.18          | Replace          | 0                 | 0                        | Check          | mm      |  |
| One Time Key In       | Main         |         |                 | ANTENNA, ELECTRICAL LOWER REAR  | 1   | 157.40                  | 157.40         | <del>10.00</del><br>25 | 141.66          | Replace          | 0                 | 0118.05                  | Check          | ✓ mm ✓  |  |
| One Time Key In       | Main         |         |                 | END PANEL COVER, DECK TRIM HOLE | 1   | 46.10                   | 46.10          | 25.00                  | 34.58           | Replace          | 0                 | 0                        | Not Give       | mm      |  |
| One Time Key In       | Main         |         |                 | END PANEL COVER, DECK TRIM, RR  | 1   | 121.10                  | 121.10         | 25.00                  | 90.82           | Replace          | 0                 | 0                        | Not Give       | mm      |  |
| One Time Key In       | Main         |         |                 | TAILGATE DOOR LOCK              | 1   | 444.10                  | 444.10         | 10.00                  | 399.69          | Replace          | 0                 | 0                        | Check          | mm      |  |
| One Time Key In       | Main         |         |                 | TAIL LAMP BRACKET, LH           | 1   | 30.70                   | 30.70          | 25.00                  | 23.02           | Replace          | 0                 | 0                        | Check          |         |  |
| One Time Key In       | Main         |         |                 | TAIL LAMP BRACKET, RH           | 1   | 30.70                   | 30.70          | 25.00                  | 23.02           | Replace          | 0                 | 0                        | Check          |         |  |
| One Time Key In       | Main         |         |                 | TAIL LAMP LH                    | 1   | 548.40                  | 548.40         | 10.00                  | 493.56          | Replace          | 0                 | 0                        | Check          |         |  |
| One Time Key In       | Main         |         |                 | TAIL LAMP RH                    | 1   | 557.80                  | 557.80         | 10.00                  | 502.02          | Replace          | 0                 | 0307.02                  | Check          | ✓ mm ✓  |  |
| One Time Key In       | Main         |         |                 | FENDER RR/LH                    | 1   | 766.80                  | 766.80         | 25.00                  | 575.10          | Replace          | 0                 | 0                        | Not Give       | mm      |  |
| Total Spare Part Cost |              |         |                 |                                 |     |                         |                |                        | 10,488.84       | Surveyor Total   |                   |                          | 2,114.08       |         |  |
| Lump Sum Discount (%) |              |         |                 |                                 |     |                         |                |                        | 20.00           | Lump Sum Dis (%) |                   |                          | 20             |         |  |
| Final Spare Part Cost |              |         |                 |                                 |     |                         |                |                        | 8,391.07        | Final Sur Total  |                   |                          | 1,691.26       |         |  |

| SMRT Recommendation |              |         |                 |                               |     |                         |                |        |                 |                 |                   |                          |                | Surveyor Approval |  |  |
|---------------------|--------------|---------|-----------------|-------------------------------|-----|-------------------------|----------------|--------|-----------------|-----------------|-------------------|--------------------------|----------------|-------------------|--|--|
| BOM Type            | Costing Type | Portion | Material Number | Part Name                     | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks           |  |  |
| One Time Key In     | Main         |         |                 | STICKER SMRT LOGO             | 1   | 7.80                    | 7.80           | 0.00   | 7.80            | Replace         | 0                 | 0                        | Not Give       | nn                |  |  |
| One Time Key In     | Main         |         |                 | STICKER DECAL 6555 8888       | 1   | 21.60                   | 21.60          | 0.00   | 21.60           | Replace         | 0                 | 0                        | Not Give       | nn                |  |  |
| One Time Key In     | Main         |         |                 | FENDER RR/RH                  | 1   | 766.80                  | 766.80         | 25.00  | 575.10          | Replace         | 0                 | 0                        | Not Give       | nn                |  |  |
| One Time Key In     | Main         |         |                 | STICKER DECAL 6555 8888       | 1   | 21.60                   | 21.60          | 0.00   | 21.60           | Replace         | 0                 | 0                        | Not Give       | nn                |  |  |
| One Time Key In     | Main         |         |                 | STICKER DECAL SMRT            | 1   | 7.80                    | 7.80           | 0.00   | 7.80            | Replace         | 0                 | 0                        | Not Give       | nn                |  |  |
| One Time Key In     | Main         |         |                 | QUARTER GLASS RR/LH           | 1   | 168.10                  | 168.10         | 25.00  | 126.07          | Replace         | 0                 | 0                        | Not Give       | nn                |  |  |
| One Time Key In     | Main         |         |                 | QUARTER GLASS RR/RH           | 1   | 846.50                  | 846.50         | 25.00  | 634.88          | Replace         | 0                 | 0                        | Not Give       | nn                |  |  |
| One Time Key In     | Main         |         |                 | SEALANT W/SCREEN              | 2   | 37.00                   | 74.00          | 0.00   | 74.00           | Replace         | 0                 | 0                        | Not Give       | nn                |  |  |
| One Time Key In     | Main         |         |                 | BUMPER FRT                    | 1   | 482.00                  | 482.00         | 25.00  | 361.50          | Replace         | 1                 | 0                        | Repair         | R                 |  |  |
| One Time Key In     | Main         |         |                 | BUMPER ENERGY ABSORBER FRT    | 1   | 78.80                   | 78.80          | 25.00  | 59.10           | Replace         | 0                 | 0                        | Not Give       | nn                |  |  |
| One Time Key In     | Main         |         |                 | BUMPER REINFORCEMENT FRT      | 1   | 498.40                  | 498.40         | 25.00  | 373.80          | Replace         | 0                 | 0                        | Not Give       | nn                |  |  |
| One Time Key In     | Main         |         |                 | ARM SUB-ASSY, FR BUMPER LH    | 1   | 250.40                  | 250.40         | 25.00  | 187.80          | Replace         | 0                 | 0                        | Not Give       | nn                |  |  |
| One Time Key In     | Main         |         |                 | ARM SUB-ASSY, FR BUMPER RH    | 1   | 250.40                  | 250.40         | 25.00  | 187.80          | Replace         | 0                 | 0                        | Not Give       | nn                |  |  |
| One Time Key In     | Main         |         |                 | BUMPER GRILLE SUB-ASSY, LOWER | 1   | 311.10                  | 311.10         | 25.00  | 233.33          | Replace         | 0                 | 0                        | Not Give       | nn                |  |  |
| One Time Key In     | Main         |         |                 | BRACKET, FR BUMPER            | 1   | 110.40                  | 110.40         | 25.00  | 82.80           | Replace         | 0                 | 0                        | Not Give       | nn                |  |  |
| One Time Key In     | Main         |         |                 | NUMBER PLATE                  | 1   | 15.00                   | 15.00          | 0.00   | 15.00           | Replace         | 1                 | 15.00                    | Replace        | DEF ✓             |  |  |

Total Spare Part Cost 10,488.84

Surveyor Total 2,114.08

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 8,391.07

Final Sur Total 1,691.26

| SMRT Recommendation |              |         |                 |                    |     |                         |                |        |                 | Surveyor Approval |                   |                          |                        |
|---------------------|--------------|---------|-----------------|--------------------|-----|-------------------------|----------------|--------|-----------------|-------------------|-------------------|--------------------------|------------------------|
| BOM Type            | Costing Type | Portion | Material Number | Part Name          | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace   | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace Remarks |
| One Time Key In     | Main         |         |                 | NUMBER PLATE FRAME | 1   | 12.00                   | 12.00          | 0.00   | 12.00           | Replace           | 1                 | 12.00                    | Replace ✓ DRP          |

Total Spare Part Cost 10,488.84

Lump Sum Discount (%) 20.00

Final Spare Part Cost 8,391.07

Surveyor Total 2,114.08

Lump Sum Dis (%) 20

Final Sur Total 1,691.26

Labour's Cost Detail

| S.No.  | Costing Type | Job Scope                          | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|------------------------------------|-------------------------|-------------------------|---------|
| 1      | Main         | TO REPAIR REAR PORTION 2 END PANEL | 1,183.00                | 400 500                 |         |
| 2      | Main         | TO REPAIR FRONT PORTION            | 338.00                  | 200                     |         |
| Total: |              |                                    | 1,521.00                | 600.00                  | 700     |

Spray Cost Detail

| S.No.  | Costing Type | Job Scope                              | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|----------------------------------------|-------------------------|-------------------------|---------|
| 1      | Main         | TO RESPRAY REAR BUMPER                 | 378.00                  | 200                     |         |
| 2      | Main         | TO RESPRAY REAR PANEL                  | 180.00                  | 0 100                   |         |
| 3      | Main         | TO RESPRAY TAIL GATE                   | 378.00                  | 200                     |         |
| 4      | Main         | TO RESPRAY TAILGATE OUTSIDE GARNISH    | 180.00                  | 100                     |         |
| 5      | Main         | TO RESPRAY SPOILER                     | 180.00                  | 0                       |         |
| 6      | Main         | TO RESPRAY REAR FENDER LH              | 378.00                  | 0                       |         |
| 7      | Main         | TO RESPRAY REAR FENDER RH              | 378.00                  | 0                       |         |
| 8      | Main         | TO REPSRAY FRONT BUMPER                | 378.00                  | 200                     |         |
| 9      | Main         | TO SPRAY FRONT BUMPER LOWER SUB GRILLE | 180.00                  | 0                       |         |
| Total: |              |                                        | 2,610.00                | 700.00                  |         |

Ⓡ Supp. To respray bumper beam 180

100 ✓

Total: \$900

Other Cost Detail

| S.No.  | Costing Type | Job Scope                           | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|-------------------------------------|-------------------------|-------------------------|---------|
| 1      | Main         | TO CHECK WIRING AND SYSTEM FUNCTION | 80.00                   | 20                      |         |
| Total: |              |                                     | 1,770.00                | 290.00                  |         |

| S.No.         | Costing Type | Job Scope                                                               | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|---------------|--------------|-------------------------------------------------------------------------|-------------------------|-------------------------|---------|
| 2             | Main         | TO APPLY RUST-PROOFING ON AFFECTED AREA                                 | 200.00                  | 0                       |         |
| 3             | Main         | TO TEST AND REFIT REVERSE SENSOR SYSTEM                                 | 120.00                  | 20                      |         |
| 4             | Main         | TO TRANSFER REAR TAILGATE MECHANISM                                     | 120.00                  | 50                      |         |
| 5             | Main         | TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET) <i>SN</i>             | 250.00                  | 0                       |         |
| 6             | Main         | TO REMOVE & REFIT REAR QUARTER GLASS LH                                 | 120.00                  | 0                       |         |
| 7             | Main         | TO REMOVE & REFIT REAR QUARTER GLASS RH                                 | 120.00                  | 0                       |         |
| 8             | Main         | TO REMOVE / REFIT WINDSCREEN                                            | 240.00                  | 120                     |         |
| 9             | Main         | TO REMOVE / REFIT SEAT                                                  | 120.00                  | 0                       |         |
| 10            | Main         | TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR     | 120.00                  | 50                      |         |
| 11            | Main         | TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE | 120.00                  | 30                      |         |
| 12            | Main         | TO WASH AND VACUUM                                                      | 60.00                   | 0                       |         |
| 13            | Main         | TO REPLACE SUNDRY PARTS                                                 | 100.00                  | 0                       |         |
| <b>Total:</b> |              |                                                                         | <b>1,770.00</b>         | <b>290.00</b>           |         |

19 5134

## Summary

|                          | Estimator Assessment(\$) | Surveyor Assessment(\$)        |
|--------------------------|--------------------------|--------------------------------|
| Total Spare Part Detail  | 8,391.07                 | 1,691.26                       |
| Total Labour Cost        | 1,521.00                 | 600.00                         |
| Total Spray Painting     | 2,610.00                 | 700.00                         |
| Other                    | 1,770.00                 | 290.00                         |
| Overall Total            | 14,292.07                | 3,281.26                       |
| Lump Sum Repair Option   |                          |                                |
| Lump Sum Total           | 14,300.00                | 3,300.00                       |
| Surveyor Approved Amount |                          | 3,300.00                       |
| No of Repair Days*       | 10                       | 6                              |
| Remarks                  |                          | L/S REPAIR, PHOTO AFTER PAINT. |
| Surveyor Name            |                          | Hwee Jie                       |



Signature

Estimator Assesment(\$)

Surveyor Assesment(\$)



Survey Date

18/03/2019

Save

Clear

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer


Signature:

Date:

Poh kin

Section A - Accident Details

|                                    |                    |
|------------------------------------|--------------------|
| Registration Number                | SHC4705M           |
| Case Reference Number              | TAX/03/19/2063     |
| Registration Date                  | 10/12/2014         |
| Company Type                       | SMRT Taxis Pte Ltd |
| Make                               | TOYOTA             |
| Model                              | PRIUS              |
| Name of Driver                     | TAN ENG LEE        |
| Type of Accident                   | Head to Rear       |
| Accident Date and Time             | 15/3/2019 9:00 AM  |
| Accident Reported Date and Time    | 15/3/2019 10:22 AM |
| Is Surveyor Required?              | No                 |
| Survey by                          |                    |
| Vehicle is Towed Back?             | No                 |
| Towed Back Date and Time           |                    |
| Replacement Vehicle issued?        | No                 |
| Job Card Number                    | 24100603           |
| Special Instruction to ARC, if any | TP                 |
| Prepared Date and Time             | 15/3/2019 2:08 PM  |
| Chassis Number                     |                    |
| Mileage                            |                    |
| Work Shop                          |                    |
| Repair Completion Date and Time    |                    |



Section B - Summary of Repair Estimates

| Summary of Repair Estimates  |                                                                                     |                                                                                     |
|------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
|                              | Quotation from ARC                                                                  | Adjusted by Surveyor, if applicable                                                 |
| Total Labour Cost            | \$1,721.00                                                                          | \$700.00                                                                            |
| Total Spray Cost             | \$2,970.00                                                                          | \$900.00                                                                            |
| Total Spare Part Cost        | \$11,543.68                                                                         | \$2,535.14                                                                          |
| Total Other Cost             | \$1,770.00                                                                          | \$290.00                                                                            |
| <b>TOTAL COST</b>            | <b>\$18,004.68</b>                                                                  | <b>\$4,425.14</b>                                                                   |
| Lump Sum Total               | \$18,000.00                                                                         | \$4,450.00 (L/S)                                                                    |
| Number of Repair Days        | 10.0                                                                                | 6.0                                                                                 |
| Prepared / Adjusted By       | Zhi Yang Phua                                                                       | Hwee Jie (LKK) / AIG                                                                |
| ARC / Surveyor Sign Off Date |                                                                                     | 27/03/2019 11:45 AM                                                                 |
| Signature                    |  |  |
| Remarks                      | SUP = 1 DAYS                                                                        | L/S REPAIR, PHOTO AFTER PAINT.                                                      |

## Section C - Quotation and Accident Invoice Details

|                  |              |                |  |
|------------------|--------------|----------------|--|
| Quotation Number | QN-1904-0001 | Invoice Number |  |
| Quotation Date   | 01.04.2019   | Invoice Date   |  |
| Invoice Amount   |              | Prepared Date  |  |

## Section D - Details of Repair Estimates

## Part 1 - Labour Works

| Job Scope                | Quotation from AR | Adjusted by Surveyor, if applicable |
|--------------------------|-------------------|-------------------------------------|
| TO REPAIR REAR END PANEL | \$200.00          | \$100.00                            |
| TO REPAIR REAR PORTION   | \$1,183.00        | \$400.00                            |
| TO REPAIR FRONT PORTION  | \$338.00          | \$200.00                            |
| Total Labour             | \$1,721.00        | \$700.00                            |

## Part 2 - Spray Painting &amp; Panel Beating Related Works

| Job Scope                              | Quotation from ARC | Adjusted by Surveyor, if applicable |
|----------------------------------------|--------------------|-------------------------------------|
| TO RESPRAY REAR PANEL                  | \$180.00           | \$100.00 ✓                          |
| TO RESPRAY BUMPER BEAM                 | \$180.00           | \$100.00 ✓                          |
| TO RESPRAY REAR BUMPER                 | \$378.00           | \$200.00 ✓                          |
| TO RESPRAY REAR PANEL                  | \$180.00           | \$0.00                              |
| TO RESPRAY TAIL GATE                   | \$378.00           | \$200.00 ✓                          |
| TO RESPRAY TAILGATE OUTSIDE GARNISH    | \$180.00           | \$100.00 ✓                          |
| TO RESPRAY SPOILER                     | \$180.00           | \$0.00                              |
| TO RESPRAY REAR FENDER LH              | \$378.00           | \$0.00                              |
| TO RESPRAY REAR FENDER RH              | \$378.00           | \$0.00                              |
| TO REPSRAY FRONT BUMPER                | \$378.00           | \$200.00 ✓                          |
| TO SPRAY FRONT BUMPER LOWER SUB GRILLE | \$180.00           | \$0.00                              |
| Total Spray Painting & Panel Beating   | \$2,970.00         | \$800.00                            |

## Part 3 - Other Costs - Accident and Accident Repair Related Expense

| Job Scope                                                               | Quotation from ARC | Adjusted by Surveyor, if applicable |
|-------------------------------------------------------------------------|--------------------|-------------------------------------|
| TO CHECK WIRING AND SYSTEM FUNCTION                                     | \$80.00            | \$20.00                             |
| TO APPLY RUST-PROOFING ON AFFECTED AREA                                 | \$200.00           | \$0.00                              |
| TO TEST AND REFIX REVERSE SENSOR SYSTEM                                 | \$120.00           | \$20.00                             |
| TO TRANSFER REAR TAILGATE MECHANISM                                     | \$120.00           | \$50.00                             |
| TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)                       | \$250.00           | \$0.00                              |
| TO REMOVE & REFIT REAR QUARTER GLASS LH                                 | \$120.00           | \$0.00                              |
| TO REMOVE & REFIT REAR QUARTER GLASS RH                                 | \$120.00           | \$0.00                              |
| TO REMOVE / REFIT WINDSCREEN                                            | \$240.00           | \$120.00                            |
| TO REMOVE / REFIT SEAT                                                  | \$120.00           | \$0.00                              |
| TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR     | \$120.00           | \$50.00                             |
| TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE | \$120.00           | \$30.00                             |
| TO WASH AND VACUUM                                                      | \$60.00            | \$0.00                              |
| TO REPLACE SUNDRY PARTS                                                 | \$100.00           | \$0.00                              |
| Total Other Costs                                                       | \$1,770.00         | \$290.00                            |

# SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd  
80 Woodlands Industrial Park E4, Singapore  
FAX Number: 63685592  
Estimator Telephone Number: 68602623  
Accident Reporting Number: 68602672

Date Generated: 02/04/2018  
User ID: PehEuan

|             |  |                               |      |             |        |            |         |           |   |
|-------------|--|-------------------------------|------|-------------|--------|------------|---------|-----------|---|
|             |  | STICKER DECAL 6555 8888       | 0.00 | \$21.60     | 0.00   | \$0.00     | Replace | Not Given | X |
| 61604-47090 |  | FENDER RR/RH                  | 0.00 | \$766.80    | 0.00   | \$0.00     | Replace | Not Given | X |
|             |  | STICKER DECAL 6555 8888       | 0.00 | \$21.60     | 0.00   | \$0.00     | Replace | Not Given | X |
|             |  | STICKER DECAL SMRT            | 0.00 | \$7.90      | 0.00   | \$0.00     | Replace | Not Given | X |
| 62720-47031 |  | QUARTER GLASS RR/LH           | 0.00 | \$168.10    | 0.00   | \$0.00     | Replace | Not Given | X |
| 62710-47130 |  | QUARTER GLASS RR/RH           | 0.00 | \$846.50    | 0.00   | \$0.00     | Replace | Not Given | X |
|             |  | SEALANT W/SCREEN              | 0.00 | \$37.00     | 0.00   | \$0.00     | Replace | Not Given | X |
| 52119-47930 |  | BUMPER FRT                    | 1.00 | \$482.00    | 100.00 | \$0.00     | Replace | Repair    | X |
| 52611-47080 |  | BUMPER ENERGY ABSORBER FRT    | 0.00 | \$78.80     | 0.00   | \$0.00     | Replace | Not Given | X |
| 52021-47023 |  | BUMPER REINFORCEMENT FRT      | 0.00 | \$498.40    | 0.00   | \$0.00     | Replace | Not Given | X |
| 57014-47030 |  | ARM SUB-ASSY, FR BUMPER LH    | 0.00 | \$250.40    | 0.00   | \$0.00     | Replace | Not Given | X |
| 57013-47030 |  | ARM SUB-ASSY, FR BUMPER RH    | 0.00 | \$250.40    | 0.00   | \$0.00     | Replace | Not Given | X |
| 53102-47020 |  | BUMPER GRILLE SUB-ASSY, LOWER | 0.00 | \$311.10    | 0.00   | \$0.00     | Replace | Not Given | X |
| 52114-47140 |  | BRACKET, FR BUMPER            | 0.00 | \$110.40    | 0.00   | \$0.00     | Replace | Not Given | X |
|             |  | NUMBER PLATE                  | 1.00 | \$15.00     | 0.00   | \$15.00    | Replace | Replace   | X |
|             |  | NUMBER PLATE FRAME            | 1.00 | \$12.00     | 0.00   | \$12.00    | Replace | Replace   | X |
| Total       |  |                               |      | \$13,261.00 |        | \$2,114.13 |         |           |   |

## Added Spare Parts / Material Usage After Surveyor Signed off

| Part Number | Portion | Stock Number | Part Name                      | Quantity | List Price \$ | Discount (%) | Final Price (\$) | ARC Check Replace | Surveyor Check Replace |
|-------------|---------|--------------|--------------------------------|----------|---------------|--------------|------------------|-------------------|------------------------|
|             |         | 52023-12240  | BUMPER REINFORCEMENT REAR      | 1.00     | \$205.70      | 25.00        | \$154.28         | Replace           | Replace                |
|             |         | 52015-47050  | ARM SUB-ASSY, RR BUMPER RH     | 1.00     | \$139.60      | 25.00        | \$104.70         | Replace           | Replace                |
|             |         | 52016-47030  | ARM SUB-ASSY, RR BUMPER LH     | 1.00     | \$139.60      | 25.00        | \$104.70         | Replace           | Replace                |
|             |         | 52575-47020  | BUMPER SIDE RETAINER RR/RH     | 1.00     | \$94.80       | 25.00        | \$71.10          | Replace           | Replace                |
|             |         | 89997-30070  | ANTENNA, ELECTRICAL LOWER REAR | 1.00     | \$157.40      | 25.00        | \$118.05         | Replace           | Replace                |
|             |         | 81551-47180  | TAIL LAMP RH                   | 1.00     | \$557.80      | 10.00        | \$502.02         | Replace           | Replace                |
| Total       |         |              |                                |          | 1,294.90      |              | 1,054.85         |                   |                        |

3168.98  
-20%

2535.18

+ 700.00

+ 1190.00

4425.18

45 \$4450/-

**Part 4 - Spare Parts / Material Usage**

| Part Number | Portion | Stock Number   | Part Name                         | Quantity | List Price (\$) | Discount (%) | Final Price (\$) | Estimator Approved | Surveyor Approved |
|-------------|---------|----------------|-----------------------------------|----------|-----------------|--------------|------------------|--------------------|-------------------|
|             |         | 52159-47805    | BUMPER REAR                       | 1.00     | \$458.60        | 25.00        | \$343.95         | Replace            | Replace           |
|             |         | 52023-12240    | BUMPER REINFORCEMENT REAR         | 0.00     | \$205.70        | 0.00         | \$0.00           | Replace            | Check             |
|             |         | 52016-47030    | ARM SUB-ASSY, RR BUMPER LH        | 0.00     | \$139.60        | 0.00         | \$0.00           | Replace            | Check             |
|             |         | 52015-47050    | ARM SUB-ASSY, RR BUMPER RH        | 0.00     | \$139.60        | 0.00         | \$0.00           | Replace            | Check             |
|             |         | 52576-47020    | BUMPER SIDE RETAINER RR/LH        | 0.00     | \$94.80         | 0.00         | \$0.00           | Replace            | Check             |
|             |         | 52575-47020    | BUMPER SIDE RETAINER RR/RH        | 0.00     | \$94.80         | 0.00         | \$0.00           | Replace            | Check             |
|             |         |                | SENSOR REVERSE                    | 1.00     | \$180.00        | 0.00         | \$180.00         | Replace            | Replace           |
|             |         |                | PIXEL STICKER                     | 2.00     | \$60.00         | 0.00         | \$120.00         | Replace            | Replace           |
|             |         | 76891-47020    | BUMPER LIP REAR                   | 1.00     | \$228.90        | 25.00        | \$171.68         | Replace            | Replace           |
|             |         | 76088-47020    | BUMPER LIP COVER RR/LH            | 1.00     | \$72.20         | 25.00        | \$54.15          | Replace            | Replace           |
|             |         | 76087-47020    | BUMPER LIP COVER RR/RH            | 1.00     | \$118.10        | 25.00        | \$88.58          | Replace            | Replace           |
|             |         | 58308-47011    | UNDER COVER SUB-ASSY, RR FLOOR    | 0.00     | \$514.50        | 0.00         | \$0.00           | Replace            | Check             |
|             |         | 58307-47060    | END PANEL                         | 0.00     | \$602.10        | 0.00         | \$0.00           | Replace            | Check             |
|             |         |                | SEALANT SIKAFLEX                  | 0.00     | \$37.00         | 0.00         | \$0.00           | Replace            | Check             |
|             |         | 67005-47241    | TAILGATE ASY                      | 1.00     | \$1,007.90      | 25.00        | \$755.93         | Replace            | Replace           |
|             |         | 76801-47070-B0 | TAILGATE OUTSIDE GARNISH          | 1.00     | \$504.90        | 100.00       | \$0.00           | Replace            | Repair            |
|             |         | 75310-47020    | EMBLEM REAR                       | 1.00     | \$60.30         | 25.00        | \$45.23          | Replace            | Replace           |
|             |         | 75374-47051    | NAME PLATE (HYBRID)               | 1.00     | \$51.90         | 25.00        | \$38.93          | Replace            | Replace           |
|             |         | 75442-47030    | NAME PLATE (PRIUS)                | 1.00     | \$60.80         | 25.00        | \$45.60          | Replace            | Replace           |
|             |         | 75443-47030    | NAME PLATE (TOYOTA)               | 1.00     | \$51.90         | 25.00        | \$38.93          | Replace            | Replace           |
|             |         |                | NUMBER PLATE                      | 1.00     | \$15.00         | 0.00         | \$15.00          | Replace            | Replace           |
|             |         |                | NUMBER PLATE FRAME                | 1.00     | \$12.00         | 0.00         | \$12.00          | Replace            | Replace           |
|             |         | 75574-47020    | TAIL GATE DOOR GLASS MOULDING, LH | 1.00     | \$29.40         | 25.00        | \$22.05          | Replace            | Replace           |
|             |         | 75573-47080    | TAIL GATE DOOR GLASS MOULDING, RH | 1.00     | \$29.40         | 25.00        | \$22.05          | Replace            | Replace           |
|             |         | 75575-47030    | MOULDING BACK WINDOW, LOWER NO.1  | 1.00     | \$29.40         | 25.00        | \$22.05          | Replace            | Replace           |
|             |         |                | SEALANT W/SCREEN                  | 3.00     | \$37.00         | 0.00         | \$111.00         | Replace            | Replace           |
|             |         | 76085-47910    | SPOILER REAR                      | 0.00     | \$953.70        | 0.00         | \$0.00           | Replace            | Not Given         |
|             |         | 81006-47011    | 3RD BRAKE LAMP                    | 0.00     | \$231.30        | 0.00         | \$0.00           | Replace            | Check             |
|             |         | 67938-47031C0  | TAILGATE TRIM, LH                 | 0.00     | \$85.90         | 0.00         | \$0.00           | Replace            | Check             |
|             |         | 67751-47040C0  | TAILGATE TRIM, LOWER              | 0.00     | \$180.70        | 0.00         | \$0.00           | Replace            | Check             |
|             |         | 67937-47031C0  | TAILGATE TRIM, RH                 | 0.00     | \$88.30         | 0.00         | \$0.00           | Replace            | Check             |
|             |         | 64750-47030C0  | TAILGATE TRIM, UPPER              | 0.00     | \$49.60         | 0.00         | \$0.00           | Replace            | Check             |
|             |         | 67750-47071C0  | TAILGATE, BOARD ASSY              | 0.00     | \$246.90        | 0.00         | \$0.00           | Replace            | Check             |
|             |         | 89997-30070    | ANTENNA, ELECTRICAL LOWER REAR    | 0.00     | \$157.40        | 0.00         | \$0.00           | Replace            | Check             |
|             |         | 64718-47031B0  | END PANEL COVER, DECK TRIM HOLE   | 0.00     | \$46.10         | 0.00         | \$0.00           | Replace            | Not Given         |
|             |         | 64718-47031B0  | END PANEL COVER, DECK TRIM RR     | 0.00     | \$121.10        | 0.00         | \$0.00           | Replace            | Not Given         |
|             |         | 69350-47030    | TAILGATE DOOR LOCK                | 0.00     | \$444.10        | 0.00         | \$0.00           | Replace            | Check             |
|             |         | 52563-47010    | TAIL LAMP BRACKET, LH             | 0.00     | \$30.70         | 0.00         | \$0.00           | Replace            | Check             |
|             |         | 52562-47010    | TAIL LAMP BRACKET, RH             | 0.00     | \$30.70         | 0.00         | \$0.00           | Replace            | Check             |
|             |         | 81561-47170    | TAIL LAMP LH                      | 0.00     | \$548.40        | 0.00         | \$0.00           | Replace            | Check             |
|             |         | 81551-47180    | TAIL LAMP RH                      | 0.00     | \$557.80        | 0.00         | \$0.00           | Replace            | Check             |
|             |         | 81602-47091    | FENDER RR/LH                      | 0.00     | \$766.80        | 0.00         | \$0.00           | Replace            | Not Given         |
|             |         |                | STICKER SMRT LOGO                 | 0.00     | \$7.80          | 0.00         | \$0.00           | Replace            | Not Given         |

## **Poh Kin (LKKAUTO)**

---

**From:** Poh Kin (LKKAUTO)  
**Sent:** Friday, 28 June 2019 3:15 PM  
**To:** Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis)  
**Cc:** Admin A  
**Subject:** RE: LOD Re: Accident on 15/3/2019 involving SHC 4705M & SGK 5725T (AIG's insured) Our Ref: TAX/03/19/2063/lg  
**Attachments:** ATA SHC 4705M.pdf; DV SHC 4705M.pdf

### **WITHOUT PREJUDICE** **SAVE AS TO COSTS**

Our Ref: CC3/AIG19004938/Jfb3  
Your Ref: TAX/03/19/2063/lg

Dear Lee Gek,

We refer to the above matter.

We hereby confirmed settlement at global sum of **\$5,880.00**(all in) on this matter.

Please duly sign the DV and ATA attached and return with Authorization to ACT of your hirer to us (LKK) for payment processing.

Your prompt action will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."


Best Regards,

**Poh Kin, Chong (Mr)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2132 | email: [pohkin@lkkauto.com](mailto:pohkin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



AUTO  
CONSULTANTS  
PTE LTD

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

---

**From:** Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) [<mailto:LeeGek@smrt.com.sg>]  
**Sent:** Wednesday, 26 June 2019 5:19 PM



## Poh Kin (LKKAuto)

**From:** Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) <LeeGek@smrt.com.sg>  
**Sent:** Wednesday, 26 June 2019 5:19 PM  
**To:** Poh Kin (LKKAuto)  
**Cc:** Admin A  
**Subject:** LOD Re: Accident on 15/3/2019 involving SHC 4705M & SGK 5725T (AIG's insured)  
Our Ref: TAX/03/19/2063/lg

Dear Poh Lin,

Your offer of \$5,650.00 is unacceptable. Our taxi was laid-up for \*\*10 days at the workshop but we are prepared to accept 9 days for LOU (6 + 1 (2 Saturdays) + 2 Sundays).

Please reconsider your offer and let us know if you are agreeable to settle our claim at a global sum of \$5,880.00. Thanks.

\*\*

|                             |         |                                                     |         |
|-----------------------------|---------|-----------------------------------------------------|---------|
| 15/3/19 (Fri)               | 0.5 day | our driver reported                                 |         |
| 16/3/19 (Sat)               | 1 day   |                                                     |         |
| 17/3/19 (Sun)               | 1 day   |                                                     |         |
| 18/3/19 (Mon)               | 1 day   | notified your office of PRS & our taxi was surveyed | 1 day   |
| 19/3/19 (Tues)              | 1 day   |                                                     | 1       |
| 20/3/19 (Wed)               | 1 day   |                                                     | 1       |
| 21/3/19 (Thurs)             | 1 day   |                                                     | 1       |
| 22/3/19 (Fri)               | 1 day   |                                                     | 1       |
| 23/3/19 (Sat)               | 1 day   | we open half day                                    | 0.5 day |
| 24/3/19 (Sun)               | 1 day   |                                                     | 0       |
| 25/3/19 (Mon)               | 0.5 day |                                                     | 0.5     |
| 10 days at workshop         |         |                                                     | 6       |
| working days as recommended |         |                                                     |         |

Regards

Tan Lee Gek (DID: 6866 2647)  
Claims Department  
SMRT Automotive Services Pte Ltd



6 + 3 days = 9 days.

9/5 \$1

**From:** Poh Kin (LKKAuto) [mailto:pohkin@lkkauto.com]

**Sent:** 24/06/2019 09:37

**To:** Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis)

**Cc:** Admin A

**Subject:** RE: LOD Re: Accident on 15/3/2019 involving SHC 4705M & SGK 5725T (AIG's insured) Our Ref: TAX/03/19/2063/lg

**Importance:** High

## Poh Kin (LKKAuto)

---

**From:** Poh Kin (LKKAuto)  
**Sent:** Monday, 24 June 2019 9:37 AM  
**To:** LeeGek@smrt.com.sg  
**Cc:** Admin A  
**Subject:** RE: LOD Re: Accident on 15/3/2019 involving SHC 4705M & SGK 5725T (AIG's insured) Our Ref: TAX/03/19/2063/lg

**Importance:** High

**WITHOUT PREJUDICE**  
**SAVE AS TO COSTS**

Our Ref: CC3/AIG19004938/Jfb3  
Your Ref: TAX/03/19/2063/lg

Dear Lee Gek,

We refer to the above matter and your letter of demand.

Towards an amicable settlement and without admission of liability to our Insured's part, we offer settlement at global sum of **\$5,650.00**(all in) on this matter.

Kindly confirm acceptance.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."


Best Regards,

**Poh Kin, Chong (Mr)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2132 | email: [pohkin@lkkauto.com](mailto:pohkin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



AUTO  
CONSULTANTS  
PTE LTD

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.



## Poh Kin (LKKAuto)

**From:** Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) <LeeGek@smrt.com.sg>  
**Sent:** Friday, 17 May 2019 10:14 AM  
**To:** CS A Team; Admin A  
**Subject:** LOD Re: Accident on 15/3/2019 involving SHC 4705M & SGK 5725T (AIG's insured)  
Our Ref: TAX/03/19/2063/lg  
img-517101036-0001.pdf  
**Attachments:**  
**Categories:** clear

Dear All,

We quantify our claim as follows:-

|                |                                   |                   |
|----------------|-----------------------------------|-------------------|
| Cost of Repair | \$4,450.00                        | 4450.00 / 4450.00 |
| Loss of Rental | \$1,091.40 ( 10 days x \$109.14 ) | 818.55 / 982.26   |
| Loss of Income | \$600.00 ( 10 day x \$60.00 )     | 375.00 / 450.00   |
| LTA Search Fee | \$7.00                            | 7.00 / 7.00       |
| <b>Total</b>   | <b>\$6,148.40</b>                 |                   |

We enclose the following documents:

- 1) Repair invoice
- 2) Proof of rental rate
- 3) GIA report
- 4) Accident vehicle laid-up report
- 5) LTA search

Please let us have your offer soon. Thanks.

Regards

Tan Lee Gek (DID: 6866 2647)

Claims Department

SMRT Automotive Services Pte Ltd



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

### CLAIM SUBFOLDER TRACKING

| Case | Notified                                | Est Submitted | Adj Assigned                                      | Adj Rpt                                              | Adj Submitted                                  | Ins Auth'ed | Status                                                          |
|------|-----------------------------------------|---------------|---------------------------------------------------|------------------------------------------------------|------------------------------------------------|-------------|-----------------------------------------------------------------|
| Main | 19 Mar 2019<br><a href="#">Edit Reg</a> |               | 18 Mar 2019 00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$4,450.00</b><br><a href="#">Edit Estimates</a> | <b>S\$4,450.00</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main                                                                                                                                                                          | Reference | Claim Details                                                                             | Documents  | <a href="#">Show All</a> |         |             |              |            |       |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|-------------------------------------------------------------------------------------------|------------|--------------------------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>                                                                                       |           |                                                                                           |            |                          |         |             |              |            |       |
| Insured: <b>Kom Mun Kiet</b> , ID: S6832907H                                                                                                                                  |           |                                                                                           |            |                          |         |             |              |            |       |
| Main Claimant: <b>SMRT TAXIS PTE LTD</b> , Co. Reg. No.: 198905369K                                                                                                           |           |                                                                                           |            |                          |         |             |              |            |       |
| Vehicle Reg. No.: <b>SHC4705M</b>                                                                                                                                             |           | Date of Loss: 15/03/2019 08:00 - :59<br>[51 Months and 5 Days From LTA Reg Date (Man Yr)] |            |                          |         |             |              |            |       |
| Claim Type: <b>TP / 0553231190SG</b>                                                                                                                                          |           | Policy/Cover Note No.: 0100657079 (Third Party Only)                                      |            |                          |         |             |              |            |       |
| Vehicle Reg. No. (Insured): <b>SGK5725T</b>                                                                                                                                   |           | Policy No. (Claimant): D-18090213MFSH                                                     |            |                          |         |             |              |            |       |
|                                                                                                                                                                               |           | Excess:                                                                                   |            |                          |         |             |              |            |       |
| Repairer: <b>SMRT Automotive Services Pte Ltd (Woodlands)</b> 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628                                               |           |                                                                                           |            |                          |         |             |              |            |       |
| Handling Insurer: <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Syed-Yusoff, Saliha</b> ] Saliha.Syed-Yusoff@aig.com           |           |                                                                                           |            |                          |         |             |              |            |       |
| Claimant's Insurer: <b>MS First Capital Insurance Ltd (HQ)</b> - Tel: 62222311                                                                                                |           |                                                                                           |            |                          |         |             |              |            |       |
| Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ONG HWEE JIE</b> ] ... [Final Rpt due 28/03/2019]                                      |           |                                                                                           |            |                          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>                                                 |           |                                                                                           |            |                          |         |             |              |            |       |
| There are no mail for this case.                                                                                                                                              |           |                                                                                           |            |                          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span> |           |                                                                                           |            |                          |         |             |              |            |       |
| Due Date                                                                                                                                                                      | Priority  | Type                                                                                      | Task Group | Subject                  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.                                                                                                                                                                   |           |                                                                                           |            |                          |         |             |              |            |       |



## Claim Documents

**\*SHC4705M (0553231190SG)**  
**[SGK5725T]**

TP

**SMRT TAXIS PTE LTD**

**Mar 15 2019 8:00AM**

**[Kom Mun Kiet]**

**SMRT Automotive Services Pte Ltd**

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)
[View](#)
[View In Browser](#)

### Letters/Correspondences

| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ)                         | 1 per page | Thumbnail | Print |
|----|--------------|-----------------------------------------------------------|------------|-----------|-------|
| 1  | (Draft)      | <b>Third Party Express Settlement – Payment Breakdown</b> | 1          | Edit      |       |

### Photos/Images

| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | 3 per page | Thumbnail | Print |
|----|-----------------|-----------------------------------|------------|-----------|-------|
| 1  | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 2  | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 3  | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 4  | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 5  | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 6  | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 7  | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 8  | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 9  | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 10 | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 11 | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 12 | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 13 | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 14 | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 15 | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 16 | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 17 | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 18 | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 19 | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 20 | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 21 | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 22 | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 23 | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 24 | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 25 | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 26 | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 27 | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 28 | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 29 | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 30 | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 31 | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 32 | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 33 | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 34 | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 35 | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 36 | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |
| 37 | 22/03/19 10:11  | General View                      | 1          | Load JPG  | ✓     |

| Letters/Correspondences |                 |                                           | 1 per page ▼                                                                                   | <input checked="" type="checkbox"/> |
|-------------------------|-----------------|-------------------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No                      | Finalized On    | LKK Auto Consultants Pte Ltd (HQ)         | Thumbnail                                                                                      | Print                               |
| 38                      | 22/03/19 10:11  | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 39                      | 22/03/19 10:11  | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 40                      | 22/03/19 10:11  | Dismantled Parts                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 41                      | 22/03/19 10:11  | Dismantled Parts                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 42                      | 22/03/19 10:11  | Dismantled Parts                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 43                      | 22/03/19 10:11  | Dismantled Parts                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 44                      | 22/03/19 10:11  | Dismantled Parts                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 45                      | 22/03/19 10:11  | Dismantled Parts                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 46                      | 22/03/19 10:11  | Dismantled Parts                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 47                      | 22/03/19 10:11  | Dismantled Parts                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 48                      | 22/03/19 10:11  | Dismantled Parts                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 49                      | 22/03/19 10:11  | Dismantled Parts                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 50                      | 22/03/19 10:11  | Dismantled Parts                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 51                      | 22/03/19 10:11  | Dismantled Parts                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 52                      | 22/03/19 10:11  | Dismantled Parts                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 53                      | 22/03/19 10:11  | Dismantled Parts                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 54                      | 22/03/19 10:11  | Dismantled Parts                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 55                      | 22/03/19 10:11  | Dismantled Parts                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 56                      | 22/03/19 10:11  | Dismantled Parts                          |  Load JPG  | <input checked="" type="checkbox"/> |
| 57                      | 22/03/19 10:11  | Dismantled Parts                          |  Load JPG | <input checked="" type="checkbox"/> |
| 58                      | 22/03/19 10:11  | Dismantled Parts                          |  Load JPG | <input checked="" type="checkbox"/> |
| 59                      | 22/03/19 10:11  | Dismantled Parts                          |  Load JPG | <input checked="" type="checkbox"/> |
| 60                      | 26/04/19 09:24  | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 61                      | 26/04/19 09:24  | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 62                      | 26/04/19 09:24  | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 63                      | 26/04/19 09:24  | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 64                      | 26/04/19 09:24  | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 65                      | 26/04/19 09:24  | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 66                      | 26/04/19 09:24  | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 67                      | 26/04/19 09:24  | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 68                      | 26/04/19 09:24  | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation           |                 |                                           | 1 per page ▼                                                                                   | <input checked="" type="checkbox"/> |
| No                      | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)         | Thumbnail                                                                                      | Print                               |
| 1                       | 19/03/19 18:14  | TP ESTIMATE- MARKED                       |  Load PDF |                                     |
| 2                       | 19/03/19 18:14  | TP GIA REPORT                             |  Load PDF |                                     |
| 3                       | 04/05/19 11:19  | LETTER TO OI                              |  Load PDF |                                     |
| 4                       | 24/10/19 11:15  | AUTHORISATION TO ACT                      |  Load PDF |                                     |
| 5                       | 24/10/19 11:15  | LOD                                       |  Load PDF |                                     |
| 6                       | 24/10/19 11:15  | LTA SEARCH                                |  Load PDF |                                     |
| 7                       | 24/10/19 11:15  | RELEASE VOUCHER                           |  Load PDF |                                     |
| 8                       | 24/10/19 11:15  | RENTAL MILEAGE                            |  Load PDF |                                     |
| 9                       | 24/10/19 11:15  | RENTAL RECEIPT                            |  Load PDF |                                     |
| 10                      | 24/10/19 11:15  | WORKSHOP INVOICE                          |  Load PDF |                                     |
| No                      | Finalized On    | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbnail                                                                                      | Print                               |
| 1                       | 20/03/19 11:32  | OI GIA REPORT                             |  Load PDF |                                     |

## Documents Checklist

### DOCUMENTS CHECKLIST

There are no document checklists configured.

[Reset](#)
[Save](#)
[Print](#)

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

|                   |                     |        |                           |
|-------------------|---------------------|--------|---------------------------|
| Vehicle No:       | SGK5725T (Insd veh) | Model: | TOYOTA PRIUS TAXI 1.8 (A) |
|                   | SHC4705M (TP veh)   |        |                           |
| Date of Accident: | 15/03/2019          |        |                           |

|                                                                                                      |   |       |     |     |    |                              |
|------------------------------------------------------------------------------------------------------|---|-------|-----|-----|----|------------------------------|
| Global Sum Settlement                                                                                | : | [ X ] | Yes | [ ] | No |                              |
| Repair Estimate                                                                                      | : | \$    |     |     |    | 19,513.00                    |
| Final Repair Cost                                                                                    | : | \$    |     |     |    | 5,880.00                     |
| Loss of Use                                                                                          | : | \$    |     |     |    | 9.00 days at \$50.00 per day |
| Rental (if any)                                                                                      | : | \$    |     |     |    | 9 days                       |
| LTA / GIA Search Fee                                                                                 | : | \$    |     |     |    |                              |
| Others:                                                                                              | : | \$    |     |     |    |                              |
|                                                                                                      | : | \$    |     |     |    |                              |
| Final Settlement Sum (GLOBAL SUM)                                                                    | : | \$    |     |     |    | 5,880.00                     |
| <b>Is Third Party Workshop GIA Registered?</b> [ ] YES [ X ] NO (Kindly indicate below)              |   |       |     |     |    |                              |
| <b>A) For Non GIA Registered Workshop:</b> Agreed Liability ____ 100 ____ (%)                        |   |       |     |     |    |                              |
| <b>B) For GIA Registered Workshop:</b> BOLA Applicable: Yes/ No BOLA Scenario No: ____               |   |       |     |     |    |                              |
| BOLA Liability: ____ (%) Assessed Liability (*): ____ 0 ____ (%)                                     |   |       |     |     |    |                              |
| * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply. |   |       |     |     |    |                              |
| Remarks _____                                                                                        |   |       |     |     |    |                              |

| Payment Instruction: Payee's Breakdown |                    |   |             |
|----------------------------------------|--------------------|---|-------------|
| 1)                                     | SMRT TAXIS PTE LTD | : | \$ 5,880.00 |
| 2)                                     |                    | : | \$          |
| 3)                                     |                    | : | \$          |
| 4)                                     |                    | : | \$          |

NUR SHAQILAH BTE ABDOL WAHAB

24 Oct  
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG19004938/JKB3S2  
**Date:** 24/10/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0100657079  
**Claimant Vehicle No :** SHC4705M **Insured Vehicle No :** SGK5725T  
Date of Loss: 15/03/2019 Nature of Claim: TP Claim No: 0553231190SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC4705M**  
Make & Model: TOYOTA PRIUS TAXI, 1.8 (A) Engine No: 2ZR6230133  
Reg. Date: 10/12/2014 (Man. Year: 2014) Chassis No: JTDKN36U605753749  
Colour: Maroon Odometer: 0 km  
Engine Capacity: 1798 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15  
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm  
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

### COST OF CLAIMS

|                                          | Repairer's       | Adjuster's      | Difference       | Diff %       |
|------------------------------------------|------------------|-----------------|------------------|--------------|
| Parts                                    | 13,682.00        | 3,168.97        | 10,513.03        | 76.84        |
| Miscellaneous Items                      | 0.00             | 0.00            | 0.00             |              |
| Labour                                   | 5,831.00         | 1,890.00        | 3,941.00         | 67.59        |
| Paintwork Labour                         | 0.00             | 0.00            | 0.00             |              |
| Towing                                   | 0.00             | 0.00            | 0.00             |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>19,513.00</b> | <b>5,058.97</b> | <b>14,454.03</b> | <b>74.07</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                  | <b>4,450.00</b> |                  |              |
| <b>Nett Amount (S\$)</b>                 | <b>19,513.00</b> | <b>4,450.00</b> | <b>15,063.00</b> | <b>77.19</b> |
| + Loss of Use (9.0 x S\$50.00/day) (S\$) |                  | 450.00          |                  |              |
| + Car Rental (9.0 x S\$109.14/day) (S\$) |                  | 982.26          |                  |              |
| + Doc/Search Fee (S\$)                   |                  | 7.00            |                  |              |
| <b>Nett Liability (S\$)</b>              |                  | <b>5,889.26</b> |                  |              |
| <b>Global Sum Settlement (S\$)</b>       |                  | <b>5,880.00</b> |                  |              |

### INSPECTION

Date of Assignment: 18/03/2019  
Date Inspected: 18/03/2019 Inspected At: SMRT Automotive Services Pte Ltd (Woodlands)  
60 Woodlands Industrial Park E4  
Singapore 757705  
Estimated Period of Repair: 6.0 days

**Adjuster:** ONG HWEE JIE

**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. | Particulars                                   | Condition     | Repairer's | Amount    |
|-----|-----|----------|-----------------------------------------------|---------------|------------|-----------|
| 1   | 1   |          | *BUMPER REAR (DISC 25%)                       | Buckled       | 458.60 F   | *343.95 F |
| 2   | 1   |          | *BUMPER REINFORCEMENT REAR (DISC 25%)         | Dented        | 205.70 F   | *154.28 F |
| 3   | 1   |          | *ARM SUB-ASSY RR BUMPER LH (DISC 25%)         | Cracked       | 139.60 F   | *104.70 F |
| 4   | 1   |          | *ARM SUB-ASSY RR BUMPER RH (DISC 25%)         | Cracked       | 139.60 F   | *104.70 F |
| 5   | 1   |          | *BUMPER SIDE RETAINER RR/LH (DISC 25%)        | Cracked       | 94.80 F    | *71.10 F  |
| 6   | 1   |          | *BUMPER LIP REAR (DISC 25%)                   | Deformed      | 228.90 F   | *171.68 F |
| 7   | 1   |          | *BUMPER LIP COVER RR/LH (DISC 25%)            | Deformed      | 72.20 F    | *54.15 F  |
| 8   | 1   |          | *BUMPER LIP COVER RR/RH (DISC 25%)            | Deformed      | 118.10 F   | *88.58 F  |
| 9   | 1   |          | *TAILGATE ASY (DISC 25%)                      | Buckled       | 1,007.90 F | *755.92 F |
| 10  | 1   |          | *EMBLEM REAR (DISC 25%)                       | Necessary     | 60.30 F    | *45.23 F  |
| 11  | 1   |          | *NAME PLATE (HYBRID) (DISC 25%)               | Necessary     | 51.90 F    | *38.93 F  |
| 12  | 1   |          | *NAME PLATE (PRIUS) (DISC 25%)                | Necessary     | 60.80 F    | *45.60 F  |
| 13  | 1   |          | *NAME PLATE (TOYOTA) (DISC 25%)               | Necessary     | 51.90 F    | *38.93 F  |
| 14  | 1   |          | *TAIL GATE DOOR GLASS MOULDING, LH (DISC 25%) | Necessary     | 29.40 F    | *22.05 F  |
| 15  | 1   |          | *TAIL GATE DOOR GLASS MOULDING, RH (DISC 25%) | Necessary     | 29.40 F    | *22.05 F  |
| 16  | 1   |          | *MOULDING, BACK WINDOW, LOWER NO.1 (DISC 25%) | Necessary     | 29.40 F    | *22.05 F  |
| 17  | 1   |          | *ANTENNA ELECTRICAL, LOWER REAR (DISC 25%)    | Necessary     | 157.40 F   | *118.05 F |
| 18  | 1   |          | *TAIL LAMP RH (DISC 10%)                      | Cut           | 557.80 F   | *502.02 F |
| 19  | 1   |          | *SENSOR REVERSE (SN)                          | Shorted       | 180.00 F   | *180.00 F |
| 20  | 2   |          | *PIXEL STICKER (SN)                           | Necessary     | 120.00 F   | *120.00 F |
| 21  | 1   |          | *NUMBER PLATE (SN)                            | Deformed      | 15.00 F    | *15.00 F  |
| 22  | 1   |          | *NUMBER PLATE FRAME (SN)                      | Cracked       | 12.00 F    | *12.00 F  |
| 23  | 3   |          | *SEALANT W/SCREEN (SN)                        | Necessary     | 111.00 F   | *111.00 F |
| 24  | 1   |          | *NUMBER PLATE (SN)                            | Deformed      | 15.00 F    | *15.00 F  |
| 25  | 1   |          | *NUMBER PLATE FRAME (SN)                      | Deformed      | 12.00 F    | *12.00 F  |
| 26  | 1   |          | *BUMPER SIDE RETAINER RR/RH                   | Not Necessary | 94.80 F    | *- F      |
| 27  | 1   |          | *UNDER COVER SUB-ASSY, RR FLOOR               | Not Necessary | 514.50 F   | *- F      |
| 28  | 1   |          | *END PANEL                                    | Not Necessary | 602.10 F   | *- F      |
| 29  | 1   |          | *SEALANT SIKAFLEX                             | Not Necessary | 37.00 F    | *- F      |
| 30  | 1   |          | *SPOILER REAR                                 | Not Necessary | 953.70 F   | *- F      |
| 31  | 1   |          | *3RD BRAKE LAMP                               | Not Necessary | 231.30 F   | *- F      |
| 32  | 1   |          | *TAILGATE TRIM, LH                            | Not Necessary | 85.90 F    | *- F      |
| 33  | 1   |          | *TAILGATE TRIM, LOWER                         | Not Necessary | 180.70 F   | *- F      |
| 34  | 1   |          | *TAILGATE TRIM, RH                            | Not Necessary | 88.30 F    | *- F      |
| 35  | 1   |          | *TAILGATE TRIM, UPPER                         | Not Necessary | 49.60 F    | *- F      |
| 36  | 1   |          | *TAILGATE, BOARD ASSY                         | Not Necessary | 246.90 F   | *- F      |
| 37  | 1   |          | *END PANEL COVER, DECK TRIM HOLE              | Not Necessary | 46.10 F    | *- F      |
| 38  | 1   |          | *END PANEL COVER, DECK TRIM, RR               | Not Necessary | 121.10 F   | *- F      |
| 39  | 1   |          | *TAILGATE DOOR LOCK                           | Not Necessary | 444.10 F   | *- F      |
| 40  | 1   |          | *TAIL LAMP BRACKET, LH                        | Not Necessary | 30.70 F    | *- F      |
| 41  | 1   |          | *TAIL LAMP BRACKET, RH                        | Not Necessary | 30.70 F    | *- F      |
| 42  | 1   |          | *TAIL LAMP LH                                 | Not Necessary | 548.40 F   | *- F      |
| 43  | 1   |          | *FENDER RR/LH                                 | Not Necessary | 766.80 F   | *- F      |
| 44  | 1   |          | *STICKER SMRT                                 | Not Necessary | 7.80 F     | *- F      |
| 45  | 1   |          | *STICKER DECAL 6555 8888                      | Not Necessary | 21.60 F    | *- F      |
| 46  | 1   |          | *FENDER RR/RH                                 | Not Necessary | 766.80 F   | *- F      |
| 47  | 1   |          | *STICKER DECAL 6555 8888                      | Not Necessary | 21.60 F    | *- F      |
| 48  | 1   |          | *STICKER DECAL SMRT                           | Not Necessary | 7.80 F     | *- F      |
| 49  | 1   |          | *QUARTER GLASS RR/LH                          | Not Necessary | 168.10 F   | *- F      |
| 50  | 1   |          | *QUARTER GLASS RR/RH                          | Not Necessary | 846.50 F   | *- F      |
| 51  | 2   |          | *SEALANT W/SCREEN                             | Not Necessary | 74.00 F    | *- F      |
| 52  | 1   |          | *BUMPER ENERGY ABSORBER FRT                   | Not Necessary | 78.80 F    | *- F      |
| 53  | 1   |          | *BUMPER REINFORCEMENT FRT                     | Not Necessary | 498.40 F   | *- F      |
| 54  | 1   |          | *ARM SUB-ASSY, FR BUMPER LH                   | Not Necessary | 250.40 F   | *- F      |
| 55  | 1   |          | *ARM SUB-ASSY, FR BUMPER RH                   | Not Necessary | 250.40 F   | *- F      |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                    | Condition                | Repairer's       | Amount          |
|-----|-----|----------|--------------------------------|--------------------------|------------------|-----------------|
| 56  | 1   |          | *BUMPER GRILLE SUB-ASSY, LOWER | Not Necessary            | 311.10 F         | *- F            |
| 57  | 1   |          | *BRACKET, FR BUMPER            | Not Necessary            | 110.40 F         | *- F            |
| 58  | 1   |          | *TAILGATE OUTSIDE GARNISH      | Repair                   | 504.90 F         | *- F            |
| 59  | 1   |          | *BUMPER FRT                    | Repair                   | 482.00 F         | *- F            |
| 60  | 1   |          | *SOLAR FILM (SN)               | Not Necessary            | 250.00 F         | *- F            |
|     |     |          |                                | <b>Total Parts (S\$)</b> | <b>13,682.00</b> | <b>3,168.97</b> |

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                      | Particulars                                                              | Lab.Type | Repairer's | Amount   |
|-------------------------|--------------------------------------------------------------------------|----------|------------|----------|
| <u>Labour Items</u>     |                                                                          |          |            |          |
| 1                       | PANEL BEATING & BODYWORK.                                                | New      | 1,521.00   | 700.00   |
| 2                       | SPRAY PAINT.                                                             | New      | 2,790.00   | 900.00   |
| 3                       | TO CHECK WIRING AND SYSTEM FUNCTION.                                     | New      | 80.00      | 20.00    |
| 4                       | TO APPLY RUST-PROOFING ON AFFECTED AREA.                                 | New      | 200.00     | 0.00     |
| 5                       | TO TEST AND REFIX REVERSE SENSOR SYSTEM.                                 | New      | 120.00     | 20.00    |
| 6                       | TO TRANSFER REAR TAILGATE MECHANISM.                                     | New      | 120.00     | 50.00    |
| 7                       | TO REMOVE & REFIT REAR QUARTER GLASS LH.                                 | New      | 120.00     | 0.00     |
| 8                       | TO REMOVE & REFIT REAR QUARTER GLASS RH.                                 | New      | 120.00     | 0.00     |
| 9                       | TO REMOVE / REFIT WINDSCREEN.                                            | New      | 240.00     | 120.00   |
| 10                      | TO REMOVE / REFIT SEAT.                                                  | New      | 120.00     | 0.00     |
| 11                      | TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.     | New      | 120.00     | 50.00    |
| 12                      | TO WASH AND VACUUM.                                                      | New      | 60.00      | 0.00     |
| 13                      | TO REPLACE SUNDRY PARTS.                                                 | New      | 100.00     | 0.00     |
| 14                      | TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE. | New      | 120.00     | 30.00    |
| Gross Labour Cost (S\$) |                                                                          |          | 5,831.00   | 1,890.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >