



Poh Kin

Section A - Accident Details

Registration Number	SHC4705M
Case Reference Number	TAX/03/19/2063
Registration Date	10/12/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	TAN ENG LEE
Type of Accident	Head to Rear
Accident Date and Time	15/3/2019 9:00 AM
Accident Reported Date and Time	15/3/2019 10:22 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24100603
Special Instruction to ARC, if any	TP
Prepared Date and Time	15/3/2019 2:08 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



PohSuan

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,721.00	\$700.00
Total Spray Cost	\$2,970.00	\$900.00
Total Spare Part Cost	\$11,543.68	\$2,535.14
Total Other Cost	\$1,770.00	\$290.00
TOTAL COST	\$18,004.68	\$4,425.14
Lump Sum Total	\$18,000.00	\$4,450.00 (L/S)
Number of Repair Days	10.0	6.0
Prepared / Adjusted By	Zhi Yang Phua	Hwee Jie (LKK) / AIG
ARC / Surveyor Sign Off Date		27/03/2019 11:45 AM
Signature		
Remarks	SUP = 1 DAYS	L/S REPAIR, PHOTO AFTER PAINT.



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number: 63685502
Estimator Telephone Number: 65652623
Accident Reporting Number: 64662672

Date Generated: 02/04/2019
User ID: Peh Guan

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1904-0001	Invoice Number	
Quotation Date	01.04.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR END PANEL	\$200.00	\$100.00
TO REPAIR REAR PORTION	\$1,183.00	\$400.00
TO REPAIR FRONT PORTION	\$338.00	\$200.00
Total Labour	\$1,721.00	\$700.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR PANEL	\$180.00	\$100.00
TO RESPRAY BUMPER BEAM	\$180.00	\$100.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$100.00
TO RESPRAY SPOILER	\$180.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$0.00
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00
TO SPRAY FRONT BUMPER LOWER SUB GRILLE	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$2,970.00	\$800.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$50.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$250.00	\$0.00
TO REMOVE & REFIT REAR QUARTER GLASS LH	\$120.00	\$0.00
TO REMOVE & REFIT REAR QUARTER GLASS RH	\$120.00	\$0.00
TO REMOVE / REFIT WINDSCREEN	\$240.00	\$120.00
TO REMOVE / REFIT SEAT	\$120.00	\$0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$50.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$30.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$1,770.00	\$290.00



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore
Fax Number: 63955562
Estimator Telephone Number: 68052623
Accident Reporting Number: 68662672
Date Generated: 02/04/2019
User ID: PchSuan

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace ✓
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check X
		52016-47030	ARM SUB-ASSY, RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Check X
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check X
		52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Check X
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Check X
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace ✓
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace ✓
		76891-47020	BUMPER LIP REAR	1.00	\$228.90	25.00	\$171.68	Replace	Replace ✓
		76088-47020	BUMPER LIP COVER RR/LH	1.00	\$72.20	25.00	\$54.15	Replace	Replace ✓
		76087-47020	BUMPER LIP COVER RR/RH	1.00	\$118.10	25.00	\$88.58	Replace	Replace ✓
		58308-47011	UNDER COVER SUB-ASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Check X
		58307-47060	END PANEL	0.00	\$602.10	0.00	\$0.00	Replace	Check X
			SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Check X
		67005-47241	TAILGATE ASY	1.00	\$1,007.90	25.00	\$755.93	Replace	Replace ✓
		76801-47070-B0	TAILGATE OUTSIDE GARNISH	1.00	\$504.90	100.00	\$0.00	Replace	Repair ✓
		75310-47020	EMBLEM REAR	1.00	\$60.30	25.00	\$45.23	Replace	Replace ✓
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace ✓
		75442-47030	NAME PLATE (PRIUS)	1.00	\$60.80	25.00	\$45.60	Replace	Replace ✓
		75443-47030	NAME PLATE (TOYOTA)	1.00	\$51.90	25.00	\$38.93	Replace	Replace ✓
			NUMBER PLATE	1.00	\$15.00	0.00	\$15.00	Replace	Replace ✓
			NUMBER PLATE FRAME	1.00	\$12.00	0.00	\$12.00	Replace	Replace ✓
		75574-47020	TAIL GATE DOOR GLASS MOULDING, LH	1.00	\$29.40	25.00	\$22.05	Replace	Replace ✓
		75573-47080	TAIL GATE DOOR GLASS MOULDING, RH	1.00	\$29.40	25.00	\$22.05	Replace	Replace ✓
		75575-47030	MOULDING BACK WINDOW, LOWER NO.1	1.00	\$29.40	25.00	\$22.05	Replace	Replace ✓
			SEALANT W/SCREEN	3.00	\$37.00	0.00	\$111.00	Replace	Replace ✓
		76085-47910	SPOILER REAR	0.00	\$953.70	0.00	\$0.00	Replace	Not Given X
		81006-47011	3RD BRAKE LAMP	0.00	\$231.30	0.00	\$0.00	Replace	Check X
		67938-47031C0	TAILGATE TRIM, LH	0.00	\$85.90	0.00	\$0.00	Replace	Check X
		67751-47040C0	TAILGATE TRIM, LOWER	0.00	\$180.70	0.00	\$0.00	Replace	Check X
		67937-47031C0	TAILGATE TRIM, RH	0.00	\$88.30	0.00	\$0.00	Replace	Check X
		64790-47030C0	TAILGATE TRIM, UPPER	0.00	\$49.60	0.00	\$0.00	Replace	Check X
		67750-47071C0	TAILGATE, BOARD ASSY	0.00	\$246.90	0.00	\$0.00	Replace	Check X
		89997-30070	ANTENNA, ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Check Y
		64718-47031B0	END PANEL COVER, DECK TRIM HOLE	0.00	\$46.10	0.00	\$0.00	Replace	Not Given X
		64716-47031B0	END PANEL COVER, DECK TRIM RR	0.00	\$121.10	0.00	\$0.00	Replace	Not Given X
		69350-47030	TAILGATE DOOR LOCK	0.00	\$444.10	0.00	\$0.00	Replace	Check X
		52563-47010	TAIL LAMP BRACKET, LH	0.00	\$30.70	0.00	\$0.00	Replace	Check X
		52562-47010	TAIL LAMP BRACKET, RH	0.00	\$30.70	0.00	\$0.00	Replace	Check X
		81561-47170	TAIL LAMP LH	0.00	\$548.40	0.00	\$0.00	Replace	Check X
		81551-47180	TAIL LAMP RH	0.00	\$557.80	0.00	\$0.00	Replace	Check X
		81602-47091	FENDER RR/LH	0.00	\$766.80	0.00	\$0.00	Replace	Not Given X
			STICKER SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given X

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park Ed, Singapore
FAX Number : 6365552
Estimate Telephone Number : 68662023
Accident Reporting Number : 68662072

Date Generated : 02/04/2018

User ID : PehSuan

		STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	X
	61804-47090	FENDER RR/RH	0.00	\$766.80	0.00	\$0.00	Replace	Not Given	X
		STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	X
		STICKER DECAL SMRT	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	X
	62720-47031	QUARTER GLASS RR/LH	0.00	\$168.10	0.00	\$0.00	Replace	Not Given	X
	62710-47130	QUARTER GLASS RR/RH	0.00	\$846.50	0.00	\$0.00	Replace	Not Given	X
		SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
	52119-47930	BUMPER FRT	1.00	\$482.00	100.00	\$0.00	Replace	Repair	X
	52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Not Given	X
	52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Not Given	X
	57014-47030	ARM SUB-ASSY, FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given	X
	57013-47030	ARM SUB-ASSY, FR BUMPER RH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given	X
	53102-47020	BUMPER GRILLE SUB- ASSY, LOWER	0.00	\$311.10	0.00	\$0.00	Replace	Not Given	X
	52114-47140	BRACKET, FR BUMPER	0.00	\$110.40	0.00	\$0.00	Replace	Not Given	X
		NUMBER PLATE	1.00	\$15.00	0.00	\$15.00	Replace	Replace	X
		NUMBER PLATE FRAME	1.00	\$12.00	0.00	\$12.00	Replace	Replace	X
Total				\$13,261.00		\$2,114.13			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	1.00	\$139.60	25.00	\$104.70	Replace	Replace
		52016-47030	ARM SUB-ASSY, RR BUMPER LH	1.00	\$139.60	25.00	\$104.70	Replace	Replace
		52575-47020	BUMPER SIDE RETAINER RR/RH	1.00	\$94.80	25.00	\$71.10	Replace	Replace
		89997-30070	ANTENNA, ELECTRICAL LOWER REAR	1.00	\$157.40	25.00	\$118.05	Replace	Replace
		81551-47190	TAIL LAMP RH	1.00	\$557.80	10.00	\$502.02	Replace	Replace
Total					1,294.90		1,054.85		

3168.98

-20%

2535.18

+ 700.00

+ 1190.00

4425.18

Lis \$4450/-