

15/5/2010

INS. CASE OWNER:

CC 4/AXA1900

LKK:

IDAC:

ASSIGNMENT

Surveyor:

Kenneth

DOI:

16/3/19

Date / Time:

14/12/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHO 5946L

Name of Insured:

TRANS - LAB.

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

16/12/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

LEO W SORN 16/12/19

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

S9M01HCL / 104868

Policy No.:

VPE 101620520

Make / Model:

KIA NITRO

Place of Accident:

Dunlop ST

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

SLY 67114



INSRS:

WSP:

Tel:

Liability:

RMKS:

Esteem



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time	STAGE	DATE/PIC
SLY 67114-x	Non-Reporting ltr (1st):	
SHO 5946L-x	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☒
	After call ltr to OI:	☒
	Authorisation To Act:	☒
	Release Voucher:	☒
	Final Repair Bill:	☒
	Car Rental Invoice:	☒
	Towing Invoice:	☒
	LTA / GIA:	☒
	Medical Bill:	☒
	PIR:	☒
	Mandate/Reject Instruction:	☒
	LOD	☒
	Payment Breakdown Form:	☒
	Post-Repair Photos:	☒
	Others:	☒
PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost:	SS 15,933.71	Confirm by: Kenneth
Final Liability:	% 100 (Agreed / Assessed)	Email ☐ Call ☐
Repair Cost:	SS 17,091.87	Email ☐ Call ☐
Loss of Rental (LOR):	SS 483.00 (7 days) x \$69	If NO or B 28, Ass. Lia:
Loss of Use (LOU):	SS - (S x days)	
Loss of Income (LOI):	SS - (S x days)	
LOR only ☒ LOU only ☐ LOR + LOU ☐ LOR + LO ☐ [Tick only one]		
GIA/LTA Search	SS 7.48	
Medical:	SS -	
Disbursement:	SS - (e.g. Tow/ Independent)	
Legal Cost	SS -	
Total:	SS 17,574.79	Global Sum SS: 17,100.00
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	SS 17,100.00	Name 1: Esteem Performance Pte Ltd
Payee 2: (Strike if N.A.)	SS -	Name 2:
Payee 3: (Strike if N.A.)	SS -	Name 3:

X GIA

ASS. REC. BY:

REF:

AdA/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

Estern

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

860k 70c

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5-6 days

Res.: Yes or No

Lum Sum:

1.811 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLT 67117

Yr Regn:

12, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota

c.c.

1798

Colour:

M. Silver

A/C: Insured / Std / NI / NA

Sp. Reading

118410

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDKBFU403539041

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

2

mm

R/Bal.

9

mm

L/Bal.

2

mm

L/Bal.

9

mm

D.O.A.

16/3/19

D.O.I.

19/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to

PIP \$15973.71 / - (Red = \$4406.85 / 227.)

* 6 repair days + 1 TRS = 7 days.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format:

Lump Sum / I.B.I: (\$



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

Repair Estimates

SLJ 6711 Y

Parts	(a) Cost / List Price Items	\$	21,023.49
	Plus/Less 25%	\$	5,255.87
	Total of Cost / List	\$	15,767.62
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	45.00
Total Parts Cost		\$	15,812.62
Labour		\$	3,010.00
Total		\$	18,822.62

The above total will be subjected to 7% G.S.T.

Finalised

19078.28

4769.57

14308.71

45

14353.71

1520 1620

15873.71

15923.71

Not Authorized
Penny Bepaint

Name of Surveyor

Kenneth

Company

UKL

Survey conducted on

19/3/19

at

14:00

Remarks By Surveyor

(a) The repair of this vehicle is ☒ authorized / Is not authorized until further notice.

(b) Recommended Days of Repair : 5-6 day(s)

(c) Resurvey : Required / ☒ Not Required

(d) Excess : \$

(e) Signature of surveyor

Sc

Date: 19/3/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLJ 6711 Y**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU403539041**

Submit By : **Carmen Lim**
Year Manufacture : **2016**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate	1	\$45.00	✓ S.N	✓
2	Front number plate garnish	1	\$129.00	✓	✓
3	Bonnet	1	\$812.40	✓	✓
4	Bonnet lock	1	\$130.00	✓	✓
5	Bonnet hinge LH	1	\$57.80	✓	✓
6	Bonnet hinge RH	1	\$57.80	✓	✓
7	Bonnet heat insulator	1	\$440.12	✓	✓
8	Bonnet heat insulator clip	10	\$35.00		✓
9	Front support panel centre	1	\$338.50	✓	✓
10	Front support panel LH	1	\$213.50	✓	✓
11	Front support panel RH	1	\$213.50	✓	✓
12	Headlamp panel LH	1	\$89.20	✓	✓
13	Headlamp panel RH	1	\$89.20	✓	✓
14	Support panel lower	1	\$387.95		X
15	Front support panel top garnish	1	\$285.40	✓	✓
16	Front support panel top garnish clip	10	\$35.00	✓	✓
17	Air duct No. 1	1	\$195.40	✓	✓
18	Air duct - inlet No. 2	1	\$109.75	✓	✓
19	Brace panel	1	\$105.20		✓
20	Condenser	1	\$1,544.70	✓	✓
21	Radiator	1	\$1,841.80	✓	✓
22	Radiator fan motor RH	1	\$455.70	✓	✓
23	Radiator fan motor LH	1	\$491.79	✓	✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

7530.56

7441.36

7828.56

SN: 4K

Spare Parts

Vehicle No. : **SLJ 6711 Y**

Make & Model : **TOYOTA PRIUS**

Chassis No : **JTDKB3FU403539041**

Submit By : **Carmen Lim**

Year Manufacture : **2016**

Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Radiator fan blade LH <i>Dis</i>	1	\$197.80	/	<i>(2)</i>
25	Radiator fan blade RH <i>Dis</i>	1	\$219.80	/	<i>(2)</i>
26	Radiator top hose <i>SL</i>	1	\$49.80		X
27	Radiator bottom hose <i>SL</i>	1	\$46.95		X
28	Radiator spare tank <i>SL</i>	1	\$186.70		<i>3</i>
29	Headlamp LH <i>MSL</i>	1	\$2,531.60	/	<i>(2)</i>
30	Headlamp RH <i>MSL</i>	1	\$2,531.60	/	<i>1</i>
31	Front bumper <i>B</i>	1	\$450.80	/	<i>1</i>
32	Front bumper clip <i>SL</i>	10	\$40.00	/	<i>1</i>
33	Front bumper reinforcement - upper <i>B</i>	1	\$711.50	/	<i>(2)</i>
34	Front bumper reinforcement - lower <i>B</i>	1	\$245.30	/	<i>(2)</i>
35	Front bumper side retainer RH <i>Dis</i>	1	\$107.20	/	<i>1</i>
36	Front bumper side retainer LH <i>Dis</i>	1	\$107.20	/	<i>1</i>
37	Front bumper upper grille <i>CM</i>	1	\$321.90	/	<i>1</i>
38	Front bumper lower grille <i>CM</i>	1	\$148.60	/	<i>1</i>
39	Front bumper emblem <i>CM</i>	1	\$87.10	/	<i>1</i>
40	Front bumper tow cover RH <i>SL</i>	1	\$25.70		X
41	Front bumper tow cover LH <i>SL</i>	1	\$25.70		X
<i>(42)</i>	Front bumper sponge - upper <i>CM</i>	1	\$89.81	/	<i>(2)</i>
<i>(43)</i>	Front bumper sponge - lower <i>CM</i>	1	\$135.70	/	<i>(2)</i>
44	Fog lamp LH <i>MSL</i>	1	\$910.70	/	<i>(2)</i>
45	Fog lamp RH <i>MSL</i>	1	\$910.70	/	<i>(2)</i>
46	Engine under cover <i>CM</i>	1	\$198.30	/	<i>(2)</i>

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

9945-61 ✓

Spare Parts

Vehicle No. : **SLJ 6711 Y**
 Make & Model : **TOYOTA PRIUS**
 Chassis No : **JTDKB3FU403539041**


Submit By : **Carmen Lim**
 Year Manufacture : **2016**
 Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
47	Engine under cover clip <i>nn</i>	10	\$35.00		X
48	Washer tank <i>Sh</i>	1	\$195.60		X
49	Washer tank motor <i>Sh</i>	1	\$196.74		X
50	RH front fender <i>R</i>	1	\$868.70		X
51	RH front fender undershield <i>Sh</i>	1	\$185.64		✓
52	RH front fender undershield clip <i>nn</i>	10	\$25.00		✓
53	RHF fender wording "HYBRID" <i>nn</i>	1	\$44.17		✓
54	LH front fender <i>R</i>	1	\$868.70		X
55	LH front fender undershield <i>Sh</i>	1	\$195.60		X
56	LH front fender undershield clip <i>nn</i>	10	\$25.00		X
57	LHF fender wording "HYBRID" <i>nn</i>	1	\$44.17		X
58					
59					
60					
61					
62					
63					
64					
65					
66					
67					
68					
69					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

44.17 ✓



Submit By : Carmen Lim
Year of Manufacture : 2016

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

ESTEEM PERFORMANCE PTE LTD

BLK 5033 ANG MO KIO INDUSTRIAL PARK 2

#01-259 SINGAPORE 569536

Tel:64841221 Fax:64847829

Spare Parts

Vehicle No. :

SLJ 6711 Y

Make & Model :

TOYOTA PRIUS

Chassis No. :

JTDKB3FU403539041

Submit By :

Year Manufacture :

Engine No. :

Cost / List**Supplementary**

S/No.	Part Description	Qty	Unit Price	Price
1	Air Cleaner Box <i>CMA</i>	1	\$957.80	✓
2	Front bumper reinforcement lower bracket LH <i>Ry</i>	1	\$137.30	✓
3	Front bumper reinforcement lower bracket RH <i>Ry</i>	1	\$137.30	✓
4	Front bumper top rubber <i>CMA</i>	1	\$34.40	✓
5	Air Duct No.3 <i>nd</i>	1	\$49.74	✓
6	Radiator fan cowling <i>CMA</i>	1	\$241.40	✓
7		1		
8		1		
9		1		
10		1		
11		1		
12		1		
13		1		
14		1		
15		1		
16		1		
17		1		
18		1		
19		1		
20		4		
21		1		
22		1		
23		1		

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

1557.94 ✓



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLJ 6711 Y

Parts	(a) Cost / List Price Items	\$	21,023.49
	Plus/Less 25%	\$	5,255.87
	Total of Cost / List	\$	15,767.62
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	45.00
Total Parts Cost		\$	15,812.62
Labour		\$	3,010.00
Total		\$	18,822.62

The above total will be subjected to 7% G.S.T.



Not Authorized
Rebody B & paint

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 19/3/19 at 14:00

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 5-6 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$

(e) Signature of surveyor : Le Date: 19/3/19

\$20380.56



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLJ 6711 Y**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU403539041**

Submit By : **Carmen Lim**
Year Manufacture : **2016**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate	1	\$45.00	S.N	✓
2	Front number plate garnish	1	\$129.00		✓
3	Bonnet	1	\$812.40		✓
4	Bonnet lock	1	\$130.00		✓
5	Bonnet hinge LH	1	\$57.80		?
6	Bonnet hinge RH	1	\$57.80		?
7	Bonnet heat insulator	1	\$440.12		?
8	Bonnet heat insulator clip	10	\$35.00		?
9	Front support panel centre	1	\$338.50		?
10	Front support panel LH	1	\$213.50		?
11	Front support panel RH	1	\$213.50		?
12	Headlamp panel LH	1	\$89.20		X
13	Headlamp panel RH	1	\$89.20		?
14	Support panel lower	1	\$387.95		X
15	Front support panel top garnish	1	\$285.40		✓
16	Front support panel top garnish clip	10	\$35.00		✓
17	Air duct	1	\$195.40		?
18	Air duct - inlet	1	\$109.75		?
19	Brace panel	1	\$105.20		?
20	Condenser	1	\$1,544.70		?
21	Radiator	1	\$1,841.80		?
22	Radiator fan motor RH	1	\$455.70		?
23	Radiator fan motor LH	1	\$491.79		?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SLJ 6711 Y**

Make & Model : **TOYOTA PRIUS**

Chassis No. : **JTDKB3FU403539041**

Submit By : **Carmen Lim**

Year Manufacture : **2016**

Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Radiator fan blade LH	1	\$197.80		?
25	Radiator fan blade RH	1	\$219.80		?
26	Radiator top hose <i>SL</i>	1	\$49.80		X
27	Radiator bottom hose <i>SL</i>	1	\$46.95		X
28	Radiator spare tank	1	\$186.70		?
29	Headlamp LH	1	\$2,531.60		?
30	Headlamp RH <i>NGE M</i>	1	\$2,531.60		✓
31	Front bumper <i>B</i>	1	\$450.80		✓
32	Front bumper clip <i>SL</i>	10	\$40.00		✓
33	Front bumper reinforcement - upper	1	\$711.50		?
34	Front bumper reinforcement - lower	1	\$245.30		?
35	Front bumper side retainer RH <i>DIY</i>	1	\$107.20		✓
36	Front bumper side retainer LH <i>DIY</i>	1	\$107.20		✓
37	Front bumper upper grille <i>CM</i>	1	\$321.90		✓
38	Front bumper lower grille <i>CM</i>	1	\$148.60		✓
39	Front bumper emblem <i>CM</i>	1	\$87.10		✓
40	Front bumper tow cover RH <i>SL</i>	1	\$25.70		X
41	Front bumper tow cover LH <i>SL</i>	1	\$25.70		X
42	Front bumper sponge - upper	1	\$89.81		?
43	Front bumper sponge - lower	1	\$135.70		?
44	Fog lamp LH	1	\$910.70		?
45	Fog lamp RH	1	\$910.70		?
46	Engine under cover	1	\$198.30		?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts


Vehicle No. : **SLJ 6711 Y**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU403539041**

Submit By : **Carmen Lim**
Year Manufacture : **2016**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
47	Engine under cover clip	10	\$35.00		7
48	Washer tank	1	\$195.60		X
49	Washer tank motor	1	\$196.74		X
50	RH front fender	1	\$868.70		X
51	RH front fender undershield	1	\$185.64		✓
52	RH front fender undershield clip	10	\$25.00		✓
53	RHF fender wording "HYBRID"	1	\$44.17		✓
54	LH front fender	1	\$868.70		X
55	LH front fender undershield	1	\$195.60		X
56	LH front fender undershield clip	10	\$25.00		X
57	LHF fender wording "HYBRID"	1	\$44.17		X
58					
59					
60					
61					
62					
63					
64					
65					
66					
67					
68					
69					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



Submit By : Carmen Lim
Year of Manufacture : 2016

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	7200G
Vehicle Details	
Vehicle No.:	SLJ6711Y
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	2ZRR971180
Chassis No.:	JTDKB3FU403539041
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$31,008.00
Original Registration Date:	21 Dec 2016
First Registration Date:	21 Dec 2016
Transfer Count:	0
Actual ARF Paid:	\$5,412.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Dec 2026
PARF Rebate Amount:	\$4,059.00
Intended COE Rebate Details	
COE Expiry Date:	20 Dec 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$56,000.00
COE Rebate Amount:	\$43,400.00
Total Rebate Amount:	\$47,459.00

The information contained herein is correct as at 20 Mar 2019

OK

Service Request Details

Claim

S9M01HC1

Reference

None

Loss Date

16 March 2019

Report Date

19 Mar 2019 9:02:00 AM

Request Date

19 March 2019

Due Date

19 March 2020

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Finish the work

Complete Work

More

Vehicle Information

Incident Vehicle Registration #

SLJ6711Y

Make

TPVD TOYOTA

Model

PRIUS HYBRID 1.8 CVT

Primary Contact/Insured

TRANS-CAB SERVICES PTE LTD

No.2 ANG MO KIO STREET 63, 569111, Singapore

Claim Handler

CHAN Kian Chuan

6568804269

kianchuan.chan@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Tuesday, 19 March 2019 9:18 AM
To: assignments
Cc: Admin A
Subject: FW: REQUEST FOR PRI SURVEY SLJ6711Y
Attachments: MSGR-MARS00002310-SLJ6711Y-GIA (1).pdf

10.12am @ 19/3/19

Carmen
Vehicle In-

SMARTCLAIM NEW CASE

SPOKEN WITH CARMEN -VEH IN ***KINDLY ARRANGE KENNETH SURVEY TODAY ASAP

Best Regards,

Shu Pei | Admin

LKK Auto (S) Pte Ltd

Phone: 6366-0622 | Email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carmen Lim <carmen@esteempref.com.sg>
Sent: Monday, 18 March 2019 4:55 PM
To: SG Motor Survey <motor.survey@axa.com.sg>
Cc: serena@esteempref.com.sg
Subject: REQUEST FOR PRI SURVEY SLJ6711Y

Dear Sir/Madam,

**NOTICE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS
PURSUANT TO AXA ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES
(NIMAP)**

We act for the Motor Vehicle Insurance Pte Ltd who has appointed the under-mentioned workshop to repair his motor vehicle no SLJ6711Y.

Please be informed that the said vehicle can be inspected at :

Name: Motor Vehicle Insurance Performance Pte Ltd

Add: 51, Paya Ubi Industrial Park, Ubi Avenue 1, Singapore 571718

Tel :

Fax :

We hereby give 2 clear days notice to conduct a pre-repair inspection of the said vehicle at the above-mentioned workshop during office hours.

If you fail to conduct a pre-repair inspection within the next 2 working days excluding any intervening Saturday or public holiday, the above-mentioned workshop will commence repairs should you fail to conduct a pre-repair inspection.

We request your Priority / LKK to survey the car.

Thank you



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 20/03/2019

Survey Details:

Date of loss	167/3/2019
Date of appointment	19-Mar-19
Date of survey	19-Mar-19
Location of survey	ESTEEM PERFORMANCE PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SLJ 6711Y
Make and Model	TOYOTA PRIUS
Date of registration	21/12/2016
Excess	
Market Value	\$76,000
Parf Rebate	\$47,459
Nett Loss	\$28,541

Repair details:

Initial Estimate	\$ 18,822.62
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 14,353.71
Check items (estimate)	
Labour	\$ 1,620.00
Total	\$ 15,973.71
Lump Sum(if applicable)	\$ -

Number of days for repair	5-6 DAYS
---------------------------	----------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

We have not authorized repairs. BOLA 4 b ; INSURED FROM MINOR ROAD

Mandate:

Liability(TP)		100%
Proposed repair cost	\$	17,091.87
Loss of rental	\$	483.00 \$69 x 7 days
LTA search fees	\$	7.48
Proposed Total	\$	17,582.35



RE: Re:MANDATE IA - ESTEEM - SLJ 6711Y

Type

🔔 Question

Message

Hi KC, TP reject offer. Counter propose as per their LOD. Kindly let us have your instruction/approval.

Thanks - CCL

Reply



Re:MANDATE IA - ESTEEM - SLJ 6711Y

Type

🔔 Question

Message

PLS PROCEED AS FOLLOWS COR \$15,200.00 (W/GST) LOR \$483 LTA \$7.48 TOTAL \$15,690.48 ~
\$15,700.00 ALL IN

Reply



Re:RE: Re:MANDATE IA - ESTEEM - SLJ 6711Y

Type

🔗 Question

Message

REVISED OFFER \$16,700.00 ALL IN

Reply



RE: Re:RE: Re:RE: Re:MANDATE IA - ESTEEM - SJ 6711Y

Type

🔔 Question

Message

Hi KC, TP reject offer, counter propose G/S \$17,300. Kindly let us have your approval/instruction. Thanks -
CCL

Reply

**Re:RE: Re:RE: Re:MANDATE IA - ESTEEM - SLJ 6711Y**

Type

Question

Message

REVISED OFFER @ \$17,100.00

[Reply](#)



**Re:RE: Re:RE: Re:RE: Re:MANDATE IA - ESTEEM - SLJ
6711Y**

Type

 Question

Message

MAINTAIN

Reply



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 250, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Your Ref : SHD 594 L

Our Ref : CIV1301884 / SLJ 6711 Y

Date : 19-06-19

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

RE : ACCIDENT INVOLVING SLJ 6711 Y & SHD 594 L
ACCIDENT DATE 16-03-2019
ACCIDENT ALONG JUNCTION OF CLIVE STREET AND DUNLOP STREET

We are the workshop for the owner of motor vehicle no : SLJ 6711 Y which was involved in the captioned accident. The vehicle was surveyed by an independent appraiser and the claims below are based on its recommendation sum being for the repair cost and the period of repair (Strictly on a Without Prejudice Basis)

As the accident was caused by the negligent act of your insured SHD 594 L we are submitting these claims for your consideration.

1	Cost of repair	S \$	17,091.87
2	Loss of rental <u>7</u> days @ \$ <u>69</u> / day	S \$	483.00
3	Surveyor Fee	S \$	0.00
4	GIA report fees (S\$ 15.00 for search fee & S\$ 14.00 for each report fee)	S \$	0.00
5	LTA Fee	S \$	7.48
		S \$	17,582.35

We enclosed herewith the following documents to support the claims:-

- a) Authorization letter
- b) Final repair bill(s)
- c) LTA search
- d) GIA report(s) / result
- e) Insurance certificate, etc.....

Kindly look into the matter and let us hear from you on the settlement of our client's claim as soon as possible. Thank you.

Yours faithfully

Carmen Lim

Claims Executive

Email : carmen@esteemperf.com.sg



ESTEEM
PERFORMANCE

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio Industrial Park 2, #01-259/01-251, Singapore 569536.

Tel : 6484 1221 Fax : 6484 7829

385 Sin Ming Drive (Inside Vicom) Singapore 575718.

Tel : 6753 2112 Fax : 6451 0394

Co. Reg No. : 200005485N GST Reg No. : 20-0005485-N

M/S : AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

ATTN: Motor Claim Department

Your Ref No: SHD594L
Claim Type: Third Party
Accident Date: 16/03/2019
TP Veh Reg No: SHD594L

Claim No: CER1301449
Final No: CIV1301884
Date: 17 May 2019
Policy No: A29114756MKF
Veh Reg No: SLJ6711Y
Make/Model: TOYOTA PRIUS
HYBRID 1.8 CVT
Chassis No: JTDKB3FU403539041
Engine No: 2ZRR971180
Reg. Date:

Tax Invoice to Vehicle No :SLJ6711Y

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
Others			
1 COST OF REPAIR	1 PCS	15,973.71	
		15,973.71	15,973.71
Total			S\$ 15,973.71
Add GST @ 7%			1,118.16
Total Amount Payable			<u>S\$ 17,091.87</u>

TOTAL: SINGAPORE DOLLAR SEVENTEEN THOUSAND NINETY ONE AND CENTS EIGHTY SEVEN ONLY

The above vehicle was surveyed by KENNETH on 19/03/2019

For Esteem Performance Pte Ltd



AUTHORISED SIGNATURE

E. & O. E.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM19004945/Kgb3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: KIAN CHUAN			Date : 14-11-2019	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 594L	Veh. Inspected	SLJ 6711Y	
Policy No.	VPX/P1680520	Coverage (\$)	0.00	
Claim No.	S9M01HC1	Excess (\$)	0.00	
Assign From	KIAN CHUAN	Assign Date	19/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTDKB3FU403539041	Colour	METALLIC SILVER	
Odometer	118410	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	8 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	8 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	9 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/03/2019	Inspection Date	19/03/2019	
Survey held at	ESTEEM PERFORMANCE PTE LTD BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 6711Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT NUMBER PLATE GARNISH (CONSISTENT)	CRACKED	129.00	129.00
1	BONNET (CONSISTENT)	BENT	812.40	812.40
1	BONNET LOCK (CONSISTENT)	DISTORTED	130.00	130.00
1	BONNET HINGE LH (CONSISTENT)	DISTORTED	57.80	57.80
1	BONNET HINGE RH (CONSISTENT)	DISTORTED	57.80	57.80
1	BONNET HEAT INSULATOR (CONSISTENT)	CRACKED	440.12	440.12
10	BONNET HEAT INSULATOR CLIP (CONSISTENT)	NOT NECESSARY	35.00	-
1	FRONT SUPPORT PANEL CENTRE (CONSISTENT)	BUCKLED	338.50	338.50
1	FRONT SUPPORT PANEL LH (CONSISTENT)	BENT	213.50	213.50
1	FRONT SUPPORT PANEL RH (CONSISTENT)	BENT	213.50	213.50
1	HEADLAMP PANEL LH (CONSISTENT)	DAMAGED	89.20	89.20
1	HEADLAMP PANEL RH (CONSISTENT)	BENT	89.20	89.20
1	SUPPORT PANEL LOWER (CONSISTENT)	TO REPAIR SEE LABOUR	387.95	-
1	FRONT SUPPORT PANEL TOP GARNISH (CONSISTENT)	CRACKED	285.40	285.40
10	FRONT SUPPORT PANEL TOP GARNISH CLIP (CONSISTENT)	NECESSARY	35.00	35.00
1	AIR DUCT NO.1 (CONSISTENT)	CRACKED	195.40	195.40
1	AIR DUCT - INLET NO.2 (CONSISTENT)	DENTED	109.75	109.75
1	BRACE PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	105.20	-
1	CONDENSER (CONSISTENT)	BENT / PUNCTURE	1,544.70	1,544.70
1	RADIATOR (CONSISTENT)	BENT	1,841.80	1,841.80
1	RADIATOR FAN MOTOR RH (CONSISTENT)	JAMMED	455.70	455.70
1	RADIATOR FAN MOTOR LH (CONSISTENT)	JAMMED	491.79	491.79
1	RADIATOR FAN BLADE LH (CONSISTENT)	DISTORTED	197.80	197.80
1	RADIATOR FAN BLADE RH (CONSISTENT)	DISTORTED	219.80	219.80
1	RADIATOR TOP HOSE (CONSISTENT)	SERVICEABLE	49.80	-
1	RADIATOR BOTTOM HOSE (CONSISTENT)	SERVICEABLE	46.95	-
1	RADIATOR SPARE TANK (CONSISTENT)	SERVICEABLE	186.70	-
1	HEADLAMP LH (CONSISTENT)	MTG CRACKED	2,531.60	2,531.60
1	HEADLAMP RH (CONSISTENT)	MTG CRACKED	2,531.60	2,531.60

Report Ref No. CC4/ASM19004945/Kgb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER (CONSISTENT)	BENT	450.80	450.80
10	FRONT BUMPER CLIP (CONSISTENT)	NECESSARY	40.00	40.00
1	FRONT BUMPER REINFORCEMENT - UPPER (CONSISTENT)	BENT	711.50	711.50
1	FRONT BUMPER REINFORCEMENT - LOWER (CONSISTENT)	BENT	245.30	245.30
1	FRONT BUMPER SIDE RETAINER RH (CONSISTENT)	DISTORTED	107.20	107.20
1	FRONT BUMPER SIDE RETAINER LH (CONSISTENT)	DISTORTED	107.20	107.20
1	FRONT BUMPER UPPER GRILLE (CONSISTENT)	CRACKED	321.90	321.90
1	FRONT BUMPER LOWER GRILLE (CONSISTENT)	CRACKED	148.60	148.60
1	FRONT BUMPER EMBLEM (CONSISTENT)	CRACKED	87.10	87.10
1	FRONT BUMPER TOW COVER RH (CONSISTENT)	SERVICEABLE	25.70	-
1	FRONT BUMPER TOW COVER LH (CONSISTENT)	SERVICEABLE	25.70	-
1	FRONT BUMPER SPONGE - UPPER (CONSISTENT)	CRACKED	89.81	89.81
1	FRONT BUMPER SPONGE - LOWER (CONSISTENT)	CRACKED	135.70	135.70
1	FOG LAMP LH (CONSISTENT)	MTG CRACKED	910.70	910.70
1	FOG LAMP RH (CONSISTENT)	MTG CRACKED	910.70	910.70
1	ENGINE UNDER COVER (CONSISTENT)	CRACKED	198.30	198.30
10	ENGINE UNDER COVER CLIP (CONSISTENT)	NOT NECESSARY	35.00	-
1	WASHER TANK (CONSISTENT)	SERVICEABLE	195.60	-
1	WASHER TANK MOTOR (CONSISTENT)	SERVICEABLE	196.74	-
1	RH FRONT FENDER (CONSISTENT)	TO REPAIR SEE LABOUR	868.70	-
1	RH FRONT FENDER UNDERSHIELD (CONSISTENT)	SERVICEABLE	185.84	-
10	RH FRONT FENDER UNDERSHIELD CLIP (CONSISTENT)	NOT NECESSARY	25.00	-
1	RHF FENDER WORDING "HYBRID" (CONSISTENT)	NECESSARY	44.17	44.17
1	LH FRONT FENDER (CONSISTENT)	TO REPAIR SEE LABOUR	868.70	-
1	LH FRONT FENDER UNDERSHIELD (CONSISTENT)	SERVICEABLE	195.60	-
10	LH FRONT FENDER UNDERSHIELD CLIP (CONSISTENT)	NOT NECESSARY	25.00	-
1	LHF FENDER WORDING "HYBRID" (CONSISTENT)	NOT NECESSARY	44.17	-
1	AIR CLEANER BOX (CONSISTENT) (ADDITIONAL)	CRACKED	957.80	957.80
1	FRONT BUMPER REINFORCEMENT LOWER BRACKET LH (CONSISTENT) (ADDITIONAL)	BENT	137.30	137.30

Report Ref No. CC4/ASM19004945/Kgb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER REINFORCEMENT LOWER BRACKET RH (CONSISTENT) (ADDITIONAL)	BENT	137.30	137.30
1	FRONT BUMPER TOP RUBBER (CONSISTENT) (ADDITIONAL)	CUT	34.40	34.40
1	AIR DUCT NO.3 (CONSISTENT) (ADDITIONAL)	DENTED	49.74	49.74
1	RADIATOR FAN COWLING (CONSISTENT) (ADDITIONAL)	CRACKED	241.40	241.40
	LESS 25% DISCOUNT		-5,645.41	-4,769.57
			16,936.22	14,308.71
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN) (CONSISTENT)	BENT	45.00	45.00
			45.00	45.00
	LABOUR			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER, BONNET, SUPPORT PANEL, RH FENDER, LHF FEDNER) INCLUSIVE OF THE REPAIR OF SUPPORT PANEL LOWER, BRACE PANEL, RH FRONT FENDER AND LH FRONT FENDER.		1,200.00	600.00
	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER, BONNET, SUPPORT PANEL, RH FENDER, LHF FEDNER)		1,400.00	800.00
	TO CHECK WIRING & FOCUS HEADLAMP.		50.00	20.00
	TO REMOVE & REFIT RADIATOR, CONDENSER TO ASSIST WORK LOAD, TO TOP UP A/C GAS.		150.00	100.00
	TO TUFF COAT.		150.00	50.00
	TOWING.		60.00	50.00
			3,010.00	1,620.00
	GRAND TOTAL		19,991.22	15,973.71
	RECOMMENDED COST OF REPAIRS			15,973.71

Report Ref No. CC4/ASM19004945/Kgb3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.